

ASSIGNED BY: CS3 / MSG17021219 / qb-102 11/11/17  
 Maimen Wilson ASSIGNMENT OFFICER:  
 From: Monica Chung MSIG 13032018  
 Estimated Cost: \_\_\_\_\_  
 OD  TP / WS / TR RES / OD RES / EVA / INV / MV / CS  
 To Inspect Vehicle No: YN 2332J Insured: SFU 8478X  
 at Workshop no: Bak Heng Motor Tel: 9788 8579  
 of 5032, AMK Ind Park 2, #01-291, 569535  
 Policy No: 27588995 SMP Claim No: 535657  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ Date: 3/11/2017  
 (Client's Record)  
 CA / REV / REP. / REV 24 HRS: 'wp' 13.11.2017 @ 11am owner waiting  
 Date/Time: 10.22am @ 7/11/17 Person Contacted: Kelvin H.O.D. Endorsement  
 Status:  INACT

Date/Time	Action/Instructions (X) Estimate	YN# Profile
	YN 2332J - X	
	SFU 8478X - X	
	Dismantle Part : 14.11.2017	
	After repair : 17.11.2017	

18/11/17 7:50pm Email to Monica Chung from Maimen.  
 15/3/18 submit LS @ 3400, 4 days (Red @ 7800, 45%)

RECEIVED 2018

REF: MSH1

2300C

Surveyor  
Maiman

ASSIGNMENT

From: \_\_\_\_\_ Date: 13-11-2017

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YN 2332J

at Workshop m/s Bak Heng

of 5032 Amk Ind Park 2 #01-29

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: YN 2332J Yr Regn: 2011, Apr 08

Type: M.Car / M.Cycle / Bus / Van / Tray / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: ISUZU FVR34SUAD c.c. 7790

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 37331.5 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JALFVR 34737-0143

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition) Item owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Tyre Size: F: 275 / 70 R22.5

R: 275 / 70 R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or West Lake (V)

Front 375 (CR)

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 31/11/2017 D.O.I. 13/11/2017

Survey held at As Above 11:15 am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Light Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

Range \$ 3500 - 4500

3 Day Repair

RECEIVED 05 MAR 2018

21/2/2018

Date/Time, File Pass to? 13/11/2017  : Preli. Report

1) 08/13/2018  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: 180

Transportation: \_\_\_\_\_

\_\_\_\_\_ S + RS. SI

Photos \_\_\_\_\_

Others \_\_\_\_\_

\_\_\_\_\_

TOTAL 180

Report Format: PRS. MEX TP

Lump Sum / I.B.I. (\$) 3400

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17021219/Wqb-1

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-03-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFU 8478X	Veh. Inspected	YN 2332J
Policy No.	27588995SMP	Coverage (\$)	0.00
Claim No.	535657	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	13/03/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	03/11/2017	Inspection Date	13/03/2018
Survey held at	BAK HENG MOTOR REPAIRING CO. BLOCK 5032 ANG MO KIO INDUSTRIAL PARK II, #01-291 SINGAPORE 569535		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Nov 2017		07 Nov 2017 10:20 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS

[Created by insurer]

<b>Insured:</b>	LEO CHI WEI, ID: S7417323C, Tel: +6597660540, Email: NOEMAIL		
<b>Main Claimant:</b>	POWER-VAC INDUSTRIAL SERVICES PTE LTD, Co. Reg. No.: 200405173K		
<b>Vehicle Reg. No.:</b>	YN2332J	<b>Date of Loss:</b>	03/11/2017 15:00 - :59
<b>Claim Type:</b>	TP / 535657	<b>Policy/Cover Note No.:</b>	27588995SMP (Comprehensive) Coverage: 30/09/2017 - 29/09/2018
<b>Vehicle Reg. No. (Insured):</b>	SFU8478X	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	
<b>Repairer:</b>	Bak Heng Motor Repairing (HQ) 5032, ANG MO KIO INDUS PARK 2, #01-291, 569535 Ang Mo Kio - Tel: 9788 8579		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 08/11/2017]		
<b>Driver/Custodian (Insured):</b>	LEO CHI WEI (43 / Male), NRIC: S7417323C, Tel: +6597660540		
<b>Adj Asg. Remarks:</b>	PRI		

#### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

#### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

木興連嗎呷汽車修理公司  
**BAK HENG MOTOR REPAIRING CO.,**

Block 5032, Ang Mo Kio Industrial Park II, #01-291, Singapore 2056.

TEL: 4816829, 4816820

Reg. No: 235661000X

INVOICE NO. BH/TCMG/08/18

Date: 8<sup>th</sup> January 2018

M/S/ Power-Vac Industrial Services Pte Ltd  
C/O Blk 5032 Ang Mo Kio Ind Park 2  
#01-291  
Singapore 569535

**COST OF REPAIRS FOR VEHICLE NO. YN 2332 J**

Lump sum costs of repairs : S\$6,200.00

Singapore Dollars : Six Thousand Two Hundred Only.

Yours faithfully



.....  
M/s Bak Heng Motor Repairing Co.



# POWER-VAC Industrial Services Pte Ltd

## QUOTATION

Co. Regn. & GST No. 20-0202300-C

Page 1 of 1

To: 01048  
 EPM ENGINEERING PTE LTD  
 531 UPPER CROSS ST, #04-48, HONG LIM  
 COMPLEX  
 SINGAPORE 050531  
 Telephone: 9178-3617

From  
 JOHN  
 Handphone: 9670-0213  
 Quotation No. PVI/17-02-019  
 Date: 03/07/2017

Attention: Mr Patrick  
 e-mail: tr133\_engineer@yahoo.com.sg

Dear Sir/Madam,

Subject: QUOTATION FOR RENTAL OF VACUUM TANKER SERVICE

We are pleased to submit our quotation for your kind perusal.

Cost:

No.	Description / Frequency	Qty.	Unit Price	*Amount
1.	RENTAL ONE UNIT VACUUM TANKER WITH ONE DRIVER & ONE ASSISTANT (PER DAY) 8.00 AM - 6.00 PM	1.0	\$1,600.00	\$1,600.00

\*Price quoted is subjected to prevailing GST, currently at: 7%.

Terms of payment: 30 Days

Validity of quote: This quotation is valid for 30 days from date of issue.

Thank you and best regards

This is a computer generated quote,  
 no signature is required.

Power-Vac Industrial Services Pte Ltd

Confirmation and acceptance of order

Customer's stamp and signature

# CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009  
Fax: 62874788 Tel: 62856178

## INVOICE

M/S Power-Vac Industrial Services Pte Ltd  
C/o Blk 5032 Ang Mo Kio Industrial Park 2  
#01-291  
Singapore 569535

Invoice No: CL 11943 TP  
Our Ref: CL 11943 YN 2332 J  
Date: 8th January 2018

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	<u>Vehicle No: YN 2332 J</u> Charges for accident vehicle inspection and appraisal report, photographs, transportation & misc*** (photographs - 84 copies)			\$784.00
<b>Total:</b>				<b>\$784.00</b>

We thank you for the opportunity to serve you and assure you of our best at all times

  
PATRICK KING  
Automotive Engineer Assessor  
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"

# CARLINK CONSULTANCY


60 Hillside Drive  
Singapore 549009

Tel : 62856178

Fax : 62874788

## ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CL 11943 YN 2332 J

<b>1 REFERENCE</b>					
Date of request	:	13th November 2017			
Requested by	:	M/S Power-Vac Industrial Services Pte Ltd C/o Blk 5032 Ang Mo Kio Industrial Park 2, #01-291, Se 569535			
Type of claim	:	Third party			
Workshop	:	M/S Bak Heng Motor Repairing Co Blk 5032 Ang Mo Kio Industrial Park 2, #01-291 Singapore 569535			
Date of survey	:	13th November 2017			
Accident date	:	3rd November 2017			
<b>2 DETAILS OF VEHICLE</b>					
Registration No.	:	YN 2332 J			
Make & Model	:	Isuzu FVR34SUQD with Vacuum			
Date of registration	:	8th April 2011			
Engine No.	:	6HK1603707			
Chassis No.	:	JALFVR347B7000143			
Speedometer reading	:	373310 Km			
Transmission	:	Manual			
Colour	:	Blue			
<b>3 STATIC CHECK</b>					
Steering	:	see annex(es)	Paintwork	:	Good
Footbrake	:	see annex(es)	Modification	:	Nil
Handbrake	:	see annex(es)	General condition	:	Good
<b>4 TYRE CONDITION</b>					
		<u>Nearside/Make</u>	<u>Offside/Make</u>	<u>Size</u>	
Front tyre	:	8mm/Westlake	8mm/Westlake	:	275/70 R22.5
Rear tyre	:	8mm/bridgestone	8mm/Bridgestone	:	275/70 R22.5
<b>5 POINT OF IMPACT</b>					
See Annex(es) and Motor Accident Reports					
					
<b>6 REMARK</b>					
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.					

## Annex A : Assesement / Adjustment on Spare Parts

YN 2332 J

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
<b>List Items</b>						
1	Front bumper assy	Dented/bent	1	\$1,180.00	15%	\$1,003.00
2	Front bumper step garnish LH	Serviceable	1	\$200.00	100%	\$0.00
3	Front bumper step garnish RH	Serviceable	1	\$200.00	100%	\$0.00
4	Front bumper bracket RH	Bent	1	\$98.00	15%	\$83.30 <i>XR</i>
5	Front bumper head lamp RH	Grazed/cracked	1	\$631.00	15%	\$536.35
6	Front bumper head lamp rim garnish	Bent/cut	1	\$145.00	15%	\$123.25 <i>CRA</i>
7	Front bumper head lamp holder bracket RH	Distorted/cracked	1	\$169.00	15%	\$143.65
8	Front bumper signal lamp RH	Cracked	1	\$122.00	15%	\$103.70 <i>X NN</i>
9	Front bumper side lamp RH	Slack/cracked	1	\$120.00	15%	\$102.00 <i>X NN</i>
10	Front bumper head lamp lower garnish RH	Grazed	1	\$43.00	15%	\$36.55 <i>X SVC</i>
11	Front RH door assy	Repair	1	\$2,800.00	100%	\$0.00
12	Front RH door outer protector garnish	Slack/distorted/cut	1	\$382.00	15%	\$324.70 <i>X NN</i>
13	Front RH door signal lamp	Grazed/cracked	1	\$121.00	15%	\$102.85
14	Front RH door glass outer moulding (complete)	Serviceable	1	\$325.00	100%	\$0.00
15	Front wheel arch panel	Repair	1	\$680.00	100%	\$0.00
16	Front wheel arch panel garnish rubber RH	Grazed/cut	1	\$510.00	15%	\$433.50 <i>X NN</i>
17	Front step board (upper) RH	Grazed/distorted	1	\$310.00	15%	\$263.50
18	Front step board garnish (upper) RH	Distorted/cut	1	\$380.00	15%	\$323.00
19	Front step board (lower) RH	Grazed/bent	1	\$320.00	15%	\$272.00 <i>X SVC</i>
20	Front step board garnish (lower) RH	Grazed/slack/cut	1	\$380.00	15%	\$323.00
21	Front step board garnish stey bracket (top) RH	Bent/cut	2	\$140.00	15%	\$119.00 <i>XR</i>
22	Front step board reinforcement bracket (lower) RH	Dented/bent	1	\$510.00	15%	\$433.50 <i>X NN</i>
23	Front step board front lower splash guard RH	Cut	1	\$121.00	15%	\$102.85
24	Front wheel splash shield RH	Slack grazed	1	\$251.00	15%	\$213.35
<b>Total for Spare Parts :</b>				<b>\$10,138.00</b>		<b>\$5,043.05</b>

## Annex B : Adjustment on Labour and Spray Painting

YN 2332 J

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	Anti rust treatment	\$100.00	\$80.00 X
2	To check wiring system and lights	\$100.00	\$60.00 30
3	To remove & transfer front RH door mechanism	\$100.00	\$0.00
4	To putty and respray paint on affected area	\$1,200.00	\$900.00 500
5	To remove damaged and necessary parts and attachments; knock, jack, cut, weld, reshape and align all affected portions. Reinstall all undamaged parts and necessary new parts into original positions.	\$1,800.00	\$1,200.00 600
<b>TOTAL FOR LABOUR &amp; SPRAY PAINTING :</b>		<b>\$3,300.00</b>	<b>\$2,240.00</b>

4 days

### Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$10,138.00	\$5,043.05
TOTAL FOR LABOUR & SPRAY PAINTING :	\$3,300.00	\$2,240.00
<b>TOTAL REPAIR COSTS :</b>	<b>\$13,438.00</b>	<b>\$7,283.05</b>

## CARLINK CONSULTANCY

YN 2332 J

### Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S Bak Heng Motor Repairing Co estimated repair cost is **S\$13,438.00** and we have adjusted it to **S\$7,283.05** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.


The repairer have agreed to undertake the repairs on a contract lump sum of **S\$6,200.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of 6 working days.

We have advised the repairer that the inspection was conducted strictly on a **WITHOUT PREJUDICE** basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,  
CARLINK CONSULTANCY

  
PATRICK NG  
Automotive Engineer Assessor  
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Nov 2017		07 Nov 2017 10:20 <a href="#">Edit Adj Rpt</a>	<b>S\$3,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by Insurer]</b>							
Insured:	<b>LEO CHI WEI</b> , ID: S7417323C, Tel: +6597660540, Email: NOEMAIL								
Main Claimant:	<b>POWER-VAC INDUSTRIAL SERVICES PTE LTD</b> , Co. Reg. No.: 200405173K								
Vehicle Reg. No.:	<b>YN2332J</b>	Date of Loss:	03/11/2017 15:00 - :59						
Claim Type:	<b>TP / 535657</b>	Policy/Cover Note No.:	27588995SMP (Comprehensive) Coverage: 30/09/2017 - 29/09/2018						
Vehicle Reg. No. (Insured):	<b>SFU8478X</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Bak Heng Motor Repairing (HQ)</b> 5032, ANG MO KIO INDUS PARK 2, #01-291, 569535 Ang Mo Kio - Tel: 9788 8579								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>SIMON HO LEONG CHUAN</b> ] ... <b>[Imm.Advice due 08/11/2017]</b>								
Driver/Custodian (Insured):	LEO CHI WEI (43 / Male), NRIC: S7417323C, Tel: +6597660540								
Adj Asg. Remarks:	PRI								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*YN2332J (535657)**  
**[SFU8478X]**  
**TP**  
**POWER-VAC INDUSTRIAL SERVICES PTE LTD**  
**Nov 3 2017 3:00PM**  
**[LEO CHI WEI]**  
**Bak Heng Motor Repairing**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>		<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>		
<b>Video</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/02/18 09:33	<b>Video - Accident</b>	Load MP4	<input type="checkbox"/>
2	07/02/18 09:55	<b>Video - AccidentExtendedvideo</b>	Load MP4	<input type="checkbox"/>
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/11/17 10:20	<b>Accident Statement</b> <small>From:SC - Reg. No: SFU8478X, Claimant: LEO CHI WEI</small>	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/03/18 12:45	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
2	03/03/18 12:45	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
3	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	03/03/18 12:45	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	03/03/18 12:45	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
26	03/03/18 12:45	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
27	03/03/18 12:45	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>

28	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
29	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
30	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
31	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
32	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
33	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
34	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
35	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
36	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
37	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
38	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
39	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
40	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
41	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
42	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
43	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
44	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
45	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
46	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
47	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
48	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
49	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
50	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
51	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
52	03/03/18 12:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
53	03/03/18 12:46	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
54	03/03/18 12:46	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
55	03/03/18 12:46	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
56	03/03/18 12:46	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
57	03/03/18 12:46	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	07/11/17 10:18	PRI FROM TOMMY CHOO MARK	1	Load PDF	
2	07/11/17 10:20	TP GIA REPORT	1	Load PDF	
3	05/02/18 15:23	FRB / INVOICE FOR RENTAL OF TANKER / TP SURVEY REPORT	1	Load PDF	
4	05/02/18 15:23	TP SURVEY PHOTOS	1	Load PDF	
5	05/02/18 15:23	TP SURVEY PHOTOS	1	Load PDF	
6	05/02/18 15:24	TP SURVEY PHOTOS	1	Load PDF	
7	05/02/18 15:24	TP SURVEY PHOTOS	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/03/18 17:24	Invoice	1	Load PDF	
2	15/03/18 17:24	PHOTO	1	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

^

v

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17021219/CQBE2-1

Date: 16/03/2018

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 27588995SMP	
Claimant Vehicle No: YN2332J	Insured Vehicle No: SFU8478X	
Date of Loss: 03/11/2017	Nature of Claim: TP	Claim No: 535657

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN2332J	
Make & Model:	ISUZU CYH52T, 15.7 D (M)	Engine No: 6HK1603707
Reg. Date:	08/04/2011 (Man. Year: 2010)	Chassis No: JALFVR347B7000143
Colour:	Blue	Odometer: 373310 km
Engine Capacity:	7790 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	West Lake 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,138.00	3,134.80	7,003.20	69.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,130.00	2,170.00	65.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,438.00</b>	<b>4,264.80</b>	<b>9,173.20</b>	<b>68.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>13,438.00</b>	<b>3,400.00</b>	<b>10,038.00</b>	<b>74.70</b>

#### INSPECTION

Date of Assignment:	07/11/2017	
Date Inspected:	13/11/2017 Inspected At:	Bak Heng Motor Repairing (HQ) 5032, ANG MO KIO INDUS PARK 2, #01-291 Singapore 569535
Estimated Period of Repair:	4.0 days	

**Adjuster:** SIMON HO LEONG CHUAN

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 15 Mar 2018)
<b>Parts:</b>	N/A ISUZU CYH52T 15.7 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YN2332J)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Dented / Bent	1,180.00 F	*1,180.00 FL
2	1		*FRONT BUMPER STEP GARNISH LH	Serviceable	200.00 F	*- FL
3	1		*FRONT BUMPER STEP GARNISH RH	Serviceable	200.00 F	*- FL
4	1		*FRONT BUMPER BRACKET RH	Repair	98.00 F	*- FL
5	1		*FRONT BUMPER HEAD LAMP RH	Grazed / Cracked	631.00 F	*631.00 FL
6	1		*FRONT BUMPER HEAD LAMP RIM GARNISH	Cracked	145.00 F	*145.00 FL
7	1		*FRONT BUMPER HEAD LAMP HOLDER BRACKET RH	Distorted / Cracked	169.00 F	*169.00 FL
8	1		*FRONT BUMPER SIGNAL LAMP RH	Not Necessary	122.00 F	*- FL
9	1		*FRONT BUMPER SIDE LAMP RH	Not Necessary	120.00 F	*- FL
10	1		*FRONT BUMPER HEAD LAMP LOWER GARNISH RH	Serviceable	43.00 F	*- FL
11	1		*FRONT RH DOOR ASSY	Repair	2,800.00 F	*- FL
12	1		*FRONT RH DOOR OUTER PROTECTOR GARNISH	Not Necessary	382.00 F	*- FL
13	1		*FRONT RH DOOR SIGNAL LAMP	Grazed / Cracked	121.00 F	*121.00 FL
14	1		*FRONT RH DOOR GLASS OUTER MOULDING (COMPLETE)	Serviceable	325.00 F	*- FL
15	1		*FRONT WHEEL ARCH PANEL	Repair	680.00 F	*- FL
16	1		*FRONT WHEEL ARCH PANEL GARNISH RUBBER RH	Not Necessary	510.00 F	*- FL
17	1		*FRONT STEP BOARD (UPPER) RH	Grazed / Distorted	310.00 F	*310.00 FL
18	1		*FRONT STEP BOARD GARNISH (UPPER) RH	Distorted / Cut	380.00 F	*380.00 FL
19	1		*FRONT STEP BOARD (LOWER) RH	Serviceable	320.00 F	*- FL
20	1		*FRONT STEP BOARD GARNISH (LOWER) RH	Grazed / Slack / Cut	380.00 F	*380.00 FL
21	2		*FRONT STEP BOARD GARNISH STEY BRACKET (TOP) RH	Repair	140.00 F	*- FL
22	1		*FRONT STEP BOARD REINFORCEMENT BRACKET (LOWER) RH	Not Necessary	510.00 F	*- FL
23	1		*FRONT STEP BOARD FRONT LOWER SPLASH GUARD RH	Cut	121.00 F	*121.00 FL
24	1		*FRONT WHEEL SPLASH SHIELD RH	Slack Grazed	251.00 F	*251.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,138.00</b>	<b>3,688.00</b>
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	553.20
<b>Total Parts (\$\$)</b>	<b>10,138.00</b>	<b>3,134.80</b>

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	ANTI RUST TREATMENT	New	100.00	0.00
2	TO CHECK WIRING AND LIGHTS	New	100.00	30.00
3	TO REMOVE & TRANSFER FRONT RH DOOR MECHANISM	New	100.00	0.00
4	TO PUTTY AND RESPRAY PAINT ON AFFECTED AREA	New	1,200.00	500.00
5	TO REMOVE DAMAGED AND NECESSARY PARTS AND ATTACHMENTS; KNOCK, JACK, CUT, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS. REINSTALL ALL UNDAMAGED PARTS AND NECESSARY NEW PARTS INTO ORIGINAL POSITIONS	New	1,800.00	600.00
<b>Gross Labour Cost (\$)</b>			<b>3,300.00</b>	<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >