

Signature

Tanpin

REF:

ASM (AXA)

4894 (11wa) 201

ASSIGNMENT

From:

Date:

13/3/18

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

SGE 20941

at Workshop mis:

cycle & Carriage

of:

209 Pandan Garden

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

Client's Record:

COCO

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS / up?

Date: Person Contacted:

Vehicle: IN / OUT

Date Time Action / Instruction

Veh No:

SGE 20941

Page:

March

201

Type: Motor / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Mitsubishi Hage

1193.

Colour:

Silver

Insured: Std / N / NA

So Reading:

18583

Radio: Insured: Std / N / NA

Eng No:

C No:

MMBSTA13AH400 4301

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

185/55R15

R.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front:

6

Rear:

6

R.Bal:

--

R.Bal:

--

L.Bal:

6

L.Bal:

--

D.O.A.

D.O.

13/3/18 @ 1730

Survey held at:

CRC Pandan Gdn.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S, U/C

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time File Pass to:

☐ : Preli. Report
☐ : Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format:

Lum Sum: 1.5

Add Fee:

☐ : Steel
☐ : Iron
☐ : Tech
☐ : Res

\$

\$

\$

\$

Survey Fee
Transportation
Lum Sum
Add Fee