

ASS. REC. BY:

REF:

C93 / MSG18004837 / Gbd

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

mlh

Date/Time:

14032018 8-56am

Estimated Cost:

Bill to:

~~OD~~ / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJF 78067

Insured:

SKU 85244

at Workshop m/s

ACE AUTOLUTION

Tel:

6844 1184

of

13 Kaki Bukit Rd 4 #03-29

Policy No:

A80437837ATT

Claim No:

551463

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05032018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

15.032018

H.O.D. Endorsement:

Date/Time:

14032018 2:56pm

Person Contacted:

AMIG

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SJF 78067 - NA / C7218004260 / r3
	SKU 85244 - x
	Dismantle Part: 16032018
	After repair: 20032018

DUA: 05032018

WATERLOO


REF:

de-registered

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SJF 7807 Yr Regn: - /  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda Fit c.c. 1339  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: - T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GR6-1054127  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In Order / Jammed / Leaked / Burnt or  
 Brake: In Order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195 / 55 R15  
 R: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front 6 mm Rear 6 mm  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 05032018 D.O.I. 15032018 @ 12:10pm  
 Survey held at ACE Evolution  
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
\$ 3000 - \$ 4000

URGENT

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair:

1) 13072018  
 Date/Time, File Return to?

Resurvey No. of Trip:

2) \_\_\_\_\_  
 Report Format : PRS-  
 Lump Sum / I.B.I. (\$) \_\_\_\_\_

Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Invs (\$)  
 Weekend (\$)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 ) S - RS. \$  
 ) Photos  
 ) Others  
 )  
 TOTAL

120
50
10
180

### ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018		14 Mar 2018 08:56 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
<b>Insured:</b>	TEH SWEE PING, ID: S8484706B, Tel: +6581392996, Email: SPINGTEH@YAHOO.COM	
<b>Main Claimant:</b>	HO WEE HONG, ID: S7538390H	
<b>Vehicle Reg. No.:</b>	<b>SJF780G</b>	<b>Date of Loss:</b> 05/03/2018 13:00 - :59
<b>Claim Type:</b>	<b>TP / 551463</b>	<b>Policy/Cover Note No.:</b> A80437837ATT (Comprehensive) Coverage: 20/08/2017 - 19/08/2018
<b>Vehicle Reg. No. (Insured):</b>	<b>SKU8524L</b>	<b>Policy No. (Claimant):</b>
		<b>Excess:</b> S\$500.00
<b>Repairer:</b>	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre, 417807 Kaki Bukit - Tel: 68441184	
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]	
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/03/2018]	
<b>Driver/Custodian (Insured):</b>	TEH SWEE PING (33 / Male), NRIC: S8484706B, Tel: +6581392996	

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018		14 Mar 2018 08:56 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>		
Insured:	<b>TEH SWEE PING</b> , ID: S8484706B, Tel: +6581392996, Email: SPINGTEH@YAHOO.COM			
Main Claimant:	<b>HO WEE HONG</b> , ID: S7538390H			
Vehicle Reg. No.:	<b>SJF780G</b>	Date of Loss:	05/03/2018 13:00 - :59	
Claim Type:	<b>TP / 551463</b>	Policy/Cover Note No.:	A80437837ATT (Comprehensive) Coverage: 20/08/2017 - 19/08/2018	
Vehicle Reg. No. (Insured):	<b>SKU8524L</b>	Policy No. (Claimant):		
		Excess:	S\$500.00	
Repairer:	<b>Ace Autolution Pte Ltd (KAKI BUKIT)</b> 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre, 417807 Kaki Bukit - Tel: 68441184			
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]			
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Imm.Advice due 15/03/2018]</b>			
Driver/Custodian (Insured):	TEH SWEE PING (33 / Male), NRIC: S8484706B, Tel: +6581392996			
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.				
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>			<a href="#">View All</a>	<a href="#">Search Tasks</a>
			<a href="#">Create New Task</a>	<a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>
				<b>Handler</b>
				<b>Assigned By</b>
				<b>Completed On</b>
				<b>Created On</b>
				<b>Done?</b>
No results.				

## Claim Documents

**\*SJF780G (551463)**

**[SKU8524L]**

**TP**

**HO WEE HONG**

**Mar 5 2018 1:00PM**

**[TEH SWEE PING]**

**Ace Autolution Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>	
<b>Assessment Reports</b>			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/03/18 15:14	<b>Accident Statement</b> <small>From:OD - Reg. No: SKU8524L, Claimant: TEH SWEE PING</small>	Load HTM	
<b>Photos/Images</b>			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/07/18 15:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	12/07/18 15:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	12/07/18 15:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	12/07/18 15:30	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	12/07/18 15:31	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
22	12/07/18 15:31	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
23	12/07/18 15:31	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
24	12/07/18 15:31	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
25	12/07/18 15:31	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
26	12/07/18 15:31	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
27	12/07/18 15:31	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
28	12/07/18 15:31	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
29	12/07/18 15:31	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
30	12/07/18 15:31	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
31	12/07/18 15:31	<b>Photo After Spray</b>	Load JPG	<input checked="" type="checkbox"/>
32	12/07/18 15:31	<b>Photo After Spray</b>	Load JPG	<input checked="" type="checkbox"/>
33	12/07/18 15:31	<b>Photo After Spray</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
35	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
36	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
37	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
38	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
39	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
40	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
41	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
42	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
43	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
44	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
45	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
46	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
47	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
48	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
49	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
50	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
51	12/07/18 15:31	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/03/18 15:26	SJF780G e-file report	Load PDF	
2	13/03/18 15:31	TP PRI Request	Load PDF	
3	14/03/18 08:53	TP reject SJE - assign LKK	Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004837/GBE2

Date: 13/07/2018

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: A80437837ATT	
Claimant Vehicle No : SJF780G	Insured Vehicle No : SKU8524L	
Date of Loss: 05/03/2018	Nature of Claim: TP	Claim No: 551463

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJF780G</b>	Engine No:	HIDDEN
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61054127
Reg. Date:	(Man. Year: )	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	14/03/2018	
Date Inspected:	15/03/2018 Inspected At:	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	5.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** CATHERINE CHONG KAI LING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REGISTRATION DATE UNABLE TO TRADE:DUE TO VEHICLE DE-REGISTER

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2018)
<b>Parts:</b> 144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJF780G)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
-----------------------------------------------

< END OF ESTIMATES >