

Surveyor:
Mumukh

REF: C33 / MSG 18004846 / EVD392

Special Instruction: Paper Survey

US: \$ 5500.00

ASSIGNMENT (Office)

From (Person): Monica Chung of MSG Date/Time: 19042018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: W4 Appraisal

Workshop: Jementah Motor

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: GP 1769S Insured: SLF 6698Z
at Workshop m/s Jementah Motor Tel: 9299 6636 (Ah Chuan)
of 14 Defu Lane 10 #01-406

Policy No: Claim No: 551977

Sum Insured: Excess:

Make of Veh: D.O.A. 11-03-2018
(Client's Record)

Don't Indize
H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 7 days)

Date/Time: Submit Final Fig days (Red \$ / %; Original days)

Date/Time	Action/Instruction
	GP 1769S - x
	SLF 6698Z - x
04/05/18	To Submit L/S 4K with 5 days of v. (Red 1500, 27%) at PRS photos seen 9
RECEIVED 04 MAY 2018	

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

PRS & PS

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

- | | |
|--|-----------------------------|
| 1) Date/Time 4/5 - typist File Pass to | 2) Date/Time File Return to |
| 3) Date/Time File Pass to | 4) Date/Time File Return to |
| 5) Date/Time File Pass to | 6) Date/Time File Return to |

ASS. REC. BY:

REF:

C83/MSG/8001846/Gd3

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

Monica chung

of

MSG

Date/Time: 13/3/18 @ 3:48pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GP 1769S

Insured:

SLF 66982

at Workshop m/s

Jementah Motor Works

Tel:

92996636

of

14 Defu Lane 10 #01-406

Policy No:

28978136QMY

Claim No:

SS1977

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

10:27am @ 14/3/18

Person Contacted:

Ah chuan

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

GP 1769S - X

SLF 66982 - X

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		13 Mar 2018 15:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	LEE HOCK KIER, ID: S1510976I, Tel: +6598295133, Email: kler61@hotmail.com		
Main Claimant:	ADSTRAGOLD PTE LTD, Co. Reg. No.: 201025481M		
Vehicle Reg. No.:	GP1769S	Date of Loss:	11/03/2018 10:00 - :59
Claim Type:	TP / 551977	Policy/Cover Note No.:	28978136QMY (Comprehensive) Coverage: 05/09/2017 - 04/09/2018
Vehicle Reg. No. (Insured):	SLF6698Z	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406, 539195 Defu Lane - Tel: 92996636		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/03/2018]		
Driver/Custodian (Insured):	LEE HOCK KIER (57 / Male), NRIC: S1510976I, Tel: +6598295133		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Monica Chung <Monica_Chung@sg.msig-asia.com>
Sent: Thursday, 19 April, 2018 2:14 PM
To: assignments@lkkauto.com
Subject: TP GP1769S DOA - 11/03/18 Our Ref: 551977

Dear Catherine,

We have shared the documents for paper adjustment in Merimen.

Meanwhile, please upload the preliminary advice for our reference.

Thanks.

Regards,

Monica Chung

Assistant Executive, Claims Services (Motor)

D: +65 6594 2552 | F: +65 6225 7402 | monica_chung@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647.Singapore 542224
Email: Winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

Our Ref: WG/TP/2018-83
Invoice No: TP/JEM/2018-83
Vehicle No: GP1769S
Attn: ADSTRAGOLD PTE LTD
Company: JEMENTAH MOTOR WORKZ
Address: Blk 14, #01-4006.Defu Lane 10.Singapore 539195

Date 25 March 2018

Invoice

Surveyor Fee:	S\$280
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$58/- (@ \$1 per photo, total 58 photos)
Total:	S\$438

Surveyor: Winsong Goh
Signature: 
Date: 25/3/2018



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542234
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

41

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S ADSTRAGOLD PTE LTD
C/O Jementah Motor Works
Blk 14, #01-4006, Defu Lane 10
Singapore 539195

Date : 25 March 2018
Our Ref : WG/TP/2018-83

REFERENCE PARTICULARS

Date of Accident : 11 March 2018
Date of Inspection : 12 March 2018

Type of Inspection : Third Party Claim
Date of Re-Inspn : 14 March 2018

VEHICLE PARTICULARS

Registration No : GPI769S
Make : TOYOTA
Model : LITEACE 4DR
Year : 2004

Engine No : 3C4002634
Chassis No : CR425010592
Odometer : 311607km
Colour : Silver

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near side	Yokohama	165R13C
Front Off Side	Yokohama	165R13C
Rear Near Side	Yokohama	165R13C
Rear off Side	Yokohama	165R13C

Thread Balance
5 mm
5 mm
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front left portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was S\$5,500.00 nett at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Seven (07) working days.

Enclosed Fifty-eight (58) photographs depicting damage to the vehicle.

Inspection conducted at : Jementah Motor Works
Blk 14, #01-4006, Defu Lane 10, Singapore 539195

In accordance to your instruction, we have not authorise repairs and inspection was conducted strictly on a "WITHOUT PREJUDICE BASIS".

VEHICLE NO : GP1769S
MODEL : LITEACE 4DR

Our Ref : WG/TP/2018-83

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1 FRONT BUMPER	1	GRAZED	\$ 615.40	\$ 615.40
2 FRONT BUMPER SIDE RETAINER	2	NECESSARY	\$ 80.00	\$ 80.00
3 FRONT LH BUMPER SIDE COVER	1	DEFORMED	\$ 125.00	\$ 125.00
4 FRONT LH HEADLAMP	1	NOT NECESSARY	\$ 317.00	\$ -
5 FRONT LH SIDE LAMP	1	CRACKED	\$ 135.00	\$ 135.00
6 FRONT LH HEADLAMP GARNISH RIM	1	CRACKED	\$ 172.10	\$ 172.10
7 FRONT GRILLE	1	CRACKED	\$ 290.00	\$ 290.00
8 FRONT GRILLE EMBELM	1	NECESSARY	\$ 44.70	\$ 44.70
9 FRONT LH FENDER	1	DENTED	\$ 790.30	\$ 790.30
10 FRONT LH FENDER INNER SHIELD	1	DEFORMED	\$ 137.43	\$ 137.43
11 FRONT LH MUD FLAP	1	CRACKED	\$ 102.30	\$ 102.30
12 FRONT LH DOOR PANEL	1	DENTED	\$ 1,028.40	\$ 1,028.40
13 FRONT LH DOOR WING MIRROR	1	DISTORDED	\$ 512.09	\$ 512.09
14 FRONT LH DOOR INNER TRIM	1	NOT NECESSARY	\$ 310.20	\$ -
15 FRONT LH DOOR LOCK ASSY	1	NOT NECESSARY	\$ 381.40	\$ -
16 FRONT LH KNUCKLE ARM	1	BENT	\$ 519.02	\$ 519.02
17 FRONT LH KNUCKLE BEARING	1	NECESSARY	\$ 139.20	\$ 139.20
18 FRONT LH SHOCK ABSORBER	1	BENT	\$ 424.50	\$ 424.50
19 FRONT LH LOWER ARM	1	BENT	\$ 390.03	\$ 390.03
20 REAR LH SLIDING DOOR	1	REPAIR	\$ -	\$ -
			\$ 6,514.07	\$ 5,505.47
		Less 25%	\$ 1,628.52	\$ 1,376.37
			\$ 4,885.55	\$ 4,129.10
B) S/NETT ITEM				
21 FRONT BUMPER CLIP	1	NECESSARY	\$ 60.00	\$ 50.00
22 RIM	1	GRAZED	\$ 600.00	\$ 500.00
23 BRAKE FULID	1	NECESSARY	\$ 50.00	\$ 40.00
			\$ 710.00	\$ 590.00
		Parts Total :	\$ 5,595.55	\$ 4,719.10
C) LABOUR CHARGES & MISC				
24 CHECK FRONT WIRING AND LIGHTNING			\$ 60.00	\$ 50.00
25 CHECK FRONT WHEEL ALIGNMENT			\$ 150.00	\$ 12.00
26 REMOVE AND REPLACE FRONT UNDERCAARIAGE PARTS			\$ 300.00	\$ 180.00
27 TRANSFER PARTS, ATTACHMENT FROM OLD DOOR TO NEW			\$ 200.00	\$ 180.00
28 PANEL BEATING ON AFFECTED AREAS			\$ 1,000.00	\$ 800.00
29 SPRAY PAINTING ON AFFECTED AREAS			\$ 900.00	\$ 800.00
30 APPLY ANTI RUST ON AFFECTED AREAS			\$ 150.00	\$ 130.00
		Labour Total :	\$ 2,660.00	\$ 2,152.00
		Total Parts and Laboure :	\$ 8,255.55	\$ 6,871.10

FINAL LUMP SUM ADJUSTMENT

\$ 5,500.00

4991.93

\$ days. 4S 4000/-

POINT OF IMPACT

The impact was confined to the front left portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$5,500.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
WG APPRAISAL SERVICES

Winson Goh
Automotive Appraiser



JEMENTAH MOTOR WORKS

Blk 14, #01-406, Defu Lane 10.Singapore 539195
Tel: 92996636 Fax: 62857054

INVOICE

ADSTRAGOLD PTE LTD

Invoice No.	JEM/18/83
Our Ref.	GP1769S
Your Ref.	-
Date	25 March 2018

No.	Description	Qty	Unit Price	Total
1	To supply labour and materials to repair below mentioned vehicle to its pre-accident condition. Vehicle: <u>GP1769S</u> Make/Model: <u>TOYOTA / LITEACE 4DR</u> Accident Date: <u>11 March 2018</u>			\$5,500.00
Amount Due				\$5,500.00

[Signature]
JEMENTAH MOTOR WORKS
14 Defu Lane 10 #01-406
Singapore 539195

Authorised Signatory

Enquire Vehicle & Owner Information (Vehicle No. SLF6698Z As At 11 Mar 2018 / 10:05:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: CY.GP1769S.18.HW.WP(

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S1510976I
Owner Name: LEE HOCK KIER
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 215
Registered Street Name: BEDOK SOUTH AVENUE 1
Registered Unit No.: # 03 - 03
Registered Building Name: -
Registered Postal Code: 469338

Current Vehicle Details

Vehicle No.: SLF6698Z
Make Description/Model: TOYOTA / COROLLA ALTIS 1.6 CVT
Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Thank you



Phee Lay San has successfully logged out.

Your last login date and time was 12 Mar 2018, 15:15:27.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SLF6698Z	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	12 Mar 2018 / 15:16:25

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		13 Mar 2018 15:48 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE HOCK KIER, ID: S1510976I, Tel: +6598295133, Email: kier61@hotmail.com		
Main Claimant:	ADSTRAGOLD PTE LTD, Co. Reg. No.: 201025481M		
Vehicle Reg. No.:	GP1769S	Date of Loss:	11/03/2018 10:00 - :59 [160 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 551977	Policy/Cover Note No.:	28978136QMY (Comprehensive) Coverage: 05/09/2017 - 04/09/2018
Vehicle Reg. No. (Insured):	SLF6698Z	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406, 539195 Defu Lane - Tel: 92996636		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Imm.Advice due 14/03/2018]		
Driver/Customer (Insured):	LEE HOCK KIER (57 / Male), NRIC: S1510976I, Tel: +6598295133		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GP1769S (551977)
[SLF6698Z]**

TP

ADSTRAGOLD PTE LTD

Mar 11 2018 10:00AM

[LEE HOCK KIER]

Jementah Motor Works

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/03/18 15:42	Accident Statement From:OD - Reg. No: SLF6698Z, Claimant: LEE HOCK KIER	Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/04/18 09:25	General View	Load JPG ☒	☒
2	23/04/18 09:25	General View	Load JPG ☒	☒
3	23/04/18 09:25	General View	Load JPG ☒	☒
4	23/04/18 09:25	General View	Load JPG ☒	☒
5	23/04/18 09:25	General View	Load JPG ☒	☒
6	23/04/18 09:25	General View	Load JPG ☒	☒
7	23/04/18 09:25	General View	Load JPG ☒	☒
8	23/04/18 09:25	General View	Load JPG ☒	☒
9	23/04/18 09:25	General View	Load JPG ☒	☒
10	23/04/18 09:25	General View	Load JPG ☒	☒
11	23/04/18 09:25	General View	Load JPG ☒	☒
12	23/04/18 09:25	General View	Load JPG ☒	☒
13	23/04/18 09:25	General View	Load JPG ☒	☒
14	23/04/18 09:25	General View	Load JPG ☒	☒
15	23/04/18 09:25	General View	Load JPG ☒	☒
16	23/04/18 09:25	General View	Load JPG ☒	☒
17	23/04/18 09:25	General View	Load JPG ☒	☒
18	23/04/18 09:25	General View	Load JPG ☒	☒
19	23/04/18 09:25	General View	Load JPG ☒	☒
20	23/04/18 09:25	General View	Load JPG ☒	☒
21	23/04/18 09:25	General View	Load JPG ☒	☒
22	23/04/18 09:25	General View	Load JPG ☒	☒
23	23/04/18 09:25	General View	Load JPG ☒	☒
24	23/04/18 09:25	General View	Load JPG ☒	☒
25	23/04/18 09:25	General View	Load JPG ☒	☒
26	23/04/18 09:25	General View	Load JPG ☒	☒
27	23/04/18 09:25	General View	Load JPG ☒	☒
28	23/04/18 09:25	General View	Load JPG ☒	☒
29	23/04/18 09:27	Reinspection Photo	Load JPG ☒	☒
30	23/04/18 09:27	Reinspection Photo	Load JPG ☒	☒
31	23/04/18 09:27	Reinspection Photo	Load JPG ☒	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
33	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
34	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
35	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
36	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
37	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
38	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
39	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
40	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
41	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
42	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
43	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
44	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
45	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
46	23/04/18 09:27	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/03/18 15:45	TP GP1769S GIA REPORT	 Load PDF	
2	19/04/18 14:07	SURVEY BILL, SURVEY REPORT, REPAIR BILL, LTA SEARCH RECEIPT	 Load PDF	
3	19/04/18 14:07	SURVEY PHOTOS1	 Load PDF	
4	19/04/18 14:07	SURVEY PHOTOS2	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004846/DVD3S2
Date: 04/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28978136QMY
Claimant Vehicle No :	GP1769S	Insured Vehicle No :	SLF6698Z
Date of Loss:	11/03/2018	Nature of Claim:	TP
		Claim No:	551977

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GP1769S	Engine No:	3C4002634
Make & Model:	TOYOTA LITEACE, 2.2 4DRM (A)	Chassis No:	CR425010592
Reg. Date:	27/10/2004 (Man. Year: 2004)	Odometer:	311608 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	165 R13	Rear Tyre Size:	165 R13
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,595.55	3,399.93	2,195.62	39.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	1,592.00	1,068.00	40.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,255.55	4,991.93	3,263.62	39.53
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	8,255.55	4,000.00	4,255.55	51.55

INSPECTION

Date of Assignment:	13/03/2018		
Date Inspected:	14/03/2018	Inspected At:	Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406 Singapore 539195
Estimated Period of Repair:	5.0 days		

Adjuster: BRYAN TANI

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 May 2018)

Parts: N/A TOYOTA LITEACE 2.2 4DRM (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GP1769S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Grazed	615.40 FL	*615.40 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	80.00 FL	*80.00 FL
3	1		*FRONT LH BUMPER SIDE COVER	No such part	125.00 FL	*- FL
4	1		*FRONT LH HEADLAMP	Not Necessary	317.00 FL	*- FL
5	1		*FRONT LH SIDE LAMP	Not Necessary	135.00 FL	*- FL
6	1		*FRONT HEADLAMP GARNISH RIM	Not Necessary	172.10 FL	*- FL
7	1		*FRONT GRILLE	Not Necessary	290.00 FL	*- FL
8	1		*FRONT GRILLE EMBLEM	Not Necessary	44.70 FL	*- FL
9	1		*FRONT LH FENDER	Dented	790.30 FL	*790.30 FL
10	1		*FRONT LH FENDER INNER SHIELD	Deformed	137.43 FL	*137.43 FL
11	1		*FRONT LH MUD FLAP	Cracked	102.30 FL	*102.30 FL
12	1		*FRONT LH DOOR PANEL	Dented	1,028.40 FL	*1,028.40 FL
13	1		*FRONT LH DOOR WING MIRROR	Not Necessary	512.09 FL	*- FL
14	1		*FRONT LH DOOR INNER TRIM	Not Necessary	310.20 FL	*- FL
15	1		*FRONT LH DOOR LOCK ASSY	Not Necessary	381.40 FL	*- FL
16	1		*FRONT LH KNUCKLE ARM	Bent	519.02 FL	*519.02 FL
17	1		*FRONT LH KNUCKLE BEARING	Necessary	139.20 FL	*139.20 FL
18	1		*FRONT LH SHOCK ABSORBER	Bent	424.50 FL	*424.50 FL
19	1		*FRONT LH LOWER ARM	Bent	390.03 FL	*390.03 FL
20	1		*REAR LH SLIDING DOOR (NPA)	Repair	0.00 FL	*- FL
21	1		*FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
22	1		*RIM	Grazed	600.00 FS	*200.00 FS
23	1		*BRAKE FULID	Not Necessary	50.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	7,224.07	4,456.58
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,628.52	1,056.65
Total Parts (\$\$)	5,595.55	3,399.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT WIRING AND LIGHTING.	New	60.00	0.00
2	CHECK FRONT WHEEL ALIGNMENT.	New	150.00	12.00
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS.	New	200.00	180.00
4	TRANSFER PARTS, ATTACHMENT FROM OLD DOOR TO NEW.	New	200.00	60.00
5	PANEL BEATING ON AFFECTED AREAS.	New	1,000.00	600.00
6	SPRAY PAINTING ON AFFECTED AREAS.	New	900.00	700.00
7	APPLY ANTI RUST ON AFFECTED AREAS.	New	150.00	40.00
Gross Labour Cost (S\$)			2,660.00	1,592.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >