

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ118004852/NQD3S2**Date:** 20/08/2018REFERENCE

Insured/Claimant:	STUDIO ONE FIVE	Policy No:	DMCPHQ17-003724	
Date of Loss:	06/03/2018	Nature of Claim:	OD	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG1353P		
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Engine No:	1KD2709428
Reg. Date:	08/06/2017 (Man. Year: 2017)	Chassis No:	KDH2010222572
Colour:	Grey	Odometer:	12261 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,131.50	4,174.50	5,957.00	58.80
Miscellaneous Items	110.00	40.00	70.00	63.64
Labour	2,780.00	1,200.00	1,580.00	56.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,021.50	5,414.50	7,607.00	58.42
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	12,521.50	4,914.50	7,607.00	60.75
+ GST 7.00/7.00% (S\$)	876.51	344.02	532.49	60.75
Nett Amount (S\$)	13,398.01	5,258.52	8,139.49	60.75

INSPECTION

Date of Assignment:	13/03/2018 Present Location:	Elite Automotive Pte Ltd (HQ) Elite Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands Singapore 757322
Date Inspected:	14/03/2018 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: Sebastian Yeang Wai Keen**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2018)
Parts:	213	TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG1353P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT END PANEL (WCP)	Bent	350.00 F	*350.00 F
2	1		*FRONT PANEL EMBLEM (WCP)	Necessary	40.00 F	*40.00 F
3	1		*FRONT PANEL INNER STICKER - BIG PIECE (WCP)	Not Necessary	30.00 F	*- F
4	1		*FRONT PANEL INNER STICKER - SMALL PIECE (WCP)	Not Necessary	30.00 F	*- F
5	2		*FRONT PANEL HINGE (WCP)	Not Necessary	80.00 F	*- F
6	1		*FRONT PANEL LOCK (WCP)	Not Necessary	60.00 F	*- F
7	1		*FRONT LOCK PANEL (WCP)	Not Necessary	60.00 F	*- F
8	1		*FRONT INNER GRILLE (WCP)	Deformed	250.00 F	*250.00 F
9	1		*FRONT UPPER CHROME MOULDING (WCP)	Scratched	650.00 F	*650.00 F
10	1		*FRONT LOWER CHROME MOULDING (NPA) (WCP)	Scratched	0.00 F	*- F
11	10		*FRONT GRILLE CLIPS (WCP)	Not Necessary	30.00 F	*- F
12	2		*HEADLAMP (WCP)	Scratched	2,400.00 F	*1,200.00 F
13	1		*FRONT BUMPER (WCP)	Cracked	280.00 F	*280.00 F
14	1		*FRONT BUMPER GRILLE (WCP)	Deformed	150.00 F	*150.00 F
15	1		*RHS FRONT FOG LAMP (WCP)	Not Necessary	150.00 F	*- F
16	1		*RHS FRONT FOG LAMP BRACKET (WCP)	Deformed	60.00 F	*60.00 F
17	1		*RHS FRONT FOG LAMP COVER (WCP)	Deformed	50.00 F	*50.00 F
18	10		*FRONT UPPER GRILLE CLIPS (WCP)	Necessary	30.00 F	*15.00 F
19	10		*FRONT LOWER GRILLE CLIPS (WCP)	Necessary	30.00 F	*15.00 F
20	1		*A/C CONDENSER C/W RECEIVER DRYER (WCP)	Not Necessary	550.00 F	*- F
21	1		*RADIATOR (WCP)	Not Necessary	750.00 F	*- F
22	1		*RADIATOR FAN COWLING (WCP)	Not Necessary	180.00 F	*- F
23	1		*RADIATOR FAN BLADE (WCP)	Not Necessary	120.00 F	*- F
24	1		*RADIATOR FAN MOTOR (WCP)	Not Necessary	500.00 F	*- F
25	1		*OIL COOLER UNIT (WCP)	Not Necessary	650.00 F	*- F
26	1		*A/C HIGH PRESSURE PIPE (WCP)	Not Necessary	150.00 F	*- F
27	1		*A/C COOLING PIPE (WCP)	Not Necessary	180.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*A/C DISCHARGE PIPE (WCP)	Not Necessary	150.00 F	*- F
29	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	180.00 F	*180.00 F
30	2		*FRONT BUMPER BRACKET (WCP)	Deformed	140.00 F	*140.00 F
31	1		*FRONT SUPPORT PANEL (WCP)	Repair	280.00 F	*- F
<u>Supplementary #1</u>						
32	1		*AIR CLEANER (WCP)	Cracked	250.00 F	*250.00 F
F=Franchise part.						
					Sub Total (\$\$)	8,810.00 3,630.00
					+ Margin on L,N Items 15.00/15.00% (\$\$)	1,321.50 544.50
					Total Parts (\$\$)	10,131.50 4,174.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BONNET SEALER (NECESSARY)	50.00	40.00
2	1	FRONT NUMBER PLATE (NOT NECESSARY)	60.00	0.00
Sub Total (\$\$)			110.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Labour charges to remove & install front end attachments & fittings to enable repair; to cut & weld front panellings where necessary; to straighten & repair front panel reinforcement & support, front end chassis member & reinforcement, to replace damaged parts as listed above	New	1,300.00	500.00
2	To spray painting on front upper panel (inner & outer), front support panel, front bumper, RHS front corner panel, LHS front corner panel and front chassis members	New	1,200.00	600.00
3	To remove & replace headlamps, check lightings and focus headlights	New	50.00	40.00
4	To remove & replace A/C ccondenser C/W receiver dryer & pipings; to vacuum & charge up gas	New	150.00	0.00
5	To remove & replace radiator & electric fan & cowling; to pressurize cooling system	New	80.00	60.00
Gross Labour Cost (\$\$)			2,780.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >