

22/03/2002

ASS. REC. BY:

REF:

CS/FCI 8004558/KH102

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): CWS Sarena Lee of FCI Date/Time: 14/03/2018 3:46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLP 5560R Insured: SHA 1239Yat Workshop m/s Hui Yang Tel: 6451 5752of Blk 176 Sin Ming Drive #04-02Policy No: _____ Claim No: D18001960MFGH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 08/03/2018
(Client's Record)CA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: _____Date/Time: _____ Person Contacted: Bel Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLP 5560R - X</u>
	<u>SHA 1239Y - CS/FCI 8000603 / Uqd3h2</u>
<u>14/03</u>	<u>L1 Lmp @ 6400 Confirm & enal (Red: 7309.59! 53%)</u>

Signature

REF: TQ

ASSIGNMENT

From: _____ Date: 12032018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 5560Rat Workshop m/s Hui Yangof Sim Ming

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8152k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLP 5560R Yr Regn: 06, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Estima c.c. 2362Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 16664 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACR 50 7145958Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 8 mmL/Bal. 7 mm L/Bal. 8 mmD.O.A. 8/3/18 D.O.I. 14/3/18Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Fr d/s & r/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/3 FR pass to Customer

RECEIVED 12 APR 2018

Date/Time. File Pass to?

☐

Prel. Report

☒

Final Report

1) PH Typist

Date/Time. File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 64003x15+45170+455050+5033398



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004858/Ktb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1239Y	Veh. Inspected	SLP 5560R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001960MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	14/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/03/2018	Inspection Date	14/03/2018	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	08-03-2018	Our Ref No. D18001960MFSH
Accident Date	08-03-2018	Claim Type. Third Party
Insured Vehicle	SHA1239Y	Third Party Vehicle. SLP5560R
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	6451 5752/ 90473466	Fax No. 6451 4658
Survey Type	WITHOUT PREJUDICE: EST. COR - \$11,443.09	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

08/03/2018

Owner: YI XIN LEASING

ESTIMATE TO REPAIR TOYOTA ESTIMA AERAS - SLP5560R

1pc	front LH fender	Bu	\$ 781.45	—
1pc	front LH fender inner shield	CM	\$ 374.45	—
8pcs	front LH fender inner shield clip @\$5.00	Lu	\$ 40.00	—
1pc	front LH headlamp	CM	\$ 2,823.45	—
1pc	front LH headlamp lower bracket	R	\$ 191.50	X
1pc	front LH air box spare tank	CMs	\$ 381.10	—
1pc	front LH air box spare tank hose	CM	\$ 125.10	—
1pc	front LH absorber	By	\$ 790.00	—
1pc	front LH knuckle arm	BT	\$ 608.00	—
1pc	front LH knuckle bearing	Lu	\$ 566.00	—
1pc	front LH lower arm	Lu	\$ 511.00	X
1pc	front LH drive shield	R	\$ 2,550.00	X
1pc	front bumper	Tu	\$ 972.50	—
10pcs	front bumper clip @\$5.00	Lu	\$ 50.00	—
2pcs	front bumper side retainer @\$132.10	also CM	\$ 264.20	—
1pc	front bumper number plate garnish	CM	\$ 381.90	—
1pc	front bumper beam	R	\$ 181.52	X
1pc	front bumper lower grille	Lu	\$ 281.90	X
1pc	front bumper LH LED fog lamp	CM	\$ 574.45	—
1pc	front bumper LH LED fog lamp top garnish	MT	\$ 281.90	—
1pc	front bumper sponge	CM	\$ 182.10	X
1pc	front bumper reinforcement	R	\$ 561.60	X
			\$ 13,474.12	
less 25%			\$ 3,368.53	
			\$ 10,105.59	
1pc	front LH sport rim	Lu	\$ 680.00	X
1pc	front LH tyre	Lu	\$ 250.00	X
remove & refit front LH undercarriage			\$ 320.00	200
alignment			\$ 80.00	60
towing		(B11)	\$ 120.00	60
tuffkote			\$ 120.00	30
wiring			\$ 80.00	20
spray painting			\$ 950.00	450
labour charges			\$ 1,000.00	400
Total			\$ 13,705.59	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Not Authorised
L1 Per \$6400
Resurvey After Repair
3 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004858/Ktbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 16-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1239Y	Veh. Inspected	SLP 5560R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001960MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	14/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ACR507145958	Colour	METALLIC SILVER	
Odometer	16664	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	DUNLOP	7 mm	
L/H Front Tyre	225/50 R18	DUNLOP	7 mm	
R/H Rear Tyre	225/50 R18	DUNLOP	8 mm	
L/H Rear Tyre	225/50 R18	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/03/2018	Inspection Date	14/03/2018	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 5560R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT LH FENDER	BUCKLED	781.45	781.45
1	FRONT LH FENDER INNER SHIELD	CRACKED	374.45	374.45
8	FRONT LH FENDER INNER SHIELD CLIP @\$5.00	NECESSARY	40.00	40.00
1	FRONT LH HEADLAMP	CRACKED	2,823.45	2,823.45
1	FRONT LH HEADLAMP LOWER BRACKET	TO REPAIR SEE LABOUR	191.50	-
1	FRONT LH AIR BOX SPARE TANK	CRACKED	381.10	381.10
1	FRONT LH AIR BOX SPARE TANK HOSE	CRACKED	125.10	125.10
1	FRONT LH ABSORBER	BENT	790.00	790.00
1	FRONT LH KNUCKLE ARM	BENT	608.00	608.00
1	FRONT LH KNUCKLE BEARING	NECESSARY	566.00	566.00
1	FRONT LH LOWER ARM	SERVICEABLE	511.00	-
1	FRONT LH DRIVE SHIELF	TO REPAIR SEE LABOUR	2,550.00	-
1	FRONT BUMPER	TORN	972.50	972.50
10	FRONT BUMPER CLIP @\$5.00	NECESSARY	50.00	50.00
2	FRONT BUMPER SIDE RETAINER @\$132.10	N/S CRACKED	264.20	132.10
1	FRONT BUMPER NUMBER PLATE GARNISH	CUT	381.90	381.90
1	FRONT BUMPER BEAM	TO REPAIR SEE LABOUR	181.52	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	281.90	-
1	FRONT BUMPER LH LED FOG LAMP	CRACKED	574.45	574.45
1	FRONT BUMPER LH LED FOG LAMP TOP GARNISH	MISSING	281.90	281.90
1	FRONT BUMPER SPONGE	CRACKED	182.10	182.10
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	561.60	-
LESS 25% DISCOUNT			-3,368.53	-2,266.13
			10,105.59	6,798.37
SPECIAL NETT ITEMS				
1	FRONT LH SPORT RIM (SN)	TO REPAIR SEE LABOUR	680.00	-

Report Ref No. CS/FCI18004858/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LH TYRE (SN)	SERVICEABLE	250.00	-
			930.00	-
	LABOUR			
	REMOVE & REFIT FRONT LH UNDERCARRIAGE.		320.00	200.00
	ALIGNMENT.		80.00	60.00
	TOWING.		120.00	60.00
	TUFFKOTE.		120.00	30.00
	WIRING.		80.00	20.00
	SPRAY PAINTING.		950.00	450.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF FRONT LH HEADLAMP LOWER BRACKET,FRONT LH DRIVE SHIELD,FRONT BUMPER BEAM,FRONT BUMPER REINFORCEMENT AND FRONT LH SPORT RIM.		1,000.00	400.00
			2,670.00	1,220.00
	GRAND TOTAL		13,705.59	8,018.37
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,400.00

Report Ref No. CS/FCI18004858/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.