

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5721J -**AAD1803-090**

Not Authored
Mercury B4 part **\$3025.47**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5721J - JHOW

VF1ABL15AUC281623

RENAULT

LATITUDE

12.03.2018

AIG**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42	
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75	
3	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.22	
4	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i> 151.41	
5	1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 151.41	
6	1	BUMPER SUPPORT FRT LH	\$	<i>Sn</i> 123.88	
7	1	BUMPER SUPPORT FRT RH	\$	<i>Sn</i> 123.88	
8	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	
9	1	RADAIOR GRILLE	\$	<i>Sn</i> 1,707.78	
10	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36	} X
11	1	RADAIOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75	
12	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90	
13	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
14	1	AIR CLEANER LOWER	\$	<i>Sn</i> 352.64	
15	1	AIR CLEANER HOSE	\$	<i>Sn</i> 76.14	
16	1	LOWER ARM LH	\$	<i>Sn</i> 685.76	
17	1	KUNCKLE ARM LH	\$	<i>Sn</i> 846.98	
18	1	ABSORBER FRT LH	\$	<i>Sn</i> 360.54	
19	1	BONNET	\$	<i>R</i> 1,941.63	
20	1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43	
21	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	
22	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83	
23	1	WHEELARCH FRT LH	\$	<i>Sn</i> 278.84	
24	1	DOOR MIRROR LH	\$	<i>Sn</i> 1,483.40	
25	1	DOOR MIRROR GLASS LH	\$	<i>Sn</i> 148.20	} X
26	1	DOOR MIRROR BACK COVER LH	\$	<i>Sn</i> 218.46	
27	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66	
28	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50	
29	1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55	
30	1	DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66	

TOTAL \$ 21,883.00**10%** \$ 2,188.30

\$ 19,694.70

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-090

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5721J -

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	na	66.00	✓
2	1SET	WHEELARCH CLIP LH	\$	na	66.00	
3	1	TOW COVER FRT	\$	sn	14.50	
4	1	CAP HUB LH FRT	\$	sn	35.00	
5	1	RIM LH FRT	\$	sn	385.00	
6	1	TYRE LH FRT	\$	sn	330.00	
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	na	9.80	
8	1SET	BUMEPR RETAINER FRT CLIP LH	\$	na	12.50	
9	1	DOOR STICKER "Trans-cab"	\$	na	80.00	
10	1	DOOR STICKER "Classic"	\$	na	30.00	

TOTAL	\$	1,028.80
TOTAL PARTS	\$	20,723.50

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 ³⁰⁰⁰ ~~4400~~

To Check Electrical Lighting Concerned.

\$ 170.00 ²⁰⁰

Putty and spray painting of the affected portion.

\$ 3,000.00 ⁴⁴⁰⁰

To check steering geometry and computer wheel alignment

\$ na 220.00 X

Towing Fees

\$ na 120.00 X

To transfer of tire, rim and on wheel balancing.

\$ na 170.00 X

To rust-proofing of the affected areas.

\$ na 170.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ na 170.00 X

(PARTS BY PARTS)**Repair Days****10 Days***2 days*

LKK Auto Consultants hence notify the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Part(s) must be confirmed
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ 6,820.00

Over All Total \$ 27,543.50