

A REC. BY:

REF:

CS3/CTL18004915 / S-bor

Special Instruction:

Single 8 days

Surveyor:

Selvick

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTL

Date/Time:

14032018 3:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

YM 448E

Insured:

YN 297R

at Workshop m/s

Hing Lee motor

Tel:

of

Blk 7 Yew Tee Ind Est 397D

Policy No.:

DMCVSN3067731700

Claim No.:

SNM18001240C02

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 07082018

CA / REV / REP. / REV 24 HRS wpr

H.O.D. Endorsement:

Date/Time:

15032018 9:49am

Person Contacted:

Mr. Lai

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

YM 448E - X

YN 297R - X

Dismantle Part : 20032018

Surveyor:

REF: CTJ WJP

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: JW 4403E Yr Regn: 2006, Aug 24

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ISUZU NPRTIL C.C. 4570

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 434048 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JANPR 71 L 6710373

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 7.00-16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Swallow

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 15/5/18 @ 1:50pm

Survey held at Hing Lee

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Front, Rear, N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

15/5/18 : No Estimate / GIA Range = \$18 - \$20k 20 days.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) 22/05/2018

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: 150

2) _____

Transportation: _____

Report Format: PR

Add Fee: ☐ : Site Insp (\$ _____)

\$ + RS. \$ _____

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Invs (\$ _____)

Others _____

☐ : Weekend (\$ _____)

Lump Sum / I.B.I. (\$) _____

TOTAL

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Mar 2018		14 Mar 2018 15:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GRM INTERNATIONAL PTE LTD, Co. Reg. No.: 201330859G		
Main Claimant:	SENG CHOON FARM PTE LTD, Co. Reg. No.: 198700888H		
Vehicle Reg. No.:	YM4403E	Date of Loss:	07/03/2018 06:00 - :59
Claim Type:	TP / SNM18D01240C02	Policy/Cover Note No.:	DMCVSN3067731700 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	YN297R	Policy No. (Claimant):	17-MB010750-R08
		Excess:	S\$0.00
Repairer:	Hing Lee Motor Car Repair & Welder Works (HQ) 397D Woodlands Road, 677996 Woodlands - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/03/2018]		
Driver/Custodian (Insured):	RAMASAMY MURUGESAN (47 / Male), NRIC: S7168807J, Tel: +6590884499		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

15032018 @ 949am
mr. Lai veh in

2

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Mar 2018		14 Mar 2018 15:31 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: GRM INTERNATIONAL PTE LTD , Co. Reg. No.: 201330859G									
Main Claimant: SENG CHOON FARM PTE LTD , Co. Reg. No.: 198700888H									
Vehicle Reg. No.: YM4403E		Date of Loss: 07/03/2018 06:00 - :59 [138 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D01240C02		Policy/Cover Note No.: DMCVSN3067731700 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): YN297R		Policy No. (Claimant): 17-MB010750-R08							
		Excess: \$0.00							
Repairer: Hing Lee Motor Car Repair & Welder Works (HQ) 397D Woodlands Road, 677996 Woodlands - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 23/03/2018]									
Driver/Custodian (Insured): RAMASAMY MURUGESAN (47 / Male) , NRIC: S71688073, Tel: +6590884499									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YM4403E (SNM18D01240C02)**
[YN297R]
TP
SENG CHOON FARM PTE LTD
Mar 7 2018 6:00AM
[GRM INTERNATIONAL PTE LTD]
Hing Lee Motor Car Repair & Welder Works

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 17:23	Accident Statement	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 17:19	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	07/03/18 17:19	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	07/03/18 17:19	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	07/03/18 17:19	Accident Photo [Linked Accident Report Documents]	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 17:16	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	07/03/18 17:16	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	07/03/18 17:16	DRIVER'S IC & DRIVING LICENCE [Linked Accident Report Documents]	Load TIF	
4	07/03/18 17:16	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	Load TIF	

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/03/18 15:31	PRS	Load PDF	
2	14/03/18 15:31	OI GIA REPORT	Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 10:12	LKKPhotosIn6-1	Load PDF	
2	22/05/18 10:12	LKKPhotosIn6-2	Load PDF	

Linked Accident Report Documents

View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 17:23	Accident Statement	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 17:19	Accident Photo	Load JPG	☒
2	07/03/18 17:19	Accident Photo	Load JPG	☒
3	07/03/18 17:19	Accident Photo	Load JPG	☒
4	07/03/18 17:19	Accident Photo	Load JPG	☒

Documentation			1 per page	☒
---------------	--	--	------------	-------------------------------------

Assessment Reports				1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail	Print
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail	Print
1	07/03/18 17:16	Sketch Plan	1	Load TIF	
2	07/03/18 17:16	Sketch Plan #2	1	Load TIF	
3	07/03/18 17:16	DRIVER'S IC & DRIVING LICENCE	1	Load TIF	
4	07/03/18 17:16	CERTIFICATE OF INSURANCE	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118004915/SBE2

Date: 22/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3067731700

Claimant Vehicle
No: YM4403EInsured Vehicle
No: YN297R

Date of Loss: 07/03/2018

Nature of Claim: TP

Claim
No: SNM18D01240C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YM4403E

Make & Model: ISUZU NPR71L, 4.6 D (M)

Engine No: 4HG1395840

Reg. Date: 24/08/2006 (Man. Year: 2006)

Chassis No: JAANPR71L67103731

Colour: White

Odometer: 434048 km

Engine Capacity: 4570 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00-16LT

Rear Tyre Size: 7.00-16LT

Front Left Side: Swallow 6 mm

Rear Left Side: Swallow 6 mm

Front Right Side: Swallow 6 mm

Rear Right Side: Swallow 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/03/2018

Date Inspected: 15/03/2018 Inspected At:

Hing Lee Motor Car Repair & Welder
Works (HQ)
397D Woodlands Road
Singapore 677996

Estimated Period of Repair: 20.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$18,000.00 -\$20,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 May 2018)	
Parts:	N/A	ISUZU NPR71L 4.6 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YM4403E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >