



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2014 PORSCHE MACAN 2.0 A/T ABS PORXXX (SKP878U)

Date of Loss

10 March 2018

Time of Loss

9.00

Loss Description

SKP878U (INSD) HIT KERB

Comment

Workshop Details

Total Rebate Amount

102705

Nett Loss Amount

\$97,295.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

14/06/2018



Days of work completion *

92



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKP878U

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

24/07/2014



Mileage

17541

Age of Vehicle

3

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2014

ASSESSMENT INFO...

2014

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

AURIS HANS JOERG THOMAS

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... PORSCHE MACAN 2.0 A/T ABS

ASSESSMENT INFO... PORSCHE

CATEGORY Model

POLICY INFORMAT... PORXXX

ASSESSMENT INFO... MACAN 2.0 A/T ABS D/AIRBAG AWD

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WP1ZZZ95ZFLB01675

CATEGORY Date of Birth

FNOL INFORMATI... 12 March 1961

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 57

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... WP1ZZZ95ZFLB01675

CATEGORY Engine No

POLICY INFORMAT... 056057

ASSESSMENT INFO... 056057

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1984

CATEGORY Sum Insured

POLICY INFORMAT... 200000

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 200000

FNOL INFORMATI... 2

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF... ▼

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2016

POST SURVEY INF... dd/mm/yyyy 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY Address

FNOL INFORMATI... 261 BUKIT TIMAH ROAD, #09-05,
259703, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S2771377G

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

15/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

2000

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

265/45R20

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

195/40R20

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			PROTECTIVE FILM			Necessary	63.2		20		50.56	Reviewir
		2	1			P95B-833-021--GRV/DOOR SHELL REAR (LH)			Damaged	1833.1		20		1466.48	Reviewir
		3	1			INSULATION			Necessary	8.7		20		6.96	Reviewir
		4	1			DOOR SEAL OUTER			Necessary	219.9		20		175.92	Reviewir
		5	6			CLIP			Necessary	0.8		20		3.84	Reviewir
		6	2			GASKET			Necessary	0.8		20		1.28	Reviewir
		7	2			COMBINATION SCREW (WH03)			Necessary	2.4		20		3.84	Reviewir
		8	1			CAVITY PRESERVATION			Serviceable	0	0	0	0	0	Deny
		9	1			DOOR ARRESTER			Necessary	89.6		20		71.68	Reviewir
		10	4			HEXAGON SOCKET HEAD BOLT			Necessary	1.5		20		4.8	Reviewir
		11	2			COMBINATION SCREW			Necessary	1.7		20		2.72	Reviewir
		12	1			DOOR SEAL			Necessary	128.2		20		102.56	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR / BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		13	1			DOOR SEAL			Necessary	168.6		20		134.88	Reviewir
		14	1			DOOR TRIM REAR BLACK LH			Damaged	514.3		20		411.44	Reviewir
		15	1			STONE GUARD LH			Serviceable	0	0	0	0	0	Deny
		16	1			REPAIR KIT			Necessary	99.1		20		79.28	Reviewir
		17	1			P95B-839-475- - GV9/MOULDING			Necessary	140.7		20		112.56	Reviewir
		18	1			SILL COVER			Damaged	235.3		20		188.24	Reviewir
		19	1			SOUND ABSORBER			Necessary	33.7		20		26.96	Reviewir
		20	1			P95B-810-971-E -/WHEEL- HOUSING LINER			Deformed	218.2		20		174.56	Reviewir
		21	1			ALLOY WHEEL			Serviceable	0	0	0	0	0	Deny
		22	1			P95B-853-541-A -/BRACKET			Necessary	44.3		20		35.44	Reviewir

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RE
		1		TO REMOVE / REPLACE DAMAGED LH REAR DOOR & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN C PILLAR & FITTING WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE	3120	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RE
		2		TO SPRAY PAINT LH REAR DOOR, C PILLAR	2200	0	0	Reviewing		
		3		TO CARRY OUT BODY ANTI-RUST PRESERVATION TO AFFECTED AREAS	100	0	0	Reviewing		
		4		TO TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY	780	0	0	Reviewing		
		5		TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS	0	0	0	Deny		
		6		TO REMOVE / REPLACE TYRES & RIMS @ \$60/-	0	0	0	Deny		
		7		TO SUPPLY 1 PCS TYRE \$980.00 EA	0	0	0	Deny		
		8		TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR	600	0	0	Reviewing		
		9		TO SUPPLY 1 PC NO PLATE \$70.00 EA	70	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 6 DAYS	Reviewing			
☐		2	SUNDRIES	Reviewing	50	NECESSARY	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount\$7,974.00

Claim Amount\$7,974.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$6,870.00	\$6,870.00
Miscellaneous	\$50.00	\$50.00
Excess	-\$2,000.00	-\$2,000.00
Spare Parts	\$3,054.00	\$3,054.00

Submit for Review