

22/03/2002

REF:

CS/FCL18004928/Kgbn2

Special Instruction:

ASS. REC. BY:

Surveyor:

ASSIGNMENT (Office)

From (Person): CWS Wren Jaw of

FCL

Date/Time: 15/03/2018 1242pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 9186L

Insured: SHC 780X

at Workshop m/s

Hui Yang

Tel: 6451 5152

of

Blk 176 Sim Ming Drive #04-01

Policy No:

Claim No:

D18002115MTSH

Sum Insured:

Excess:

D.O.A. 13/03/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

15/03/2018 1:27pm

Person Contacted:

Bel

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKD 9186L - X

SHC 780X - CS/FCL16013862/Kgbn2

DCA: 23/7/16

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S'K 80 9186

Yr Regn:

18/1/2012

2012

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Atlas

c.c

1598

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

134745

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR053REE104128445

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Michelin

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

13/3/18

D.O.I.

15/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/3

Ph pass to Corbure

21 Rps @ 3500

confirmed Malco (Rd @ 3329.38, 48%)

RECEIVED 10 MAR 2012

Date/Time, File Pass to?

☐

: Prel. Report

1) 16/3 10:30

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TP

3500

145

50

50

28

273

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004928/Kqb		
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877		Date : 15-03-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 780X	Veh. Inspected	SKD 9186L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002115MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	15/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/03/2018	Inspection Date	15/03/2018	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002115MFSH

Date: 16 March 2018

Our Ref: CS/FCI18004928/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKD 9186L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/03/2018 at the premises of M/s HUI YANG, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,829.38</u>
Revised Estimate Amount	: S\$ <u>4,395.05</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the rear o/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	14-03-2018	Our Ref No. D18002115MFSH
Accident Date	13-03-2018	Claim Type. Third Party
Insured Vehicle	SHC0780X	Third Party Vehicle. SKD9186L
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 16 March 2018 12:14 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002115MFSH/1
Attachments: CSFCI18004928Kqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SKD 9186L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 15 March 2018 1:29 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002115MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 15 March, 2018 12:42 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002115MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

13.03.2018

Owner: MKM Car Leasing Pte Ltd

ESTIMATE TO REPAIR TOYOTA ALITS - SKD9186L

1pc	rear boot cover
1pc	rear boot cover outer chrome
1pc	rear boot cover " 1.6 " emblem
1pc	rear boot cover TOYOTA logo
1pc	rear boot cover " COROLLA " emblem
1pc	rear boot cover " ALTIS " emblem
1pc	rear boot cover " VVT-I " emblem
1pc	rear boot cover " DUAL " emblem
2pcs	rear boot cover reflector @\$191.60
1pc	rear boot cover inner rubber
1pc	rear boot cover inner lock
2pcs	rear RH taillamp @\$374.45
2pcs	rear RH taillamp lower bracket @\$123.05
1pc	rear bumper
2pcs	rear bumper side retainer 1 @\$132.25
2pcs	rear bumper side retainer 2 @\$131.30
1pc	rear bumper spone & reinforcement
2pcs	rear bumper side reflector @\$181.25
1pc	rear end panel
1pc	rear end panel inner garnish
2pcs	rear end panel side bracket @\$132.10

less 25%

1set reverse sensor

wiring
tuffkote
spray painting
labour charges
Total

Let's Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Not Authorised
L1 Rep & 3500d
Pursuing After Paint
5 days

Br	\$	819.60	✓
Ln	\$	203.25	X
Nbr	\$	43.75	—
Nr	\$	28.85	—
Nr	\$	57.70	—
Nr	\$	58.85	—
Nr	\$	28.85	—
Nr	\$	28.85	✓
Ln	\$	383.20	X
Ref/Dir	\$	182.25	506m
Nr	\$	191.60	✓
C/S EM	\$	748.90	✓
C/S EM	\$	246.10	✓
Br	\$	374.85	—
Ln	\$	264.50	X
Ln	\$	262.60	X
Dir/CM	\$	272.45	✓
Ln	\$	362.50	X
Br	\$	781.90	✓
Ref/Dir	\$	287.75	✓
Nr	\$	264.20	X

\$ 5,892.50

\$ 1,473.13

\$ 4,419.38

s.nett \$ 280.00 2005m

\$ 100.00 201

\$ 80.00 601

\$ 950.00 7201

\$ 1,000.00 7001

\$ 6,829.38



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004928/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 780X	Veh. Inspected	SKD 9186L
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18002115MFSH	Excess (\$)	0.00
	Assign From	LURENE	Assign Date	15/03/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	MR053REE104128445	Colour	METALLIC GREY
	Odometer	134745	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	13/03/2018	Inspection Date	15/03/2018
	Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 9186L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT COVER	BUCKLED	819.60	819.60
1	REAR BOOT COVER OUTER CHROME	SERVICEABLE	203.25	-
1	REAR BOOT COVER "1.6" EMBLEM	NECESSARY	43.75	43.75
1	REAR BOOT COVER TOYOTA LOGO	NECESSARY	28.85	28.85
1	REAR BOOT COVER "COROLLA" EMBLEM	NECESSARY	57.70	57.70
1	REAR BOOT COVER "ALTIS" EMBLEM	NECESSARY	58.85	58.85
1	REAR BOOT COVER "VVT-I" EMBLEM	NECESSARY	28.85	28.85
1	REAR BOOT COVER "DUAL" EMBLEM	NECESSARY	28.85	28.85
2	REAR BOOT COVER REFLECTOR @\$191.60	SERVICEABLE	383.20	-
1	REAR BOOT COVER INNER LOCK	DENTED	191.60	191.60
2	REAR RH TAILLAMP @\$374.45	O/S CRACKED / N/S SERVICEABLE	748.90	374.45
2	REAR RH TAILLAMP LOWER BRACKET @\$123.05	O/S CRACKED	246.10	123.05
1	REAR BUMPER	BUCKLED	374.85	374.85
2	REAR BUMPER SIDE RETAINER @\$132.25	SERVICEABLE	264.50	-
2	REAR BUMPER SIDE RETAINER 2 @\$131.30	SERVICEABLE	262.60	-
1	REAR BUMPER SPONE & REINFORCEMENT	DISTORTED / CRACKED	272.45	272.45
2	REAR BUMPER SIDE REFLECTOR @\$181.25	SERVICEABLE	362.50	-
1	REAR END PANEL	BENT	781.90	781.90
1	REAR END PANEL INNER GARNISH	MTG DISTORTED	287.75	287.75
2	REAR END PANEL SIDE BRACKET @\$132.10	TO REPAIR SEE LABOUR	264.20	-
	LESS 25% DISCOUNT		-1,427.56	-868.13
			4,282.69	2,604.37
1	REAR BOOT COVER INNER RUBBER (50%)(SN)	DENTED / DISTORTED	182.25	91.12
	LESS 25% DISCOUNT		-45.56	-
			136.69	91.12

Report Ref No. CS/FCI18004928/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPECIAL NETT ITEMS	DENTED		
	SET REVERSE SENSOR (SN)		280.00	200.00
			280.00	200.00
	LABOUR			
	WIRING.		100.00	20.00
	TUFFKOTE.		80.00	60.00
	SPRAY PAINTING.		950.00	720.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR END PANEL SIDE BRACKET.		1,000.00	700.00
			2,130.00	1,500.00
GRAND TOTAL			6,829.38	4,395.49
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/FCI18004928/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.