

REF:

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGP34072 Yr Regn: 2006/DECType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish. C.C. 1794Colour: White A/C: Insured / Std / NI / NASp. Reading: 334335 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2NE100324959Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 14/03/18Survey held at MG SolutionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TPAXA</u>
	<u>COE Expiry: 31/08/26</u>
	<u>MV: 58K. LG \$4,800.00</u>
	<u>PV: 46.1K. CRAB: \$5,791.28 (54%)</u>
	<u>Net: 11.9K</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18004950/Ahb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 15-03-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKJ 30E	Veh. Inspected	SGP 3407Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/03/2018	Inspection Date	14/03/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AXA INSURANCE	DATE	: 14/03/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGP3407Z		
MODEL	: TOYOTA WISH 1.8A	Vic	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 14-Mar-18
		TIME	: 14:40HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented,</i>	1	\$ 1,588.30	\$ 1,588.30
2	TAIL GATE HINGE <i>new</i>	2	\$ 69.00	\$ 138.00
3	TAILGATE DAMPER <i>new</i>	2	\$ 244.30	\$ 488.60
4	TAIL GATE TOP LOCK <i>Dented</i>	1	\$ 468.40	\$ 468.40
5	TAIL GATE LOWER CATCH <i>new</i>	1	\$ 62.00	\$ 62.00
6	TAIL GATE INNER TRIM <i>new</i>	1	\$ 422.00	\$ 422.00
7	TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 366.20	\$ 366.20
8	TAILGATE DETECTOR <i>not on</i>	1	\$ 112.20	\$ 112.20
9	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 165.00	\$ 165.00
10	REAR BUMPER <i>Dented</i>	1	\$ 688.30	\$ 688.30
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 72.00	\$ 144.00
12	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 52.00	\$ 104.00
13	REAR BUMPER STAY <i>Dented</i>	2	\$ 74.50	\$ 149.00
14	TAILLAMP <i>crushed</i>	2	\$ 411.20	\$ 822.40
15	REAR END PANEL <i>Dented,</i>	1	\$ 568.00	\$ 568.00
16	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 255.30	\$ 255.30

4908.60

3681.45

TOTAL PRICE \$ 6,541.70

LESS 25% \$ 1,635.43

SUB TOTAL PRICE

\$ 4,906.28

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>the one</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
3	TAILGATE WINDSCREEN SEALANT <i>the</i>	1	\$ 60.00	\$ 60.00
4	TAILGATE WINDSCREEN INNER SEAL <i>the</i>	1	\$ 60.00	\$ 60.00
5	TAILGATE INNER TRIM BOARD CLIP (SET) <i>MT</i>	1	\$ 30.00	\$ 30.00
6	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
7	TAIL LAMP CLIP (SET) <i>the</i>	1	\$ 35.00	\$ 35.00
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>the</i>	1	\$ 50.00	\$ 50.00
9	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
10	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00
		380	TOTAL	\$ 745.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	800	
3	WIRING CHECK	\$ 150.00	30	
4	TUFF COAT	\$ 200.00	50	
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 180.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 180.00	50	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	100	
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$180.00	X	
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00	X	
10	TRANSFER TAILGATE MECHANISM	\$ 180.00	80	

TOTAL

\$4,940.00

1970

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,651.28

TOTAL LABOUR COST : \$ 4,940.00

TOTAL REPAIR COST : \$ 10,591.28

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Admin by
H/S 14/03/18
06 days.
total: 603145
H/S: 4.8K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

<< Service Request Details

Claim

S8M00ALK

Reference

None 

Loss Date

March 10, 2018

Request Date

March 14, 2018

Due Date

March 21, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

14032018 @ 1.58pm

Jack veh in

Adrian

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGP3407Z

Make

Model

Primary Contact/Insured

LAU HOOI KHENG

79 FARLEIGH AVENUE, SERANGOON GARDEN ESTATE, 557853, Singapore
91909190

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

3/14/18 1:46 PM

FROM

NG Stacey

SUBJECT

Direct settlement

BODY

Please proceed for DS. however, do note that MCF d...





**Re:<MANDATE IA> S8M00ALK ACCIDENT INVOLVING
VEHICLES SKJ 30E(OJ) AND SGP 3407Z(TP) ON
10/03/2018 TOTAL: \$5,703.45**

Type

🔗 Question

Message

BOA apply. Please proceed

Reply

LETTER OF AUTHORITY

Name : MAZLAN BIN AMAT
Address : BLK 339 WOODLANDS AVE 1
#04-549 SINGAPORE 730339

Contact No : _____

TO: AXA INSURANCE SINGAPORE PTE LTD

Dear Sirs,

ACCIDENT INVOLVING SGP3407Z AND SKJ30E ON 10/03/2018
AT/ ALONG CTE TOWARDS AYE

I/We, MAZLAN BIN AMAT, am/are the registered owner of
motor car no. SGP3407Z

Please note that I have assigned all compensations monies due to me/us in the above said accident to M/S MG SOLUTION PTE LTD.

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned accident to M/S MG SOLUTION PTE LTD and forward your settlement cheque to M/S MG SOLUTION PTE LTD whom I had authorized to collect the said compensation monies.

Thank you


Signature of Claimant


Witness By

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: MAZLAN BIN AWAT
CAR/ LORRY/CYCLE: REG NO: SGP 3407Z POLICY NO:
ACCIDENT CLAIM NO:

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle

Registered No. SGP 3407Z from the repairers,

Messrs MG SOLUTION PTE LTD

And that all repairs necessary as a result of an accident in which the said vehicle was involved on or
about the 10 day of 03 2018 have been completed to my / our satisfaction, and that

I / we have no further claim on the above company in Respect thereof.

Date: Signature:

Co's Stamp: NRIC No:

14/3/2018

Vehicle In 14/3/2018

12/3/2018

Vehicle Out 20/3/2018

Time = 3 days & 4 hrs

SGP 3407Z



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

PROFORMA BILL

Bill To:

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Bill No : 188164

Date : 28-May-2018

Vehicle Number : SGP 3407Z

ATTN : MOTOR CLAIMS DEPARTMENT

QTY	CLAIM	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 4,800.00
BEFORE GST		4,800.00
7% GST		336.00
TOTAL		\$ 5,136.00

Tax Invoice will be issue upon amount finalised.

Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis with sole intention of resolving the matter amicably without parties resorting to legal proceeding. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Co's stamp & Authorised Signature

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKJ 30E (Insd veh)	Model:	TOYOTA WISH
	SGP 3407Z (TP veh)		
Date of Accident:	10/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	11,332.67
Final Repair Cost	:	\$	5,136.00
Loss of Use	:	\$	560.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	7.45

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	5,703.45

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability <u>100</u> (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): <u>0</u> (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	MG SOLUTION PTE LTD	:	\$ 5,703.45

NUR SHAQILAH BTE ABDOL
WAHAB

20/02/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18004950/Ahb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: STACEY NG

Date : 20-02-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 30E	Veh. Inspected	SGP 3407Z
Policy No.	P1835306	Coverage (\$)	0.00
Claim No.	S8M00ALK	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	15/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ZNE100324959	Colour	WHITE
Odometer	334335	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	MICHELIN	6 mm
L/H Front Tyre	205/55R16	MICHELIN	6 mm
R/H Rear Tyre	205/55R16	MICHELIN	6 mm
L/H Rear Tyre	205/55R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/03/2018	Inspection Date	14/03/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 3407Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE (CONSISTENT)	DENTED	1,588.30	1,320.00
2	TAIL GATE HINGE @ \$69.00 (CONSISTENT)	NOT NECESSARY	138.00	-
2	TAILGATE DAMPER @ \$244.30 (CONSISTENT)	NOT NECESSARY	488.60	-
1	TAIL GATE TOP LOCK (CONSISTENT)	DAMAGED	468.40	468.40
1	TAIL GATE LOWER CATCH (CONSISTENT)	NOT NECESSARY	62.00	-
1	TAIL GATE INNER TRIM (CONSISTENT)	NOT NECESSARY	422.00	-
1	TAILGATE WEATHER STRIP (CONSISTENT)	CUT	366.20	366.20
1	TAILGATE DETECTOR (CONSISTENT)	NOT NECESSARY	112.20	-
1	TAILGATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	165.00	165.00
1	REAR BUMPER (CONSISTENT)	DEFORMED	688.30	688.30
2	REAR BUMPER SIDE RETAINER @ \$72.00 (CONSISTENT)	NECESSARY	144.00	106.00
2	REAR BUMPER REFLECTOR @ \$52.00 (CONSISTENT)	NOT NECESSARY	104.00	-
2	REAR BUMPER STAY @ \$74.50 (CONSISTENT)	DENTED	149.00	149.00
2	TAILLAMP @ \$411.20 (CONSISTENT)	CRACKED	822.40	822.40
1	REAR END PANEL (CONSISTENT)	DENTED	568.00	568.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	255.30	255.30
	LESS 25% DISCOUNT		-1,635.42	-1,227.15
			4,906.28	3,681.45
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	TAIL GATE SEALANT (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	TAILGATE WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	30.00
1	TAILGATE WINDSCREEN INNER SEAL (SN) (CONSISTENT)	NECESSARY	60.00	30.00
1	SET TAILGATE INNER TRIM BOARD CLIP (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET TAIL LAMP CLIP (SN) (CONSISTENT)	NECESSARY	35.00	20.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	10.00
1	REAR END PANEL INSULATION SEAL (SN) (CONSISTENT)	NECESSARY	150.00	60.00

Report Ref No. CC4/ASM18004950/Ahb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	220.00	200.00
			745.00	380.00
	LABOUR			
	PANEL BEATING, REMOVING AND REPLACING PARTS.		1,800.00	800.00
	SPRAY PAINTING TO AFFECTED AREA.		1,800.00	800.00
	WIRING CHECK.		150.00	30.00
	TUFF COAT.		200.00	50.00
	REMOVE AND REFIX UPHOSTERY TO FACILITATE REPAIR.		180.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		180.00	50.00
	REMOVE AND REFIX TAILGATE WINDSCREEN.		120.00	100.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
	REMOVE AND REFIX TAILGATE WINDSCREEN.	NOT NECESSARY	150.00	-
	TRANSFER TAILGATE MECHANISM.		180.00	80.00
			4,940.00	1,970.00
GRAND TOTAL			10,591.28	6,031.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CC4/ASM18004950/Ahb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.