

INS. CASE OWNER:

Cynthia

CC4 ASM AXA1800 4956, Fj0352

LKK: IDAC:

Surveyor:

Esc

DOI:

ASSIGNMENT

16/3/18

Date / Time:

15/3/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XE 2770L

Claim No.:

S8M00AQP | 35005

Name of Insured:

MCS LOGISTICS (S) PIV

Policy No.:

PI 174163

Insured Tel No.:

HP:

Make / Model:

VO TRUCKS

Excess Sec II :SS

D.O.A.:

17/3/18

Place of Accident:

Turn of Pioneer Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

bulldog

If NO, Driver Name / Age:

M. MUBIM

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SKW 3570A



INSRS: WSP: Tel: Liability: RMKS:

city auto



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

| Date/Time | STAGE | DATE / PIC |
|---|-----------------------------------|--|
| 16/3/18 | Non-Reporting ltr (1st): | |
| | Non-Reporting ltr (2nd): | |
| | Non-Reporting ltr (Final): | |
| | Notification ltr (if non-pickup): | |
| 26/4/2018 4:35pm polkin | Call OI: | 26/4/2018 vic. de 2014 |
| | After call ltr to OI: | |
| | Documentation Check List: | Handler Typist |
| | Notification ltr (if non-pickup) | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | After call ltr to OI: | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | Authorisation To Act: | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | Release Voucher: | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | Final Repair Bill: | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | Car Rental Invoice: | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | Towing Invoice: | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | LTA / GIA : | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | Medical Bill: | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | PIR: | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | Mandate/Reject Instruction: | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | LOD | <input checked="" type="checkbox"/> <input type="checkbox"/> |
| | Payment Breakdown Form: | <input type="checkbox"/> <input type="checkbox"/> |
| | Post-Repair Photos: | <input type="checkbox"/> <input type="checkbox"/> |
| | Others: | <input type="checkbox"/> <input type="checkbox"/> |
| PRELIMINARY ADVICE Date/Time: 16/3/18 Sent By: [Signature] | | |
| FINALIZATION Date/Time: Confirm with: Confirm by: | | |
| Repair Cost: SS (days) Reduction: % Email <input type="checkbox"/> Call <input type="checkbox"/> | | |
| FINAL SETTLEMENT Date/Time: 26-3-19 Confirm with: V. P. M. Email <input type="checkbox"/> Call <input type="checkbox"/> | | |
| Final Liability: % 100 (Agred / Assessed) BOLA S/N No. : 27 | | |
| Repair Cost: SS 9,148.50 | | |
| Loss of Rental (LOR): SS (days) | | |
| Loss of Use (LOU): SS 960 (\$ 80 x 12 days) | | |
| Loss of Income (LOI): SS (\$ x days) | | |
| LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> (Tick only one) | | |
| GIA/LTA Search: SS 2.xx | | |
| Medical: SS - | | |
| Disbursement: SS - (e.g. Tow/Independent) | | |
| Legal Cost: SS - | | |
| Total: SS 10,110.50 Global Sum SS: 10,110.xx | | |
| FINAL PAYMENT Date/Time: Confirm with: Email <input type="checkbox"/> Call <input type="checkbox"/> | | |
| Payee 1: SS 10,110.xx Name 1: CITY AUTO PIRE LTD | | |
| Payee 2: (Strike if N.A.) SS X Name 2: X | | |
| Payee 3: (Strike if N.A.) SS X Name 3: X | | |

CLAIM SETTLEMENT 27/3/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18004956/Kjb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 15-03-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------|----------------|------------|
| Insured Veh. | XE 2770L | Veh. Inspected | SKW 3570A |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 15/03/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 13/03/2018 | Inspection Date | 15/03/2018 |
| Survey held at | CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643. | | |

5a. Remarks

| |
|---|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|---|



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201803-000323(00)

AXA INSURANCE SINGAPORE PTE LTD

NO. 8
SHENTON WAY
AXA TOWER
SINGAPORE 068811

Date : 14/03/2018
Vehicle No. : SKW3570A
Make/Model : TOYOTA WISH 1.8X A

Contact : 62208751/62208751

Fax No. :

*Not Authorized
1-B.I.L.L. Inq @?*

Mileage (km) : 0
Chassis No. : ZGE206024484
Accident Date : 13/03/2018 00:00:00
Claim No. : XE2770L
Reference : SKW3570A
Policy No. : MSD/VPCP/17-002217

| S/No | Particular | Quantity | Unit Price | Amount S\$ |
|---------------------|--------------------------------|----------|------------|------------|
| LIST ITEMS : | | | | |
| 1 | Rear number plate lamp | 2.0 | 67.90 | 135.80 ? |
| 2 | Tailgate | 1.0 | 1,420.70 | 1,420.70 ✓ |
| 3 | Tailgate hinge | 2.0 | 91.60 | 183.20 X |
| 4 | Tailgate damper | 2.0 | 279.84 | 559.68 ? |
| 5 | Tailgate lock | 1.0 | 313.70 | 313.70 ✓ |
| 6 | Tailgate striker | 1.0 | 32.10 | 32.10 ? |
| 7 | Tailgate weatherstrip | 1.0 | 377.60 | 377.60 ✓ |
| 8 | Tailgate logo | 1.0 | 60.79 | 60.79 ✓ |
| 9 | Tailgate emblem - valve matic | 1.0 | 44.17 | 44.17 ✓ |
| 10 | Tailgate outer chrome moulding | 1.0 | 298.54 | 298.54 ✓ |
| 11 | Tailgate outer handle switch | 1.0 | 179.60 | 179.60 ? |
| 12 | Tailgate lamp | 2.0 | 291.60 | 583.20 ✓ |
| 13 | Tailgate glass | 1.0 | 1,071.60 | 1,071.60 ✓ |
| 14 | Tailgate innerboard | 1.0 | 375.60 | 375.60 ✓ |
| 15 | Rear wiper arm | 1.0 | 61.40 | 61.40 ? |
| 16 | Rear wiper blade | 1.0 | 34.75 | 34.75 ? |
| 17 | Rear wiper motor | 1.0 | 801.90 | 801.90 ? |
| 18 | Rear bumper | 1.0 | 541.60 | 541.60 ✓ |
| 19 | Rear bumper reflector | 2.0 | 67.80 | 135.60 X |
| 20 | Rear bumper retainer | 2.0 | 78.30 | 156.60 X |
| 21 | Rear bumper bracket | 2.0 | 77.60 | 155.20 X |
| 22 | Rear end panel | 1.0 | 521.60 | 521.60 ✓ |
| 23 | Rear end panel bracket | 2.0 | 98.20 | 196.40 ? |
| 24 | Rear end panel top garnish | 1.0 | 337.80 | 337.80 ? |
| 25 | Taillamp | 2.0 | 379.20 | 758.40 X |
| 26 | Taillamp panel RH | 1.0 | 197.60 | 197.60 ? |
| 27 | Rear RH fender | 1.0 | 1,411.60 | 1,411.60 ✓ |
| 28 | Rear RH fender trimboard | 1.0 | 680.95 | 680.95 ✓ |
| 29 | Rear LH fender trimboard | 1.0 | 352.10 | 352.10 ? |
| 30 | Rear RH fender glass | 1.0 | 396.70 | 396.70 ✓ |
| 31 | Rear RH fender air duct | 1.0 | 127.50 | 127.50 ? |
| 32 | Rear smart entry sensor | 1.0 | 178.40 | 178.40 ? |
| 33 | Rear luggage room box | 1.0 | 345.20 | 345.20 ? |
| 34 | Rear deck box | 1.0 | 311.90 | 311.90 ? |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201803-000323(00)

AXA INSURANCE SINGAPORE PTE LTD

NO. 8
SHENTON WAY
AXA TOWER
SINGAPORE 068811

Contact : 62208751/62208751

Fax No. :

Date : 14/03/2018

Vehicle No. : SKW3570A

Make/Model : TOYOTA WISH 1.8X A

Mileage (km) : 0

Chassis No. : ZGE206024484

Accident Date : 13/03/2018 00:00:00

Claim No. : XE2770L

Reference : SKW3570A

Policy No. : MSD/VPCP/17-002217

| S/No | Particular | Quantity | Unit Price | Amount S\$ |
|------------------------|--|----------|------------|-----------------------|
| 35 | Rear deck board - center | 1.0 | 792.60 | 792.60 ? |
| 36 | Rear deck board - LH | 1.0 | 212.60 | 212.60 ? |
| 37 | Rear deck board - RH | 1.0 | 212.60 | 212.60 ? |
| 38 | Rear floor pan | 1.0 | 782.90 | 782.90 X |
| 39 | Rear bumper mudguard | 2.0 | 77.80 | 155.60 X |
| 40 | Clip | 18.0 | 3.21 | 57.78 X |
| List Total : | | | | 15,553.56 |
| 25% Discount S\$ | | | | 3,888.34 |
| | | | | <u>11,665.22</u> (17) |
| SPECIAL NET : | | | | |
| 1 | Rear number plate | 1.0 | 25.00 | 25.00 } 45.50 |
| 2 | Rear number plate casing | 1.0 | 35.00 | 35.00 |
| 3 | Tailgate glass sealant | 1.0 | 40.00 | 40.00 ✓ |
| 4 | Reverse sensor | 1.0 | 350.00 | 350.00 200.00 |
| 5 | Rear view camera | 1.0 | 385.00 | 385.00 ? |
| 6 | Rear RH fender glass sealant | 1.0 | 40.00 | 40.00 ✓ |
| 7 | Rear floor pan insulator paste | 1.0 | 150.00 | 150.00 X |
| SPECIAL NET Total S\$: | | | | <u>1,025.00</u> |
| LABOUR : | | | | |
| | *To remove and install rear windscreen glass | 1.0 | 120.00 | 120.00 ✓ |
| | *To remove and install rear RH fender glass | 1.0 | 120.00 | 120.00 60.00 |
| | *To install rear view camera and reverse sensor | 1.0 | 180.00 | 180.00 80.00 |
| | *To supply panel sealant and to seal off all weld spot seam and gaps | 1.0 | 90.00 | 90.00 60.00 |
| | *To spray under coating | 1.0 | 120.00 | 120.00 90.00 |
| | *To check wiring and lighting | 1.0 | 80.00 | 80.00 20.00 |
| | *To remove and refix rear seats and upholstery | 1.0 | 180.00 | 180.00 120.00 |
| | - To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts | 1.0 | 1,500.00 | 1,500.00 1200.00 |
| | - Spray painting on affected & replace parts | 1.0 | 1,600.00 | 1,600.00 1200.00 |
| | | | | <u>3,990.00</u> |

16680.17

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201803-000323(00)

AXA INSURANCE SINGAPORE PTE LTD
NO. 8
SHENTON WAY
AXA TOWER
SINGAPORE 068811

Date : 14/03/2018
Vehicle No. : SKW3570A
Make/Model : TOYOTA WISH 1.8X A

Contact : 6220875162208751 Fax No. :

Mileage (km) : 0
Chassis No. : ZGE206024484
Accident Date : 13/03/2018 00:00:00
Claim No. : XE2770L
Reference : SKW3570A
Policy No. : MSD/VPCP/17-002217

| S/No | Particular | Quantity | Unit Price | Amount S\$ |
|------|------------|----------|------------|------------|
|------|------------|----------|------------|------------|

E. & O.E.

| | |
|------------------------|------------------|
| Total S\$: | 16,680.22 |
| GST 7% S\$: | 1,167.62 |
| Amount Due S\$: | 17,847.84 |

for CITY AUTO PTE LTD

◀ Re:RE: FOLLOW-UP FOR DS INSTRUCTION

Type

🔗 Question

Message

PROCEED DS

Reply

◀ **Re:RE: FOLLOW-UP FOR DS INSTRUCTION**

Type

📘 Information

Message

Pls try to resolve this matter within our mandate of S\$14,000.00 subject to surveyor finalization and recommended LOU. XY 18 Mar 2019 (Bulk Settlement)

Reply



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-80/82, SIN MING ROAD, SINGAPORE 575643
 TEL: 6453 1235, 6452 0650 FAX: 6453 7944
 24hrs Towing Services Tel: 9623 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA INSURANCE SINGAPORE PTE LTD
 NO 8
 SHENTON WAY
 AXA TOWER
 SINGAPORE 068811

Estimate : QUOT201803-000323(00)

Date : 14/03/2018

Vehicle No : SKW3570A

Make/Model : TOYOTA WISH 1.8X A

Contact : 6220875162208751

Fax No. :

Mileage (km) : 0

Chassis No. : ZGE206024484

Accident Date : 13/03/2018 00:00:00

Claim No. : XE2770L

Reference : SKW3570A

Policy No. : MSDV/PCP/17-002217

Not Authorized
Libby & JSSD

| S/No | Particular | Quantity | Unit Price | Amount S\$ |
|---------------------|--------------------------------|----------|------------|------------|
| LIST ITEMS : | | | | |
| 1 | Rear number plate lamp | 2.0 | 67.90 | 135.80 |
| 2 | Tailgate | 1.0 | 1,420.70 | 1,420.70 |
| 3 | Tailgate hinge | 2.0 | 91.60 | 183.20 |
| 4 | Tailgate damper | 2.0 | 279.84 | 559.68 |
| 5 | Tailgate lock | 1.0 | 313.70 | 313.70 |
| 6 | Tailgate striker | 1.0 | 32.10 | 32.10 |
| 7 | Tailgate weatherstrip | 1.0 | 377.60 | 377.60 |
| 8 | Tailgate logo | 1.0 | 60.79 | 60.79 |
| 9 | Tailgate emblem - valve matic | 1.0 | 44.17 | 44.17 |
| 10 | Tailgate outer chrome moulding | 1.0 | 298.54 | 298.54 |
| 11 | Tailgate outer handle switch | 1.0 | 179.60 | 179.60 |
| 12 | Tailgate lamp | 2.0 | 291.60 | 583.20 |
| 13 | Tailgate glass | 1.0 | 1,071.60 | 1,071.60 |
| 14 | Tailgate innerboard | 1.0 | 375.60 | 375.60 |
| 15 | Rear wiper arm | 1.0 | 61.40 | 61.40 |
| 16 | Rear wiper blade | 1.0 | 34.75 | 34.75 |
| 17 | Rear wiper motor | 1.0 | 801.90 | 801.90 |
| 18 | Rear bumper | 1.0 | 541.80 | 541.80 |
| 19 | Rear bumper reflector | 2.0 | 67.80 | 135.60 |
| 20 | Rear bumper retainer | 2.0 | 78.30 | 156.60 |
| 21 | Rear bumper bracket | 2.0 | 77.60 | 155.20 |
| 22 | Rear end panel | 1.0 | 521.60 | 521.60 |
| 23 | Rear end panel bracket | 2.0 | 98.20 | 196.40 |
| 24 | Rear end panel top garnish | 1.0 | 337.80 | 337.80 |
| 25 | Taillamp | 2.0 | 379.20 | 758.40 |
| 26 | Taillamp panel RH | 1.0 | 197.60 | 197.60 |
| 27 | Rear RH fender | 1.0 | 1,411.60 | 1,411.60 |
| 28 | Rear RH fender trimboard | 1.0 | 680.95 | 680.95 |
| 29 | Rear LH fender trimboard | 1.0 | 352.10 | 352.10 |
| 30 | Rear RH fender glass | 1.0 | 396.70 | 396.70 |
| 31 | Rear RH fender air duct | 1.0 | 127.50 | 127.50 |
| 32 | Rear smart entry sensor | 1.0 | 178.40 | 178.40 |
| 33 | Rear luggage room box | 1.0 | 345.20 | 345.20 |
| 34 | Rear deck box | 1.0 | 311.90 | 311.90 |

2 pcs

219.00

509.00

285.60
MS REX

955.00

1 pc

10,758.05

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-6920979-4

AXA INSURANCE SINGAPORE PTE LTD
 NO. 8
 SHENTON WAY
 AXA TOWER
 SINGAPORE 068811

Contact : 62208751/62208751

Fax No. :

Estimate : QUOT201803-000323(00)

Date : 14/03/2018

Vehicle No. : SKW3570A

Make/Model : TOYOTA WISH 1.8X A

Mileage (km) : 0

Chassis No. : ZGE206024484

Accident Date : 13/03/2018 00:00:00

Claim No. : XE2770L

Reference : SKW3570A

Policy No. : MSD/VPCP/17-002217

| S/No | Particular | Quantity | Unit Price | Amount S\$ |
|------------------------|--|----------|------------|----------------------|
| 35 | Rear deck board - center | 1.0 | 792.60 | 792.60 <i>JA</i> |
| 36 | Rear deck board - LH | 1.0 | 212.60 | 212.60 <i>JA</i> |
| 37 | Rear deck board - RH | 1.0 | 212.60 | 212.60 <i>JA</i> |
| 38 | Rear floor pan | 1.0 | 782.90 | 782.90 <i>R</i> |
| 39 | Rear bumper mudguard | 2.0 | 77.80 | 155.60 <i>JA</i> |
| 40 | Grip | 18.0 | 3.21 | 57.78 <i>JA</i> |
| List Total : | | | | 15,553.58 |
| 25% Discount S\$ | | | | 3,888.34 |
| | | | | 11,665.22 |
| SPECIAL NET : | | | | |
| 1 | Rear number plate | 1.0 | 25.00 | 25.00 <i>JA</i> |
| 2 | Rear number plate casing | 1.0 | 35.00 | 35.00 <i>JA</i> |
| 3 | Tailgate glass sealant | 1.0 | 40.00 | 40.00 <i>JA</i> |
| 4 | Reverse sensor | 1.0 | 350.00 | 350.00 <i>JA</i> |
| 5 | Rear view camera | 1.0 | 385.00 | 385.00 <i>300SN</i> |
| 6 | Rear RH fender glass sealant | 1.0 | 40.00 | 40.00 <i>JA</i> |
| 7 | Rear floor pan insulator paste | 1.0 | 150.00 | 150.00 <i>JA</i> |
| SPECIAL NET Total S\$: | | | | 1,025.00 |
| LABOUR : | | | | |
| | *To remove and install rear windscreen glass | 1.0 | 120.00 | 120.00 <i>JA</i> |
| | *To remove and install rear RH fender glass | 1.0 | 120.00 | 120.00 <i>JA</i> |
| | *To install rear view camera and reverse sensor | 1.0 | 180.00 | 180.00 <i>JA</i> |
| | *To supply panel sealant and to re-align all worn spot seam and gaps | 1.0 | 90.00 | 90.00 <i>JA</i> |
| | *To spray under coating | 1.0 | 120.00 | 120.00 <i>JA</i> |
| | *To check wiring and lighting | 1.0 | 80.00 | 80.00 <i>JA</i> |
| | *To remove and refix rear seats and upholstery | 1.0 | 180.00 | 180.00 <i>JA</i> |
| | - To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts | 1.0 | 1,500.00 | 1,500.00 <i>1200</i> |
| | - Spray painting on affected & replace parts | 1.0 | 1,600.00 | 1,600.00 <i>1200</i> |
| | | | | 3,990.00 |

CONTINUE NEXT PAGE

Page 2 of 3

16680.17



Re:RE: FOLLOW-UP FOR DS INSTRUCTION

Type

 Information

Message

Pls try to resolve this matter within our mandate of S\$14,000.00 subject to surveyor finalization and recommended LOU. XY 18 Mar 2019 (Bulk Settlement)

Reply



CITY AUTO PTE LTD

One Stop Automotive Solution
BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Your ref: CC4/ASM18004956/Kjb3
Our ref: SKW3570A

22/11/2018

WITHOUT PREJUDICE

Attn: Motor Claim Dept

AXA INSURANCE SINGAPORE PTE LTD
NO. 8
SHENTON WAY
AXA TOWER
SINGAPORE 068811

Dear Sir/Mdm,

Accident involving SKW3570A and XE2770L on 13/03/2018

We refer to the above said accident.

We enclosed here with relevant documents as stated below:-

- Repair tax invoice
- Letter of authorization
- GIA search receipt

As instructed, we are claiming the following as stated below:-

| | | |
|----------------------------------|---|---------------------|
| Cost of Repair | : | S\$ 9,148.50 |
| Loss of use (12 Days x \$100.00) | : | S\$ 1,200.00 |
| LTA Search Fee | : | S\$ 2.00 |
| | | <u>S\$10,350.50</u> |

We do not have the survey report and photographs as our client's motor vehicle was surveyed by your appointed surveyor.

Please kindly let us know whether you are prepared to settle our client's claim & we look forward to hear from you soonest.

Thanks & regards

Veronica Law (Claim dept.)
Tel: 6453 1235
Fax: 64537944
Email: cityauto@singnet.com.sg

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

| | | | |
|-------------------|---------------------|--------|-----------------|
| Vehicle No: | XE 2770L (Insd veh) | Model: | TOYOTA WISH (A) |
| | SKW 3570A (TP veh) | | |
| Date of Accident: | 13/03/2018 | | |

| | | | | |
|-----------------------|-----|---|-----------------------------|----------------------------|
| Global Sum Settlement | : | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | |
| Repair Estimate | :\$ | | 17,847.78 | |
| Final Repair Cost | :\$ | | 9,148.50 | |
| Loss of Use | :\$ | | 960.00 | 12 days at \$80.00 per day |
| Rental (if any) | :\$ | | | days |
| LTA / GIA Search Fee | :\$ | | 2.00 | |

| | | |
|---------|-----|--|
| Others: | :\$ | |
|---------|-----|--|

| | | |
|-----------------------------------|-----|-----------|
| | :\$ | |
| Final Settlement Sum (GLOBAL SUM) | :\$ | 10,110.00 |

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

| Payment Instruction: Payee's Breakdown | | |
|--|-------------------|----------------|
| 1) | CITY AUTO PTE LTD | : \$ 10,110.00 |

NUR SHAQILAH BTE ABDOL
WAHAB

06/05/2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18004956/Kjb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: CYNTHIA LOH

Date : 06-05-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------|----------------|------------|
| Insured Veh. | XE 2770L | Veh. Inspected | SKW 3570A |
| Policy No. | P1934163 | Coverage (\$) | 0.00 |
| Claim No. | S8M00AQP | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 15/03/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-----------------|--------------|--------------------|
| Make & Model | TOYOTA WISH (A) | c.c | 1797 |
| Engine No. | HIDDEN | Year of Reg. | 2015 |
| Chassis No. | ZGE206024484 | Colour | METALLIC BLACK |
| Odometer | 67042 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|-----------|----------|---------|
| R/H Front Tyre | 195/65R15 | YOKOHAMA | 6 mm |
| L/H Front Tyre | 195/65R15 | YOKOHAMA | 6 mm |
| R/H Rear Tyre | 195/65R15 | YOKOHAMA | 6 mm |
| L/H Rear Tyre | 195/65R15 | YOKOHAMA | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---------------------------|-----------------|------------|
| Accident Date | 13/03/2018 | Inspection Date | 15/03/2018 |
| Survey held at | 160 SIN MING DRIVE #05-01 | | |
| Repairer | CITY AUTO PTE LTD | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 3570A

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---|-------------------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 2 | REAR NUMBER PLATE LAMP @ \$67.90 (CONSISTENT) | MTG CRACKED | 135.80 | 135.80 |
| 1 | TAILGATE (CONSISTENT) | BENT | 1,420.70 | 1,420.70 |
| 2 | TAILGATE HINGE @ \$91.60 (CONSISTENT) | TO REPAIR SEE LABOUR | 183.20 | - |
| 2 | TAILGATE DAMPER @ \$279.84 (CONSISTENT) | SERVICEABLE | 559.68 | - |
| 1 | TAILGATE LOCK (CONSISTENT) | JAMMED | 313.70 | 313.70 |
| 1 | TAILGATE STRIKER (CONSISTENT) | TO REPAIR SEE LABOUR | 32.10 | - |
| 1 | TAILGATE WEATHERSTRIP (CONSISTENT) | DENTED / CUT | 377.60 | 219.00 |
| 1 | TAILGATE LOGO (CONSISTENT) | NECESSARY | 60.79 | 60.79 |
| 1 | TAILGATE EMBLEM - VALVE MATIC (CONSISTENT) | NECESSARY | 44.17 | 44.17 |
| 1 | TAILGATE OUTER CHROME MOULDING (CONSISTENT) | CRACKED | 298.54 | 298.54 |
| 1 | TAILGATE OUTER HANDLE SWITCH (CONSISTENT) | DENTED | 179.60 | 179.60 |
| 2 | TAILGATE LAMP @ \$291.60 (CONSISTENT) | N/A SCRATCHED / O/S CRACKED | 583.20 | 583.20 |
| 1 | TAILGATE GLASS (CONSISTENT) | SHATTERED | 1,071.60 | 1,071.60 |
| 1 | TAILGATE INNERBOARD (CONSISTENT) | BUCKLED | 375.60 | 375.60 |
| 1 | REAR WIPER ARM (CONSISTENT) | SERVICEABLE | 61.40 | - |
| 1 | REAR WIPER BLADE (CONSISTENT) | SERVICEABLE | 34.75 | - |
| 1 | REAR WIPER MOTOR (CONSISTENT) | DISTORTED / JAMMED | 801.90 | 509.00 |
| 1 | REAR BUMPER (CONSISTENT) | BUCKLED | 541.60 | 541.60 |
| 2 | REAR BUMPER REFLECTOR @ \$67.80 (CONSISTENT) | O/S CRACKED / N/S SERVICEABLE | 135.60 | 67.80 |
| 2 | REAR BUMPER RETAINER @ \$78.30 (CONSISTENT) | O/S DISTORTED | 156.60 | 78.30 |
| 2 | REAR BUMPER BRACKET @ \$77.60 (CONSISTENT) | O/S CRACKED | 155.20 | 77.60 |
| 1 | REAR END PANEL (CONSISTENT) | BENT | 521.60 | 521.60 |
| 2 | REAR END PANEL BRACKET @ \$98.20 (CONSISTENT) | O/S BENT | 196.40 | 98.20 |
| 1 | REAR END PANEL TOP GARNISH (CONSISTENT) | MTG DISTORTED | 337.80 | 285.60 |
| 2 | TAILLAMP @ \$379.20 (CONSISTENT) | N/S SERVICEABLE / O/S CRACKED | 758.40 | 379.20 |
| 1 | TAILLAMP PANEL RH (CONSISTENT) | BENT | 197.60 | 197.60 |
| 1 | REAR RH FENDER (CONSISTENT) | BUCKLED | 1,411.60 | 955.00 |

Report Ref No. CC4/ASM18004956/Kjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| 1 | REAR RH FENDER TRIMBOARD (CONSISTENT) | CRACKED | 680.95 | 680.95 |
| 1 | REAR LH FENDER TRIMBOARD (CONSISTENT) | SERVICEABLE | 352.10 | - |
| 1 | REAR RH FENDER GLASS MLOG (CONSISTENT) | MTG NECESSARY | 396.70 | 128.00 |
| 1 | REAR RH FENDER AIR DUCT (CONSISTENT) | DENTED | 127.50 | 127.50 |
| 1 | REAR SMART ENTRY SENSOR (CONSISTENT) | CRACKED | 178.40 | 178.40 |
| 1 | REAR LUGGAGE ROOM BOX (CONSISTENT) | SERVICEABLE | 345.20 | - |
| 1 | REAR DECK BOX (CONSISTENT) | SERVICEABLE | 311.90 | - |
| 1 | REAR DECK BOARD - CENTER (CONSISTENT) | SERVICEABLE | 792.60 | - |
| 1 | REAR DECK BOARD - LH (CONSISTENT) | SERVICEABLE | 212.60 | - |
| 1 | REAR DECK BOARD - RH (CONSISTENT) | SERVICEABLE | 212.60 | - |
| 1 | REAR FLOOR PAN (CONSISTENT) | TO REPAIR SEE LABOUR | 782.90 | - |
| 2 | REAR BUMPER MUDGUARD @ \$77.80 (CONSISTENT) | SERVICEABLE | 155.60 | - |
| 18 | CLIP @ \$3.21 (CONSISTENT) | NOT NECESSARY | 57.78 | - |
| | LESS 25% DISCOUNT | | -3,888.39 | -2,382.26 |
| | | | 11,665.17 | 7,146.79 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | REAR NUMBER PLATE (SN) (CONSISTENT) } | DENTED | 25.00 | 45.00 |
| 1 | REAR NUMBER PLATE CASING (SN) (CONSISTENT) } | | 35.00 | - |
| 1 | TAILGATE GLASS SEALANT (SN) (CONSISTENT) | NECESSARY | 40.00 | 40.00 |
| 1 | REVERSE SENSOR (SN) (CONSISTENT) | DENTED | 350.00 | 200.00 |
| 1 | REAR VIEW CAMERA (SN) (CONSISTENT) | SHORTED | 385.00 | 300.00 |
| 1 | REAR RH FENDER GLASS SEALANT (SN) (CONSISTENT) | NECESSARY | 40.00 | 40.00 |
| 1 | REAR FLOOR PAN INSULATOR PASTE (SN) (CONSISTENT) | NOT NECESSARY | 150.00 | - |
| | | | 1,025.00 | 625.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE AND INSTALL REAR WINDSCREEN GLASS. | | 120.00 | 120.00 |
| | TO REMOVE AND INSTALL REAR RH FENDER GLASS. | | 120.00 | 60.00 |
| | TO INSTALL REAR VIEW CAMERA AND REVERSE SENSOR. | | 180.00 | 80.00 |
| | TO SUPPLY PANEL SEALANT AND TO SEAL OFF ALL WHEN SPOT SEAM AND GAPS. | | 90.00 | 60.00 |
| | TO SPRAY UNDER COATING. | | 120.00 | 90.00 |

Report Ref No. CC4/ASM18004956/Kjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|-----------|---------------------------|-------------------|
| | TO CHECK WIRING AND LIGHTING. | | 80.00 | 20.00 |
| | TO REMOVE AND REFIX REAR SEATS AND UPHOLSTERY. | | 180.00 | 120.00 |
| | TO KNOCK JACK DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE HINGE, TAILGATE STRIKER AND REAR FLOOR PAN. SPRAY PAINTING ON AFFECTED & REPLACE PARTS. | | 1,500.00 | 1,200.00 |
| | | | 1,600.00 | 1,200.00 |
| | | | 3,990.00 | 2,950.00 |
| | GRAND TOTAL | | 16,680.17 | 10,721.79 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONSISTENT) | | | 8,550.00 |

Report Ref No. CC4/ASM18004956/Kjb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.