

REF: C91/SPF18004957/BVb52

Special Instruction:

Paper Survey

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 15032018
 Estimated Cost: Bill to:

HS: \$ 6100-00

Third Parties:

Claimant:

Surveyor: PAL'S Appraiser

Workshop: Han Car Repair.

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SKS 4785L Insured: QX 574H

at Workshop m/s Han Car Repair. Tel: 9777 7266

of Bldg 1001 Bukit Merah Lane 3 #01-49

Policy No: Claim No: AEMD/105/001/2018/015

Sum Insured: Excess:

Make of Veh: D.O.A. 09032018

(Client's Record)

19/3

Do Not Finalize

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 8 days)

Date/Time: 12/1/18 Submit Final Fig LS \$3800, 5 days (Red \$2360 / 37 %; Original _____ days)

Date/Time	Action/Instruction
	SKS 4785L - Net / AEMD/18004957/Y
	QX 574H - X
21/2/19	To re-open indicate upper range pls pass to typist (HYN 26/2/19)
	upper Range \$4K - \$5K (Est)
26/2/19	reopen not only * 1st close date 16/2/18 *
	RECEIVED 12 JUL 2018

Cebs 21/2/19
 12/7/2018

URGENT

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

1) Date/Time 12/7-typist File Pass to

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

ASS. REC. BY:

REF: CS3/SPF18004957 / v6

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time 15/03/2018

Estimated Cost: Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 4785L Insured: QX 574H

at Workshop m/s: Han Car Repair Tel: 9777 7266

of Bk 1001 Bukit Merah Lane 3

Policy No: Claim No: AEMD/105/009/2018/025

Sum Insured: Excess:

Make of Veh: D.O.A 01/03/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: 15/03/2018 4:28pm Person Contacted: Susan Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
15/03/2018 4:28pm	According to the repairer, vehicle already start repair.
4:30pm	Call Abdul Rahman, he ask to take after repair photo.
	SKS 4785L - NGA / NGA18004957 / X
	QX 574H - X



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2018/025

Date: 12th July 2018

Our Ref: CS1/SPF18004957/Bvbs2

M/s Automotive Engineering & MGT Division
Accident Claim Section
(Singapore Police Force)
1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333
(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

Physical Re-visit
EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SKS 4785L INSURED VEHICLE: QX 574H ACCIDENT DATE: 09/03/2018

We thank you for your instruction on 15/03/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKS 4785L from M/s PAL'S Appraiser Pte Ltd.
- b) Colour damaged vehicle photographs of SKS 4785L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKS 4785L
Make & Model	: Hyundai Elantra
Year of Registration	: 2015
Chassis Number	: KMHDH41CMFU434396
Engine Capacity	: 1591 cc

- 2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 4785L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP	CUT	834.00	682.50
1	FRONT GRILLE	CUT	273.00	273.00
1	FRONT GRILLE LOGO	CUT	68.00	34.10
1	FRONT GRILLE CHROME MOULDING	NECESSARY	78.00	78.00
1	FRONT BUMPER	CUT	512.00	512.00
1	FRONT BUMPER FOG LAMP	CRACKED	233.00	233.00
1	FRONT BUMPER FOG LAMP BRACKET	CUT	56.00	56.00
1	FRONT BUMPER REINFORCEMENT	INTACT	388.00	-
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	64.00	64.00
1	FRONT BUMPER SPONGE	BROKEN	138.00	138.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	583.00	-
1	FRONT FENDER INNER SHIELD	CUT	129.00	129.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	983.00	-
1	FRONT WASHER TANK	BROKEN	113.40	113.40
1	FRONT DOOR	TO REPAIR SEE LABOUR	1,221.00	-
1	FRONT DOOR RUBBER	NOT NECESSARY	128.00	-
1	FRONT DOOR SIDE MIRROR	TO REPAIR SEE LABOUR	377.00	-
1	FRONT WHEEL HUB	DENTED	410.00	410.00
1	FRONT WHEEL BEARING	NECESSARY	123.00	123.00
1	FRONT SHOCK ABSORBER	SERVICEABLE	281.50	-
1	FRONT LOWER ARM	BENT	296.00	296.00
1	FRONT KNUCKLE ARM	DENTED	373.80	373.80
1	FRONT KNUCKLE ARM BEARING	NECESSARY	127.60	127.60
1	FRONT STABILIZER BAR LINK	SERVICEABLE	69.00	-
	LESS 20% DISCOUNT		-1,571.86	-728.68
			6,287.44	2,914.72
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	FRONT NUMBER PLATE (SN)	INTACT	50.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	50.00	50.00
1	FRONT TYRE (SN)	NOT NECESSARY	320.00	-
1	FRONT SPORT RIM (SN)	DAMAGED	550.00	400.00
			1,020.00	500.00
	LABOUR			
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		60.00	40.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		350.00	200.00
	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.		180.00	60.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT FENDER, FRONT SUPPORT PANEL, FRONT DOOR AND FRONT DOOR SIDE MIRROR.		750.00	450.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		750.00	600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		120.00	40.00
			2,210.00	1,390.00
	GRAND TOTAL		9,517.44	4,804.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CS1/SPF18004957/Bvbs2

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MA SME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 4785L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP	CUT	834.00	682.50
1	FRONT GRILLE	CUT	273.00	273.00
1	FRONT GRILLE LOGO	CUT	68.00	34.10
1	FRONT GRILLE CHROME MOULDING	NECESSARY	78.00	78.00
1	FRONT BUMPER	CUT	512.00	512.00
1	FRONT BUMPER FOG LAMP	CRACKED	233.00	233.00
1	FRONT BUMPER FOG LAMP BRACKET	CUT	56.00	56.00
1	FRONT BUMPER REINFORCEMENT	INTACT	388.00	-
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	64.00	64.00
1	FRONT BUMPER SPONGE	BROKEN	138.00	138.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	583.00	-
1	FRONT FENDER INNER SHIELD	CUT	129.00	129.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	983.00	-
1	FRONT WASHER TANK	BROKEN	113.40	113.40
1	FRONT DOOR	TO REPAIR SEE LABOUR	1,221.00	-
1	FRONT DOOR RUBBER	NOT NECESSARY	128.00	-
1	FRONT DOOR SIDE MIRROR	TO REPAIR SEE LABOUR	377.00	-
1	FRONT WHEEL HUB	DENTED	410.00	410.00
1	FRONT WHEEL BEARING	NECESSARY	123.00	123.00
1	FRONT SHOCK ABSORBER	SERVICEABLE	281.50	-
1	FRONT LOWER ARM	BENT	296.00	296.00
1	FRONT KNUCKLE ARM	DENTED	373.80	373.80
1	FRONT KNUCKLE ARM BEARING	NECESSARY	127.60	127.60
1	FRONT STABILIZER BAR LINK	SERVICEABLE	69.00	-
	LESS 20% DISCOUNT		-1,571.86	-728.68
			6,287.44	2,914.72
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	50.00

Report Ref No. CS1/SPF18004957/Bvbs2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	INTACT	50.00	-
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	50.00	50.00
1	FRONT TYRE (SN)	NOT NECESSARY	320.00	-
1	FRONT SPORT RIM (SN)	DAMAGED	550.00	400.00
			1,020.00	500.00
	LABOUR			
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		60.00	40.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		350.00	200.00
	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.		180.00	60.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT FENDER, FRONT SUPPORT PANEL, FRONT DOOR AND FRONT DOOR SIDE MIRROR.		750.00	450.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		750.00	600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		120.00	40.00
			2,210.00	1,390.00
GRAND TOTAL			9,517.44	4,804.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS1/SPF18004957/Bvbs2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00 (EST)

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.