

REF: C31 / SPF 180004957 / B v b s 2

Special Instruction:

Paper Survey

ASSIGNMENT (Office)

From (Person); Abdul Rahman of SPF Date/Time: 15032018
Estimated Cost: _____ Bill to: _____

4/5: \$ 6100.00

Third Parties:

Claimant:

Surveyor: PAL'S Appraiser

Workshop: Han Car Repair.

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SKS 4785L Insured: QX 574H

at Workshop m/s Han Car Repair. Tel: 9773 3066

of Blok 1001 Bukit Merah Lane 3 #01-49

Policy No: _____ Claim No: ALMD/105/009/2018/025

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 09/03/2016

(Client's Record)


Do Not Finalize

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 8 days)

Date/Time: 12/1/18 Submit Final Fig LS \$3800, 5 days (Red \$300 / 37 %; Original days)

Date/Time	Action/Instruction
	SKS 11785L - N8A / AT418004646 / Y QX 5711H - X
	DA: 09/03/18  12/7/2018
	RECEIVED 12 JUL 2018 URGENT

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

Transport

Photos

Others

Total

1) Date/Time 12/7-14pist File Pass to

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time File Return to

ASS. REC. BY:

REF: CS3/SPF18004957 / v6

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 15/03/2018

Estimated Cost: Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 4785L Insured: QX 574H

at Workshop m/s Han Car Repair Tel: 9777 7266

of Blk 1001 Bukit Merah Lane 3

Policy No: Claim No: AEMD/105/009/2018/025

Sum Insured: Excess:

Make of Veh: D.O.A. 09/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: 15/03/2018 4:28pm Person Contacted: Susan Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
15/03/2018 4:28pm	According to the repairer, vehicle already start repair.
4:30pm	Call Abdul Rahman, he ask to take after repair photo.
	SKS 4785L - NGA / M618004616 / Y
	QX 574H - X
	DA: 09/03/18



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SKS4785L

Our Ref : AEMD/105/009/2018/025

Date : 15 March 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT ON 9 MARCH 2018 INVOLVING POLICE VEHICLE QX574H AND OTHER VEHICLE SKS4785L

We refer to the above matter.

- 2 Please arrange for a Pre-Repair Inspection of vehicle no. **SKS4785L** at **M/s Han Car Repairs of Blk 1001 Bukit Merah Lane 3 #01-49, Singapore 159718.**
- 3 Estimates were not provided by the workshop.
- 4 For appointment, please contact **Ms Susan** at **HP: 97777266 / DID: 62710275.**
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

cc : Amy Lim Law Practice Ref: 2018.1115.PD.HCR(QX574H) Via Fax: 64915638 (FYI, pls)

A FORCE FOR THE NATION

Veron Chen (LKKAUTO)

From: Olivia Lau (LKKAUTO)
Sent: Friday, 29 June 2018 4:16 PM
To: Frankie THAY (SPF); Veron Chen (LKKAUTO)
Cc: Abdul Rahman MOHAMAD SALIM (SPF); SUR; assignments;
lkkauto.photos@gmail.com
Subject: [SPF]: RE: Accident on 09/03/2018 involving police vehicle QX 574 and other vehicle
SKS 4785L // LKK Ref: CS3/SPF18004957/vb
Attachments: CCE29062018_0013.pdf

[Urgent – 10 days to WOS]

LKK Ref: CS3/SPF18004957/vb

Hi Frankie,

Please provide us the survey report and photographs. You may send it to lkkauto.photos@gmail.com, if total file size is above 10MB.

Thank you.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today

From: Frankie THAY (SPF) [mailto:Frankie_THAY@spf.gov.sg]
Sent: Friday, 29 June, 2018 3:03 PM
To: Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>
Cc: Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>;
catherinechong90.cc@gmail.com
Subject: RE; Accident on 09/03/2018 involving police vehicle QX 574 and other vehicle SKS 4785L

Your Ref : SKS 4785L

Our Ref : AEMD/105/009/2018/025

Olivia,

Appraisal assessment was activated on 15/03/2018, please expedite the report as the third party's lawyer given 10 days of notice to serve Writ Of Summons.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 03-18020/DY / 2018
Date of Report : 9 Apr 2018

Starburst Engineering Ptd Ltd
c/o Blk 1001 Bukit Merah Lane 3
#01-49 Alexandra Village
Singapore 159718

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 9 Mar 2018

As per your instruction dated 13 Mar 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SKS 4785 L. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SKS 4785 L
Model : Hyundai Elantra
Year / Capacity : 2015/1591
Chassis No : KMHDH41CMFU434396
Engine No : G4FGEU173257
Mileage : 89602
Colour : Blue

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	205/55 R16	Michelin	5.00	mm	Sport
REAR	O/S	:	205/55 R16	Michelin	5.00	mm	Sport
FRONT	N/S	:	205/55 R16	Michelin	5.00	mm	Sport
REAR	N/S	:	205/55 R16	Michelin	5.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the o/s front portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Han Car Repairs
Blk 1001 Bukit Merah Lane 3
#01-49 Alexandra Village
Singapore 159718

5. Estimated normal period of repair : 8 working days including lead time to complete.

6. Enclosed number of photograph : 113 copies.

7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SKS 4785 L
Report No: TP/ 03-18020/DY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front headlamp	Damage	\$ 834.00	\$ 682.50 834.00 CUT ✓
1	Front grille	Damage	\$ 273.00	\$ ✓ 273.00 CUT ✓
1	Front grille logo	Damage	\$ 68.00	\$ 34.10 68.00 CUT ✓
1	Front grille chrome moulding	Necessary	\$ 78.00	\$ 78.00 NEC ✓
1	Front bumper	Damage	\$ 512.00	\$ ✓ 512.00 CUT ✓
1	Front bumper fog lamp	Damage	\$ 233.00	\$ ✓ 233.00 CRA ✓
1	Front bumper fog lamp bracket	Damage	\$ 56.00	\$ ✓ 56.00 CUT ✓
1	Front bumper reinforcement	Intact	\$ 388.00	\$
2	Front bumper side retainers	Necessary	\$ 64.00	\$ ✓ 64.00 NEC ✓
1	Front bumper sponge	Damage	\$ 138.00	\$ ✓ 138.00 BR ✓
1	Front fender	Damage	\$ 583.00	\$ 583.00 R X
1	Front fender inner shield	Damage	\$ 129.00	\$ ✓ 129.00 CUT ✓
1	Front support panel	Repair	\$ 983.00	\$
1	Front washer tank	Damage	\$ 113.40	\$ ✓ 113.40 BR ✓
1	Front door	Damage	\$ 1221.00	\$ 1221.00 R X
1	Front door rubber	Necessary	\$ 128.00	\$ 128.00 NN X
1	Front door side mirror	Damage	\$ 377.00	\$ 377.00 R X
1	Front wheel hub	Damage	\$ 410.00	\$ 410.00 DD ✓
1	Front wheel bearing	Necessary	\$ 123.00	\$ 123.00 NEC ✓
1	Front shock absorber	Damage	\$ 281.50	\$ 281.50 SVC X
1	Front lower arm	Damage	\$ 296.00	\$ ✓ 296.00 BT ✓
1	Front knuckle arm	Damage	\$ 373.80	\$ ✓ 373.80 DD ✓
1	Front knuckle arm bearing	Necessary	\$ 127.60	\$ ✓ 127.60 NEC ✓
1	Front stabilizer bar link	Damage	\$ 69.00	\$ 69.00 SVC X
			\$ 7859.30	\$ 6488.30 3643.40
Discount 20.0%			\$ 1571.86	\$ 1297.66 728.68
			\$ 6287.44	\$ 5490.64 2914.72
<u>Special Nett Items</u>				
1	Front bumper clip (1 set)	Necessary	\$ 50.00	\$ ✓ 50.00 NEC ✓
1	Front number plate	Intact	\$ 50.00	\$
1	Front fender inner shield clip (1 set)	Necessary	\$ 50.00	\$ 50.00 NEC ✓
1	Front tyre (Depreciation)	Damage	\$ 320.00	\$ 160.00 NN X
1	Front sport rim	Damage	\$ 550.00	\$ 400.00 550.00 ✓
			\$ 1020.00	\$ 840.00 500.00

Spare Parts Total \$ 7307.44 \$ ~~6000.64~~ 3414.72

Vehicle No: SKS 4785 L
Report No: TP/ 03-18020/DY / 2018


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 7307.44	\$ ^{3414.72} 6000.64
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 60.00	\$ 40.00 ✓
2	To remove and refit front undercarriage.	\$ 350.00	\$ 200.00
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 180.00	\$ 120.00 60.00 ✓
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 750.00	\$ ^{450.00} 550.00
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 750.00	\$ 660.00 60.00 ✓
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 120.00	\$ 60.00 40.00 ✓
Total		\$ 9517.44	\$ ^{4804.74} 7630.64

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:


\$ 6100.00

SDLS: SIX THOUSAND ONE HUNDRED ONLY


Qualified Appraiser

L/S 3800/-

Repair days - 5


11/7/18



Your Ref: AEMD/105/009/2018/025

Date: 12th July 2018

Our Ref: CS1/SPF18004957/Bvbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SKS 4785L INSURED VEHICLE: QX 574H ACCIDENT DATE: 09/03/2018**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKS 4785L from M/s PAL'S Appraiser Pte Ltd.
- b) Colour damaged vehicle photographs of SKS 4785L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKS 4785L
Make & Model	: Hyundai Elantra
Year of Registration	: 2015
Chassis Number	: KMHDH41CMFU434396
Engine Capacity	: 1591 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 4785L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP	CUT	834.00	682.50
1	FRONT GRILLE	CUT	273.00	273.00
1	FRONT GRILLE LOGO	CUT	68.00	34.10
1	FRONT GRILLE CHROME MOULDING	NECESSARY	78.00	78.00
1	FRONT BUMPER	CUT	512.00	512.00
1	FRONT BUMPER FOG LAMP	CRACKED	233.00	233.00
1	FRONT BUMPER FOG LAMP BRACKET	CUT	56.00	56.00
1	FRONT BUMPER REINFORCEMENT	INTACT	388.00	-
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	64.00	64.00
1	FRONT BUMPER SPONGE	BROKEN	138.00	138.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	583.00	-
1	FRONT FENDER INNER SHIELD	CUT	129.00	129.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	983.00	-
1	FRONT WASHER TANK	BROKEN	113.40	113.40
1	FRONT DOOR	TO REPAIR SEE LABOUR	1,221.00	-
1	FRONT DOOR RUBBER	NOT NECESSARY	128.00	-
1	FRONT DOOR SIDE MIRROR	TO REPAIR SEE LABOUR	377.00	-
1	FRONT WHEEL HUB	DENTED	410.00	410.00
1	FRONT WHEEL BEARING	NECESSARY	123.00	123.00
1	FRONT SHOCK ABSORBER	SERVICEABLE	281.50	-
1	FRONT LOWER ARM	BENT	296.00	296.00
1	FRONT KNUCKLE ARM	DENTED	373.80	373.80
1	FRONT KNUCKLE ARM BEARING	NECESSARY	127.60	127.60
1	FRONT STABILIZER BAR LINK	SERVICEABLE	69.00	-
	LESS 20% DISCOUNT		-1,571.86	-728.68
			6,287.44	2,914.72
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	50.00

Report Ref No. CS1/SPF18004957/Bvbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	INTACT	50.00	-
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	50.00	50.00
1	FRONT TYRE (SN)	NOT NECESSARY	320.00	-
1	FRONT SPORT RIM (SN)	DAMAGED	550.00	400.00
			1,020.00	500.00
	LABOUR			
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		60.00	40.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		350.00	200.00
	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.		180.00	60.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT FENDER, FRONT SUPPORT PANEL, FRONT DOOR AND FRONT DOOR SIDE MIRROR.		750.00	450.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		750.00	600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		120.00	40.00
			2,210.00	1,390.00
GRAND TOTAL			9,517.44	4,804.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS1/SPF18004957/Bvbs2

LIM TEOW GUAN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.