

A.S.S. REC. BY:

REF: CG/FCI18004962/Kfbn2 Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS Eileen Lee

of

FCI

Date/Time:

15/03/2018 3:10pm

Estimated Cost:

Bill to:

OL / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5311 J

Insured:

SHD 3008T

at Workshop m/s

Trans Cab

Tel:

6287 6666

of

No. 2 AMK St 63

Policy No:

Claim No:

D18002140MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi

H.O.D. Endorsement:

Date/Time:

15/03/2018 3:20pm

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 5311 J - CC4 / AXA 16002350 / J493d2

DCA: 21.11.16

SHD 3008T - NS / INC 1605704 / H1vbn2

DCA: 170816

ASS. REC. BY:

REF: FC21

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SAC 53117Yr Regn: 03, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitudec.c: 1895Colour h. white / R

A/C: Insured / Std / NI / NA

Sp. Reading 528352

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABLI5AUC. 276806

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: F: Giti 215/60R16R: FalkenBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 9 mmL/Bal. 8 mmL/Bal. 9 mmD.O.A. 14/3/18D.O.I. 19/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rra

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/3196 pcr to CctherinL1 Log @ 1200 (Red: 35705.96 : 96%)

RECEIVED 20 MAR 2018

Date/Time, File Pass to?

28/3 Typist

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair: 2

Resurvey No. of Trlp: _____

Add Fee: ☐

: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee: 26x15=390Transportation: 50Photos 50Others 9TOTAL 619Report Format: TPLump Sum / I.B.I.: (\$ 1200)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18004962/Ktb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3008T	Veh. Inspected	SHC 5311J
Policy No.		Coverage (\$)	0.00
Claim No.	D18002140MFSH	Excess (\$)	0.00
Assign From	CWS(EILEEN LEE)	Assign Date	15/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/03/2018	Inspection Date
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002140MFSH

Date: 28/3/2018

Our Ref: CS/FC118004962/Ktb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5311J

Please be informed that we had conducted the inspection of the abovementioned vehicle 19/3/2018 at the premises of M/s Trans Cab and have the following to report: -

Workshop Estimate Amount	: S\$ <u>36,905.96</u>
Revised Estimate Amount	: S\$ <u>1,200.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Comments/ Present Status:

Damages Consistent.
Repair cost economical

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	15-03-2018	Our Ref No. D18002140MFSH
Accident Date	14-03-2018	Claim Type. Third Party
Insured Vehicle	SHD3008T	Third Party Vehicle. SHC5311J
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 28 March 2018 1:42 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002140MFSH/1
Attachments: PRELI ADVISED SHC 5311J.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 5311J**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 15 March 2018 3:33 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002140MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 15 March, 2018 3:10 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002140MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5311J
Vehicle to be Exported:	Yes
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000885
Chassis No.:	VF1ABL15AUC276806
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	21 Mar 2014
First Registration Date:	21 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	20 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00
COE Rebate Amount:	\$29,490.00
Total Rebate Amount:	\$38,863.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Mar 2018

OK

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5311J - FCIL**AAD1803-120***Not Notified
11/12/2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5311J - CANDY

VF1ABL15AUC276806

RENAULT

LATITUDE

14.03.2018

FCIL**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Buclm</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84	}
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99	
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	
9	1	ROCKER PANEL OUTER RH	\$	<i>Sn</i> 987.49	
10	1	FENDER PANEL REAR RH	\$	<i>Sn</i> 3,299.13	
11	1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i> 671.45	}
12	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	
13	1	TAILLAMP RH	\$	<i>Sn</i> 552.55	
14	1	TAILLAMP PANEL RH	\$	<i>Sn</i> 986.70	
15	1	EXHAUST REAR	\$	<i>Sn</i> 7,489.05	
16	1	EXHAUST CAP REAR	\$	<i>Sn</i> 230.49	
17	1	DOOR PANEL REAR RH	\$	<i>Sn</i> 2,844.66	
18	1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82	
19	1	DOOR HINGE UPPER RH	\$	<i>Sn</i> 274.50	
20	1	DOOR HINGE LOWER RH	\$	<i>Sn</i> 300.55	
21	1	DOOR CHECK REAR RH	\$	<i>Sn</i> 203.06	}
22	1	DOOR LOCK REAR RH	\$	<i>Sn</i> 908.75	
23	1	DOOR GRAB HANDLE REAR RH	\$	<i>Sn</i> 210.96	
24	1	DOOR HANDLE OUTER REAR RH	\$	<i>Sn</i> 126.49	
25	1	DOOR HANDLE CAP REAR RH	\$	<i>Sn</i> 35.52	
26	1	DOOR HANDLE SEAL REAR RH	\$	<i>Sn</i> 7.89	
27	1	DOOR HANDLE COVER REAR RH	\$	<i>Sn</i> 13.22	
28	1	DOOR HANDLE MODULE REAR RH	\$	<i>Sn</i> 133.60	
29	1	DOOR FINISHER REAR RH	\$	<i>Sn</i> 423.10	
30	1	DOOR WHEATHESTRIIP REAR RH	\$	<i>Sn</i> 410.66	
31	1	DOOR SEAL REAR RH	\$	<i>Sn</i> 162.02	
32	1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>Sn</i> 334.69	
33	1	DOOR MOULDING REAR RH	\$	<i>Sn</i> 176.82	
34	1	DOOR PANEL FRT RH	\$	<i>Sn</i> 2,844.66	

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5311J - FCIL**AAD1803-120**

TOTAL	\$	26,744.60
10%	\$	2,674.46
	\$	24,070.14

Specical Nett

1	1SET	PARKING AID	\$	<i>ns</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	} X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	
8	1	EXHAUST MOUNTING REAR	\$	<i>sn</i>	17.82	
9	1	TAILLAMP CLIP RH	\$	<i>nn</i>	5.00	
10	1SET	WHEELARCH CLIP RR RH	\$	<i>nn</i>	66.00	
11	2	REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00	
12	1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	
14	1	CAP HUB RH RR	\$	<i>sn</i>	35.00	
15	1	RIM RH RR	\$	<i>sn</i>	385.00	
16	1	TYRE RH RR	\$	<i>sn</i>	330.00	
17	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i>	80.00	
18	1	DOOR STICKER "Classic"	\$	<i>nn</i>	30.00	
19	1	DOOR STICKER "6555-3333"	\$	<i>nn</i>	80.00	

TOTAL	\$	2,225.82
TOTAL PARTS	\$	26,295.96

Putty And Spray Painting Of The Affected Portion. \$ 4,500.00 *220/*

To reinstall rear bumper parking sensor. \$ *nn* 170.00 X

To Rust-Proofing Of The Affected Areas. \$ *nn* 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 4,200.00 *200/*

To transfer of bootlid fittings, attachments and perform water seepage test. \$ *nn* 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5311J - FCIL**AAD1803-120**

To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
Towing Fees	\$	<i>nn</i> 120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X

TOTAL	\$	10,610.00
Over All Total	\$	36,905.96

(PARTS BY PARTS)**Repair Days***15 Days**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004962/Ktbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3008T	Veh. Inspected	SHC 5311J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002140MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	15/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC276806	Colour	METALLIC WHITE / RED	
Odometer	528352	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	FALKEN	9 mm	
L/H Rear Tyre	215/60 R16	FALKEN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/03/2018	Inspection Date	19/03/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5311J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BUCKLED / DENTED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	987.49	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR RH	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-

Report Ref No. CS/FCI18004962/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-2,674.46	-110.85
			24,070.14	997.61
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	SET WHEELARCH CLIP RR RH (SN)	NOT NECESSARY	66.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	CAP HUB RH RR (SN)	SERVICEABLE	35.00	-
1	RIM RH RR (SN)	SERVICEABLE	385.00	-
1	TYRE RH RR (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/FCI18004962/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
			2,225.82	99.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER RH,FENDER PANEL REAR RH,TAILLAMP PANEL RH,EXHAUST REAR,EXHAUST CAP REAR,DOOR PANEL REAR RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR LOCK REAR RH AND DOOR PANEL FRT RH.		4,200.00	200.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			10,610.00	420.00
GRAND TOTAL			36,905.96	1,516.61
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/FCI18004962/Ktbn2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.