

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18005016/ATBE2

Date: 28/05/2018

REFERENCE

Insured/Claimant:	HUANG JIANLUN, LESLIE	Policy No:	1800017175
Date of Loss:	13/03/2018	Nature of Claim:	OD
		Claim No:	5562535021SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFU11L	Engine No:	CVK049714
Make & Model:	AUDI A4, 2.0 (A)	Chassis No:	WAUZZZF44JA068483
Reg. Date:	07/02/2018 (Man. Year: 2017)	Odometer:	1978 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,877.00	3,526.60	10,350.40	74.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	3,052.00	1,500.00	32.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	18,429.00	6,578.60	11,850.40	64.30
+ GST 7.00/7.00% (\$\$)	1,290.03	460.50	829.53	64.30
Nett Amount (\$\$)	19,719.03	7,039.10	12,679.93	64.30

INSPECTION

Date of Assignment:	16/03/2018		
Date Inspected:	16/03/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,902.00 FS	*1,521.60 FS
2	2		*FRONT BUMPER SECURING STRIP	Not Necessary	60.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - LOWER	Not Necessary	171.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	180.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	73.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LH	Not Necessary	118.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	1,155.00 FS	*- FS
8	1		*FRONT BUMPER PARKING AID SENSOR (2 PCS)	Damaged-only 1 pc	421.00 FS	*168.40 FS
9	1		*FRONT PARKING SENSOR SEAL	Necessary	15.00 FS	*11.84 FS
10	1		*FRONT BUMPER GUIDE - LH	Cracked	31.00 FS	*24.56 FS
11	1		*FRONT FENDER - LH	Dented	665.00 FS	*532.00 FS
12	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	44.00 FS	*- FS
13	1		*FRONT FENDER BRACKET - LH FRONT	Not Necessary	31.00 FS	*- FS
14	1		*FRONT FENDER BRACKET - LH CENTER	Not Necessary	43.00 FS	*- FS
15	1		*FRONT FENDER BRACKET - LH REAR	Not Necessary	27.00 FS	*- FS
16	1		*SET FRONT FENDER RIVET	Necessary	24.00 FS	*18.56 FS
17	1		*FRONT FENDER BRACE - LH	Not Necessary	103.00 FS	*- FS
18	1		*HEADLIGHT TRIM - LH	Necessary	20.00 FS	*15.36 FS
19	1		*FRONT FENDER TRIM - LH OUTER	Not Necessary	27.00 FS	*- FS
20	1		*FRONT WHEEL SPOILER - LH	Cracked	63.00 FS	*50.16 FS
21	1		*FRONT BUMPER SPOILER - LH LOWER	Deformed	30.00 FS	*23.92 FS
22	1		*FRONT FENDER STONE CHIP GUARD - LH	Necessary	44.00 FS	*34.56 FS
23	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	215.00 FS	*171.60 FS
24	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	78.00 FS	*- FS
25	1		*LED HEADLIGHT - LH	Not Necessary	6,973.00 FS	*- FS
26	1		*HEADLIGHT WASHER CYLINDER - LH	Cracked	184.00 FS	*147.20 FS
27	1		*WASHER CYLINDER BRACKET - LH	Not Necessary	6.00 FS	*- FS
28	1		*RIM - LH FRONT	Cut	749.00 FS	*749.00 FS
29	1		*FRONT NO. PLATE	Not Necessary	25.00 FS	*- FS
30	1		*SUNDRIES	Necessary	400.00 FS	*57.84 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 13,877.00 3,526.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	1,500.00	1,100.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,552.00	3,052.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >