

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3514Z

DATE 16/3/2018 13:57

MAKE :

MODEL : HYUNDAI i40

LKK/Kalvin Phyp
L. Ke
LONPAC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
	Rear Bumper Reflector Lamp (LH)			\$ 32.00
	SUB TOTAL			\$ 1,939.35
	LESS 20%			\$ 387.87
	DISCOUNTED TOTAL			\$ 1,551.48
	Rear No. Plate			\$ 25.00
	License Plate cover X repl			\$ 100.00
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
				\$ 510.70
	Labour Charge			200
	Panel Beating			\$ 250.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 670.00
	ESTIMATE TOTAL			\$ 2,732.18

16/3/18 1500 hrs
2 DYS
P/P
Before Part + p/h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey to re-evaluate any painting
- To display damaged parts during resurvey
- Parts prices are subject to information
- Third party claims on a no-fault basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Rep:

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.