

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

## **ESTIMATE FOR SKP6869G**

FWD Singapore Pte Ltd

Motor Claims Department 6 Temasek Boulevard #18-01 Suntec Tower Four Singapore 038986 68208888

Vehicle & Document Information

WIP No 22071

Reg No/Reg Date

SKP6869G / 11/06/2014

Date In/Mileage Chassis No

ARAMA OCA WDD2120362A968698

Engine No

27492030148709

Make/Model

MB/E 250 2.0 CGI SEDAN (W212

Colour/Trim

021 197 Obsidian B1/ 042 211 Leather Ant

Description of Goods / Services   Seah   Seah   Description of Goods / Services   City   Unit Price   Disc%   Amount	Account No Terms Date/Time Printed CSE Operator		
BPNSUN	FFX00002 Credit 16/03/2018/ 14:19 VS 356 / Vincent	t Seah	
POLICY NO/ACC DATE : 2003/18 / TP CAR NO.: SKR8/22Y=FWD DATE IN/DATE SURVEY: BY/AUTHRIZED ON : A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT SPINSUB TRANSFER RIM AND BALANCING TYRE. NETT LHR A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT A BPILAB REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELBASE LEFT REAR M MOULDING M MOULDING M REAR BUMPER	- 1 日本 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Qty Unit Price Disc% Amount	
A BPILAB  USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO  IDENTIFICATION STANDARD. NETT  S BPNSUB  TRANSFER RIM AND BALANCING TYRE. NETT  LHR  A BPILAB  TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT  A BPILAB  TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT  A BPILAB  TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT  A BPILAB  BISASSEMBLE AND REPLACE LHR.DOOR, LHR.FENDER, REAR BUMPER  A BPILAB  BISASSEMBLE AND REPLACE LHR.DOOR, LHR.FENDER, REAR BUMPER  A BPILAB  REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELBASE  LEFT REAR  M MOULDING  M LEFT REAR DOOR BOTTOM INSULATION  M LEFT REAR DOOR WEATHERSTRIP  M LEFT REAR OOR WEATHERSTRIP  M LEFT REAR OOR WEATHERSTRIP  M LEFT REAR OOR MEATHERSTRIP  M LEFT REAR DOOR  M LEFT REAR ORNAMENTAL COVER  M LEFT REAR DOOR  M LEFT REAR ORNAMENTAL COVER  M LEFT REAR DOOR  M LEFT REAR DOOR MEATHERSTRIP  M LOO 2127-98  M LEFT REAR DOOR  M LEFT	POLICY NO/ACC DATE :2100375815 // 15.03.18  DRIVE IN/EXCESS :15.03.18 // TP CAR NO.:SKR8722Y=FWD  DATE IN/DATE SURVEY:	AL TAX INVOIC	
S BPNSUB     TRANSFER RIM AND BALANCING TYRE. NETT     LHR A BPILAB     REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR NETT     LHR DOOR A BPILAB     TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT A BPILAB     DISASSEMBLE AND REPLACE LHR DOOR, LHR FENDER, REAR BUMPER A BPIRES     RESPRAY ON REAR BUMPER, LHR FENDER, LHR DOOR A BPILAB     RESPRAY ON REAR BUMPER, LHR FENDER, THR DOOR A BPILAB     REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELBASE     LEFT REAR M MOULDING M MOULDING M MOULDING M MOULDING M ABSORBING LEFT REAR DOOR M ABSORBING LEFT REAR DOOR M LEFT REAR DOOR BOTTOM INSULATION M LEFT REAR DOOR BOTTOM INSULATION M LEFT REAR DOOR WEATHERSTRIP M LOO 2127-98 20.00 1702-38	A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO	0.10	0.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR NETT LHR DOOR  A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT  A BPILAB DISASSEMBLE AND REPLACE LHR DOOR, LHR FENDER, REAR BUMPER  A BPIRES RESPRAY ON REAR BUMPER, LHR FENDER, LHR DOOR  A BPILAB REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELBASE LEFT REAR M MOULDING M MOULDING 1.00 128.17 20.00 102.54 M MOULDING REAR BUMPER 1.00 1630.57 20.00 1304.46 M ABSORBING LEFT REAR DOOR M ABSORBING LEFT REAR DOOR M LEFT REAR DOOR BOTTOM INSULATION 1.00 29.18 20.00 23.34 LEFT REAR DOOR WEATHERSTRIP 1.00 280.72 20.00 26.14 LEFT REAR DOOR WEATHERSTRIP 1.00 85.80 20.00 26.14 LEFT REAR DOOR 1.00 85.80 20.00 26.68 M LEFT REAR DOOR 1.00 85.80 20.00 68.64 M LEFT REAR DOOR 1.00 2127.98 20.00 1702.38	S BPNSUB TRANSFER RIM AND BALANCING TYRE. NETT	66	0.00
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT  A BPILAB DISASSEMBLE AND REPLACE LHR DOOR, LHR FENDER, REAR BUMPER  A BPIRES RESPRAY ON REAR BUMPER, LHR FENDER, LHR DOOR  A BPILAB REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELBASE LEFT REAR  M MOULDING 1.00 128.17 20.00 102.54 M MOULDING 1.00 128.17 20.00 102.54 M REAR BUMPER 1.00 1630.57 20.00 1304.46 M ABSORBING LEFT REAR DOOR 1.00 4.26 20.00 3.41 M LEFT REAR DOOR BOTTOM INSULATION 1.00 29.18 20.00 23.34 M LEFT REAR DOOR WEATHERSTRIP 1.00 280.72 20.00 224.58 M LEFT REAR ORNAMENTAL COVER 1.00 85.80 20.00 68.64 M LEFT REAR ORNAMENTAL COVER 1.00 85.80 20.00 68.64	A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR		0.00
A BPILAB DISASSEMBLE AND REPLACE LHR DOOR, LHR FENDER, REAR BUMPER A BPIRES RESPRAY ON REAR BUMPER, LHR FENDER, LHR DOOR A BPILAB REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELBASE LEFT REAR M MOULDING M MOULDING M REAR BUMPER M REAR BUMPER M ABSORBING LEFT REAR DOOR M LEFT REAR DOOR BOTTOM INSULATION M LEFT REAR DOOR TOP INSULATION M LEFT REAR DOOR WEATHERSTRIP M LEFT REAR OOR WEATHERSTRIP M LEFT REAR REAR DOOR M LEFT REAR OOR WEATHERSTRIP M LEFT REAR RANDOR WEATHERSTRIP M LEFT REAR OOR WEATHERSTRIP M LEFT REAR OOR WEATHERSTRIP M LEFT REAR OOR WEATHERSTRIP M LEFT REAR ORNAMENTAL COVER M LEFT REAR OOR WEATHERSTRIP M LEFT REAR OOR WEATHERSTRIP M LEFT REAR ORNAMENTAL COVER M LEFT REAR DOOR M LEFT REAR DOOR M LEFT REAR OOR WEATHERSTRIP M LEFT REAR ORNAMENTAL COVER M LEFT REAR OOR WEATHERSTRIP M LEFT REAR DOOR WEATHERSTRIP M L	A BPILAB	540	0.00
A BPIRES RESPRAY ON REAR BUMPER, LHR FENDER, LHR DOOR  A BPILAB REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELBASE LEFT REAR  M MOULDING M MOULDING M REAR BUMPER M REAR BUMPER M ABSORBING LEFT REAR DOOR M LEFT REAR DOOR BOTTOM INSULATION M LEFT REAR DOOR TOP INSULATION M LEFT REAR DOOR WEATHERSTRIP M LEFT REAR ORNAMENTAL COVER M LEFT REAR DOOR M LEFT REAR ORNAMENTAL COVER M LEFT REAR DOOR M LEFT REAR ORNAMENTAL COVER M LEFT REAR DOOR M LEFT REAR ORNAMENTAL COVER M LEFT REAR DOOR M LEFT REAR DO	A BPILAB	3360	0.00
A BPILAB  REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELBASE  LEFT REAR  M MOULDING  M REAR BUMPER  M ABSORBING LEFT REAR DOOR  M LEFT REAR DOOR BOTTOM INSULATION  M LEFT REAR DOOR WEATHERSTRIP  M LEFT REAR DOOR WEATHERSTRIP  M LEFT REAR ORNAMENTAL COVER  M LEFT REAR DOOR  M LEFT R	A BPIRES	2400	0.00
M MOULDING       1.00       128.17       20.00       102.54         M REAR BUMPER       1.00       1630.57       20.00       1304.46         M ABSORBING LEFT REAR DOOR       1.00       4.26       20.00       3.41         M LEFT REAR DOOR BOTTOM INSULATION       1.00       29.18       20.00       23.34         M LEFT REAR DOOR TOP INSULATION       1.00       32.68       20.00       26.14         M LEFT REAR DOOR WEATHERSTRIP       1.00       280.72       20.00       224.58         M LEFT REAR ORNAMENTAL COVER       1.00       85.80       20.00       68.64         M LEFT REAR DOOR       1.00       2127.98       20.00       1702.38	A BPILAB REMOVE CARRIAGE ASSY FROM VEHICLE FRAME FOR REPLACEMENT OF WHEELE		0.00
M REAR BUMPER       1.00       1630.57       20.00       1304.46         M ABSORBING LEFT REAR DOOR       1.00       4.26       20.00       3.41         M LEFT REAR DOOR BOTTOM INSULATION       1.00       29.18       20.00       23.34         M LEFT REAR DOOR TOP INSULATION       1.00       32.68       20.00       26.14         M LEFT REAR DOOR WEATHERSTRIP       1.00       280.72       20.00       224.58         M LEFT REAR ORNAMENTAL COVER       1.00       85.80       20.00       68.64         M LEFT REAR DOOR       1.00       2127.98       20.00       1702.38	M MOULDING	1.00 128.17 20.00 102	2.54
M ABSORBING LEFT REAR DOOR       1.00       4.26       20.00       3.41         M LEFT REAR DOOR BOTTOM INSULATION       1.00       29.18       20.00       23.34         M LEFT REAR DOOR TOP INSULATION       1.00       32.68       20.00       26.14         M LEFT REAR DOOR WEATHERSTRIP       1.00       280.72       20.00       224.58         M LEFT REAR ORNAMENTAL COVER       1.00       85.80       20.00       68.64         M LEFT REAR DOOR       1.00       2127.98       20.00       1702.38			
M LEFT REAR DOOR BOTTOM INSULATION       1.00       29.18       20.00       23.34         M LEFT REAR DOOR TOP INSULATION       1.00       32.68       20.00       26.14         M LEFT REAR DOOR WEATHERSTRIP       1.00       280.72       20.00       224.58         M LEFT REAR ORNAMENTAL COVER       1.00       85.80       20.00       68.64         M LEFT REAR DOOR       1.00       2127.98       20.00       1702.38			
M LEFT REAR DOOR TOP INSULATION       1.00       32.68       20.00       26.14         M LEFT REAR DOOR WEATHERSTRIP       1.00       280.72       20.00       224.58         M LEFT REAR ORNAMENTAL COVER       1.00       85.80       20.00       68.64         M LEFT REAR DOOR       1.00       2127.98       20.00       1702.38			
M LEFT REAR DOOR WEATHERSTRIP 1.00 280.72 20.00 224.58 M LEFT REAR ORNAMENTAL COVER 1.00 85.80 20.00 68.64 M LEFT REAR DOOR 1.00 2127.98 20.00 1702.38		l l	
M LEFT REAR ORNAMENTAL COVER 1.00 85.80 20.00 68.64 M LEFT REAR DOOR 1.00 2127.98 20.00 1702.38			
M LEFT REAR DOOR 1.00 2127.98 20.00 1702.38			
1.00 128.04 20.00 102.43			
	I FUK DOOK LANELING	1.00 120.04 20.00 102	4.43

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Cycle & Carriage

## **ESTIMATE FOR SKP6869G**

FWD Singapore Pte Ltd

Motor Claims Department 6 Temasek Boulevard #18-01 Suntec Tower Four Singapore 038986 68208888

Vehicle & Document Information

WIP No 22071

SKP6869G Reg No/Reg Date / 11/06/2014

Date In/Mileage

WDD2120362A968698 Chassis No

Engine No

27492030148709

Make/Model

MB/E 250 2.0 CGI SEDAN (W212

Colour/Trim

021 197 Obsidian B1/ 042 211 Leather Ant

Account No	Terms	Date/Time Printed	CS	E	Operator					
FFX00002	Credit	16/03/2018/ 14:	19 VS		356 / Vincent	Seah				
	2011/14	Description of	Goods / Serv	rices	and the second second		Qty	Unit Price	Disc%	Amount
M RIVET M LEFT REAR I M DISK WHEEL	PAIR KLT - DOOR OTR  FENDER -LHR TORSION ON BAR ABSORBER G STRUT OD STRUT TROL ARM KNUCKLE A	LHR DOOR OTR GL. WINDOW BAR ROD	ASS		FICE		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	164.19 154.72 120.85 3.12 2200.17 668.92 56.65 215.94 545.25 100.82 209.79 181.39 227.60 181.39 264.92 1681.31 2045.53	20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00	131.3 123.7 96.6 44.9 1760.1 668.9 45.3 172.7 436.2 80.6 167.8 145.1 182.0 145.1 211.9 1345.0 1636.4

Confirmed & accepted by

20,114.73

7% GST on 20114.73

1408.03

Total Payable

21,522.76

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg