Surveyor Melmela : From (Person Estimated Co.	Gabriel V	ASSI	18005123/4vd. GNMENT (Office)		19/3/1881:52pm
OD TP WY To Inspect Vo	S/TP RES / OD RE chicle No: m/s Kaki Bk 1	SKU	1258 Z	Insured: SH	D 4192L 557272
Policy No:			Claim No: _		
Sum Insured: Make of Veh (Client's Recor			Excess:	D.O.A.	1813/18
CA / REV	/ REP. / REV 24 H 2·11pm 6 19/3/14		acted. Ah Hwar	H,O,D. I	Endotsement:
Date/Time	Action/Instruction SKU925 SHD 4192	87-X	imate		

(08/11/13) Wel REF:		
ASS. REC. BY: March	111/	
20	ASSIGNMENT	
From: Date:	Veh No: SKU924	-27 VEROON 6 06
Estimated Cost:	Type: MCarl M.Cycle / Bus / Val	n / Lorry / Taxi / Prime Mover /
OD TP WS TP RES OD RES / EVA / INV / MV	Truck / Troiler or	
To Inspect Vehicle No: S KU925		2 27.7
at Workshop m/s Sing hai	Colour We-Lo	Scting C.C 2362 A/C: Insured/Std/NI/NA
of Jany Van	111-52	THE ANALYSIS CONTRACTOR AND THE ANALYSIS OF T
	Sp.Reading / 47/45	T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:	26201-0
Policy No.	C/No: J1EG!	8500005 M250
Claims No.	Gen. Cond Good / Fair / Poor / B	Surnt
Sum Insured: Excess:	Steering: Iteraer / Jammed / Lea	
(Client's Record)	Brake: Interder / Jammed / Lea	
Make of Veh:	Modi: Nil /S/Rim / STD A/Rin	/
	Tyre Size: F: 2/	(S-/ 60R16
(Policy Condition)	R:	
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / L	IZA /MIC POHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or	
Bal. or Market Value:	Eront	Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm	R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. of mm	L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A.	D.O.I. 19/7/10
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at	115/10
CA / REV / REP. / 24 HRS ESE 19	6 WY Des. of Damages : Frt / Rear / C	DIS / N/S / U/C / Roofton or
Vehicle: IN	1	2_
Date:Person Contacted:	The U/C / Chassis frame / E	Body Structure affected due to collision.
Date / Time Action / Instruction		
274 (58,36	0 1 11/1	
6/418 contino 1/5 4 80	for who At hue	(Red 11,700.90, 669)
11-		
BESELVED 6 s.M.	13 0010	
RECEIVED 4 B W	417 ZUIB	
Districtions Ella Base In 2	. 7	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:	V
1) : Final Report	Resurvey No. of Trip:	Survey Fee:
Date/Time, File Return to?	W-2000 PT 200 W	Transportation:
2) X6/3- typict Add	d Fee: Site Insp (\$) _s+R\$,\$I
With the second	: Interview (\$) Photos 16
Report Format: merimen	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 5800 2	: Weekend (\$)
		TOTAL 460

(08/11/13)

wef



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Action to the second se	Ref : CS/III18005123 Date : 19-03-2018 Code : III2	a/Ovd3
Policy Particul		
Action to the second se		11 11 11 11 11 11 11 11 11 11 11 11 11
	ars :- THIRD PARTY CLAI	M
SHD 4192L	Veh. Inspected	SKU 9258Z
	Coverage (\$)	0.00
	Excess (\$)	0.00
GABRIEL WEE	Assign Date	19/03/2018
Vehicle P	articulars & Condition	
	c.c	0
HIDDEN	Year of Reg.	
	Colour	
175	Steering	
	Modification	
Cor	nditions of Tyres	
Size	Make	Balance
9		mm
		mm
		mm
		mm
Descr	ription of Damages	
THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COL	neral Information	Contract to the second
18/03/2018	Inspection Date	19/03/2018
t SIONG HAI MOTOR WORK	SHOP	
1 KAKI BUKIT AVENUE 6 # 02-03 AUTOBAY SINGAPORE 417883.		
	Remarks	THE RESERVE
	SINGAPORE 417883.	SINGAPORE 417883.

Nivitha (LKK Auto)

From:

Motor Claim - III <motorclaim@iii.com.sg>

Sent:

Monday, 19 March 2018 1:52 PM

To:

Ruby Ong; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)

Cc:

Sherini Pillai

Subject:

RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKU9258Z [OUR REF.

TCL.GCN.ro.50101.18.shm]

Dear Sir / Mdm.

Please conduct a survey on TP vehicle SKU9258Z and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Ruby Ong [mailto:ruby@htapartners.com.sg]

Sent: 19 March, 2018 10:57 AM

To: Motor Claim - III < motorclaim@iii.com.sg>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKU9258Z [OUR REF. TCL.GCN.ro.50101.18.shm]

Importance: High

Your ref:

SHD 4192L

WITHOUT PREJUDICE

Our ref:

TCL.GCN.ro.50101.18.shm

19 March 2018

India International Insurance Pte Ltd

By Email Only

Motor Claims Department 64 Cecil Street

#04-02 IOB Building Singapore 069428

VERY URGENT

Dear Sirs

CLAIMANT: KHOO SOON KOON

ACCIDENT INVOLVING SKU 9258Z & SHD 4192L ALONG CTE TOWARDS CITY ON 18 MARCH 2018 @ ABOUT 1230HRS

We are instructed by Khoo Soon Koon to notify you of a road traffic accident on 18 March 2018 at about 1230hrs along CTE towards city involving our client's vehicle registration number SKU 9258Z and vehicle registration number SHD 4192L driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, our client propose to appoint Marcus of LKK Auto Consultants Pte Ltd as the single joint expert to carry out the pre-repair survey for SKU 9258Z.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue

Siong Hai Motor & Trading

1 Kaki Bukit Avenue 6 #02-03 Autobay Singapore 417883

Contact Person:

Mr Ah Huat (H/P: 6555 7272)

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel: 6533 0212 ext 257

Tel: 6533 0212 ext 257 Fax: 6533 0313 / 6338 3536

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	0062J
Vehicle No.:	SKU9258Z
Vehicle to be Exported:	No
Intended De-registration Date:	23 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PREVIA 8 SEATER
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	2AZ2266018
Chassis No.:	JTEGD52M700002839
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$37,302.00
Original Registration Date:	30 Jun 2006
First Registration Date:	30 Jun 2006
Transfer Count:	3
Actual ARF Paid: Intended PARF Rebate Details	\$41,033.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	<u>s</u>
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	29 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$24,240.00
COE Rebate Amount:	\$15,836.00
Total Rebate Amount: Message	\$15,836.00

The information contained herein is correct as at 23 Mar 2018

applicable), whichever is earlier.

SIONG HAI MOTOR AND TRADING

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 65557272

Fax: 67411019

H/P: 93365311 (Ah Huat)

19/03/2018

Model:Toyota Previa

Vehicle No:SKU9258Z	Model:Toyota Previa	19/4/
QTY	List Items	Prices the she
1	Rear windscreen moulding	nec 181.95 —
1	Rear tailgate /491:50	35/Sel 1585
1	Rear tailgate logo 68./0	nu 76.95 —
1	Rear tailgate Toyota emblem 62.20	M 96.8 -
1	Rear tailgate Previa emblem	1ec 91.7
2	Rear tailgate L/R lamps @335.3	1 7 671.6 X
1	Rear tailgate centre reflector	17 281.95 X
1	Rear tailgate outer chrome	1 1 287.65 X
2	Rear tailgate number plate lamps @97.10	194.2 X
1	Rear tailgate inner lock 409.10	m/4m 580.25
1	Rear tailgate lock striker	11 68.5 X
1	Rear tailgate inner trim board	11 \$561.15 €
1	Rear tailgate weatherstrip	A1 \$254 ℃
2	Rear tailgate L/R hinges @82.60	1 ↑ \$165.20 ≈
2	Rear tailgate L/R dampers @281.20	11 562.4 a
1	Rear tailgate inner pull pocket	11 86.52 ∝
2	Rear tailgate L/R side stoppers @42.50	11 85 4
2	Rear tailgate L/R side stopper strikers @49.00	
2	Rear L/R tail lamps @323.10	11 645.2
2	Rear L/R taillamp filler panels @361.20	17 \$722 ×
1	Rear bumper 681.10	DO/OC \$1,339.50
2	Rear L/R bumper reflectors @83.15	11 \$165 X
2	Rear bumper L/R tow hook cover @44.40	1 1 88.8 🗶
2	Rear bumper L/R inner sponges @121.50	1. 243 A
2	Rear bumper L/R side brackets @68.50	1 137 4
2	Rear bumper L/R side retainers @64.43	128.86
1	Rear end panel	3/400 609.66
1	Rear end panel inner trim	Try 246.65
1	Rear end panel inner trim lower	77 \$254 X
1	Rear smart keyless sensor	\$190 >
1	Rear floor board	00/ way \$581
1	Rear floor mat	11 \$482 X
1	Rear floor compartment panel	15/1/20 \$708
2	Rear L/R fender inner shields @62.15	, 17 \$124
2	Rear L/R fender inner trim boards @626.00	MSDC/1-1 \$1,252 1°C
1	Rear exhaust silencer	N+ \$717 A
1	Rear exhaust mountings	20 \$86 9
1	Rear air-con blower assy	1 1,816 ×
		Total \$16,247.82 16464 49
		Less 25% \$4,061.97
		\$12,185.90 12348 36

Special Nett Items

1	Rear windscreen sealant	ner 80 40
1	Rear reverse camera	17 , 480 X
1	Rear reverse sensor (set)	Short 350 200
1	Rear bumper clip (set)	Ne 45
1	Rear end panel trim clip (set)	11 45 0
1	Rear tailgate trim clip (set)	11 45 0
2	Rear L/R fender trim clip (set)	11 900
1	Rear floor panel sound proofing (set)	NA 120 0
77		\$1,255

Labour Charges	- 7
To remove, refit, replaced damaged lamps and check up	80 50
rear electrical wiring	150 PO
To remove and refit inner garnish, inner trim to	150 0
assist repair	(0)
To remove and refit reverse end camera	120 SV
To transfer tailgate mechanism and wiring	100 60
To remove and replace rear air-con blower, vaccum, refill gas	1 1 180 ∞
and conduct leakage test	12.2
To remove, refit rear windscreen glass	180 /20
To remove, refit exhaust silencer assy	11 100 X
To apply undercoating on repaired accident parts	250 6 0
To respray painting and etc	1400 /000 1500 /290
To provide workmanship,panel beating,cut,weld,	1500 / 290
remove and replacing above parts	
i i	\$4,060

ESTIMATE AND TOTAL COST FOR LABOUR

\$17,500.90 Zff 17663 37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/III18005123/UVD3N2

Date:

28/03/2018

REFERENCE

Handling

India International Insurance Pte Ltd

Policy No:

Insurer: Claimant

SKU9258Z

Insured Vehicle No:

SHD4192L

Vehicle No: Date of Loss:

18/03/2018

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKU9258Z

Make & Model:

TOYOTA ESTIMA, 2.4 (A) 30/06/2006 (Man. Year: 2006) Engine No: Chassis No: 2AZ2266018

Reg. Date: Colour:

White

JTEGD52M700002839 147785 km Odometer:

Engine Capacity: Market Value/New Car Price: 2362 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Front Right Side: Michelin 6 mm Michelin 6 mm Rear Left Side: Rear Right Side:

Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 13,603.37 0.00	Adjuster's 4,703.11 0.00	8,900.26 0.00	Diff % 65.43
Labour	4,060.00	2,600.00	1,460.00	35.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,663.37	7,303.11	10,360.26	58.65
Approved Total (Overridden) (S\$)		5,800.00		
Nett Amount (S\$)	17,663.37	5,800.00	11,863.37	67.16

INSPECTION

Date of Assignment:

19/03/2018

Date Inspected:

19/03/2018 Inspected At:

Siong Hai Motor & Trading (HQ) NO 1 KAKI BUKIT AVE 6, #02-03

AUTOBAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair:

7.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 28 Mar 2018)

Parts:

M1-MPV

TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKU9258Z)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	181.95 FL	*181.95 FL
2	1		*REAR TAILGATE	Dented/Bent	1,585.00 FL *	1,492.50 FL
3	1		*REAR TAILGATE LOGO	Necessary	76.95 FL	*68.10 FL
	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	96.80 FL	*62.20 FL
	1		*REAR TAILGATE PREVIA EMBLEM	Necessary	91.70 FL	*91.70 FL
;	2		*REAR TAILGATE L/R LAMPS	Not Necessary	671.60 FL	*-FL
	1		*REAR TAILGATE CENTRE REFLECTOR	Not Necessary	281.95 FL	*- FL
3	1		*REAR TAILGATE OUTER CHROME	Not Necessary	287.65 FL	*-FL
	2		*REAR TAILGATE NUMBER PLATE LAMPS	Not Necessary	194.20 FL	*-FL
0	1		*REAR TAILGATE INNER LOCK	Dented/Jammed	580.25 FL	*409.10 FL
1	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	68.50 FL	*-FL
2	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	561.15 FL	*- FL
3	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	254.00 FL	*-FL
4	2		*REAR TAILGATE L/R HINGES	Not Necessary	165.20 FL	*- FL
5	2		*REAR TAILGATE L/R DAMPERS	Not Necessary	562.40 FL	*- FL
6	1		*REAR TAILGATE INNER PULL POCKET	Not Necessary	86.52 FL	*- FL
17	2		*REAR TAILGATE L/R SIDE STOPPERS	Not Necessary	85.00 FL	*- FL
8	2		*REAR TAILGATE L/R SIDE STOPPER STRIKERS	Not Necessary	98.00 FL	*-FL
19	2		*REAR L/R TAIL LAMPS	Not Necessary	645.20 FL	*- FL
20	2		*REAR L/R TAILLAMP FILLER PANELS	Not Necessary	722.00 FL	*-FL
21	1		*REAR BUMPER	Dented/Deformed	1,339.50 FL	*685.10 FL
22	2		*REAR L/R BUMPER REFLECTORS	Not Necessary	165.00 FL	*- FL
3	2		*REAR BUMPER L/R TOW HOOK COVER	Not Necessary	88.80 FL	*- FL
4	2		*REAR BUMPER L/R INNER SPONGES	Not Necessary	243.00 FL	*- FL
25	2		*REAR BUMPER L/R SIDE BRACKETS	Not Necessary	137.00 FL	*- FL
26	2		*REAR BUMPER L/R SIDE RETAINERS	Bent	128.86 FL	*128.86 FL
27	1		*REAR END PANEL	Badly Dented	609.66 FL	*609.66 FL
28	1		*REAR END PANEL INNER TRIM	Twisted	246.65 FL	*246.65 FL
29	1		*REAR END PANEL INNER TRIM LOWER	Not Necessary	254.00 FL	*- FL
30	1		*REAR SMART KEYLESS SENSOR	Not Necessary	190.00 FL	*- FL
31	1		*REAR FLOOR BOARD	Dented/Warped	581.00 FL	*581.00 FL
32	1		*REAR FLOOR MAT	Not Necessary	482.00 FL	*- FL
33	1		*REAR FLOOR COMPARTMENT PANEL	Badly Dented	708.00 FL	*708.00 FL
34	2		*REAR L/R FENDER INNER SHIELDS	Not Necessary	124.00 FL	*- FL
35	1		*REAR L/R FENDER INNER TRIM BOARDS	N/s Deformed/Twisted	1,252.00 FL	*626.00 FL
36	1		*REAR EXHAUST SILENCER	Not Necessary	717.00 FL	*-FL
37	1		*REAR EXHAUST MOUNTINGS	Not Necessary	86.00 FL	*- FL
38	1		*REAR AIR-CON BLOWER ASSY	Not Necessary	1,816.00 FL	*- Fl
39	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
40	1		*REAR REVERSE CAMERA	Not Necessary	480.00 FS	
41	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
	(5)		CENTER SECOND STATES OF A TRANSPORT OF A SECOND STATES OF A POST OF A SECOND STATES OF A			

No.	Qty	Part No.	Particulars C	Condition	Repairer's	Amount
42	1		*SET REAR BUMPER CLIP	Vecessary	45.00 FS	*45.00 FS
43	1		*SET REAR END PANEL TRIM CLIP	Not Necessary	45.00 FS	*-FS
44	1		*SET REAR TAILGATE TRIM CLIP	Not Necessary	45.00 FS	*-FS
45	2		*SET REAR L/R FENDER TRIM CLIP	Not Necessary	90.00 FS	*-FS
46	1			Not Necessary	120.00 FS	*-FS
F=Fra	nchise	part. S=S	pcNett. L=ListItemDisc.			
				Sub Total (S\$)	17,719.49	6,175.82
			- List Item Discount on L Item	ns 25.00/25.00% (S\$)	4,116.12	1,472.71
				Total Parts (S\$)	13,603.37	4,703.11
0			Report was unsubmitted during th	is print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Items			
O REMOVE,REFIT,REPLACED DAMAGED LAMPS AND HECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
O REMOVE AND REFIT INNER GARNISH,INNER TRIM O ASSIST REPAIR	New	150.00	80.00
O REMOVE AND REFIT REVERSE END CAMERA	New	120.00	50.00
O TRANSFER TAILGATE MECHANISM AND WIRING	New	100.00	60.00
O REMOVE AND REPLACE REAR AIR-CON LOWER, VACCUM, REFILL GAS AND CONDUCT EAKAGE TEST	New	180.00	5 <u>-</u>
O REMOVE, REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
O REMOVE, REFIT EXHAUST SILENCER ASSY	New	100.00	
O APPLY UNDERCOATING ON REPAIRED ACCIDENT ARTS	New	250.00	60.00
O RESPRAY PAINTING AND ETC	New	1,400.00	1,000.00
O PROVIDE WORKMANSHIP ,PANEL EATING,CUT,WELD,REMOVE AND REPLACING ABOVE ARTS	New	1,500.00	1,200.00
Gross Labou	r Cost (S\$)	4,060.00	2,600.00
COCCE	REMOVE AND REFIT INNER GARNISH, INNER TRIM ASSIST REPAIR REMOVE AND REFIT REVERSE END CAMERA TRANSFER TAILGATE MECHANISM AND WIRING REMOVE AND REPLACE REAR AIR-CON OWER, VACCUM, REFILL GAS AND CONDUCT EAKAGE TEST REMOVE, REFIT REAR WINDSCREEN GLASS REMOVE, REFIT EXHAUST SILENCER ASSY APPLY UNDERCOATING ON REPAIRED ACCIDENT ARTS RESPRAY PAINTING AND ETC PROVIDE WORKMANSHIP, PANEL EATING, CUT, WELD, REMOVE AND REPLACING ABOVE ARTS	REMOVE AND REFIT INNER GARNISH, INNER TRIM O ASSIST REPAIR O REMOVE AND REFIT REVERSE END CAMERA O TRANSFER TAILGATE MECHANISM AND WIRING O REMOVE AND REPLACE REAR AIR-CON COWER, VACCUM, REFILL GAS AND CONDUCT EAKAGE TEST O REMOVE, REFIT REAR WINDSCREEN GLASS O REMOVE, REFIT EXHAUST SILENCER ASSY O APPLY UNDERCOATING ON REPAIRED ACCIDENT ARTS O RESPRAY PAINTING AND ETC O PROVIDE WORKMANSHIP, PANEL EATING, CUT, WELD, REMOVE AND REPLACING ABOVE	D REMOVE AND REFIT INNER GARNISH,INNER TRIM D ASSIST REPAIR D REMOVE AND REFIT REVERSE END CAMERA D REMOVE AND REFIT REVERSE END CAMERA D TRANSFER TAILGATE MECHANISM AND WIRING D REMOVE AND REPLACE REAR AIR-CON LOWER,VACCUM,REFILL GAS AND CONDUCT CAKAGE TEST D REMOVE,REFIT REAR WINDSCREEN GLASS D REMOVE,REFIT EXHAUST SILENCER ASSY D APPLY UNDERCOATING ON REPAIRED ACCIDENT D RESPRAY PAINTING AND ETC D RESPRAY PAINTING AND ETC D PROVIDE WORKMANSHIP,PANEL EATING,CUT,WELD,REMOVE AND REPLACING ABOVE ARTS

< END OF ESTIMATES >