



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 4537K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	635.40	-
2	FRONT BUMPER SIDE RETAINER @\$13.00 (CONSISTENT)	SERVICEABLE	26.00	-
1	FRONT LH HEADLAMP (CONSISTENT)	CUT	958.00	958.00
1	FRONT LH HEADLAMP LOWER BRACKET (CONSISTENT)	SERVICEABLE	36.50	-
1	FRONT LH FENDER (CONSISTENT)	BENT	486.30	486.30
1	FRONT LH FENDER INNER SHIELD (CONSISTENT)	SERVICEABLE	80.40	-
1	FRONT LH DOOR (CONSISTENT)	BENT	987.50	987.50
1	FRONT LH DOOR FRAME STICKER 1 (CONSISTENT)	NECESSARY	181.50	181.50
1	FRONT LH DOOR FRAME STICKER 2(CONSISTENT)	NECESSARY	195.50	195.50
	LESS 20% DISCOUNT		-717.42	-561.76
			2,869.68	2,247.04
SPECIAL NETT ITEMS				
1	FRONT LH SIDE SKIRT (SN) (CONSISTENT)	CRACKED	480.00	480.00
			480.00	480.00
LABOUR				
	WIRING .		80.00	20.00
	TUFFKOTE.		80.00	60.00
	SPRAY PAINTING.		1,000.00	600.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF FRONT BUMPER ,		950.00	500.00
			2,110.00	1,180.00
GRAND TOTAL			5,459.68	3,907.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CC4/ASM18005183/Kps3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.