



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18005183/Kps3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 27-05-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBL 1069J	Veh. Inspected	SJL 4537K
Policy No.	VMZ/P1978275	Coverage (\$)	0.00
Claim No.	S8M00B47	Excess (\$)	0.00
Assign From		Assign Date	20/03/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA STREAM (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	RN61053502	Colour	METALLIC BLACK
Odometer	238482	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45 R17	WEST LAKE	8 mm
L/H Front Tyre	205/45 R17	WEST LAKE	8 mm
R/H Rear Tyre	205/45 R17	MICHELIN	6 mm
L/H Rear Tyre	205/45 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/03/2018	Inspection Date	26/03/2018
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------