

Surveyor

Bryan

ASSIGNMENT (Office)

CWS

From (Person)

Eileen Lee

of

FCI

Date/Time

2013/18@5:44pm

Estimated Cost

Bill to:

OD ☒ TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

PA8290G

Insured

SHD 69884

at Workshop in/

Teamwork Garage

Tel.

68442475

of

Blk 53 Ubi Ave 1 # 01-24

Policy No.

Claim No.

D18002262MFSH

Sum Insured

Excess:

Make of Veh.

(Client's Record)

D.O.A.

19/3/2018

CA / REV / REP. / REV 24 HRS

Wp

Date/Time

9:43am 20/3/18

Person Contacted

Darren

H.O.D. Endorsement

Vehicle

☒ IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

PA8290G-X

SHD 69884-

28/3-

Report via email preli

ASSIGNMENT

2008 Oct

PA 8290G

2018 Oct

Form
Estimated Cost
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no:

at

Insured

Policy No:

Claims No:

Sum Insured


Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value

IDAC Accident Report

Consistent? : Yes or No

GIA / FR Seen

Consistent? : Yes or No

Est. Repairs

68

days

Res:

Yes or No

Lum Sum:

20

%

Val

Yes or No

CA / REV / REP / 24 HRS

Date:

Person Contacted:

Vehicle IN / OUT

Vehicle

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Toyota Hiace

2982

Colour

Silver

A/C Insured / Std / NI / NA

Sp Reading

746082

T/Mark Insured / Std / NI / NA

Eng No:

1K71830918

C/No

KDH2230004214

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: 0 / SIRim / STD A/Rim or

Tyre Size:

F:

195 215C

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Michelin

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D/OA

19/03/2018

D/OI

20/03/2018

Survey held at

Teamwork Page ubi

Def. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S 4 Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

First cap SHD 6988u

Market Value - \$14,000/-

MV 14K

LTA 940/-

LTA 940.00

NV: 13,060/-

HL 13K

13/11/2019

Johny with Darren 4/5 6500/- with 6 days of rep (Red: 6511.29, 50%)

RECEIVED 14 NOV 2019

Cost/Type: The Pass to



: Prel. Report

Days Of Repair:

6

14/11 Typist



: Final Report

Resurvey No. of Trip:

2

Cost/Type: The Return to

Survey Fee

Transport

Add Fee:



Site Insp 15



Intention 15



Technique 15



Witness 15

Report Format:

Lump Sum / L.B 115

TP 6500/-

OSY

14/11/19

3x15=45

170+45

50

50+50

132

497



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005268/Dtd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6988U	Veh. Inspected	PA 8290G
Policy No.		Coverage (\$)	0.00
Claim No.	D18002262MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	21/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/03/2018	Inspection Date	21/03/2018
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002262MFSH

Date: 28/3/2018

Our Ref: CS/FCI18005268/Dtd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. PA 8290G.

Please be informed that we had conducted the inspection of the abovementioned vehicle 20/3/2018 at the premises of M/s Teamwork Garage and have the following to report: -

Workshop Estimate Amount	: <u>S\$ 7,701.69</u>
Revised Estimate Amount	: <u>S\$ 7,180.17</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:
The vehicle sustained damages
at the front n/s and rear o/s portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Bryan
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-03-2018	Our Ref No. D18002262MFSH
Accident Date	19-03-2018	Claim Type. Third Party
Insured Vehicle	SHD6988U	Third Party Vehicle. PA8290G
Survey Location	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	ALISON	
Contact No.	68442475/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TEAMWORK GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236130)



PRI Documents



Close



PRI Header Details

Claim No	D18002262MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TEAMWOF
Workshop Name	TEAMWORK GARAGE PTE LTD (Contact Person : ALISON)	Survey Location & Contact Details	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK Mobile: 0 , Phone: 68442475 , Fax: 68442474 EmailId: CLAIMS@TEAMWORKGARAGE.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6988U	TP Vehicle No	PA8290G
PRI Recieved Date	19-03-2018 10:46:27 PM	Surveyor Appointed Date	20-03-2018 05:43:12 PM	Surveyor Accept Date	21-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	21-03-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 28 March 2018 2:12 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002262MFSH/1
Attachments: PRELI ADVISED PA 8290G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **PA 8290G**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 21 March 2018 9:45 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002262MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 20 March 2018 5:43 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002262MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8166L
Vehicle Details	
Vehicle No.:	PA8290G
Vehicle to be Exported:	Yes
Intended De-registration Date:	20 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1KD1830918
Chassis No.:	KDH2230004214
Maximum Power Output:	-
Open Market Value:	\$41,660.00
Original Registration Date:	24 Oct 2008
First Registration Date:	24 Oct 2008
Transfer Count:	3
Actual ARF Paid:	\$2,083.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Oct 2018
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$12,989.00
COE Rebate Amount:	\$940.00
Total Rebate Amount:	\$940.00

The information contained herein is correct as at 20 Mar 2018

OK



Pte Ltd

Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H

First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

3RD PARTY CLAIM ESTIMATION

Vehicle number	PA8290G
Make / Model	TOYOTA/HIACE
Chassis number	KDH2230004214
Accident date	19 March 2018
Reference	1803-17

Qty Particulars 7.00

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER distorted	637.44 ✓
1	FRONT BUMPER UPPER BEAM s/c	385.12 x
2	FRONT BUMPER SIDE RETAINER s/c N/S broken o/s NW	65.60 131.20 x ✓
1	FRONT BUMPER REINFORCEMENT s/c	381.50 x
1	FRONT LH CORNER PANEL r/c	222.12 x
1	FRONT LH HEADLAMP crack / Scratch	681.35 ✓
1	REAR BUMPER Distorted	464.75 ✓
1	REAR BUMPER STEP PANEL H/H	231.50 x
2	REAR BUMPER RETAINER s/c o/s broken N/S NW	60.70 121.40 x ✓
1	END PANEL - INNER Distorted	681.20 ✓
1	END PANEL - OUTER Distorted	581.75 ✓
2	REAR TAILLAMP o/s crack N/S NW	340.44 680.88 ✓
2	REAR CORNER PANEL o/s distorted N/S NW	181.10 362.20 ✓
1	TAILGATE Distorted	1712.80 ✓
1	TAILGATE EMBLEM LOGO H/c	71.00 ✓
1	TAILGATE LOCK s/c	361.30 x
1	TAILGATE EMBLEM - HIACE H/c	50.00 ✓
1	SPARE TYRE BRACKET H/H	171.20 x
1	REAR EXHAUST ASSY 1/2	718.40 ✓
2	REAR EXHAUST MOUNTING s/c	30.00 x
		8677.11
		Less 20%
		1735.42
		Subtotal
		6941.69
		Balance C/F
		6941.69
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
		Balance B/F
		6941.69
1 SET	FRONT BUMPER CLIP H/c	60.00 30/-
1 SET	REAR BUMPER CLIP H/c	60.00 30/-
1 SET	REAR REVERSE SENSOR Down	400.00 220/-
1	JOINT SEALANT H/c	150.00 40/-
1	WINDSCREEN SEALANT H/c	150.00 40/-
		Subtotal
		760.00
		Balance C/F
		7701.69

6246.83
4684.89

360/-

S/No	LABOUR AND MISCELLANEOUS CHARGES	
	Balance B/F	7701.69
1	CHECK FRONT AND REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	CHECK REAR LINING, TRIM AND GARNISH	200.00 80/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 60/-
5	REMOVE AND REFIT REAR WINDSCREEN	150.00 120/-
6	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 60/-
7	PANEL BEATING ON AFFECTED AREAS	1500.00 1000/-
8	SPARY PAINTING ON AFFECTED AREAS	1600.00 800/-
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	4160.00
	Grand total	11861.69

20/03/2018 C 1600ms
 Not Antenna
 L/sun 6
 2 days
 LKK Auto
 Photo after repair
 Check MV

7274.89
 Supp 899.60
 8174.49
 4/5 6500/-
 13071.29

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Teamwork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H

First Capital Insurance Ltd
 36 Robinson Road
 #16-01 City House
 Singapore 068877

SUPPLEMENTARY

Vehicle number	PA8290G
Make / Model	TOYOTA/HIACE
Chassis number	KDH2230004214
Accident date	19 March 2018
Reference	1803-17

Qty Particulars

7.00

PARTS REPLACEMENT - LIST ITEMS		
1	RADIATOR <i>Punctured</i>	891.30 ✓
1	FRONT LH WING MIRROR BRACKET COVER (SMALL) <i>broken plastic</i>	140.30 ✓
1	REAR RH AIRVENT <i>defunct</i>	101.20 ✓
	1132.80	
	849.60	
	Less 25%	283.20
	Subtotal	849.60
	Balance C/F	849.60
LABOUR AND MISCELLANEOUS CHARGES		
S/No	Balance B/F	849.60
1	REMOVE AND REFIT AND TOP UP COOLANT	300.00 <i>50/-</i>
	50.00	
	Subtotal	300.00
	Grand total	1149.60

gn
2kk Auto

899.60

13011.29

9



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FC118005268/Dtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6988U	Veh. Inspected	PA 8290G	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002262MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	20/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	KDH2230004214	Colour	SILVER	
Odometer	746082	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	6 mm	
L/H Front Tyre	195 R15C	MICHELIN	6 mm	
R/H Rear Tyre	195 R15C	MICHELIN	6 mm	
L/H Rear Tyre	195 R15C	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/03/2018	Inspection Date	20/03/2018	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 8290G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DISTORTED	637.44	637.44
1	FRONT BUMPER UPPER BEAM	SERVICEABLE	385.12	-
2	FRONT BUMPER SIDE RETAINER	N/S BROKEN / O/S NOT NECESSARY	131.20	65.60
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	381.50	-
1	FRONT LH CORNER PANEL	TO REPAIR SEE LABOUR	222.12	-
1	FRONT LH HEADLAMP	CRACKED / SCRATCHED	681.35	681.35
1	REAR BUMPER	DENTED	464.75	464.75
1	REAR BUMPER STEP PANEL	NOT NECESSARY	231.50	-
2	REAR BUMPER RETAINER	O/S BROKEN / N/S NOT NECESSARY	121.40	60.70
1	END PANEL-INNER	DENTED	681.20	681.20
1	END PANEL-OUTER	DENTED	581.75	581.75
2	REAR TAILLAMP	O/S CRACKED / N/S NOT NECESSARY	680.88	340.44
2	REAR CORNER PANEL	O/S DISTORTED / N/S NOT NECESSARY	362.20	181.10
1	TAILGATE	DENTED	1,712.80	1,712.80
1	TAILGATE EMBLEM LOGO	NECESSARY	71.00	71.00
1	TAILGATE LOCK	SERVICEABLE	361.30	-
1	TAILGATE EMBLEM-HIACE	NECESSARY	50.00	50.00
1	SPARE TYRE BRACKET	NOT NECESSARY	171.20	-
1	REAR EXHAUST ASSY	BENT	718.40	718.40
2	REAR EXHAUST MOUNTING	SERVICEABLE	30.00	-
	LESS 20% DISCOUNT		-1,735.42	-
	LESS 25% DISCOUNT		-	-1,561.63
			6,941.69	4,684.90
1	RADIATOR (ADDITIONAL)	PUNCTURE	891.30	891.30

Report Ref No. CS/FCI18005268/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LH WING MIRROR BRACKET COVER (SMALL) (ADDITIONAL)	BROKEN / DISLODGE	140.30	140.30
1	REAR RH AIRVENT (ADDITIONAL)	DEFORMED	101.20	101.20
	LESS 25% DISCOUNT		-283.20	-283.20
			849.60	849.60
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	400.00	220.00
1	JOINT SEALANT (SN)	NECESSARY	150.00	40.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00
			820.00	360.00
	LABOUR			
	CHECK FRONT AND REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	CHECK REAR LINING, TRIM AND GARNISH.		200.00	80.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND RENEW REAR EXHAUST ASSY.		150.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS, INCLUSIVE OF THE REPAIR OF FRONT LH CORNER PANEL.		1,500.00	1,000.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,600.00	800.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
	REMOVE AND REFIT AND TOP UP COOLANT (ADDITIONAL).		300.00	50.00
	-		-	-
	-		-	-
	-		-	-
			4,460.00	2,280.00
GRAND TOTAL			13,071.29	8,174.50



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,500.00
---	--	--	----------

Report Ref No. CS/FCI18005268/Dtd3n2

MARKET VALUE: \$14,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$940.00=NETT VALUE: \$13,060.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.