



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC18005269/T1hb3

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 21-03-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 768H	Veh. Inspected	SHB 8407C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/03/2018	Inspection Date	20/03/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51, BLAQUE L, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE, 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised
Our ref: CC3/LPC18005269/T1hb3

Date: 20.03.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB8407C

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.03.2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	16,140.85
Revised Estimate Amount	: S\$	8,542.98
"Check" Items Amount	: S\$	6,652.86
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 9 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

Shu Pei (LKKAuto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 22 March 2018 9:35 AM
To: Shu Pei (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving SGJ768H (OI : LPC - TBA) and SHB8407C (TP : LKK REF - CC3/LPC18005269/T1hb3) on 18.03.2018
Attachments: 22032018092905.pdf

Our Ref :18/18/18/VP05/020475

Dear Shu Pei,

Attached insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 21 March, 2018 5:38 PM
To: GERALD POH WEE BIN; ERIC WOO JUN KIAT; ONG LI LI
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAuto); Vic (LKKAuto)
Subject: Direct Settlement - Accident Involving SGJ768H (OI : LPC - TBA) and SHB8407C (TP : LKK REF - CC3/LPC18005269/T1hb3) on 18.03.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHB 8407C at M/s Premier Automotive Services Pte Ltd - Changi.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

19-Mar-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8407 C

1pc	Front bumper	\$	811.11 <i>de</i>
1pc	Front bumper sponge	\$	218.03 <i>? de</i>
1pc	Front bumper reinforcement	\$	636.40 <i>X ny</i>
1pc	Front bumper reinforcement lower	\$	223.88 <i>X n1</i>
2 pcs	Front n/s & o/s bumper side bracket @\$32.51	\$	65.02 <i>rec</i>
2 pcs	n/s & o/s headlamp @\$1531.57	\$	3,063.14 <i>con</i>
1pc	Bonnet grille	\$	566.46 <i>con</i>
1pc	Bonnet	\$	1,220.40 <i>bt</i>
2 pcs	Bonnet hinge @\$79.18	\$	158.36 <i>bt</i>
1pc	Support panel	\$	1,292.20 <i>? penta bt</i>
1pc	Horn	\$	78.30 <i>X an</i>
1 pc	Aircon condensor	\$	745.00 <i>? dd</i>
1 pc	Radiator	\$	670.60 <i>X ny</i>
1 pc	Blower Assy	\$	423.60 <i>X an</i>
1 pc	Tailgate	\$	2,292.30 <i>bt</i>
1 pc	Tailgate lower garnish	\$	362.61 <i>ant</i>
1 pc	Emblem I30	\$	27.80 <i>na</i>
1 pc	Emblem CRDI	\$	29.40 <i>na</i>
1 pc	Emblem Hyundai	\$	29.40 <i>na</i>
1 pc	Rear bumper	\$	811.11 <i>de</i>
1 pc	Rear bumper sponge	\$	79.20 <i>de</i>
1 pc	Rear bumper reinforcement	\$	815.64 <i>bt</i>
1 pc	Rear bumper reinforcement centre	\$	79.20 <i>X ny</i>
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40 <i>na</i>
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	\$	215.00 <i>na</i>
		\$	15,018.56 <i>12906.58</i>
		Less 20%	\$ 3,003.71 <i>10325.26</i>
		\$	12,014.85

S/NETT

1 set	Rear bumper clips	\$	48.00 <i>na</i>
1 set	Front bumper clips	\$	48.00 <i>na</i>
1 set	Reverse sensor	\$	280.00 <i>na</i>
1 set	Tailgate sticker	\$	100.00 <i>na</i>
1 pc	Front no. plate	\$	50.00 <i>45 con</i>
1 pc	Rear no. plate	\$	50.00 <i>30 con</i>

471

19-Mar-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8407 C

Towing Fee	\$	50.00 ✓
Sundry etc	\$	50.00 30
To dismantle and replace reverse sensor and test system	\$	80.00 30
Top up gas	\$	120.00 100? ✓
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, floorboard etc	\$	1,400.00 1200
To putty and spray painting on the rear bumper, tailgate, lower garnish, end panel, floorboard panel, front bumper, bonnet, bonnet grille	\$	1,600.00 1200
To apply rustproofing on the repaired and replaced panels	\$	250.00 100
Total	\$	16,140.85

2710

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tang Jie 97495744
- WP
20/3/18 @ 4pm
Resurvey before paint
Resurvey check items
9 days
sev@lkkauto.com

10325.26
471
2710

\$13506.26 #
9 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC18005269/T1db3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 23-12-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 768H	Veh. Inspected	SHB 8407C
Policy No.	Z18VP05017112	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020475	Excess (\$)	0.00
Assign From		Assign Date	20/03/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I30	c.c	1582
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	TMAD281UVHJ121517	Colour	SILVER
Odometer	251031	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXXIS	6 mm
L/H Front Tyre	195/65 R15	MAXXIS	6 mm
R/H Rear Tyre	195/65 R15	MAXXIS	6 mm
L/H Rear Tyre	195/65 R15	MAXXIS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/03/2018	Inspection Date	20/03/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8407C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	811.11	811.11
1	FRONT BUMPER SPONGE	DEFORMED	218.03	218.03
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	636.40	-
1	FRONT BUMPER REINFORCEMENT LOWER	NOT NECESSARY	223.88	-
2	FRONT N/S & O/S BUMPER SIDE BRACKET @\$32.51	NECESSARY	65.02	65.02
2	N/S & O/S HEADLAMP @\$1531.57	CRACKED	3,063.14	3,063.14
1	BONNET GRILLE	CRACKED	566.46	566.46
1	BONNET	BENT	1,220.40	1,220.40
2	BONNET HINGE @\$79.18	BENT	158.36	158.36
1	SUPPORT PANEL	BENT	1,292.20	1,292.20
1	HORN	NOT NECESSARY	78.30	-
1	AIRCON CONDENSOR	DENTED	745.00	745.00
1	RADIATOR	NOT NECESSARY	670.60	-
1	BLOWER ASSY	NOT NECESSARY	423.60	-
1	TAILGATE	BENT	2,292.30	2,292.30
1	TAILGATE LOWER GARNISH	CUT	362.61	362.61
1	EMBLEM I30	NECESSARY	27.80	27.80
1	EMBLEM CRDI	NECESSARY	29.40	29.40
1	EMBLEM HYUNDAI	NECESSARY	29.40	29.40
1	REAR BUMPER	DEFORMED	811.11	811.11
1	REAR BUMPER SPONGE	DEFORMED	79.20	79.20
1	REAR BUMPER REINFORCEMENT	BENT	815.64	815.64
1	REAR BUMPER REINFORCEMENT CENTRE	NOT NECESSARY	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20	NECESSARY	104.40	104.40
2	REAR BUMPER N/S & O/S REFLECTOR @\$107.50	DISTORTED	215.00	215.00
	LESS 20% DISCOUNT		-3,003.71	-2,581.32
			12,014.85	10,325.26
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00

Report Ref No. CC3/LPC18005269/T1db3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	SET TAILGATE STICKER (SN)	NECESSARY	100.00	100.00
1	FRONT NO PLATE (SN)	CRACKED	50.00	45.00
1	REAR NO PLATE (SN)	CRACKED	50.00	30.00
1	SUNDRY (SN)	NECESSARY	50.00	30.00
			626.00	501.00
	LABOUR			
	TOWING FEE.		50.00	50.00
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.		80.00	30.00
	TOP UP GAS.		120.00	100.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK-OUT, STRAIGHTEN,REPAIR,RESHAPE OF THE END PANEL,FLOORBOARD ETC.		1,400.00	1,200.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER,TAILGATE,TAILGATE LOWER GARNISH,END PANEL,FLOORBOARD PANEL,FRONT BUMPER,BONNET,BONNET GRILLE.		1,600.00	1,200.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		250.00	100.00
			3,500.00	2,680.00
	GRAND TOTAL		16,140.85	13,506.26
	RECOMMENDED COST OF REPAIRS			13,506.26

Report Ref No. CC3/LPC18005269/T1db3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.