

22/03/2007

ASS. REC. BY:

REF: CS/FCI18005273/Ktd3ⁿ² Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Lurene jaw of FCI Date/Time: 20/3/18 @ 4:53pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 5130 H Insured: SHD 8517H

at Workshop m/s: Cheng Hoe Motor Tel: 6481 2001

of Blk 1019, Yishun Ind. Prk A # 01-374

Policy No: _____ Claim No: D18002236 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19/03/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement: _____

Date/Time: 9:15am @ 21/3/18 Person Contacted: Dorlyn Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLS 5130H - X</u>
	<u>SHD 8517H - CS/FCI16024092/Rlg h3m2 D.O.A 9/12/16</u>
<u>23/3 @ 10:23am</u>	<u>Revert via email on preli</u>
<u>12/11</u>	<u>61 Rm @ 2850 Cabinn Ture (Red: 2332.15, 45%)</u>

REF: FCI

ASSIGNMENT

From: _____ Date: 21/3/18
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SL55130H
 at Workshop m/s Cheng Hoe Motor
 of No. 10, AMK Ind. Park 2A #01-04
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 06 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP: / 24 HRS ^{1wp}
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL55130H Yr Regn: 09 12
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: HONDA 1.8 250 c.c. 2500
 Colour: In Black A/C: Insured / Std / NI / NA
 Sp. Reading: 79528 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTHBK 262 X 05178068
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45R17
 R: 245/45R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 7 mm R/Bal: 7 mm
 L/Bal: 7 mm L/Bal: 7 mm
 D.O.A: 19/3/18 D.O.I: 21/3/18
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 & M
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 13 File pass to Catherine

RECEIVED 12 NOV 2018

Date/Time: File Pass to? : Preli. Report
 : Final Report
 1) D/K Typist
 Date/Time: File Return to?

Days Of Repair: 6
 Resurvey No. of Trip: 2

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:
 Transportation:
) \$ + RS \$
) Photos
) Others
)
 TOTAL

140
50
50+50
25
315

Report Format: TP
 Lump Sum / I.B.!: (\$) 2850



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005273/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-03-2018	
		Code : FC12	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 8517H	Veh. Inspected	SLS 5130H
Policy No.		Coverage (\$)	0.00
Claim No.	D18002236MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	21/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/03/2018	Inspection Date	21/03/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002236MFSH

Date: 23/3/2018

Our Ref: CS/FC118005273/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLS 5130H.

Please be informed that we had conducted the inspection of the abovementioned vehicle 23/3/2018 at the premises of M/s Cheng Hoe Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>5,182.15</u>
Revised Estimate Amount	: S\$ <u>3,097.80</u>
"Check" Items Amount	: S\$ <u>1,264.17</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>_____.</u>
Nett Value	: S\$ <u>_____.</u>

Description of Damage:

The vehicle sustained damages at the rear & front.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-03-2018	Our Ref No. D18002236MFSH
Accident Date	19-03-2018	Claim Type. Third Party
Insured Vehicle	SHD8517H	Third Party Vehicle. SLS5130H
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	DORLYN	
Contact No.	664812001/0	Fax No. 64821296
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236091)



PRI Documents



Close



PRI Header Details

Claim No	D18002236MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CHENG HOE
Workshop Name	CHENG HOE MOTOR PTE LTD (Contact Person : DORLYN)	Survey Location & Contact Details	BLK 1019 YISHUN IND. PARK A #01-374 Mobile: 0 , Phone: 664812001 , Fax: 64821296 EmailId: CHMAMK@SINGNET.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHD8517H	TP Vehicle No	SLS5130H
PRI Recieved Date	19-03-2018 06:48:12 PM	Surveyor Appointed Date	20-03-2018 04:52:46 PM	Surveyor Accept Date	21-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	21-03-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 23 March 2018 10:23 AM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002236MFSH/1
Attachments: PRELI ADVISED SLS 5130H.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLS 5130H**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 21 March 2018 9:19 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002236MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 20 March 2018 4:52 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002236MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6293G
Vehicle Details	
Vehicle No.:	SLS5130H
Vehicle to be Exported:	Yes
Intended De-registration Date:	19 Mar 2018
Vehicle Make:	TOYOTA /
Vehicle Model:	LEXUS IS250 AUTO STANDARD HID
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	4GR0839233
Chassis No.:	JTHBK262X05178068
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$39,029.00
Original Registration Date:	17 Sep 2012
First Registration Date:	17 Sep 2012
Transfer Count:	3
Actual ARF Paid:	\$39,029.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Sep 2022
PARF Rebate Amount:	\$27,320.00
Intended COE Rebate Details	
COE Expiry Date:	16 Sep 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$93,990.00
COE Rebate Amount:	\$39,542.00
Total Rebate Amount:	\$66,862.00

The information contained herein is correct as at 19 Mar 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO.201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/AMK

Claim Type: Third Party

Accident Date: 19/03/2018

TP Veh Reg No: SHD8517H

Estimate No: ES1890280/AMK

Date: 20 Mar 2018

Policy No: DMPCSN3003231800

Veh Reg No: SLS5130H

Make/Model: LEXUS IS 250

Chassis No: JTHBK262X05178068

Engine No: 4GR0839233

Reg. Date: 17/09/2012

Not Authorized

6/1 Sep 8?

Bumper After Paint 6 days

Estimate Repair Cost to Vehicle No :SLS5130H

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT NUMBER PLATE GARNISH	150.60	1 PC	<i>CR</i> 150.60	<input checked="" type="checkbox"/>
2 REAR BUMPER	741.85	1 PC	<i>Bu</i> 741.85	<input checked="" type="checkbox"/>
3 REAR BUMPER REINFORCEMENT	431.60	1 PC	<i>By</i> 431.60	<input checked="" type="checkbox"/>
4 REAR BUMPER BRACKET	142.00	2 PC	<i>R</i> 284.00	<input checked="" type="checkbox"/>
5 REAR BUMPER SIDE RETAINER	50.50	2 PC	<i>Dit</i> 101.00	<input checked="" type="checkbox"/>
6 REAR BUMPER PARKING SENSOR	400.20	1 PC	<i>Shor</i> 400.20	<input checked="" type="checkbox"/>
7 REAR BUMPER SPONGE	90.20	1 PC	<i>CR</i> 90.20	<input checked="" type="checkbox"/>
8 REAR BUMPER CLIP	3.50	5 PC	<i>CR</i> 17.50	<input checked="" type="checkbox"/>
9 REAR END PANEL	598.83	1 PC	<i>R</i> 598.83	<input checked="" type="checkbox"/>
10 REAR END PANEL INNER TOP GARNISH	325.30	1 PC	<i>CR</i> 325.30	<input checked="" type="checkbox"/>
			3,541.28	
		Less 10%	354.13	3,187.15
Special Net				
11 FRONT NUMBER PLATE	35.00	1 PC	<i>CR</i> 35.00	<input checked="" type="checkbox"/>
			35.00	35.00
Labour				
12 REMOVE & REFIX FRT BUMPER,GRILLE,FRT NO PLATE GARNISH & REALIGN THE SAME	250.00	1 LA	250.00	<i>1500</i>
13 PUTTY & RESPRAY FRT BUMPER & ALL AFFECTED AREAS	250.00	1 LA	250.00	<i>2200</i>
14 REMOVE & REFIX REAR BUMPER,TAILLAMPS:TO CUT,WELD & RENEW REAR END PANEL:KNOCKING & REPAIR REAR SPARE TYRE PANEL & REALIGN THE SAME	700.00	1 LA	700.00	<i>6000</i>
15 PUTTY & RESPRAY REAR BUMPER,REAR END PANEL,REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	700.00	1 LA	700.00	<i>5000</i>
16 RUSTPROOFING	60.00	1 LA	60.00	<i>300</i>
			1,960.00	1,960.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO.201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department
WS Ref: TP/FC/AMK
Claim Type: Third Party
Accident Date: 19/03/2018
TP Veh Reg No: SHD8517H

Estimate No: ES1890280/AMK
Date: 20 Mar 2018
Policy No: DMPCSN3003231800
Veh Reg No: SLS5130H
Make/Model: LEXUS IS 250
Chassis No: JTHBK262X05178068
Engine No: 4GR0839233
Reg. Date: 17/09/2012

Estimate Repair Cost to Vehicle No :SLS5130H

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 5,182.15
			Add GST @ 7%	362.75
			Total Amount Payable	SS 5,544.90

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005273/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-11-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 8517H	Veh. Inspected	SLS 5130H
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18002236MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	20/03/2018
2. Vehicle Particulars & Condition			
Make & Model	LEXUS IS250 (A)	c.c	2500
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JTHBK262X05178068	Colour	METALLIC BLACK
Odometer	79528	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	PIRELLI	7 mm
L/H Front Tyre	225/45 R17	PIRELLI	7 mm
R/H Rear Tyre	245/45 R17	PIRELLI	7 mm
L/H Rear Tyre	245/45 R17	PIRELLI	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/03/2018	Inspection Date	21/03/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 5130H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT NUMBER PLATE GARNISH	CRACKED	150.60	150.60
1	REAR BUMPER	BUCKLED	741.85	741.85
1	REAR BUMPER REINFORCEMENT	BENT	431.60	431.60
2	REAR BUMPER BRACKET @\$142.00	TO REPAIR SEE LABOUR	284.00	-
2	REAR BUMPER SIDE RETAINER @\$50.50	DISTORTED	101.00	101.00
2	REAR BUMPER PARKING SENSOR @\$400.20	SHORTED (1 PC ONLY)	800.40	400.20
1	REAR BUMPER SPONGE	CRACKED	90.20	90.20
5	REAR BUMPER CLIP @\$3.50	NECESSARY	17.50	17.50
1	REAR END PANEL	TO REPAIR SEE LABOUR	598.83	-
1	REAR END PANEL INNER TOP GARNISH	MTG CRACKED	325.30	325.30
	LESS 10% DISCOUNT		-354.13	-225.83
			3,187.15	2,032.42
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	CRACKED	35.00	35.00
			35.00	35.00
LABOUR				
	REMOVE & REFIX FRT BUMPER,GRILLE,FRT NO PLATE GARNISH & REALIGN THE SAME.		250.00	150.00
	PUTTY & RESPRAY FRT BUMPER & ALL AFFECTED AREAS.		250.00	220.00
	REMOVE & REFIX REAR BUMPER, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR SPARE TYRE PANEL & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET AND REAR END PANEL.		700.00	600.00
	PUTTY & RESPRAY REAR BUMPER, REAR END PANEL, REAR SPARE TYRE PANEL & ALL AFFECTED AREAS.		700.00	500.00
	RUSTPROOFING.		60.00	30.00
			1,960.00	1,500.00

Report Ref No. CS/FC118005273/Ktd3n2



GRAND TOTAL		5,182.15	3,567.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,850.00

Report Ref No. CS/FCI18005273/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.