

ASS. REC. BY:

REF: CS/FCI 18005276/Tld3

Special Instruction:

Surveyor: Taufikah

ASSIGNMENT (Office)

From (Person): Sathara

of FCI

Date/Time: 2018/04/04 pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 5534E

Insured: SHB 3721C

at Workshop m/s: Ding Auto

Tel: 9733 5832

of Blk 10 Sin Ming Ind. Est. Sec. C # 01-20

Policy No:

Claim No: D18002268MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A: 19/03/2018

(Client's Record)

Insp: 249 jalan Bohn Lay

CA / REV / REP. / REV 24 HRS 'w/p'

H.O.D. Endorsement:

Date/Time: 9:53am 02/3/18

Person Contacted:

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SLD 5534E - x
	SHB 3721C - CS/FCI 17024303/Tld3n2 D.O.A: 19/12/17
	Revert thru email

Tanpiah

REF: FC 1

ASSIGNMENT

Rich: _____ Date: _____

Estimated Cost: _____

OD: WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OS
<input checked="" type="checkbox"/>	

Sal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

QA / REV / REP. / 24 HRS **WP**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Van No: SLD5534E Reg: 20/6 June.

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or _____

Make: **Toyota H115** CC: 1598

Colour: **Blue** AC Insured / Std / Nil / NA

Se. Reading: **153595** TP Acc. Insured / Std / Nil / NA

Eng No: _____

C No: **NR053KEH104552722**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / Rim / STD Air / Rim or

Tyre Size: F: **205/55R16**

R: **175**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Triangle**

Front: _____ Rear: _____

R.Bel: **6** mm R.Bel: **6** mm

L.Bel: **6** mm L.Bel: **6** mm

D.O.A: _____ D.O.I: **21/5/18 @ pm.**

Survey held at: **Ding Aun**

Des. of Damages: Pnt / Red / OS / NS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure effected due to collision:

Date / Time Action / Instruction

Confirmed with Kenneth LIS \$ 5300, 8 days

Red: \$ 13,136.12, 71%

RECEIVED 18-APR 2018

Disc Time / Fee Pass / Prel. Report

typist Final Report

Days Of Repair: **8**

Resurvey No. of Trip: **1**

Survey Fee: **8XKS:120**

Disc Time / Fee Return /

Add Fee: Site Insp: \$

Inter. Insp: \$

Test Insp: \$

Rep. Insp: \$

Report Format: **TP**

Lump Sum / : **5300**

50
50
41
461

MOTOR SURVEY ASSIGNMENT

Date	20-03-2018	Our Ref No. D18002268MFSH
Accident Date	19-03-2018	Claim Type. Third Party
Insured Vehicle	SHB3721C	Third Party Vehicle. SLD5534E
Survey Location	BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-20	
Contact Person.	YOU JING FENG	
Contact No.	64589523/ 97335832	Fax No. 64534227
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	DING AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236142)

PRI Documents

Close



PRI Header Details

Claim No	D18002268MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & DING AUT
Workshop Name	DING AUTO PTE LTD (Contact Person : YOU JING FENG)	Survey Location & Contact Details	BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-; Mobile: 97335832 , Phone: 64589523 , Fax: 6453422; EmailId: JINGFENG@DINGAUTO.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3721C	TP Vehicle No	SLD5534E
PRI Recieved Date	20-03-2018 04:47:17 PM	Surveyor Appointed Date	20-03-2018 04:03:35 PM	Surveyor Accept Date	21-03-2018 0

Survey Report Upload

Surveyor Inspection Date *	<input type="text"/>	Surveyor Report Date	21-03-2018	Upload Survey Report *	<input type="button" value="Choose File"/>
-----------------------------------	----------------------	-----------------------------	------------	-------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005276/T1rd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3721C	Veh. Inspected	SLD 5534E
Policy No.		Coverage (\$)	0.00
Claim No.	D18002268MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	21/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/03/2018	Inspection Date	21/03/2018
Survey held at	249 JALAN BOON LAY		
Repairer	DING AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002268MFSH

Our Ref: CS/FCI18005276/T1rd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLD 5534E

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28/03/2018 at the premises of M/s DING AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>18,436.12</u>
Revised Estimate Amount	: S\$ <u>6,451.00</u>
"Check" Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:
The vehicle sustained damages
At rear portion.



Yours faithfully
TAUFIKH
Automotive Assessor

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, April 16, 2018 9:06 AM
To: 'Claim Workflow System'
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002268MFSH/1
Attachments: SLD 5534E.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SLD 5534E.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, March 21, 2018 9:57 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002268MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 20 March 2018 4:03 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002268MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2018 17:02
Date Of Accident	19/03/2018 09:30
Exact Location Of Accident	REPUBLIC BLVD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD5534D SLD5534E
-----------------------------	--------------------------

Insured/Policyholder

Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999995061
Cover Note Number	

Driver

Name of Driver	CHUA GIM PENG DANIEL
NRIC No	S1348703J
Date Of Birth	10/10/1959
Occupation	OUTDOOR
Date Of Driving Pass	18/03/1986
Driving Experience	32 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92394128
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 249 JALAN BOON LAY

Postcode

Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT


Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB3721C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver CHANG KIANG LEONG
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN



A = SLD5534E
 B = SHB3721C
 Chang King Leong
 S1731170J
 90671268


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

After drop rider at Luster 3/4 I head back to East Coast Parkway. Using Republic Blvd. at the Junction I stop a Taxi (SHB3721C) driven by Chang King Leong. HP 90671268 bang me from behind.


He came down & assessed the damage & told me to report the accident & claim from his insurance firm. Approx 9:30

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:




 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

20/03/2018 11:32

JOB-NO: 85008200

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD CONTACT: 0
ADDRESS: 50 UBI AVENUE 3 0
#01-12 NIL
SINGAPORE 408866

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SLD5534E TRANS: AUTO CHASSIS: MR053REH104552722
MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A) ENGINE: 1ZRY304401
OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.
JOB-CODE: TP SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 REMOVE&REFIT REAR BUMPER REVERSE SENSOR	1.00	150.00	0.00	150.00	Y		30 ✓
2 CHECK WIRING&LIGHTING SYSTEM	1.00	100.00	0.00	100.00	Y		30 ✓
3 R&R SPARE TYRE BOARD & CARPET	1.00	200.00	0.00	200.00	Y		860 ✓
4 R&R BOOTLID COMPARTMENT	1.00	100.00	0.00	100.00	Y		60 ✓
5 TO APPLY UNDERCOATING ON THE AFFECTED AREA	1.00	150.00	0.00	150.00	Y		60 ✓
6 TO PLACE VEHICLE ON WORKBENCH	1.00	400.00	0.00	400.00	Y		200? photo ✓
7 R&R REAR WINDSCREEN GLASS	1.00	200.00	0.00	200.00	Y		X ✓
8 TO REMOVE & REFIT REAR EXHAUST PIPE	1.00	100.00	0.00	100.00	Y		60? photo ✓
9 LABOUR CHARGES-TO REMOVE&REPLACE THE ZBOVE DAMAGES, TOKNOCK OUT DENTS ON AFFECTED PORTION, ADJUST&REALIGN TO THE SAME	1.00	2,200.00	0.00	2,200.00	Y		1000 1200 ✓
10 TO PUTTY&SPRAY PAINT OF THE AFFECTED AREAS	1.00	2,000.00	0.00	2,000.00	Y		1000 ✓
11 TO REMOVE & REFIX FUEL TANK TO FACILITATE CHANGING OG SPARE TYRE FLOOR PANELS	1.00	380.00	0.00	380.00	Y		X h1 ✓
TOTAL:		5,980.00	0.00	5,980.00			
MATERIALS							
1 REAR BUMPER	1.00	545.00	136.25	408.75	L	Y	10 ✓
2 REAR BUMPER SIDE RETAINERS	1.00	230.00	57.50	172.50	L	Y	new ✓
3 REAR BUMPER SIDE RETAINERS SHORT	1.00	180.00	45.00	135.00	L	Y	new ✓
4 REAR BUMPER CLIPS	1.00	30.00	7.50	22.50	L	Y	new ✓
5 REAR BUMPER REFLECTORS	1.00	150.00	37.50	112.50	L	Y	X un ✓
6 REAR BUMPER REINFORCEMENT	1.00	380.00	95.00	285.00	L	Y	BT ✓
7 REAR BUMPER REINFORCEMENT BRACKETS	1.00	210.00	52.50	157.50	L	Y	BT ✓
8 REAR BOOT LID	1.00	885.00	221.25	663.75	L	Y	bb ✓
9 REAR BOOT LID"TOYOTA"EMBLEM	1.00	68.00	17.00	51.00	L	Y	new ✓
10 REAR BOOT LID"COROLLA"BADGE	1.00	65.00	16.25	48.75	L	Y	new ✓
11 REAR BOOT LID"ALTIS"BADGE	1.00	65.00	16.25	48.75	L	Y	new ✓
12 REAR BOOT LID OUTER CHROME MOULDING	1.00	235.00	58.75	176.25	L	Y	X un ✓
13 REAR BOOT LID INNER LOCK	1.00	350.00	87.50	262.50	L	Y	BT ✓
14 REAR BOOT LID TRIM	1.00	357.00	89.25	267.75	L	Y	X un ✓
15 REAR BOOT LID TRIM CLIPS	1.00	58.50	14.63	43.87	L	Y	X un ✓
16 REAR BOOT LID HINGES	2.00	200.00	50.00	150.00	L	Y	Ry ✓

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
17 REAR END PANEL	1.00	775.00	193.75	581.25	L	Y	bt
18 REAR END PANEL TOP GARNISH	1.00	345.00	86.25	258.75	L	Y	de
19 REAR END PANEL TOP GARNISH CLIPS	1.00	35.00	8.75	26.25	L	Y	sh
20 REAR END PANEL WEATHERSTRIP	1.00	185.00	46.25	138.75	L	Y	mi
21 REAR END PANEL INNER CENTRE TRIM	1.00	245.00	61.25	183.75	L	Y	gn
22 REAR END PANEL INNER TRIM CLIPS	1.00	35.00	8.75	26.25	L	Y	gn
23 REAR SPARE TYRE COMPARTMENT	1.00	660.00	215.00	645.00	L	Y	Rx
24 REAR SPARE TYRE COMPARTMENT FLOOR BOARD	1.00	415.00	103.75	311.25	L	Y	an
25 REAR FENDERS	1.00	2,390.00	597.50	1,792.50	L	Y	Rx
26 REAR FENDER SPLASH SHIELDS	1.00	140.00	35.00	105.00	L	Y	de
27 REAR FENDER SPLASH SHIELDS CLIPS	1.00	35.00	8.75	26.25	L	Y	nu
28 REAR FENDER INNER TRIMS	1.00	780.00	195.00	585.00	L	Y	X ny
29 REAR FENDER INNER TRIM CLIPS	1.00	90.00	22.50	67.50	L	Y	X ny
30 REAR TALLLAMP(OUTER) LH	1.00	770.00	192.50	577.50	L	Y	nt
31 REAR TALLLAMP(INNER)	1.00	590.00	147.50	442.50	L	Y	X n
32 REAR TALLLAMP CLIPS	1.00	25.00	6.25	18.75	L	Y	nu
33 REAR TALLLAMP PANEL	1.00	330.00	82.50	247.50	L	Y	Rx
34 REAR DOOR	1.00	2,640.00	660.00	1,980.00	L	Y	Rx
35 REAR WINDSCREEN GLASS MOULDING	1.00	145.00	36.25	108.75	L	Y	X nn
36 REAR EXHAUST	1.00	790.00	197.50	592.50	L	Y	Rx
37 REAR EXHAUST MOUNTINGS	1.00	190.00	47.50	142.50	L	Y	X
38 REAR EXHAUST HEAT SHIELD	1.00	145.00	36.25	108.75	L	Y	X } un
39 AIR VENT	1.00	90.00	22.50	67.50	L	Y	? } un
40 REAR BUMPER REVERSE SENSORS	1.00	260.00	0.00	260.00	S	200/Y	nu
41 REAR BOOTLID LICENSE PLATE LAMP	1.00	36.00	0.00	36.00	S	1/Y	X } un
42 REAR BOOTLID NO PLATE&CASING	1.00	80.00	0.00	80.00	S	Y	X } un
43 SEALANT	1.00	40.00	0.00	40.00	S	Y	nu
TOTAL:		16,469.50	4,013.38	12,456.12			
TOTAL PARTS & LABOUR :		22,449.50	4,013.38	18,436.12			

EXCESS/LOADING: \$5 0.00

No. Of Day: 8 days

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$5

DATE OF SURVEY: 22/13/18

SURVEYED BY: Taujib 17495749 *wp*
sure@lkhauto.com

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001
Ding Auto User 1

ESTIMATOR
STA AUTOCENTRE
TEL: _____ FAX: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

DING AUTO PTE LTD
 Blk 10 Sin Ming Industrial Estate Sector C
 #01-20
 Singapore 575645

Tel: 6452-1208 Fax: 6452-0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

20/03/2018 11:32

OWNER'S PARTICULARS

JOB-NO: 85008200

NAME: LION CITY RENTALS PTE. LTD CONTACT: 0
 ADDRESS: 50 UBI AVENUE 3 0
 #01-12 NIL
 SINGAPORE 408886

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SLD5534E TRANS: AUTO CHASSIS: MR053REH104552722
 MAKE / MODEL: TOYOTA / Altis Corolla 1.8 (A) ENGINE: 1ZRY304401
 OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.
 JOB-CODE: TP SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 REMOVE&REFIT REAR BUMPER REVERSE SENSOR	1.00	150.00	0.00	150.00	Y		30
2 CHECK WIRING&LIGHTING SYSTEM	1.00	100.00	0.00	100.00	Y		30
3 R&R SPARE TYRE BOARD & CARPET	1.00	200.00	0.00	200.00	Y		860
4 R&R BOOTLID COMPARTMENT	1.00	100.00	0.00	100.00	Y		60
5 TO APPLY UNDERCOATING ON THE AFFECTED AREA	1.00	150.00	0.00	150.00	Y		60
6 TO PLACE VEHICLE ON WORKBENCH	1.00	400.00	0.00	400.00	Y		200? photo
7 R&R REAR WINDSCREEN GLASS	1.00	200.00	0.00	200.00	Y		X
8 TO REMOVE & REFIT REAR EXHAUST PIPE	1.00	100.00	0.00	100.00	Y		60? photo
9 LABOUR CHARGES-TO REMOVE&REPLACE THE ABOVE DAMAGES, TO KNOCK OUT DENTS ON AFFECTED PORTION, ADJUST&REALIGN TO THE SAME	1.00	2,200.00	0.00	2,200.00	Y		1200
10 TO PUTTY&SPRAY PAINT OF THE AFFECTED AREAS	1.00	2,000.00	0.00	2,000.00	Y		1400
11 TO REMOVE & REFIX FUEL TANK TO FACILITATE CHANGING OG SPARE TYRE FLOOR PANELS	1.00	380.00	0.00	380.00	Y		X
TOTAL:		5,980.00	0.00	5,980.00			

MATERIALS

1 REAR BUMPER	1.00	545.00	136.25	408.75	L	Y	NO
2 REAR BUMPER SIDE RETAINERS	1.00	230.00	57.50	172.50	L	Y	new
3 REAR BUMPER SIDE RETAINERS SHORT	1.00	180.00	45.00	135.00	L	Y	new
4 REAR BUMPER CLIPS	1.00	30.00	7.50	22.50	L	Y	new
5 REAR BUMPER REFLECTORS	1.00	150.00	37.50	112.50	L	Y	X
6 REAR BUMPER REINFORCEMENT	1.00	380.00	95.00	285.00	L	Y	BA
7 REAR BUMPER REINFORCEMENT BRACKETS	1.00	210.00	52.50	157.50	L	Y	BA
8 REAR BOOT LID	1.00	665.00	221.25	443.75	L	Y	bb
9 REAR BOOT LID"TOYOTA"EMBLEM	1.00	88.00	17.00	51.00	L	Y	new
10 REAR BOOT LID"COROLLA"BADGE	1.00	65.00	16.25	48.75	L	Y	new
11 REAR BOOT LID"ALTIS"BADGE	1.00	65.00	16.25	48.75	L	Y	new
12 REAR BOOT LID OUTER CHROME MOULDING	1.00	235.00	58.75	176.25	L	Y	X
13 REAR BOOT LID INNER LOCK	1.00	350.00	87.50	262.50	L	Y	Z
14 REAR BOOT LID TRIM	1.00	357.00	89.25	267.75	L	Y	X
15 REAR BOOT LID TRIM CLIPS	1.00	58.50	14.63	43.87	L	Y	X
16 REAR BOOT LID HINGES	2.00	200.00	50.00	150.00	L	Y	Ry

3508

2800

DESCRIPTION	QTY	UNIT COSTS	ESTIMATED COSTS	ACTUAL COSTS	IND	SURDISP	PRICE
17 REAR END PANEL	1.00	775.00	193.75	581.25	L	Y	AT
18 REAR END PANEL TOP GARNISH	1.00	345.00	86.25	258.75	L	Y	de
19 REAR END PANEL TOP GARNISH CLIPS	1.00	35.00	8.75	26.25	L	Y	ak
20 REAR END PANEL WEATHERSTRIP	1.00	185.00	46.25	138.75	L	Y	rw
21 REAR END PANEL INNER CENTRE TRIM	1.00	245.00	61.25	183.75	L	Y	x
22 REAR END PANEL INNER TRIM CLIPS	1.00	35.00	8.75	26.25	L	Y	x
23 REAR SPARE TYRE COMPARTMENT	1.00	860.00	215.00	645.00	L	Y	Rx
24 REAR SPARE TYRE COMPARTMENT FLOOR BOARD	1.00	415.00	103.75	311.25	L	Y	9X
25 REAR FENDERS	1.00	2,390.00	597.50	1,792.50	L	Y	Rx
26 REAR FENDER SPLASH SHIELDS	1.00	140.00	35.00	105.00	L	Y	de
27 REAR FENDER SPLASH SHIELDS CLIPS	1.00	35.00	8.75	26.25	L	Y	new
28 REAR FENDER INNER TRIMS	1.00	780.00	195.00	585.00	L	Y	X
29 REAR FENDER INNER TRIM CLIPS	1.00	90.00	22.50	67.50	L	Y	X
30 REAR TALLAMP(OUTER) LH	1.00	770.00	192.50	577.50	L	Y	mt
31 REAR TALLAMP(INNER)	1.00	590.00	147.50	442.50	L	Y	X
32 REAR TALLAMP CLIPS	1.00	25.00	6.25	18.75	L	Y	new
33 REAR TALLAMP PANEL	1.00	330.00	82.50	247.50	L	Y	Rx
34 REAR DOOR	1.00	2,640.00	660.00	1,980.00	L	Y	Rx
35 REAR WINDSCREEN GLASS MOULDING	1.00	145.00	36.25	108.75	L	Y	X
36 REAR EXHAUST	1.00	790.00	197.50	592.50	L	Y	Rx
37 REAR EXHAUST MOUNTINGS	1.00	190.00	47.50	142.50	L	Y	X
38 REAR EXHAUST HEAT SHIELD	1.00	145.00	36.25	108.75	L	Y	X
39 AIR VENT	1.00	90.00	22.50	67.50	L	Y	?X
40 REAR BUMPER REVERSE SENSORS	1.00	280.00	0.00	280.00	S	Y	new
41 REAR BOOTLID LICENSE PLATE LAMP	1.00	36.00	0.00	36.00	S	Y	Y
42 REAR BOOTLID NO PLATE&CASING	1.00	80.00	0.00	80.00	S	Y	X
43 SEALANT	1.00	40.00	0.00	40.00	S	Y	new
TOTAL:		16,489.50	4,013.38	12,456.12			
TOTAL PARTS & LABOUR :		22,449.50	4,013.38	18,436.12			

1925

240

200

EXCESS/LOADING-SS 0.00

No. Of Day: 8 days

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: SS

DATE OF SURVEY: 22/12/18

SURVEYED BY: Taufiq 17-495749 wp-
sure@lhaauto.com

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001
Ding Auto User 1
ESTIMATOR
STA AUTOCENTRE
TEL: _____ FAX: _____

Lump sum



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005276/T1rd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-04-2018	
		Code : FC12	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 3721C	Veh. Inspected	SLD 5534E
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18002268MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	20/03/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104552722	Colour	BLUE
Odometer	153595	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	TRIANGLE	6 mm
L/H Front Tyre	205/55 R16	TRIANGLE	6 mm
R/H Rear Tyre	205/55 R16	TRIANGLE	6 mm
L/H Rear Tyre	205/55 R16	TRIANGLE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/03/2018	Inspection Date	21/03/2018
Survey held at	249 JALAN BOON LAY		
Repairer	DING AUTO PTE LTD		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 5534E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	545.00	545.00
1	REAR BUMPER SIDE RETAINERS	NECESSARY	230.00	230.00
1	REAR BUMPER SIDE RETAINERS SHORT	NECESSARY	180.00	180.00
1	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	REAR BUMPER REFLECTORS	NOT NECESSARY	150.00	-
1	REAR BUMPER REINFORCEMENT	BENT	380.00	380.00
1	REAR BUMPER REINFORCEMENT BRACKETS	BENT	210.00	210.00
1	REAR BOOT LID	BENT	885.00	885.00
1	REAR BOOT LID 'TOYOTA' EMBLEM	NECESSARY	68.00	68.00
1	REAR BOOT LID 'COROLLA' BADGE	NECESSARY	65.00	65.00
1	REAR BOOT LID 'ALTIS' BADGE	NECESSARY	65.00	65.00
1	REAR BOOT LID OUTER CHROME MOULDING	NOT NECESSARY	235.00	-
1	REAR BOOT LID INNER LOCK	BENT	350.00	350.00
1	REAR BOOT LID TRIM	NOT NECESSARY	357.00	-
1	REAR BOOT LID TRIM CLIPS	NOT NECESSARY	58.50	-
2	REAR BOOT LID HINGES	TO REPAIR SEE LABOUR	200.00	-
1	REAR END PANEL	BENT	775.00	775.00
1	REAR END PANEL TOP GARNISH	DEFORMED	345.00	345.00
1	REAR END PANEL TOP GARNISH CLIPS	NECESSARY	35.00	35.00
1	REAR END PANEL WEATHERSTRIP	TWISTED	185.00	185.00
1	REAR END PANEL INNER CENTRE TRIM	NOT NECESSARY	245.00	-
1	REAR END PANEL INNER TRIM CLIPS	NOT NECESSARY	35.00	-
1	REAR SPARE TYRE COMPARTMENT	TO REPAIR SEE LABOUR	860.00	-
1	REAR SPARE TYRE COMPARTMENT FLOOR BOARD	NOT NECESSARY	415.00	-
1	REAR FENDERS	TO REPAIR SEE LABOUR	2,390.00	-
1	REAR FENDER SPLASH SHIELDS	DEFORMED	140.00	140.00
1	REAR FENDER SPLASH SHIELDS CLIPS	NECESSARY	35.00	35.00
1	REAR FENDER INNER TRIMS	NOT NECESSARY	780.00	-
1	REAR FENDER INNER TRIM CLIPS	NOT NECESSARY	90.00	-

Report Ref No. CS/FCI18005276/T1rd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILLAMP (OUTER) LH	CUT	770.00	385.00
1	REAR TAILLAMP (INNER)	NOT NECESSARY	590.00	-
1	REAR TAILLAMP CLIPS	NECESSARY	25.00	25.00
1	REAR TAILLAMP PANEL	TO REPAIR SEE LABOUR	330.00	-
1	REAR DOOR	TO REPAIR SEE LABOUR	2,640.00	-
1	REAR WINDSCREEN GLASS MOULDING	NOT NECESSARY	145.00	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	790.00	-
1	REAR EXHAUST MOUNTINGS	NOT NECESSARY	190.00	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	145.00	-
1	AIR VENT	NOT NECESSARY	90.00	-
	LESS 25% DISCOUNT		-4,013.38	-1,233.25
			12,040.12	3,699.75
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSORS (SN)	NOT WORKING	260.00	200.00
1	REAR BOOTLID LICENSE PLATE LAMP (SN)	NOT NECESSARY	36.00	-
1	REAR BOOTLID NO PLATE & CASING (SN)	NOT NECESSARY	80.00	-
1	SEALANT (SN)	NECESSARY	40.00	40.00
			416.00	240.00
	<u>LABOUR</u>			
	REMOVE & REFIT REAR BUMPER REVERSE SENSOR		150.00	30.00
	CHECK WIRING & LIGHTING SYSTEM		100.00	30.00
	R&R SPARE TYRE BOARD & CARPET		200.00	60.00
	R&R BOOTLID COMPARTMENT		100.00	60.00
	TO APPLY UNDERCOATING ON THE AFFECTED AREA		150.00	60.00
	TO PLACE VEHICLE ON WORKBENCH		400.00	200.00
	R&R REAR WINDSCREEN GLASS	NOT NECESSARY	200.00	-
	TO REMOVE & REFIT REAR EXHAUST PIPE		100.00	60.00

Report Ref No. CS/FCI18005276/T1rd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES-TO REMOVE & REPLACE THE ZBOVE DAMAGES TO KNOCK OUT DENTS ON AFFECTED PORTION ,ADJUST & REALIGN TO THE SAME.INCLUSIVE OF THE REPAIR OF REAR BOOT LID HINGES,REAR SPARE TYRE COMPARTMENT,REAR FENDERS,REAR TAILLAMP PANEL,REAR DOOR AND REAR EXHAUST .		2,200.00	1,200.00
	TO PUTTY & SPRAY PAINT OF THE AFFECTED AREAS.		2,000.00	1,100.00
	TO REMOVE & REFIX FUEL TANK TO FACILITATE CHANGING OG SPARE TYRE FLOOR PANELS.	NOT NECESSARY	380.00	-
			5,980.00	2,800.00
GRAND TOTAL			18,436.12	6,739.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,300.00

Report Ref No. CS/FCI18005276/T1rd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.