

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 22 Mar 2018

Preliminary Advice

Vehicle No	: SLK5079R	Accident Date	: 19/03/2018
Make	: MAZDA 2	Policy No.	: DMHCSN1708051801
Assignment Date	: 21/03/2018	Excess	: S\$1,000.00
Date of Inspection	: 21/03/2018	Est. Duration of Repair	: 8.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,417.29
Revised Amount	:S\$	5,316.09
Check Items (Estimated)	:S\$	1,992.00
Total	:S\$	7,308.09

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	53,351.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,649.00

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 9/9 mm
Tyre Condition (Rear)	: 2/2 mm

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :