



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : OAC-TP-AIG ASIAVehicle No. : GBE4670PMake & Model : TOYOTA HIACEYear of Manufacture : 2015Chassis No. : JTFHT02P800181098Engine No. : 1KD2564275

Policy No. : _____

Ins Company : AIG ASIA

Excess : _____

Date of Accident : 18/03/2018Time of Accident : 05:50

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : JASMINE CHNG

Signature : _____

Contact No

6848 5726 JASMINE CHNG

Parts (a) Cost / List Price Items \$ 4,685.00Plus/Less -20% \$ -Total of Cost / List \$ 4,685.00(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 200.00Total Parts Cost (Appendix A) \$ 4,885.00Labour (Appendix B) \$ 2,400.00Total Repair Cost \$ 7,285.00**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Tan Jiah
 Company : LKK
 Survey conducted on : 28/3/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 7 day(s)(c) Resurvey : Required / Not Required humpsun(d) Excess : \$ _____ Resurvey after repair(e) Signature of surveyor : Tan JiahDate: 28/3/18 1030

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : GBE4670P Case Owner : JASMINE CHNG

Make & Model : TOYOTA HIACE Year Manufacture : 2015

Chassis No : JTFHT02P800181098 Engine No : 1KD2564275

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : OAC-TP-AIG ASIA

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR FENDER RH	1		\$ 1,455.00			be-
2	REAR BUMPER	1		\$ 410.00			de-
3	REAR BUMPER CLIPS	10		\$ 50.00			ae-
4	REAR BUMPER SIDE RETAINER RH	1		\$ 38.00			ae-
5	REAR BUMPER SIDE RETAINER LH	1		\$ 38.00			X
6	CORNER GARNISH RH	1		\$ 76.00			ae-
7	TAILLAMP RHR	1		\$ 278.00			ae-
8	LOGO- TOYOTA	1		\$ 60.00			ae-
9	STICKER-COMPANY DECAL	1					ae-
10	STICKER-HIACE	1		\$ 53.00			ae-
11	STICKER 70KM/H	1					ae-
12	TAILGATE	1		\$ 1,927.00			Rp
13	REAR END PANEL	1		\$ 300.00			
14	REVERSE SENSOR	1				\$ 200.00	?
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Vehicle No. :	<u>GBE4670P</u>	Case Owner :	<u>JASMINE CHNG</u>
Make & Model :	<u>TOYOTA HIACE</u>	Year of Manufacture :	<u>2015</u>

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.