



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2010 MERCEDES ML350 (SKW4429U)

Date of Loss

19 March 2018

Time of Loss

10.00

Loss Description

SKW4429U HIT XB9794M

Comment

Workshop Details

Total Rebate Amount

52288

Nett Loss Amount

\$32,712.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

17/06/2018



Days of work completion *

22



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKW4429U

Registration State

SINGAPORE

Mileage

226971

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2010

ASSESSMENT INFO...

2010

Purchase Date

dd/mm/yyyy



Registration Date *

26/11/2010



Age of Vehicle

7

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

ONG POH LYE

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... MERCEDES

ASSESSMENT INFO... MERCEDES BENZ

CATEGORY Model

POLICY INFORMAT... ML350

ASSESSMENT INFO... ML350

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WDC1641862A614219

CATEGORY Date of Birth

FNOL INFORMATI... 18 July 1959

POST SURVEY INF... dd/mm/yyyy

CATEGORY Age

FNOL INFORMATI... 58

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 27296731527028

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 33

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... BLK 111 MCNAIR ROAD, #03-229,
320111, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S1364685F

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

22/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

255/50R19

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

255/50R19

Front left side

NEXEN6mm

Front right side

NEXEN6mm

Rear left side

NEXEN6mm

Rear right side

NEXEN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			Front bonnet			Bent	1950				1950	Reviewing
		2	1			Front bonnet logo			Necessary	55				55	Reviewing
		3	13			Front bonnet sponge clip			Serviceable	0	0	0	0	0	Deny
		4	1			Front fender LH			Buckled	1045				1045	Reviewing
		5	1			Front fender inner shield (Front)			Deformed	280				280	Reviewing
		6	1			Front fender inner shield (rear)			Deformed	230				230	Reviewing
		7	8			Front fender inner shield clip			Necessary	5				40	Reviewing
		8	1			Front bumper			Deformed	1610				1610	Reviewing
		9	1			Front bumper retainer LH			Damaged	42				42	Reviewing
		10	1			Front bumper inner garnish/tray			Damaged	500				500	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		11	12			Front bumper inner garnish/tray rivets			Necessary	5				60	Reviewing
		12	1			Front bumper foglight LH			Damaged	230				230	Reviewing
		13	1			Front bumper sponge LH			Cracked	165				165	Reviewing
		14	1			Front bumper lower garnish			Deformed	285				285	Reviewing
		15	1			Front bumper lower metal cover			Bent	920				920	Reviewing
		16	1			Front bumper sensor far LH			Damaged	160				160	Reviewing
		17	1			Front bumper sensor CTR LH			Deformed	160				160	Reviewing
		18	1			Front bumper sensor wiring			Damaged	130				130	Reviewing
		19	1			Front bumper nozzle LH			Damaged	160				160	Reviewing
		20	1			Front bumper nozzle cover LH			Damaged	60				60	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		21	1			Front bumper nozzle hose			Damaged	85				85	Reviewing
		22	1			Front grille			Cut	800				800	Reviewing
		23	1			Front headlamp LH			Cracked	2800				2800	Reviewing
		24	1			Front headlamp balast LH			Damaged	1240				1240	Reviewing
		25	1			Front headlamp top panel LH			Bent	715				715	Reviewing
		26	1			Wiper tank			Deformed	200				200	Reviewing
		27	1			Wiper tank sensor			Damaged	30				30	Reviewing
		28	1			Front WS wiper nozzle hose			Cut	160				160	Reviewing
		29	1			Radiator spare tank			Cracked	200				200	Reviewing
		30	1			Front kunckle LH			Bent	1570				1570	Reviewing
		31	1			Front kunckle bearing LH			Serviceable	0	0	0	0	0	Deny
		32	1			Front lower arm LH			Bent	1150				1150	Reviewing
		33	1			Front top arm LH			Bent	550				550	Reviewing

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		34	1		Front shock absorber LH			Bent	590				590	Reviewing

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1	CHECK WIRING FUNCTION	30	0	0	Reviewing		
		2	ALIGNMENT	60	0	0	Reviewing		
		3	LABOUR TO REMOVE AND REPLACE UNDERCARRIAGE FRONT LH	150	0	0	Reviewing		
		4	REMOVE NECESSARY PARTS: JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN FRONT INNER PANEL, FRONT HEADLAMP TOP PANEL LH, FRONT HEADLAMP SIDE PANEL LH, FRONT BONNET, }	900	0	0	Reviewing		
		5	FRONT FENDER LH / RH , FRONT BUMPER, FRONT DOOR LH, FRONT WSSIDE PILLAR AND WHEEL HOUSING LH (BULKHEAD SHIFTED) }	0	0	0	Reviewing		
		6	PUTTY AND RESPRAY FRONT INNER PANEL, FRONT BONNET, FRONT FENDER LH / RH, FRONT BUMPER, FRONT DOOR LH, FRONT WS SIDE PILLAR AND WHEEL HOUSING LH	900	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	Front bumper reinforcement	Reviewing	700	BENT (SUPPLEMENTARY)	
		2	Front bumper reinforcement bracket LH	Reviewing	252	BENT (SUPPLEMENTARY)	
		3	Rocker panel garnish/Trim Step	Reviewing	345	CUT (SUPPLEMENTARY)	
		4	Rocker panel garnish Top Plate/Step insert	Reviewing	290	CUT (SUPPLEMENTARY)	
		5	Anti-roll bar bush 4 pcs	Reviewing	60	BENT - ONLY 2 PCS2 (SUPPLEMENTARY)	
		6	Front bumper side bush	Reviewing	20	CUT (SUPPLEMENTARY)	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		7	Vehicle on bench	Reviewing	200	(SUPPLEMENTARY)	
		8	To repair front chassis LH & RH	Reviewing	250	(SUPPLEMENTARY)	
		9	Putty and respray front chassis LH/RH	Reviewing	200	(SUPPLEMENTARY)	
		10	Front bumper foglight grille	Reviewing	80	DEFORMED (SUPPLEMENTARY)	
		11	DAYS OF REPAIR : 8 DAYS	Reviewing			
		12	FRONT NO PLATE (NOT NECESSARY)	Deny	0	OLD DAMAGE	
		13	FRONT TYRE LH (80%)	Reviewing	304	PUNCTURED	
		14	FRONT RIM LH	Reviewing	80	DENTED	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$22,593.00			Claim Amount	\$22,593.00			

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,040.00	\$2,040.00
Miscellaneous	\$2,781.00	\$2,781.00
Excess	-\$400.00	-\$400.00
Spare Parts	\$18,172.00	\$18,172.00

Submit for Review