



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 289H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT) (N)	DEFORMED	1,220.00	1,220.00
1	REAR PARKING SENSOR RH ,CENTRE (CONSISTENT) (N)	SHORTED	265.00	265.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT) (N)	NOT NECESSARY	465.00	-
1	REAR END PANEL (CONSISTENT) (N)	TO REPAIR SEE LABOUR	640.00	-
1	REAR TAIL LAMP LH (CONSISTENT) (N)	NOT NECESSARY	375.00	-
1	REAR BMW LOGO EMBLEM (CONSISTENT) (N)	NECESSARY	80.00	80.00
1	REAR 318I EMBLEM (CONSISTENT) (N)	NECESSARY	70.00	70.00
1	REAR BOOT LID LOCK (CONSISTENT) (N) (ADDITIONAL)	DENTED	280.00	280.00
			3,395.00	1,915.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (CONSISTENT) (SN)	BENT	35.00	35.00
			35.00	35.00
<u>LABOUR</u>				
	TUFF COAT.		80.00	30.00
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING AND WELDING TO KNOCK DENTS ON REAR BOOT LID.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,000.00	600.00
	TO SPRAY PAINT.		700.00	600.00
			1,780.00	1,230.00
GRAND TOTAL			5,210.00	3,180.00
RECOMMENDED COST OF REPAIRS				3,180.00

Report Ref No. CC4/ASM18005410/M1ps3q2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.