



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18005410/M1ps3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 29-04-2020



ATTN:STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 5321X	Veh. Inspected	SJK 289H
Policy No.	CV1/GA216175	Coverage (\$)	0.00
Claim No.	S8M00BJB	Excess (\$)	0.00
Assign From		Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 318I	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WBAPF72000A143007	Colour	SILVER
Odometer	366358	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	8 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	8 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	8 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/03/2018	Inspection Date	22/03/2018
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------