Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18005441/KPS3Q2

Date: 28/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SHC5657L Insured Vehicle No: SHA6954H

Vehicle No:

Date of Loss: 20/03/2018 Nature of Claim: TP Claim No: MCT18030640

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHC5657L Reg No:

Make & Model: RENAULT LATITUDE, 2.0 L (A) Engine No: M9R8839C002018 Chassis No: Reg. Date: 04/11/2014 (Man. Year: 2014) VF1ABL15AUC279750 Odometer: 482915 km

Colour: Metallic White/Red

1995 cc

Engine Capacity: Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Giti 9 mm Rear Left Side: Linglong 8 mm Front Right Side: Giti 9 mm Rear Right Side: Linglong 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,154.11	5,255.39	22,898.72	81.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,470.00	1,360.00	8,110.00	85.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,624.11	6,615.39	31,008.72	82.42
Approved Total (Overridden) (S\$)		5,300.00		
(S\$)	37,624.11	5,300.00	32,324.11	85.91
+ GST 7.00/7.00% (S\$)	2,633.69	371.00	2,262.69	85.91
Nett Amount (S\$)	40,257.80	5,671.00	34,586.80	85.91
+ Loss of Use (3.5 x S\$40.00/day) (S\$) + Car Rental (3.5 x S\$101.46/day) (S\$)		140.00		
		355.11		
	(S\$)	6,166.11		
Liable Amoun	3,083.06			
Global Sum S	3,000.00			

INSPECTION

Date of Assignment: 22/03/2018

Date Inspected: 22/03/2018 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Adjuster Report Page 2 of 5

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Oct 2019)

Parts: 143 RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: (Price-denominated Standard List) Repairer's

Print Code: (Unsubmitted, no print-code for SHC5657L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*HEADLAMP LH	Serviceable	1,184.43 FL	*-FL
2	1	*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
3	1	*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
4	1	*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
5	1	*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
6	1	*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
7	1	*DOOR PANEL FRT LH	Bent	2,844.66 FL	*2,844.66 FL
8	1	*DOOR HINGE UPPER LH L70Y	Repair	261.28 FL	*- FL
9	1	*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
10	1	*DOOR CHECK FRT LH	Serviceable	194.77 FL	*- FL
11	1	*DOOR LOCK FRT LH	Repair	908.75 FL	*- FL
12	1	*DOOR CATCH FRT LH	Repair	131.23 FL	*- FL
13	1	*DOOR HANDLE OUTER FRT LH	Serviceable	477.76 FL	*- FL
14	1	*DOOR HANDLE COVER FRT LH	Serviceable	13.22 FL	*- FL
15	1	*DOOR HANDLE MODULE FRT LH	Serviceable	133.60 FL	*- FL
16	1	*DOOR REGULATOR FRT LH	Repair	505.19 FL	*- FL
17	1	*DOOR REGULATOR MOTOR FRT LH	Serviceable	796.46 FL	*- FL
18	1	*DOOR REGULATOR GUIDE FRT LH	Serviceable	120.97 FL	*- FL
19	1	*DOOR PANEL REAR L70Y	Bent	2,844.66 FL	*2,844.66 FL
20	1	*DOOR GUIDE REAR LH L70Y	Serviceable	176.82 FL	*- FL
21	1	*DOOR HINGE UPPER LH L70Y	Repair	274.50 FL	*- FL
22	1	*DOOR HINGE LOWER L70Y	Repair	300.55 FL	*- FL
23	1	*DOOR CHECK REAR LH/RH L70Y	Serviceable	203.06 FL	*- FL
24	1	*DOOR LOCK REAR LH L70Y	Repair	908.75 FL	*- FL
25	1	*DOOR HANDLE OUTER REAR LH L70Y	Serviceable	126.49 FL	*- FL
26	1	*DOOR HANDLE CAP REAR LH L70Y	Serviceable	35.52 FL	*- FL
27	1	*DOOR HANDLE COVER REAR LH L70Y	Serviceable	13.22 FL	*- FL
28	1	*DOOR HANDLE MODULE REAR LH L70Y	Serviceable	133.60 FL	*- FL
29	1	*DOOR REGULATOR REAR LH L70Y	Repair	1,135.10 FL	*- FL
30	1	*DOOR REGULATOR MOTOR REAR LH L70Y	Repair	893.75 FL	*-FL
31	1	*DOOR FINISHER REAR LH L70Y	Serviceable	423.10 FL	*-FL
32	1	*DOOR MOULDING REAR LH L70Y	Serviceable	176.82 FL	*-FL
33	1	*DOOR CASING REAR LH L70Y	Serviceable	1,509.06 FL	*- FL
34	1	*DOOR WATER SHIELD REAR LHL L70Y	Serviceable	30.39 FL	*-FL
35	1	*DOOR CASING CLIP	Not Necessary	12.63 FL	*- FL
36	1	*DOOR CASING LIGHT L70Y	Serviceable	48.74 FL	*-FL
37	1	*DOOR FINISHE INNER REAR LH L70Y	Serviceable	323.44 FL	*- FL
38	1	*DOOR FINISHER BRACKET INNER REAR LH L70Y	Serviceable	46.97 FL	*- FL
39	1	*DOOR FINISHER BRACKET INNER REAR LH L70Y	Serviceable	20.33 FL	*-FL
40	1	*DOOR FINISHER BRACKET INNER REAR LH L70Y	Serviceable	20.33 FL	*- FL
41	1	*DOOR FINISHER BRACKET INNER REAR LH L70Y	Serviceable	20.33 FL	*- FL
42	1	*DOOR GRAB HANDLE REAR LH L70Y	Serviceable	210.96 FL	*-FL
43	1	*DOOR BLIND REAR LH L70Y	Serviceable	741.80 FL	*- FL

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 28/4/2020

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
44	1		*DOOR WEATHERSTRIP REAR LH L70Y	Serviceable	410.66 FL	*- FL
45	1		*DOOR SEAL REAR LH L70Y	Serviceable	162.02 FL	*- FL
46	1		*DOOR GLASS RUBBER SEAL REAR LH L70Y	Serviceable	229.31 FL	*- FL
47	1		*DOOR WAIST SEAL OUTER REAR LH L70Y	Serviceable	334.69 FL	*- FL
48	1		*DOOR WAIST SEAL INNER REAR LH L70Y	Serviceable	115.64 FL	*- FL
49	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
50	1		*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL
51	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
52	1		*BUMPER COVER REAR	Repair	1,108.46 FL	*- FL
53	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*- FL
54	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
55	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
56	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
57	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
58	1		*DOOR MIRROR ASSY LH	Serviceable	1,483.40 FL	*- FL
59	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
60	1		*SET BUMPER CLIP FRT	Not Necessary	66.00 FS	*- FS
61	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
62	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*-FS
63	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
64	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*-FS
65	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*-FS
66	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*-FS
67	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
68	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
69	1		*FRONT DOOR STICKER CHASSIS	Necessary	50.00 FS	*15.00 FS
70	1		*REAR DOOR STICKER 6555 3333	Necessary	80.00 FS	*60.00 FS
F=Fra	anchise	part. S=Spo	cNett. L=ListItemDisc.			
				Sub Total (S\$)	•	5,824.32
			- List Item Discount on L Items 1	0.00/10.00% (S\$)	3,070.68	568.93
				Total Parts (S\$)	28,154.11	5,255.39

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	Labour Items						
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,500.00	500.00			
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	660.00			
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00			
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00			
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00			
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00			
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00			
8	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00			
9	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.G) TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00			
10	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	120.00			
11	TO VACUUM ,REPLACE ,REFIX AND RECHAEGE AIR CONDENSER	New	380.00	0.00			
12	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00			
13	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00			
	Gross Labou	r Cost (S\$)	9,470.00	1,360.00			

Report was unsubmitted during this print-out.

< END OF ESTIMATES >