

ASS. REC. BY

REF

CS/CTI18005453/Tlgd302

Assigned Agent/Company

SURV. OF

menmen

Taufik

ASSIGNMENT (Office)

From (Person)

Irene Tay

of CTI

Date/Time: 22/3/18 @ 4:14pm

Estimated Cost

Bill by

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SJB G382E

Insured

SKV 2577T

at Workshop no:

SK Automobile

Tel.

6789 5155

of

23 kaki Bukit Ave 4 #03-01

Policy No

DMPCSN3079211701

Claim No

SNM18001484C02

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A. 17/03/2018

CA / REV / REP. / REV 24 HRS

lwp'

H.O.D. Endorsement

Date/Time

9:36am @ 23/3/18

Person Contacted

julie

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJB G382E - x

SKV 2577T - x

22/1/19 @ 4:39 PM confirmed with Hway use by 6850, 12 days.
Cost \$ 24782.56, 74%

DATE

Tanfer

REF:

CAI

ASSIGNMENT

COE 2027 Feb

2007 Feb

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop in/s: _____
 of _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 955K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / FR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 12 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date _____ Person Contacted: _____
 Vehicle: IN / OUT

WP

Veh No: SLB 6382E Yr Regn: 2007 Feb
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Stream 1.8 CC: 1799
 Colour: white A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 153622 T-Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: EN61013593
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NI / STD A/Rim or
 Tyre Size: F: 205/65R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho

Front _____ Rear _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. _____ D.O.I: 25/3/18

Survey held at: SK Automobile / Sam Lee St #44
 Des. of Damages: ☒ Fr / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Repair limit 4598500

RECEIVED 23 JAN 2019

Date/Time File Pass to:

☐ : Prelim. Report
☐ : Final Report

Date/Time File Return to:

2

Days Of Repair: 12

Resurvey No. of Trip: _____

Survey Fee:

Transportation

Add Fee:

☐ Site Insp: \$
☐ Interview: \$
☐ Tech Insp: \$
☐ Weekend: \$

Report Format:

MER-71

Lump Sum / I.B. / S

850

220

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18005453/T1qd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 23-03-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKV 2577T	Veh. Inspected	SLB 6382E
Policy No.	DMPCSN3079211701	Coverage (\$)	0.00
Claim No.	SNM18D01484C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	23/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/03/2018	Inspection Date	23/03/2018
Survey held at	1 SOON LEE STREET #04-44		
Repairer	SK AUTOMOBILE PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2018		22 Mar 2018 16:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	KOO KWONG WENG, ID: S6801067E		
Main Claimant:	LEOW SIEW MUI, ID: S1567647G		
Vehicle Reg. No.:	SLB6382E	Date of Loss:	17/03/2018 11:00 - :59
Claim Type:	TP / SNM18D01484C02	Policy/Cover Note No.:	DMPCSN3079211701 (Comprehensive)
Vehicle Reg. No. (Insured):	SKV2577T	Policy No. (Claimant):	A80453684 QMX
		Excess:	S\$0.00
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2018]		
Driver/Custodian (Insured):	KOO KWONG WENG (50 / Male), NRIC: S6801067E		
Adj Asg. Remarks:	NO EST, ASSIGN XING QUO QIANG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: SK Admin <admin@skauto.com.sg>
Sent: Tuesday, 22 January 2019 4:39 PM
To: Shiau Chan (LKKAUTO); SUR
Cc: simon koh; JING XIONG KHOO
Subject: SLB6382E

Dear Shiau Chan,

Refer to the above matter.

We agreed COR@S\$8,500.00-12 days

Thank you

--

*Regards,
Huey Lee*

SK Automobile Pte Ltd

Tel: 6789 5155 Fax: 6783 5155

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7647G

Vehicle Details

Vehicle No.: SLB6382E
Vehicle to be Exported: No
Intended De-registration Date: 19 Mar 2018
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8 A
Primary Colour: Silver
Manufacturing Year: 2006
Engine No.: R18A1715343
Chassis No.: RN61013593
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$18,919.00
Original Registration Date: 02 Feb 2007
First Registration Date: 02 Feb 2007
Transfer Count: 1
Actual ARF Paid: \$17,389.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 01 Feb 2027
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$52,077.00
COE Rebate Amount: \$46,184.00
Total Rebate Amount: \$46,184.00

The information contained herein is correct as at 19 Mar 2018

OK \$ 58300
- 46184
12116

- Beware of 2nd Hand Car Dealers(Part 2) - Blacklist Her...
- Blackvue users - please come in AGAIN 2
- Where is your favorite wanton noodle?

Post an Advertisement
Sell it yourself Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years COE Renewal! Toyota Ayla 1.5A



\$2800 Downpayment Monthly From \$688 Onwards Lowest 3.68%P.A@GV Cars Financing GV Credit Pte Ltd (Sole)

PRIME MOTOR & LEASING
SHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

« Back (1 2 3 4) Next »

Sort by Date Posted

20 results/page

61 vehicles

honda stream

Advanced Search

Image	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	honda stream	Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Honda Stream 1.8A (COE till 03/2023)	\$35,800	\$7,190 /yr	11-Mar-2008	1,799 cc	-	MPV	Available
\$2800 Down Payment, Lowest Monthly From \$688 Onwards. Low Interest At 3.68% Per Annum By GV Cars Financing. 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New Full Pure Leather Seats An... \$2800 Downpayment Monthly From \$688 Onwards. Lowest 3.68%P.A@GV Cars Financing. GV Credit Pte Ltd Posted: 19-Mar-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda								
	Honda Stream 1.8A R5Z (COE till 10/2021)	\$31,800	\$8,780 /yr	01-Nov-2006	1,799 cc	147,000 km	MPV	Available
"One Year In-House Warranty!" With Official Warranty Certificate For Peace Of Mind, Our Company Renew COE For Cars Base On Car Conditions Not On Ownership, Fully Refurbished, New Paintwork, Accident F... Carway Posted: 17-Mar-2018 Tags: 2006 Honda Stream, Honda Stream, Honda, Stream, Used Honda								
	Honda Stream 1.8A (COE till 01/2022)	\$28,800	\$7,560 /yr	08-Jan-2007	1,799 cc	-	MPV	Available
In Great Condition, No Repairs Needed. Current Carplate Number Not Included. You Will Be Receiving A Brand New Carplate Number. Posted: 09-Mar-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda								
	Honda Stream 1.8A (COE till 01/2022)	\$33,838	\$8,820 /yr	18-Jan-2007	1,799 cc	134,000 km	MPV	Available
\$5k Drive Away! Free 1 Year Car Service! Beautiful Silver Honda Stream! New 5 Years COE. Service Every 10K Km Without Fail! Non Smoker Unit! No Repair Needed! We Deliver Our Promise! Suitable For Ages... Posted: 05-Mar-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda								
Car Buying Car Selling Car Ownership Car Aftermarket On The Move Lifestyle Buy Tyres Online! Latest Special Offers from Tyresport!								
	Honda Stream 1.8A (COE till 01/2022)	\$34,500	\$8,960 /yr	24-Jan-2007	1,799 cc	141,799 km	MPV	Available
Car Almost Like New! Free 6 Months Road Tax! \$3K Drive Away! 100% Loan Approval! Bad Debts/Bankruptcy All Are Welcome! Free 1 Year Extended Premium Warranty + Servicing For Peace Of Mind. Low Maintenanc... Hamilton Autohub Pte Ltd Posted: 09-Mar-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda								
	Honda Stream 1.8A (COE till 02/2022)	\$58,300	\$6,560 /yr	06-Feb-2007	1,799 cc	220,000 km	MPV	Available
New Drive Shafts, Engine And GB Mounts, Air-conditioning And Leather Seats. Overhauled Engine And Gearbox. Great To Last Remaining 9 Years Of COE. Very Low Depre. Text To Find Out More. Posted: 13-Mar-2018 Tags: 2007 Honda Stream, Honda Stream, Honda, Stream, Used Honda								
	Honda Stream 1.8A (COE till 03/2022)	\$30,899	\$7,670 /yr	28-Mar-2007	1,799 cc	130,000 km	MPV	Available



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 19/03/2018 10:22
Date Of Accident 17/03/2018 11:45
Exact Location Of Accident LOYANG AVENUE > TPE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLB6382E
Insured/Policyholder
Name Of Registered Owner LEOW SIEW MUI
NRIC No S1567647G
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-90000000
Alternative Phone No OTHERS-90000000
Vehicle Particulars
Manufacturer HONDA
Model STREAM-1.8 L (A)
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own Insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number A80453684 QMX
Cover Note Number
Driver
Name of Driver LIM WEE MING(LIN WEIMIN)
NRIC No S8205831A
Date Of Birth 25/02/1982
Occupation INDOOR
Date Of Driving Pass 08/01/2016
Driving Experience 2 YEARS AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-83824130
Fax Number
Contact Number
Email Address DIRECTORLIN@GMAIL.COM

Address 23 PASIR RIS RISE #11-48
 Postcode 518091
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured RELATIVE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 4
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKV2577T
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBG5399G
 Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHA7538U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Reporting Centre
Name: Singapore 415933
NIC/FIN No: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN

Longant
Avenue
Towards
TPK

A
B
C
D

- (A) SLB 6382E
(B) SKY 25777
(C) GBS 53996
(D) STH 75384

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17-03-2018 at about 1145hrs, I was travelling along Longant Avenue Towards TPK. Ahead of me, there's a vehicle slow down & stop. I follow suit. All of a sudden, I felt an hard impact from the rear. Then I realised, a vehicle SKY 25777 had collided onto my rear. Due to the hard impact, my vehicle had moved and collided with STH 75384. Total 4 vehicles involved in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Singapore 415933

Reporting Centre
Name: Tel: 67416601
Fax: 67492305
Email: vac@singnet.com.sg



SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4 #03-01
Vicom Inspection Centre
Singapore 415933
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 19-Mar-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLB6382E
ADDRESS	:	MODEL	: HONDA STREAM
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUEST BY / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER	1	\$ 758.60	\$ 758.60
2	FRONT BUMPER REINFORCEMENT	1	\$ 301.20	\$ 301.20
3	FRONT BUMPER LOWER GRILLE	1	\$ 178.10	\$ 178.10
4	FRONT BUMPER FOG LAMP GARNISH	2	\$ 180.60	\$ 361.20
5	FRONT BUMPER SIDE RETAINER	2	\$ 53.00	\$ 106.00
6	FRONT GRILLE	1	\$ 449.70	\$ 449.70
7	FRONT GRILLE MOULDING	1	\$ 275.10	\$ 275.10
8	FRONT GRILLE EMBLEM	1	\$ 155.20	\$ 155.20
9	BONNET	1	\$ 950.60	\$ 950.60
10	BONNET LOCK	1	\$ 198.40	\$ 198.40
11	BONNET INSULATOR	1	\$ 124.80	\$ 124.80
12	BONNET STOPPER	2	\$ 24.00	\$ 48.00
13	BONNET HINGE	2	\$ 64.30	\$ 128.60
14	BONNET SEAL	1	\$ 98.40	\$ 98.40
15	BONNET RUBBER	1	\$ 18.00	\$ 18.00
16	ROD HOLDER	1	\$ 11.50	\$ 11.50

de 598
BT 220.20
de
X nh.
X nh.
210.30
out 245.70.
X nh.
68
Ry
Ry
X nh
X nh
Ry
X nh
X nh
X nh

17	WIPER MOTOR TOP COWLING	1	\$ 593.40	\$ 593.40	X NH
18	FRONT FENDER COWLING #82.70 each.	2	\$ 156.00	\$ 312.00	X NH 165.40
19	FRONT FENDER TOP GARNISH	2	\$ 98.60	\$ 197.20	X NH
20	HORN	2	\$ 88.70	\$ 177.40	X NH
21	HEADLAMP	2	\$ 76 888.70	\$ 76 1,694.40	LH-RH, RH-X NH
22	HEADLAMP LOWER BRACKET	2	\$ 74.30	\$ 148.60	LH-RH, RH-X NH
23	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 235.20	\$ 88.60 235.20	X de 88
24	FRONT SUPPORT PANEL	1	\$ 520.00	\$ 520.00	X de
25	AMBIENT SENSOR	1	\$ 135.30	\$ 135.30	X NH
26	AMBIENT SENSOR BRACKET	1	\$ 35.60	\$ 35.60	X NH
27	A/C CONDENSOR	1	\$ 894.80	\$ 794.50 894.80	X NH
28	A/C CONDENSOR BRACKET	2	\$ 86.90	\$ 173.80	X de
29	A/C CONDENSOR LOWER MOUNTING	2	\$ 28.50	\$ 57.00	X NH
30	AIR CON SUCTION PIPE	1	\$ 184.30	\$ 184.30	X } X NH
31	AIR CON DISCHARGE PIPE	1	\$ 164.60	\$ 164.60	X }
32	AIR CON RECEIVER PIPE	1	\$ 135.60	\$ 135.60	X }
33	RADIATOR	1	\$ 1,425.80	\$ 1284.20 1,425.80	X ? NH
34	RADIATOR BRACKET	2	\$ 45.00	\$ 90.00	X }
35	RADIATOR LOWER MOUNTING	2	\$ 28.50	\$ 57.00	X }
36	RADIATOR FAN MOTOR	1	\$ 354.20	\$ 354.20	X }
37	RADIATOR FAN BLADE	1	\$ 211.60	\$ 211.60	X }
38	RADIATOR FAN COWLING	1	\$ 296.10	\$ 48.70 296.10	X NH
39	RADIATOR UPPER HOSE	1	\$ 45.30	\$ 45.30	X }
40	RADIATOR LOWER HOSE	1	\$ 57.00	\$ 57.00	X }
41	RADIATOR RESERVE TANK	1	\$ 145.20	\$ 145.20	X }
42	EXHAUST MANIFOLD HEAT SHIELD	1	\$ 164.40	\$ 164.40	7X NH
43	RESONATOR CHAMBER	1	\$ 204.80	\$ 204.80	de
44	REAR BUMPER	1	\$ 645.30	\$ 645.30	de
45	REAR BUMPER LOWER BRACKET	2	\$ 70.40	\$ 140.80	de
46	REAR BUMPER SIDE RETAINER	2	\$ 43.80	\$ 87.60	de
47	REAR BUMPER TOWING COVER	1	\$ 38.20	\$ 38.20	de
48	TAILGATE	1	\$ 1,227.50	\$ 903.20 1,227.50	de
49	TAILGATE DAMPER	2	\$ 115.60	\$ 231.20	X NH
50	TAILGATE OUTER GARNISH	1	\$ 347.60	\$ 189 347.60	de
51	TAILGATE INNER TRIM BOARD	1	\$ 456.30	\$ 248.50 456.30	de 2
52	TAILGATE INNER TRIM HANDLE	1	\$ 28.60	\$ 28.60	de
53	TAILGATE EMBLEM	1	\$ 64.70	\$ 64.70	de
54	TAILGATE EMBLEM "STREAM"	1	\$ 69.80	\$ 69.80	de

145.50

55	TAILGATE INNER LOCK	1	\$ 385.90	\$ 385.90	dd
56	TAILGATE STRIKER	1	\$ 37.00	\$ 37.00	bt
57	TAILGATE WEATHERSTRIP	1	\$ 185.40	\$ 185.40	ent
58	TAILGATE STOPPER	2	\$ 18.00	\$ 36.00	ue
59	TAILGATE WINDSCREEN RUBBER MOULDING	1	\$ 228.30	\$ 228.30	ue
60	REAR NUMBER PLATE LAMP	2	\$ 194.20	\$ 388.40	xnn
61	TAILLAMP	2	\$ ^{348.30} 667.40	\$ ^{678.60} 1,334.80	xew
62	TAILLAMP SIDE SKRU COVER	1	\$ 25.00	\$ 25.00	xnn
63	REAR FENDER SIDE INNER TRIM	2	\$ ^{312.50} 597.60	\$ ⁶²⁵ 1,195.20	xnn
64	REAR END PANEL	1	\$ 320.80	\$ 320.80	bt
65	REAR FLOOR PANEL	1	\$ 1,120.00	\$ 1,120.00	Rx
66	REAR END PANEL CROSSMEMBER	1	\$ 343.60	\$ 343.60	Rx bt
67	REAR END PANEL SIDE EXTENSION	2	\$ 265.00	\$ 530.00	Rx
68	REAR END PANEL TOP GARNISH	1	\$ 267.80	\$ ^{116.70} 267.80	de
69	REAR END PANEL CENTER GARNISH	1	\$ 125.60	\$ 125.60	xnn
70	REAR FLOOR PANEL TOP BOARD	2	\$ 348.80	\$ ^{310.50} 697.60	xde
71	TOOL COMPARTMENT LINING	1	\$ 295.20	\$ 295.20	de
72	REAR SPARE TYRE CARRIER	1	\$ 347.00	\$ ^{197.50} 347.00	bt
73	REAR SPARE TYRE CARRIER BRACKET	1	\$ 321.00	\$ ^{121.60} 321.00	bt
74	REAR SPARE TYRE BOLT	1	\$ 74.00	\$ 74.00	bt
75	REAR CHASSIS MEMBER RH	1	\$ 879.40	\$ 879.40	Rx
76	EXHAUST SILENCER	1	\$ 485.00	\$ 485.00	bt
77	EXHAUST SILENCER MOUNTING	2	\$ 32.00	\$ 64.00	de
78	EXHAUST SILENCER HEAT SHIELD	1	\$ 93.70	\$ 93.70	xnn
79	EXHAUST CENTER PIPE	1	\$ 1,276.40	\$ 1,276.40	Rx

TOTAL PRICE	\$ 27,265.70
LESS 20%	\$ 5,453.14
SUB TOTAL PRICE	\$ 21,812.56

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE	1	\$ 30.00	\$ 30.00	bt
2	FRONT BUMPER CLIP SET	1	\$ 65.00	\$ ³⁰ 65.00	ue
3	FRONT LOWER GRILLE CLIP SET	1	\$ 30.00	\$ ²⁰ 30.00	ue
4	BONNET INSULATOR CLIP SET	1	\$ 52.00	\$ 52.00	xnn
5	BONNET LABEL	3	\$ 15.00	\$ 45.00	xnn
6	FRONT GRILLE CLIP SET	1	\$ 26.00	\$ 26.00	ue
7	FRONT SUPPORT PANEL GARNISH CLIP SET	1	\$ 48.00	\$ ²⁰ 48.00	ue
8	FRONT FENDER INNER SHIELD CLIP SET	1	\$ 74.00	\$ ³⁰ 74.00	ue

9	FRONT FENDER TOP GARNISH CLIP SET	1	\$ 28.00	\$ 28.00	x n7
10	RADIATOR COOLANT	3	\$ 25.00	\$ 75.00	x phupam
11	REVERSE SENSOR (4PCS)	1	\$ 300.00	\$ 300.00	200 n7 ✓
12	REAR NUMBER PLATE	1	\$ 30.00	\$ 30.00	bt ✓
13	REAR BUMPER CLIP SET	1	\$ 52.00	\$ 52.00	n7 ✓
14	TAILLAMP COVER GARNISH BOLT SET	1	\$ 20.00	\$ 20.00	x n7
15	REAR FENDER INNER TRIM CLIP SET	1	\$ 90.00	\$ 90.00	x n7 ✓
16	REAR END PANEL TOP GARNISH CLIP SET	1	\$ 25.00	\$ 25.00	n7 ✓
17	TAILGATE SEALANT	1	\$ 80.00	\$ 80.00	40 n7 ✓
18	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	n7 ✓
19	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	n7 ✓
20	REAR END PANEL SEALANT	1	\$ 80.00	\$ 80.00	40 n7 ✓
21	REAR FLOOR PANEL SEALANT	1	\$ 80.00	\$ 80.00	x n7 40
22	REAR FLOOR PANEL INSULATOR	1	\$ 300.00	\$ 300.00	100 n7 ✓
23	REAR CHASSIS SEALANT	1	\$ 80.00	\$ 80.00	x n7
24	SPARE TYRE	1	\$ 200.00	\$ 200.00	x n7.

TOTAL \$ 1,950.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE DAMAGE PARTS.	\$ 1,400.00	400 1200 700	
2	TO SPRAY PAINT AFFECTED AREA.	\$ 1,400.00	400 1200 600	
3	TO APPLY TUFF COAT.	\$ 150.00	80 30	
4	FOCUS AND ADJUST FRONT LIGHTING MECHANISM.	\$ 80.00	20	
5	REMOVE AND RENEW AIRCON CONDENSOR AND RE-CHARGE AIRCON GAS.	\$ 180.00	1 100	
6	REMOVE AND RENEW RADIATOR AND CONDUCT PRESSURE TEST.	\$ 150.00	1 60	
7	FRONT CHASSIS ALIGNMENT.	\$ 250.00	x n7.	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, REMOVE AND REPLACE DAMAGE PARTS.	\$ 2,400.00	1200 1000	
2	TO SPRAY PAINT AFFECTED AREA.	\$ 1,800.00	900	
3	TO APPLY TUFF COAT.	\$ 300.00	60.	
4	PERFORM REAR LIGHTING WIRING AND BULB CHECK.	\$ 80.00	30	
5	RENEW REAR FLOOR INSULATOR.	\$ 80.00	40.	
6	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.	\$ 150.00	50	
7	REMOVE AND RENEW REVERSE SENSOR AND DISTANCE SETTING.	\$ 80.00	30	
8	REAR CHASSIS ALIGNMENT.	\$ 250.00	200X	nm.
9	TRANSFER TAILGATE MECHANISM.	\$ 200.00	60.	
10	CONDUCT WATER LEAKAGE TEST.	\$ 120.00	30.	
12	REMOVE AND RENEW REAR EXHAUST PIPE SYSTEM.	\$ 150.00	80.	
13	REMOVE AND REFIX TAILGATE WINDSCREEN.	\$ 120.00	4 ✓	
14	RESET ENGINE LIGHT.	\$ 180.00	100.	

TOTAL \$ 9,520.00

ESTIMATE REPORT

TOTAL PARTS COST
TOTAL LABOUR COST
TOTAL REPAIR COST

APPROVED DETAILS

\$ 23,762.56
\$ LKK Aug 9, 520.00
\$ the Rep 33,282.55

- hence notify the Rep the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Tanphuk 9749 5749
Lumpsum
Resurvey after repair
To check repair limit.
23/3/18 @ 1745
12 days
sur@lkkauto.com
US\$ 98500

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2018		22 Mar 2018 16:14 Edit Adj Rpt	S\$8,500.00 Edit Estimates	S\$8,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOO KWONG WENG, ID: S6801067E								
Main Claimant:	LEOW SIEW MUI, ID: S1567647G								
Vehicle Reg. No.:	SLB6382E	Date of Loss:	17/03/2018 11:00 - :59 [133 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01484C02	Policy/Cover Note No.:	DMPCSN3079211701 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKV2577T	Policy No. (Claimant):	A80453684 QMX						
		Excess:	S\$0.00						
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/04/2018]								
Driver/Custodian (Insured):	KOO KWONG WENG (50 / Male), NRIC: S6801067E								
Adj Asg. Remarks:	NO EST, ASSIGN XING QUO QIANG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB6382E (SNM18D01484C02)

[SKV2577T]

TP

LEOW SIEW MUI

Mar 17 2018 11:00AM

[KOO KWONG WENG]

SK Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/03/18 10:34	Accident Statement	 Load HTM	☒
Photos/Images			3 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/03/18 10:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	19/03/18 10:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	19/03/18 10:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	19/03/18 10:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	19/03/18 10:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	19/03/18 10:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	19/03/18 10:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/19 11:04	Odometer Reading	 Load JPG	☒
2	23/01/19 11:04	Chassis Number	 Load JPG	☒
3	23/01/19 11:04	General View	 Load JPG	☒
4	23/01/19 11:04	General View	 Load JPG	☒
5	23/01/19 11:04	General View	 Load JPG	☒
6	23/01/19 11:04	General View	 Load JPG	☒
7	23/01/19 11:04	General View	 Load JPG	☒
8	23/01/19 11:04	General View	 Load JPG	☒
9	23/01/19 11:04	General View	 Load JPG	☒
10	23/01/19 11:04	General View	 Load JPG	☒
11	23/01/19 11:04	General View	 Load JPG	☒
12	23/01/19 11:04	General View	 Load JPG	☒
13	23/01/19 11:04	General View	 Load JPG	☒
14	23/01/19 11:04	General View	 Load JPG	☒
15	23/01/19 11:04	General View	 Load JPG	☒
16	23/01/19 11:04	General View	 Load JPG	☒
17	23/01/19 11:04	General View	 Load JPG	☒
18	23/01/19 11:04	General View	 Load JPG	☒
19	23/01/19 11:04	General View	 Load JPG	☒
20	23/01/19 11:04	General View	 Load JPG	☒
21	23/01/19 11:04	General View	 Load JPG	☒
22	23/01/19 11:04	General View	 Load JPG	☒
23	23/01/19 11:04	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
24	23/01/19 11:04	General View	 Load JPG	☒
25	23/01/19 11:04	General View	 Load JPG	☒
26	23/01/19 11:04	General View	 Load JPG	☒
27	23/01/19 11:04	General View	 Load JPG	☒
28	23/01/19 11:04	General View	 Load JPG	☒
29	23/01/19 11:04	General View	 Load JPG	☒
30	23/01/19 11:04	General View	 Load JPG	☒
31	23/01/19 11:04	General View	 Load JPG	☒
32	23/01/19 11:04	General View	 Load JPG	☒
33	23/01/19 11:04	General View	 Load JPG	☒
34	23/01/19 11:04	General View	 Load JPG	☒
35	23/01/19 11:04	General View	 Load JPG	☒
36	23/01/19 11:04	General View	 Load JPG	☒
37	23/01/19 11:04	General View	 Load JPG	☒
38	23/01/19 11:04	General View	 Load JPG	☒
39	23/01/19 11:04	General View	 Load JPG	☒
40	23/01/19 11:04	General View	 Load JPG	☒
41	23/01/19 11:04	General View	 Load JPG	☒
42	23/01/19 11:04	General View	 Load JPG	☒
43	23/01/19 11:04	General View	 Load JPG	☒
44	23/01/19 11:04	General View	 Load JPG	☒
45	23/01/19 11:04	General View	 Load JPG	☒
46	23/01/19 11:04	General View	 Load JPG	☒
47	23/01/19 11:04	General View	 Load JPG	☒
48	23/01/19 11:04	General View	 Load JPG	☒
49	23/01/19 11:04	General View	 Load JPG	☒
50	23/01/19 11:04	General View	 Load JPG	☒
51	23/01/19 11:04	General View	 Load JPG	☒
52	23/01/19 11:04	General View	 Load JPG	☒
53	23/01/19 11:04	General View	 Load JPG	☒
54	23/01/19 11:04	General View	 Load JPG	☒
55	23/01/19 11:04	General View	 Load JPG	☒
56	23/01/19 11:04	General View	 Load JPG	☒
57	23/01/19 11:04	General View	 Load JPG	☒
58	23/01/19 11:04	General View	 Load JPG	☒
59	23/01/19 11:04	General View	 Load JPG	☒
60	23/01/19 11:04	General View	 Load JPG	☒
61	23/01/19 11:04	General View	 Load JPG	☒
62	23/01/19 11:04	General View	 Load JPG	☒
63	23/01/19 11:04	General View	 Load JPG	☒
64	23/01/19 11:04	General View	 Load JPG	☒
65	23/01/19 11:04	General View	 Load JPG	☒
66	23/01/19 11:04	General View	 Load JPG	☒
67	23/01/19 11:04	General View	 Load JPG	☒
68	23/01/19 11:04	General View	 Load JPG	☒
69	23/01/19 11:04	General View	 Load JPG	☒
70	23/01/19 11:04	General View	 Load JPG	☒
71	23/01/19 11:04	General View	 Load JPG	☒
72	23/01/19 11:04	General View	 Load JPG	☒
73	23/01/19 11:04	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
74	23/01/19 11:04	General View	 Load JPG	☒
75	23/01/19 11:04	General View	 Load JPG	☒
76	23/01/19 11:04	General View	 Load JPG	☒
77	23/01/19 11:04	General View	 Load JPG	☒
78	23/01/19 11:04	General View	 Load JPG	☒
79	23/01/19 11:04	General View	 Load JPG	☒
80	23/01/19 11:04	General View	 Load JPG	☒
81	23/01/19 11:04	General View	 Load JPG	☒
82	23/01/19 11:04	General View	 Load JPG	☒
83	23/01/19 11:04	General View	 Load JPG	☒
84	23/01/19 11:04	General View	 Load JPG	☒
85	23/01/19 11:04	General View	 Load JPG	☒
86	23/01/19 11:04	General View	 Load JPG	☒
87	23/01/19 11:04	General View	 Load JPG	☒
88	23/01/19 11:04	General View	 Load JPG	☒
89	23/01/19 11:04	General View	 Load JPG	☒
90	23/01/19 11:04	General View	 Load JPG	☒
91	23/01/19 11:04	General View	 Load JPG	☒
92	23/01/19 11:04	General View	 Load JPG	☒
93	23/01/19 11:04	General View	 Load JPG	☒
94	23/01/19 11:04	General View	 Load JPG	☒
95	23/01/19 11:04	General View	 Load JPG	☒
96	23/01/19 11:04	General View	 Load JPG	☒
97	23/01/19 11:04	General View	 Load JPG	☒
98	23/01/19 11:04	General View	 Load JPG	☒
99	23/01/19 11:04	General View	 Load JPG	☒
100	23/01/19 11:04	General View	 Load JPG	☒
101	23/01/19 11:04	General View	 Load JPG	☒
102	23/01/19 11:04	General View	 Load JPG	☒
103	23/01/19 11:04	General View	 Load JPG	☒
104	23/01/19 11:04	General View	 Load JPG	☒
105	23/01/19 11:04	General View	 Load JPG	☒
106	23/01/19 11:04	General View	 Load JPG	☒
107	23/01/19 11:04	General View	 Load JPG	☒
108	23/01/19 11:04	General View	 Load JPG	☒
109	23/01/19 11:04	General View	 Load JPG	☒
110	23/01/19 11:04	General View	 Load JPG	☒
111	23/01/19 11:04	General View	 Load JPG	☒
112	23/01/19 11:04	General View	 Load JPG	☒
113	23/01/19 11:04	General View	 Load JPG	☒
114	23/01/19 11:04	General View	 Load JPG	☒
115	23/01/19 11:04	General View	 Load JPG	☒
116	23/01/19 11:04	General View	 Load JPG	☒
117	23/01/19 11:04	General View	 Load JPG	☒
118	23/01/19 11:04	General View	 Load JPG	☒
119	23/01/19 11:04	General View	 Load JPG	☒
120	23/01/19 11:04	General View	 Load JPG	☒
121	23/01/19 11:04	General View	 Load JPG	☒
122	23/01/19 11:04	General View	 Load JPG	☒
123	23/01/19 11:04	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
124	23/01/19 11:04	General View	 Load JPG	☒
125	23/01/19 11:04	General View	 Load JPG	☒
126	23/01/19 11:04	General View	 Load JPG	☒
127	23/01/19 11:04	General View	 Load JPG	☒
128	23/01/19 11:04	General View	 Load JPG	☒
129	23/01/19 11:04	General View	 Load JPG	☒
130	23/01/19 11:04	General View	 Load JPG	☒
131	23/01/19 11:04	General View	 Load JPG	☒
132	23/01/19 11:04	General View	 Load JPG	☒
133	23/01/19 11:04	General View	 Load JPG	☒
134	23/01/19 11:04	General View	 Load JPG	☒
135	23/01/19 11:04	General View	 Load JPG	☒
136	23/01/19 11:04	General View	 Load JPG	☒
137	23/01/19 11:04	General View	 Load JPG	☒
138	23/01/19 11:04	General View	 Load JPG	☒
139	23/01/19 11:04	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/03/18 16:13	PRS	 Load PDF	
2	22/03/18 16:13	OI GIA REPORT	 Load PDF	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/03/18 10:34	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	19/03/18 10:34	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/03/18 10:34	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/03/18 10:26	Accident Photo	 Load JPG	☒
2	19/03/18 10:26	Accident Photo	 Load JPG	☒
3	19/03/18 10:26	Accident Photo	 Load JPG	☒
4	19/03/18 10:26	Accident Photo	 Load JPG	☒
5	19/03/18 10:26	Accident Photo	 Load JPG	☒
6	19/03/18 10:26	Accident Photo	 Load JPG	☒
7	19/03/18 10:26	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/03/18 10:34	Accident Sketch Plan	 Load TIF	
2	19/03/18 10:34	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118005453/T1QD3E2

Date: 24/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3079211701
Claimant Vehicle No:	SLB6382E	Insured Vehicle No:	SKV2577T
Date of Loss:	17/03/2018	Nature of Claim:	TP
		Claim No:	SNM18D01484C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB6382E	Engine No:	R18A1715343
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	RN61013593
Reg. Date:	02/02/2007 (Man. Year: 2006)	Odometer:	153622 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,762.56	9,822.44	13,940.12	58.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,520.00	4,220.00	5,300.00	55.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,282.56	14,042.44	19,240.12	57.81
Approved Total (Overridden) (S\$)		8,500.00		
(S\$)	33,282.56	8,500.00	24,782.56	74.46
+ GST 7.00/7.00% (S\$)	2,329.78	595.00	1,734.78	74.46
Nett Amount (S\$)	35,612.34	9,095.00	26,517.34	74.46

INSPECTION

Date of Assignment: 22/03/2018

Date Inspected: 23/03/2018 Inspected At:

SK Automobile Pte Ltd (HQ)
23 Kaki Bukit Avenue 4, #03-01 Vicom
Inspection Centre
Singapore 415933

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2019)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB6382E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	758.60 FL	*598.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	301.20 FL	*220.20 FL
3	1		*FRONT BUMPER LOWER GRILLE	Deformed	178.10 FL	*178.10 FL
4	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	361.20 FL	*- FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	106.00 FL	*106.00 FL
6	1		*FRONT GRILLE	Cracked	449.70 FL	*210.30 FL
7	1		*FRONT GRILLE MOULDING	Cut	275.10 FL	*245.70 FL
8	1		*FRONT GRILLE EMBLEM	Necessary	155.20 FL	*68.00 FL
9	1		*BONNET	Repair	950.60 FL	*- FL
10	1		*BONNET LOCK	Repair	198.40 FL	*- FL
11	1		*BONNET INSULATOR	Not Necessary	124.80 FL	*- FL
12	2		*BONNET STOPPER	Not Necessary	48.00 FL	*- FL
13	2		*BONNET HINGE	Repair	128.60 FL	*- FL
14	1		*BONNET SEAL	Not Necessary	98.40 FL	*- FL
15	1		*BONNET RUBBER	Not Necessary	18.00 FL	*- FL
16	1		*ROD HOLDER	Not Necessary	11.50 FL	*- FL
17	1		*WIPER MOTOR TOP COWLING	Not Necessary	593.40 FL	*- FL
18	2		*FRONT FENDER COWLING	Torn	312.00 FL	*165.40 FL
19	2		*FRONT FENDER TOP GARNISH	Not Necessary	197.20 FL	*- FL
20	2		*HORN	Not Necessary	177.40 FL	*- FL
21	1		*HEADLAMP	N/S Cut / O/S Not Necessary	1,691.40 FL	*760.00 FL
22	1		*HEADLAMP LOWER BRACKET	N/SNecessary/O/SNot Necessary	148.60 FL	*74.30 FL
23	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	235.20 FL	*88.60 FL
24	1		*FRONT SUPPORT PANEL	Bent	520.00 FL	*520.00 FL
25	1		*AMBIENT SENSOR	Not Necessary	135.30 FL	*- FL
26	1		*AMBIENT SENSOR BRACKET	Not Necessary	35.60 FL	*- FL
27	1		*A/C CONDENSOR	Dented	894.80 FL	*794.50 FL
28	2		*A/C CONDENSOR BRACKET	Bent	173.80 FL	*173.80 FL
29	2		*A/C CONDENSOR LOWER MOUNTING	Not Necessary	57.00 FL	*- FL
30	1		*AIR CON SUCTION PIPE	Not Necessary	184.30 FL	*- FL
31	1		*AIR CON DISCHARGE PIPE	Not Necessary	164.60 FL	*- FL
32	1		*AIR CON RECEIVER PIPE	Not Necessary	135.60 FL	*- FL
33	1		*RADIATOR	Not Necessary	1,425.80 FL	*- FL
34	2		*RADIATOR BRACKET	Not Necessary	90.00 FL	*- FL
35	2		*RADIATOR LOWER MOUNTING	Not Necessary	57.00 FL	*- FL
36	1		*RADIATOR FAN MOTOR	Not Necessary	354.20 FL	*- FL
37	1		*RADIATOR FAN BLADE	Not Necessary	211.60 FL	*- FL
38	1		*RADIATOR FAN COWLING	Cracked	296.10 FL	*98.70 FL
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*RADIATOR UPPER HOSE	Not Necessary	45.30 FL	*- FL
40	1		*RADIATOR LOWER HOSE	Not Necessary	57.00 FL	*- FL
41	1		*RADIATOR RESERVE TANK	Not Necessary	145.20 FL	*- FL
42	1		*EXHAUST MANIFOLD HEAT SHIELD	Not Necessary	164.40 FL	*- FL
43	1		*RESONATOR CHAMBER	Deformed	204.80 FL	*204.80 FL
44	1		*REAR BUMPER	Deformed	645.30 FL	*645.30 FL
45	2		*REAR BUMPER LOWER BRACKET	Necessary	140.80 FL	*140.80 FL
46	2		*REAR BUMPER SIDE RETAINER	Necessary	87.60 FL	*87.60 FL
47	1		*REAR BUMPER TOWING COVER	Missing	38.20 FL	*38.20 FL
48	1		*TAILGATE	Bent	1,227.50 FL	*903.20 FL
49	2		*TAILGATE DAMPER	Not Necessary	231.20 FL	*- FL
50	1		*TAILGATE OUTER GARNISH	Cracked	347.60 FL	*189.00 FL
51	1		*TAILGATE INNER TRIM BOARD	Deformed	456.30 FL	*248.50 FL
52	1		*TAILGATE INNER TRIM HANDLE	Missing	28.60 FL	*28.60 FL
53	1		*TAILGATE EMBLEM	Necessary	64.70 FL	*64.70 FL
54	1		*TAILGATE EMBLEM STREAM	Necessary	69.80 FL	*69.80 FL
55	1		*TAILGATE INNER LOCK	Dented	385.90 FL	*145.50 FL
56	1		*TAILGATE STRIKER	Bent	37.00 FL	*37.00 FL
57	1		*TAILGATE WEATHERSTRIP	Cut	185.40 FL	*185.40 FL
58	2		*TAILGATE STOPPER	Necessary	36.00 FL	*36.00 FL
59	1		*TAILGATE WINDSCREEN RUBBER MOULDING	Necessary	228.30 FL	*228.30 FL
60	2		*REAR NUMBER PLATE LAMP	Not Necessary	388.40 FL	*- FL
61	2		*TAILLAMP	Cracked	1,334.80 FL	*678.60 FL
62	1		*TAILLAMP SIDE SKRU COVER	Not Necessary	25.00 FL	*- FL
63	2		*REAR FENDER SIDE INNER TRIM	Cracked	1,195.20 FL	*625.00 FL
64	1		*REAR END PANEL	Bent	320.80 FL	*320.80 FL
65	1		*REAR FLOOR PANEL	Repair	1,120.00 FL	*- FL
66	1		*REAR END PANEL CROSSMEMBER	Bent	343.60 FL	*343.60 FL
67	2		*REAR END PANEL SIDE EXTENSION	Repair	530.00 FL	*- FL
68	1		*REAR END PANEL TOP GARNISH	Deformed	267.80 FL	*116.70 FL
69	1		*REAR END PANEL CENTER GARNISH	Not Necessary	125.60 FL	*- FL
70	2		*REAR FLOOR PANEL TOP BOARD	Deformed	697.60 FL	*310.50 FL
71	1		*TOOL COMPARTMENT LINING	Deformed	295.20 FL	*295.20 FL
72	1		*REAR SPARE TYRE CARRIER	Bent	347.00 FL	*197.50 FL
73	1		*REAR SPARE TYRE CARRIER BRACKET	Bent	321.00 FL	*121.60 FL
74	1		*REAR SPARE TYRE BOLT	Bent	74.00 FL	*74.00 FL
75	1		*REAR CHASSIS MEMBER RH	Repair	879.40 FL	*- FL
76	1		*EXHAUST SILENCER	Bent	485.00 FL	*485.00 FL
77	2		*EXHAUST SILENCER MOUNTING	Deformed	64.00 FL	*64.00 FL
78	1		*EXHAUST SILENCER HEAT SHIELD	Not Necessary	93.70 FL	*- FL
79	1		*EXHAUST CENTER PIPE	Repair	1,276.40 FL	*- FL
80	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
81	1		*SET FRONT BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
82	1		*SET FRONT LOWER GRILLE CLIP	Necessary	30.00 FS	*20.00 FS
83	1		*SET BONNET INSULATOR CLIP	Not Necessary	52.00 FS	*- FS
84	3		*BONNET LABEL	Not Necessary	45.00 FS	*- FS
85	1		*SET FRONT GRILLE CLIP	Necessary	26.00 FS	*26.00 FS
86	1		*SET FRONT SUPPORT PANEL GARNISH CLIP	Necessary	48.00 FS	*20.00 FS
87	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	74.00 FS	*30.00 FS
88	1		*SET FRONT FENDER TOP GARNISH CLIP	Not Necessary	28.00 FS	*- FS
89	3		*RADIATOR COOLANT	Not Necessary	75.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
90	4		*REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
91	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
92	1		*SET REAR BUMPER CLIP	Necessary	52.00 FS	*52.00 FS
93	1		*SET TAILLAMP COVER GARNISH BOLT	Not Necessary	20.00 FS	*- FS
94	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	90.00 FS	*50.00 FS
95	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	25.00 FS	*25.00 FS
96	1		*TAILGATE SEALANT	Necessary	80.00 FS	*40.00 FS
97	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
98	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*60.00 FS
99	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
100	1		*REAR FLOOR PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
101	1		*REAR FLOOR PANEL INSULATOR	Necessary	300.00 FS	*100.00 FS
102	1		*REAR CHASSIS SEALANT	Not Necessary	80.00 FS	*- FS
103	1		*SPARE TYRE	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 29,215.70 12,059.80
 - List Item Discount on L Items 20.00/20.00% (S\$) 5,453.14 2,237.36

Total Parts (S\$) 23,762.56 9,822.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT, REMOVE AND REPLACE DAMAGE PARTS	New	1,400.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	600.00
3	TO APPLY TUFF COAT	New	150.00	30.00
4	FOCUS AND ADJUST FRONT LIGHTING MECHANISM	New	80.00	30.00
5	REMOVE AND RENEW AIRCON CONDENSOR AND RE-CHARGE AIRCON GAS	New	180.00	100.00
6	REMOVE AND RENEW RADIATOR AND CONDUCT PRESSURE TEST	New	150.00	60.00
7	FRONT CHASSIS ALIGNMENT	New	250.00	0.00
8	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	900.00
9	TO APPLY TUFF COAT	New	300.00	60.00
10	PERFORM REAR LIGHTING WIRING AND BULB CHECK	New	80.00	30.00
11	RENEW REAR FLOOR INSULATOR	New	80.00	40.00
12	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR	New	150.00	50.00
13	REMOVE AND RENEW REVERSE SENSOR AND DISTANCE SETTING	New	80.00	30.00
14	REAR CHASSIS ALIGNMENT	New	250.00	0.00
15	TRANFER TAILGATE MECHANISM	New	200.00	60.00
16	CONDUCT WATER LEAKAGE TEST	New	120.00	30.00
17	REMOVE AND RENEW REAR EXHAUST PIPE SYSTEM	New	150.00	80.00
18	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
19	RESET ENGINE LIGHT	New	180.00	100.00
20	TO PANEL BEAT, REMOVE AND REPLACE DAMAGE PARTS	New	2,400.00	1,200.00
Gross Labour Cost (S\$)			9,520.00	4,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >