



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## OPINION ON REPAIR COST FOR VEHICLE NO. FBD 5704A

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	FRONT HEAD COWLING	CUT	168.00
1	HEAD LAMP	CRACKED	235.00
1	HEAD COWLING BRACKET	SERVICEABLE	-
1	COWLING FRONT V GUARD	SERVICEABLE	-
1	HANDLE BAR	BENT	95.00
1	SET BALANCER	SERVICEABLE	-
1	SET MIRROR	MISSING	120.00
1	CLUTCH LEVER	CUT	75.00
1	BRAKE LEVER HOLDER BRACKET	SERVICEABLE	-
1	MUDGUARD	CUT	135.00
1	SET FORK TUBE	BENT	480.00
1	FORK UNDER BRACKET	BENT	169.00
1	FORK BRAKE DISC	SERVICEABLE	-
1	FRONT RH SIGNAL	DISTORTED	79.00
1	RADIATOR UNIT	SERVICEABLE	-
1	SET RIM EXCEL	SERVICEABLE	-
1	LEG SHIELD	SERVICEABLE	-
1	CENTRE GARNISH COVER	SERVICEABLE	-
2	SIDE FAIRING @ \$135.00	CUT	270.00
1	FRONT BASKET	CRACKED	85.00
1	RH LIGHT CONTROL SWITCH	SERVICEABLE	-
1	FORK OIL SEAL	NECESSARY	65.00
1	STEERING CONE BEARING	NECESSARY	135.00
1	FRONT WHEEL SHAFT	SERVICEABLE	-
1	SIDE COVER	CUT	55.00
1	FRONT FOOT REST	BENT	65.00
1	REAR FAIRING	CUT	50.70
	LESS 10% DISCOUNT		-228.17
			2,053.53
	<b><u>SPECIAL NETT ITEMS</u></b>		
1	EMBLEM YAMAHA (SN)	NOT NECESSARY	-
1	BODY DECAL STICKER (SN)	CUT	85.00

Report Ref No. CS3/SPF18005466/Grd3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Recommended (\$)
1	WHEEL RIM SPORKY & RE-STRING (SN)	NOT NECESSARY	-
			85.00
	<b>LABOUR</b>		
	TOWING FEES.	NOT NECESSARY	-
	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC.		250.00
	REMOVE & REPLACE FORK ASSY, TOP UP FORK OIL, REPLACE FRONT RIM DISC.	NOT NECESSARY	-
	ALIGN BODY ALIGNMENT.	NOT NECESSARY	-
			250.00
<b>GRAND TOTAL</b>			<b>2,388.53</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>	<b>1,900.00</b>
---	-----------------

Report Ref No. CS3/SPF18005466/Grd3s2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,900.00 - \$2,400.00**

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.