

ASS. REC. BY:

REP: CS/FCI18005476/Atd3n2

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

20-1/03/2018 @ 3:13pm

Estimated Cost:

Bill to:

OD (FP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 8681 Y

Insured:

SHC 2038T

at Workshop n/s

WTS Automotive

Tel:

68449449 / 87878743

of

17 kaki Bkt Rd 4 #01-58

Policy No:

Claim No:

D18002158MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/03/2018

23/8/18 @ 3pm - 3:15pm

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(wp)

Date/Time:

10:15am @ 2/3/18

Person Contacted:

jeffrey

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

GBB 8681 Y - CC6 / AK10018539 / Dn / f2q2

D.O.A: 9/9/200

SHC 2038T-X

lump Sum \$2350 (Red: 1187.23; 33%)

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBB 8681Y. Yr Regn: 2010 / June.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna. C.C. 2982Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 280461 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35Y201C201289.Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 R15C HankookR: 155 R12C Fullen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 23/03/18.Survey held at WTS.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFront o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP - 1st Cap.

RECEIVED 06 APR 2018

Date/Time, File Pass to?

1) 6/4 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: -Add Fee: ☐ : Site Insp. (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos:

Others:

TOTAL

130

50

33

213

Report Format :

Lump Sum / I.B.I. (\$) TP
23501



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005476/Atd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2038T	Veh. Inspected	GBB 8681Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002158MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	23/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/03/2018	Inspection Date	23/03/2018	
Survey held at	WTS AUTOMOTIVE SERVICES PTE LTD 17 KAKI BUKIT ROAD 4 #01-58/59/60/61/62 BARTLEY BIZCENTRE SINGAPORE 417809			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	15-03-2018	Our Ref No. D18002158MFSH
Accident Date	14-03-2018	Claim Type. Third Party
Insured Vehicle	SHC2038T	Third Party Vehicle. GBB8681Y
Survey Location	PITSTOP@BARTLEY 17 KAKI BUKIT ROAD 4 BARTLEY BIZ CENTRE #01-58	
Contact Person.	JEFFREY HO	
Contact No.	68449449/ 0	Fax No. 68449463
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WTS AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

TP 1st Cap.
Devise

Spare Parts (Appendix A)

Vehicle No. : **GBB8681Y** Submit By : **Jeffrey Ho**
Make & Model : **Toyota - DYNA 150 MANUAL 3SEATER** Year Manufacture : **2010**
Chassis No. : **JTFAT35Y20K201289** Engine No. : **1KD2011767**

S/No.	Part Description	Qty	List Price	Disposition by Surveyor
1	Front Right Door <i>Revised</i>	1	\$1,057.92	✓
2	Front Bumper <i>Best</i>	1	\$489.50	✓
3	Front Right Door hinge <i>Best</i>	1	\$148.31	✓
4	Front Headlamp Assy - RH <i>nt</i>	1	\$688.57	✓
	<i>2384.3</i>			
	<i>1788.22</i>			
	Sub total		\$2,384.30	
	List Price less -25%		(\$596.08)	
	Total on parts		\$1,788.23	
	Special Nett Items			
1	Commerical Stickers (Wordings) <i>ne 120</i>	1	\$120.00	✓
		1		
	Total on special nett		\$120.00	
	LABOUR CHARGE			
1	To Replace / Refix Front Right Door, Bumper, Door hinge, Headlamp Assy	1	\$1,000.00	<i>500</i>
2	To Check Wiring for headlamp assy	1	\$30.00	<i>1030</i>
3	To putty / Spray paint on Front Right Door, front Bumper, Door hinge	1	\$600.00	<i>500</i>
	Total on labour		\$1,630.00	
	Total on parts		\$1,788.23	
	Total on Special Nett		\$120.00	
	Sub-Total		\$3,538.23	Before gst
	Gst		\$247.68	
	Grand Total		\$3,785.91	After Gst

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

Adrian Ling 96893735
L/s 23/03/08. total 23822
04 Rps. L/s 2350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005476/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2038T	Veh. Inspected	GBB 8681Y	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002158MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	20/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JTFAT35Y20K201289	Colour	BLUE	
Odometer	280461	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	HANKOOK	6 mm	
L/H Front Tyre	195 R15C	HANKOOK	6 mm	
R/H Rear Tyre	155 R12C	FALKEN	6 mm	
L/H Rear Tyre	155 R12C	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/03/2018	Inspection Date	23/03/2018	
Survey held at	WTS AUTOMOTIVE SERVICES PTE LTD 17 KAKI BUKIT ROAD 4 #01-58/59/60/61/62 BARTLEY BIZCENTRE SINGAPORE 417809			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 8681Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT RIGHT DOOR	DENTED	1,057.92	1,057.92
1	FRONT BUMPER	BENT	489.50	489.50
1	FRONT RIGHT DOOR HINGE	BENT	148.31	148.31
1	FROTN HEADLAMP ASSY-RH	CUT	688.57	688.57
	LESS 25% DISCOUNT		-596.08	-596.08
			1,788.22	1,788.22
	SPECIAL NETT ITEMS			
1	COMMERICAL STICKERS (WORDINGS)(SN)	NECESSARY	120.00	120.00
			120.00	120.00
	LABOUR			
	TO REPLACE/REFIX FRONT RIGHT DOOR,BUMPER,DOOR HINGE,HEADLAMP ASSY.		1,000.00	500.00
	TO CHECK WIRING FOR HEADLAMP ASSY.		30.00	30.00
	TO PUTTY/SPRAY PAINT ON FRONT RIGHT DOOR,FRONT BUMPER,DOOR HINGE.		600.00	500.00
			1,630.00	1,030.00
	GRAND TOTAL		3,538.22	2,938.22
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,350.00

Report Ref No. CS/FC18005476/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.