

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	5	HEADLAMP HIGH BEAM BULB LH	Reviewing	25	DISTORTED	
<input type="checkbox"/>	6	FOGLAMP BULB LH	Reviewing	22	DISTORTED	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	39	1			FRONT WHEELHOUSE LH (NPA)		Serviceable	Repair	0				0
	40	1			FRONT DOOR LH (NPA)		Serviceable	Repair	0				0
	41	1			HEADLAMP LOWER BRACKET			Cracked	0				0
	42	1			HEADLAMP HID BULB LH			Damaged	0				0
	43	1			AIR RESONATOR BOX ASSY			Cracked	0				0

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	1		LABOUR TO FACILITATE REPAIR.	700	0	0	Reviewing	
	2		TO RESPRAY AFFECTED AREAS.	700	0	0	Reviewing	
	3		TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.	30	0	0	Reviewing	
	4		TO REMOVE AND REFIT FRONT UNDERCARRIAGE LH.	100	0	0	Reviewing	
	5		TO REMOVE AND REFIT FRONT CROSSMEMBER.	150	0	0	Reviewing	
	6		TO CONDUCT FRONT WHEEL ALIGNMENT.	80	0	0	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC.OUNT%	SALV AGE%	PART PRICE(NET)
<input type="checkbox"/>	<input type="checkbox"/>	11	1		FOGLAMP GARNISH O/S			Serviceable	0				0
<input type="checkbox"/>	<input type="checkbox"/>	12	1		FRONT NUMBER PLATE BASE HOLDER			Serviceable	0				0
<input type="checkbox"/>	<input type="checkbox"/>	13	1		FRONT GRILLE			Cracked	0				0
<input type="checkbox"/>	<input type="checkbox"/>	14	1		FRONT GRILLE LOGO			Necessary	0				0
<input type="checkbox"/>	<input type="checkbox"/>	15	1		FRONT GRILLE BRACKET O/S			Deformed	0				0
<input type="checkbox"/>	<input type="checkbox"/>	16	1		FRONT GRILLE UPPER COVER			Serviceable	0				0
<input type="checkbox"/>	<input type="checkbox"/>	17	1		HEADLAMP LH			Cracked	0				0
<input type="checkbox"/>	<input type="checkbox"/>	18	1		FRONT FENDER LH			Buckled	0				0
<input type="checkbox"/>	<input type="checkbox"/>	19	1		FRONT FENDER BRACKET LH			Necessary	0				0
<input type="checkbox"/>	<input type="checkbox"/>	20	1		FRONT FENDER INNER SHIELD LH			Damaged	0				0
<input type="checkbox"/>	<input type="checkbox"/>	21	10		FRONT FENDER SHIELD CLIPS			Necessary	0				0
<input type="checkbox"/>	<input type="checkbox"/>	22	1		FRONT LOWER ENGINE COVER			Serviceable	0				0
<input type="checkbox"/>	<input type="checkbox"/>	23	1		FRONT FENDER QUARTER GARNISH LH			Deformed	0				0
<input type="checkbox"/>	<input type="checkbox"/>	24	1		FRONT AXLE BEAM ASSY			Bent	0				0

Detailed Assessment

Inspection Date *

03/26/2018



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/55R16

Rear Tyre Size

205/55R16

FNOL INFORMATI... BLK 140 BUKIT BATOK, ST 11 #16-45,
650140, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... 596376661

CATEGORY Make

POLICY INFORMAT... NISSAN

ASSESSMENT INFO... NISSAN

CATEGORY Model

POLICY INFORMAT... SYLPHY 1.8

ASSESSMENT INFO... SYLPHY 1.8 CVT ABS D/AIRBAG 2WD

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... MNTBAAB17Z0008056

CATEGORY Date of Birth

FNOL INFORMATI... October 26, 1996

POST SURVEY INF... mm/dd/yyyy

CATEGORY Age

FNOL INFORMATI... 21

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

Accelerated survey and authorize

Claim Handler

HO Winnie
6568804833
winnie.ho@axa.com.sg

[Messages](#)
[Invoices](#)
[History](#)
[Documents](#)

[Assessment](#)
[Metrics](#)
[Notes](#)

Additional Instructions

1) est-\$10,002 2) XS-\$2800 (basic-\$300 + young & inexp-\$2500)

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	3/27/18 5:03 PM	1967	1967	In Review	<input type="button" value="Share"/>	<input type="button" value="Clone"/>
HO Winnie	3/23/18 9:26 AM			Open	<input type="button" value="Share"/>	<input type="button" value="Clone"/>

Accelerated survey and authorize

Claim Handler

HO Winnie
6568804833
winnie.ho@axa.com.sg

Messages Invoices History Documents

Additional Instructions

1) est-\$10,002 2) XS-\$2800 (basic-\$300 + young & inexp-\$2500)

Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
Final Invoice SDQ8618D -1804OPR0244.pdf	Invoice	Repairer	ETHOZ PROTECT PTE LTD (Bukit Batok)	April 19, 2018
RESURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	April 18, 2018