

ASS. REC. BY:

REF CS/FCI18005493 / Krd3ⁿ² Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

May chua

of

FCI

Date/Time:

23/3/18 @ 3:23pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLV 4694M

Insured:

SHC 3520K

at Workshop m/s:

Hui Yang Motor

Tel:

G451 5752

of

Blk 176 Sin Ming Drive # 04-02

Policy No:

Claim No:

D18002280 MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/03/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

5:22pm @ 23/3/18

Person Contacted:

Belle

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SLV 4694M-X

SHC 3520K - CS/FCI17014606 / Sube2

D.O.A: 26/7/17

beverf thru email

Kenneth confirm L/s \$6400, 4 days

Red: \$1293.22, 66%.

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

1.31 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

27/3

Rt pass to Catherine

RECEIVED 15 MAY 20

Veh No:

SLV 4894M

Yr Regn:

12, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A)

Make:

Toy C14R

c.c.

1787

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

7529

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZYX10

2074989

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R17

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

1813118

D.O.I.

26/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 27/3

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Photos

Others

TOTAL

8x15.120

170 + 120

50

50 + 50

30

470

Report Format:

1P

Lump Sum / L.B.T. (\$

6800

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005493/Krd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3520K	Veh. Inspected	SLV 4694M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002280MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	23/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/03/2018	Inspection Date		
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002280MFSH

Our Ref: CS/FCI18005493/Krd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 4694M .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.03.2018 at the premises of M/s HUI YANG MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>18,593.22</u> .
Revised Estimate Amount	: S\$ <u>6,400.00(Lump Sum)</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at front portion.



Yours faithfully
KENNETH
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-03-2018	Our Ref No. D18002280MFSH
Accident Date	18-03-2018	Claim Type. Third Party
Insured Vehicle	SHC3520K	Third Party Vehicle. SLV4694M
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236154)



PRI Documents



Close



PRI Header Details

Claim No	D18002280MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & HUI YANG
Workshop Name	HUI YANG MOTOR PTE LTD (Contact Person : BEL)	Survey Location & Contact Details	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE Mobile: 0 , Phone: 6451 5752 , Fax: 6451 4658 EmailId: HUI_YANG_MOTOR@HOTMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3520K	TP Vehicle No	SLV4694M
PRI Recieved Date	23-03-2018 05:34:10 PM	Surveyor Appointed Date	23-03-2018 03:22:31 PM	Surveyor Accept Date	23-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	23-03-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
----------------	----------------------	-------------------------------------

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

18/03/2018

Owner: VICS AUTOMOBILE

ESTIMATE TO REPAIR TOYOTA C-HR - SLV4694M

1pc	front bonnet
1pc	front bonnet inner lock
1pc	* front centre grille base
1pc	front centre grille garnish
1pc	front centre grille "TOYOTA" logo
1pc	front centre grille top garnish
1pc	front centre grille top rubber X
1pc	* front centre grille inner PCS sensor
2pcs	front headlamp @\$2821.40
2pcs	front headlamp lower beam @\$271.75 X
1pc	front bumper
2pc	front bumper side retainer @\$133.35 X
1pc	front bumper grille
1pc	front bumper lower lid
2pcs	front bumper side garnish @\$374.45
1pc	front bumper towing cover
1pc	front bumper number plate garnish
1pc	front bumper reinforcement X
2pcs	front bumper reinforcement side bracket @\$132.10 X
1pc	* front bumper spine
1pc	front bumper lower reinforcement X
2pcs	front bumper lower reinforcement bracket @\$141.45 X
1pc	* front bumper lower spine
1pc	front support panel
1pc	* front support panel centre pillar
1pc	front air-con condenser X
1pc	front radiator X

Less 25%

remove & refix A/C condensor & radiator

remove & refix radiator

reset & reprogram PCS sensor

tuffkote

wiring

spray painting

labour charges

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved for final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

R	\$	972.55	X
R	\$	274.10	X
cm	\$	591.45	✓
Bu	\$	371.50	✓
cm	\$	691.50	✓
Bu	\$	381.90	✓
su	\$	174.45	X
sh	\$	758.25	✓
nl	\$	5,642.80	✓ + 1821.40
R	\$	543.50	X
Bu	\$	974.45	✓
su	\$	266.70	X
nl	\$	274.45	✓
R	\$	680.00	✓
su	\$	748.90	X
su	\$	43.75	X
nl	\$	271.85	✓
R	\$	581.10	X
R	\$	264.20	X
cm	\$	181.90	✓
R	\$	561.90	X
R	\$	282.90	X
cm	\$	174.45	✓
R	\$	1,218.25	X
R	\$	178.25	✓
su	\$	1,218.50	X
su	\$	1,718.80	X
		\$20,042.35	
		\$5,010.59	
		\$15,031.76	
nn	\$	250.00	X
nn	\$	180.00	X
	\$	350.00	120
nn	\$	80.00	X
	\$	160.00	201
	\$	1,000.00	5001
	\$	950.00	500
		\$18,001.76	

First copy
26/03/18
Monday

Not withain

1.2.1

Running Bk paint

112p @ 6400 4 days

18593.22

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

18/03/2018

Owner: VICS AUTOMOBILE

ESTIMATE TO REPAIR TOYOTA C-HR - SLV4694M

1pc	front bonnet
1pc	front bonnet inner lock
1pc	front centre grille base
1pc	front centre grille garnish
1pc	front centre grille "TOYOTA" logo
1pc	front centre grille top garnish
1pc	front centre grille top rubber
1pc	front centre grille inner PCS sensor
2pcs	front headlamp @\$2821.40
2pcs	front headlamp lower beam @\$271.75
1pc	front bumper
1pc	front bumper side retainer @\$133.35
1pc	front bumper grille
1pc	front bumper lower lid
2pcs	front bumper side garnish @\$374.45
1pc	front bumper towing cover
1pc	front bumper number plate garnish
1pc	front bumper reinforcement
2pcs	front bumper reinforcement side bracket @\$132.10
1pc	front bumper spone
1pc	front bumper lower reinforcement
2pcs	front bumper lower reinforcement bracket @\$141.45
1pc	front bumper lower spone
1pc	front support panel
1pc	front support panel centre pillar
1pc	front air-con condenser
1pc	front radiator

Less 25%

remove & refix A/C condensor & radiator

remove & refix radiator

reset & reprogram PCS sensor

tuffkote

wiring

spray painting

labour charges

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature:

Date:



Not Authorise
1.B.1
Recovery B & paint
4 day

R	\$	972.55	X
R	\$	274.10	X
	\$	591.45	?
nd	\$	371.50	2
CM	\$	691.50	✓
Bu	\$	381.90	✓
Sn	\$	174.45	X
	\$	758.25	?
nd	\$	5,642.80	4
	\$	543.50	?
Bu	\$	974.45	✓
Sn	\$	266.70	X
nd	\$	274.45	✓
Bu	\$	680.00	✓
Sn	\$	748.90	X
Sn	\$	43.75	X
nd	\$	271.85	✓
	\$	581.10	?
	\$	264.20	?
	\$	181.90	?
	\$	561.90	?
	\$	282.90	?
	\$	174.45	?
R	\$	1,218.25	?
	\$	178.25	?
	\$	1,218.50	?
Sn	\$	1,718.80	X
	\$	20,042.35	
	\$	5,010.59	
	\$	15,031.76	
	\$	250.00	?
nn	\$	180.00	X
	\$	350.00	?
nn	\$	80.00	X
	\$	160.00	201
	\$	1,000.00	5001
	\$	950.00	500
	\$	18,001.76	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005493/Krd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3520K	Veh. Inspected	SLV 4694M	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002280MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	23/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102074989	Colour	METALLIC BLACK	
Odometer	7529	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	DUNLOP	9 mm	
L/H Front Tyre	215/60 R17	DUNLOP	9 mm	
R/H Rear Tyre	215/60 R17	DUNLOP	9 mm	
L/H Rear Tyre	215/60 R17	DUNLOP	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/03/2018	Inspection Date	26/03/2018	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4694M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	TO REPAIR SEE LABOUR	972.55	-
1	FRONT BONNET INNER LOCK	TO REPAIR SEE LABOUR	274.10	-
1	FRONT CENTRE GRILLE BASE	CRACKED	591.45	591.45
1	FRONT CENTRE GRILLE GARNISH	DENTED	371.50	371.50
1	FRONT CENTRE GRILLE "TOYOTA" LOGO	CRACKED	691.50	691.50
1	FRONT CENTRE GRILLE TOP GARNISH	BUCKLED	381.90	381.90
1	FRONT CENTRE GRILLE TOP RUBBER	SERVICEABLE	174.45	-
1	FRONT CENTRE GRILLE INNER PCS SENSOR	SHORTED	758.25	758.25
2	FRONT HEADLAMP @\$2821.40	N/S MTG CRACKED	5,642.80	2,821.40
2	FRONT HEADLAMP LOWER BEAM @\$271.75	TO REPAIR SEE LABOUR	543.50	-
1	FRONT BUMPER	BUCKLED	974.45	974.45
2	FRONT BUMPER SIDE RETAINER @\$133.35	SERVICEABLE	266.70	-
1	FRONT BUMPER GRILLE	DENTED	274.45	274.45
1	FRONT BUMPER LOWER LID	BENT	680.00	680.00
2	FRONT BUMPER SIDE GARNISH @\$374.45	SERVICEABLE	748.90	-
1	FRONT BUMPER TOWING COVER	SERVICEABLE	43.75	-
1	FRONT BUMPER NUMBER PLATE GARNISH	DENTED	271.85	271.85
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	581.10	-
2	FRONT BUMPER REINFORCEMENT SIDE BRACKET @\$132.10	TO REPAIR SEE LABOUR	264.20	-
1	FRONT BUMPER SPONE	CRACKED	181.90	181.90
1	FRONT BUMPER LOWER REINFORCEMENT	TO REPAIR SEE LABOUR	561.90	-
2	FRONT BUMPER LOWER REINFORCEMENT BRACKET @\$141.45	TO REPAIR SEE LABOUR	282.90	-
1	FRONT BUMPER LOWER SPONE	CRACKED	174.45	174.45
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	1,218.25	-
1	FRONT SUPPORT PANEL CENTRE PILLER	BENT	178.25	178.25

Report Ref No. CS/FCI18005493/Krd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT AIR-CON CONDENSER	SERVICEABLE	1,218.50	-
1	FRONT RADIATOR	SERVICEABLE	1,718.80	-
1	FRONT CENTRE GRILLE INNER RETAINER (ADDITIONAL)	DISTORTED	181.25	181.25
1	FRONT CENTRE GRILLE BEAM (ADDITIONAL)	BENT	281.85	281.85
1	FRONT SUPPORT PANEL TOP GARNISH (ADDITIONAL)	DISTORTED / DENTED	258.85	258.85
	LESS 25% DISCOUNT		-5,191.08	-2,268.33
			15,573.22	6,804.97
	SPECIAL NETT ITEMS			
1	SET FRONT NUMBER PLATE & CASING (SN) (ADDITIONAL)	BENT	50.00	45.00
			50.00	45.00
	LABOUR			
	REMOVE & REFIX A/C CONDENSER & RADIATOR.	NOT NECESSARY	250.00	-
	REMOVE & REFIX RADIATOR.	NOT NECESSARY	180.00	-
	RESET & REPROGRAM PCS SENSOR.		350.00	120.00
	TUFFKOTE.	NOT NECESSARY	80.00	-
	WIRING.		160.00	20.00
	SPRAY PAINTING.		1,000.00	500.00
	LABOUR CHARGES, INCLUSIVE OF THE REPAIR OF FRONT BONNET, FRONT BONNET INNER LOCK, FRONT HEADLAMP LOWER BEAM, FRONT BUMPER REINFORCEMENT, FRONT BUMPER REINFORCEMENT SIDE BRACKET, FRONT BUMPER LOWER REINFORCEMENT, FRONT BUMPER LOWER REINFORCEMENT BRACKET AND FRONT SUPPORT PANEL.		950.00	500.00
			2,970.00	1,140.00
	GRAND TOTAL		18,593.22	7,989.97
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,400.00

Report Ref No. CS/FCI18005493/Krd3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.