



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 MITSUBISHI LANCER 1.6M (SJW4361S)

Date of Loss

22 March 2018

Time of Loss

19.40

Loss Description

SJW4361S (INSD) > SGD3063U (TP) > SLA8212E

Comment

Workshop Details

Total Rebate Amount

7762

Nett Loss Amount

\$9,238.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

22/07/2018



Days of work completion *

51



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SJW4361S

Registration State

SINGAPORE

Mileage

246619

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2009

ASSESSMENT INFO...

2009

Purchase Date

dd/mm/yyyy



Registration Date *

25/03/2010



Age of Vehicle

7

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI... ABDUL AZIZ AMDAM BIN

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... MITSUBISHI

ASSESSMENT INFO... MITSUBISHI

CATEGORY Model

POLICY INFORMAT... LANCER 1.6M

ASSESSMENT INFO... LANCER 1.6 M

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JMYSNCS3A9U004655

CATEGORY Date of Birth

FNOL INFORMATI... 27 September 1959

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 58

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

JMYSNCS3A9U004655

CATEGORY

Engine No

POLICY INFORMAT... 4G18KC5609

ASSESSMENT INFO...

4G18KC5609

CATEGORY

Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

1584

CATEGORY

Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

0

CATEGORY

Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

17000

FNOL INFORMATI... 25

POST SURVEY INF...

CATEGORY

Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Issue Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Address

FNOL INFORMATI... BLK 898 TAMPINES STREET 81, #05-790,
520898, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Married

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S1358364A

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

26/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

850

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195/60R15

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

195/60R15

Front left side

HANKOOK8mm

Front right side

HANKOOK8mm

Rear left side

HANKOOK8mm

Rear right side

HANKOOK8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			FRONT BONNET			Buckled	380				380	Reviewing
☐		2	1			FRONT BONNET HINGE LH			Serviceable	0	0	0	0	0	Deny
☐		3	1			FRONT BONNET HINGE RH			Repair	0	0	0	0	0	Deny
☐		4	1			FRONT BONNET RUBBER FRONT			Necessary	18				18	Reviewing
☐		5	1			FRONT BONNET RUBBER CTR			Necessary	18				18	Reviewing
☐		6	1			FRONT BONNET INNER LOCK			Damaged	35				35	Reviewing
☐		7	1			FRONT GRILLE LH			Damaged	60				60	Reviewing
☐		8	1			FRONT GRILLE RH			Cracked	60				60	Reviewing
☐		9	1			FRONT GRILLE GARNISH WITH EMBLEM			Cracked	95				95	Reviewing
☐		10	6			FRONT GRILLE CLIPS			Necessary	1.5				9	Reviewing

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
	11	1			HEADLAMP LH			Cracked	240				240	Reviewing
	12	1			HEADLAMP RH			Cracked	240				240	Reviewing
	13	2			HEADLAMP CLIPS			Necessary	3				6	Reviewing
	14	1			FRONT BUMPER			Bent	350				350	Reviewing
	15	1			FRONT BUMPER SIDE RETAINER LH			Damaged	28				28	Reviewing
	16	1			FRONT BUMPER SIDE RETAINER RH			Damaged	28				28	Reviewing
	17	15			FRONT BUMPER CLIPS			Necessary	1.5				22.5	Reviewing
	18	1			FRONT BUMPER LOWER AIR GRILLE			Damaged	48				48	Reviewing
	19	1			FRONT BUMPER LOWER AIR GRILLE GARNISH LH			Cracked	28				28	Reviewing
	20	1			FRONT BUMPER LOWER AIR GRILLE GARNISH RH			Missing	28				28	Reviewing
	21	1			FRONT BUMPER NO PLATE GARNISH			Damaged	26				26	Reviewing

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		22	2		FOGLAMP COVER LH & RH			Serviceable	0	0	0	0	0	Deny
☐		23	1		FRONT FENDER LH			Repair	0	0	0	0	0	Deny
☐		24	1		FRONT FENDER COWLING RH			Serviceable	0	0	0	0	0	Deny
☐		25	8		FRONT FENDER COWLING CLIPS			Serviceable	0	0	0	0	0	Deny
☐		26	1		FRONT FENDER MOULDING CHROME RH			Necessary	10				10	Reviewing
☐		27	1		AIR CON CONDENSER			Bent	130				130	Reviewing
☐		28	1		AIR CON CONDENSER FAN MOTOR ASSY			Serviceable	0	0	0	0	0	Deny
☐		29	1		RADIATOR ASSY			Twisted	250				250	Reviewing
☐		30	1		RADIATOR FAN MOTOR			Serviceable	0	0	0	0	0	Deny
☐		31	1		RADIATOR FAN COWLING			Serviceable	0	0	0	0	0	Deny
☐		32	1		RADIATOR FAN BLADE			Serviceable	0	0	0	0	0	Deny
☐		33	2		RADIATOR TOP BRACKET LH & RH			Repair	0	0	0	0	0	Deny

Claim Portal

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
	34	1			RADIATOR TOP HOSE			Serviceable	0	0	0	0	0	Deny
	35	1			RADIATOR BOTTOM HOSE			Serviceable	0	0	0	0	0	Deny
	36	1			AIR DUCT			Serviceable	0	0	0	0	0	Deny
	37	2			AIR DUCT CLIPS			Serviceable	0	0	0	0	0	Deny
	38	1			RADIATOR SUPPORT PANEL			Bent	400				400	Reviewing
	39	1			FRONT DOOR CHROME MOULDING RH			Serviceable	0	0	0	0	0	Deny
	40	1			FRONT FENDER RH			Buckled	260				260	Reviewing

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOV
	1		TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	20	0	0	Reviewing		
	2		TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS	100	0	0	Reviewing		
	3		TO ARRANGE, SUPPLY AND SEAL OFF PEAK CAR REGISTRATION PLATE INCLUDING INSPECTION FEES ON BY THE LAND TRANSPORT AUTHORITY	80	0	0	Reviewing		

7/2/2018

Claim Portal

		EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOV
			4		TO DISMANTLE ALL DAMAGED PARTS, TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT DOOR RH, FRONT FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	600	0	0	Reviewing		
			5		TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL	600	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	1	BUNPER TOP WHITE CLIPS - 2 PC	Reviewing	5	(NECESSARY) SUPP 1 - 03/04/2018	
☐	2	HEADLAMP TOP SEAL - 2 PC	Reviewing	18	(NECESSARY) SUPP 1 - 03/04/2018	
☐	3	WASHER TANK	Reviewing	55	(DENTED) SUPP 1 - 03/04/2018	
☐	4	DAYS OF REPAIR : 6 DAYS	Reviewing			
☐	5	NUMBER PLATE	Reviewing	35	BENT	
☐	6	RADIATOR COOLANT	Reviewing	20	NECESSARY	

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		7	FRONT BUMPER RIVET - 20 PCS	Reviewing	40	NECESSARY	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$3,492.50

Claim Amount \$3,492.50

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,400.00	\$1,400.00
Miscellaneous	\$173.00	\$173.00
Excess	-\$850.00	-\$850.00

Submit for Review