

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3316J

DATE 23/3/2018 11:14

MAKE :

P/A: 22.03.18

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>distorted</i>			\$ 578.40	✓
	Rear Bumper Reinforcement ?			\$ 483.30	?
	Rear Bumper Clip <i>h/c</i>			\$ 22.00	✓
	Rear Bumper Sponge ?			\$ 137.40	?
	Rear Bumper Under Cover <i>src</i>			\$ 185.80	✓
	Rear Bumper Protector (LH/RH) <i>src</i>		\$ 38.00	\$ 76.00	✗
	SUB TOTAL			\$ 1,482.90	
	LESS 20%			\$ 296.58	
	DISCOUNTED TOTAL			\$ 1,186.32	
	Rear Bumper Reverse Sensor <i>src</i>			\$ 135.70	Nett ✓
	Rear Bumper Rubber Mat <i>h/c</i>			\$ 50.00	Nett ✓
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 250.00	200/-
	Spray Painting Charge			\$ 250.00	200/-
	Wiring Charge			\$ 50.00	20/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	TOTAL LABOUR			\$ 670.00	
	ESTIMATE TOTAL			\$ 2,042.02	
<p>23/03/2018</p> <p>Hot <i>Antenna</i></p> <p>2/sum</p> <p><i>mp</i></p> <p>LKK <i>Antenna</i></p> <p><i>8</i></p> <div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div> <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

Larry Ng