



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2006953  
INV Date 09/10/2020  
Reference CS/CTI18001519/Uka3s2-1  
Code CTI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SKG 9775X  
Insured Veh. SKD 9284L  
Claim No. SNM18D00412C02/CBS/THP  
Policy No. DMPCSN3011271804  
Accident Date 21/01/2018  
Inspection Date 02/02/2018

| Description                                  | Total         |
|--|---------------|
| Third Party Express Settlement               | 400.00        |
| Less: Invoice no. AC1801294 dated 31/01/2018 | -220.00       |
| <b>Subtotal</b>                              | <b>180.00</b> |
| <b>GST (7%)</b>                              | <b>12.60</b>  |
| <b>Grand Total</b>                           | <b>192.60</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                               |            |   |
|--|---|-------------------------------|------------|---|
| CHINA TAIPING INSURANCE (S) PTE LTD  |   | Ref : CS/CTI18001519/Uka3s2-1 |            |   |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909  |   | Date : 09-10-2020             |            |  |
|  |   | Code : CTI                    |            |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                               |            |   |
| Insured Veh.   | SKD 9284L   | Veh. Inspected                | SKG 9775X  |   |
| Policy No.   | DMPCSN3011271804  | Coverage (\$)                 | 0.00       |   |
| Claim No.  | SNM18D00412C02/CBS/THP  | Excess (\$)                   | 0.00       |   |
| Assign From  | ALFRED TOH  | Assign Date                   | 02/02/2018 |   |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                               |            |   |
| Make & Model   | B.M.W. 520I (A)   | c.c                           | 1997       |   |
| Engine No.   | HIDDEN  | Year of Reg.                  | 2012       |   |
| Chassis No.  | WBAXG120X0DX51013   | Colour                        | WHITE      |   |
| Odometer   | 132334  | Steering                      | IN ORDER   |   |
| Brakes   | IN ORDER  | Modification                  | SPORTS RIM |   |
| General  | GOOD  |                               |            |   |
| <b>3. Conditions of Tyres</b>  |   |                               |            |   |
|  | Size  | Make                          | Balance    |   |
| R/H Front Tyre   | 225/55 R17  | PIRELLI                       | 6 mm       |   |
| L/H Front Tyre   | 225/55 R17  | PIRELLI                       | 6 mm       |   |
| R/H Rear Tyre  | 225/55 R17  | PIRELLI                       | 6 mm       |   |
| L/H Rear Tyre  | 225/55 R17  | PIRELLI                       | 6 mm       |   |
| <b>4. Description of Damages</b>   |   |                               |            |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.<br><br>DAMAGES SEE DETAILS.        |   |                               |            |   |
| <b>5. General Information</b>  |   |                               |            |   |
| Accident Date  | 21/01/2018  | Inspection Date               | 02/02/2018 |   |
| Survey held at   | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                               |            |   |
| <b>5a. Remarks</b>   |   |                               |            |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                               |            |   |
| <b>5b. Estimate Days of Repair</b>   |   |                               |            |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | <b>7 Working Days</b>         |            |   |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 9775X

| Qty | Description of Parts                | Condition            | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|-------------------------------------|----------------------|----------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>  |                      |                            |                   |
| 1   | REAR WINDSCREEN MOULDING            | NECESSARY            | 118.20                     | 118.20            |
| 1   | REAR BUMPER                         | TORN                 | 1,431.40                   | 1,431.40          |
| 1   | REAR BUMPER SIDE HOLDER N/S         | CRACKED              | 141.65                     | 141.65            |
| 4   | REAR BUMPER PDC SENSORS @ \$215.00  | NOT NECESSARY        | 860.00                     | -                 |
| 1   | SET REAR BUMPER CLIPS               | NECESSARY            | 60.00                      | 60.00             |
| 1   | TAILLAMP N/S                        | NOT NECESSARY        | 680.50                     | -                 |
| 1   | REAR FENDER N/S                     | BADLY DENTED         | 1,710.55                   | 1,710.55          |
| 1   | REAR FENDER UNDERCOVER N/S          | TORN                 | 288.20                     | 288.20            |
| 1   | SET REAR FENDER UNDERCOVER CLIS N/S | NECESSARY            | 50.00                      | 50.00             |
| 1   | REAR FENDER INNER PANEL N/S         | TO REPAIR SEE LABOUR | 1,192.00                   | -                 |
| 1   | REAR DOOR N/S                       | DENTED / WARPED      | 1,689.00                   | 1,689.00          |
| 1   | REAR DOOR INNER LOCK N/S            | NOT NECESSARY        | 820.00                     | -                 |
| 1   | REAR DOOR GLASS OUTER MOULDING N/S  | NECESSARY            | 192.75                     | 192.75            |
| 1   | REAR DOOR INNER WEATHERSTRIP N/S    | NECESSARY            | 185.30                     | 185.30            |
| 1   | REAR DOOR INNER SIDE RUBBER N/S     | NECESSARY            | 110.35                     | 110.35            |
| 1   | REAR DOOR GLASS REGULATOR MOTOR N/S | NOT NECESSARY        | 745.00                     | -                 |
| 1   | ROCKER PANEL GARNISH N/S            | DEEP CUT             | 699.20                     | 699.20            |
| 1   | REAR SPORT RIM N/S                  | CRACKED              | 859.70                     | 859.70            |
| 1   | REAR WISHBONE N/S                   | BENT                 | 552.85                     | 552.85            |
| 1   | REAR KNUCKLE ARM N/S                | BENT                 | 1,248.20                   | 1,248.20          |
| 1   | REAR SHOCK ABSORBER N/S             | BENT                 | 496.80                     | 496.80            |
| 1   | REAR INTERGAL LINK N/S              | TWISTED              | 121.65                     | 121.65            |
| 1   | REAR DRIVE SHAFT N/S                | NOT NECESSARY        | 1,900.90                   | -                 |
| 1   | REAR WHEEL HUB BEARING N/S          | DAMAGED / NECESSARY  | 189.85                     | 189.85            |
| 1   | REAR STABILIZER SWING SUPPORT N/S   | BENT                 | 90.70                      | 90.70             |
| 1   | REAR HUB HUB N/S                    | BENT                 | 924.60                     | 924.60            |
| 1   | REAR DOOR RIM CAP N/S               | GRAZED               | 23.75                      | 23.75             |
| 2   | FRONT HEADREST REPAIR KIT @ \$95.00 | NOT NECESSARY        | 190.00                     | -                 |
| 1   | REAR TORSION ARM N/S                | TWISTED              | 322.30                     | 322.30            |

Report Ref No. CS/CTI18001519/Uka3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
|     | LESS 5% DISCOUNT   |               | -                         | -575.35           |
|     |  |               | 17,895.40                 | 10,931.65         |
|     | <b><u>SPECIAL NETT ITEMS</u></b>   |               |                           |                   |
| 1   | REAR TYRE N/S (LOCAL PURCHASE @ \$200.00 DISC 60%) (SN)  | GRAZED        | 300.00                    | 120.00            |
| 1   | REAR WINDSCREEN SEALANT (SN)   | NECESSARY     | 50.00                     | 40.00             |
|     |  |               | 350.00                    | 160.00            |
|     | <b><u>LABOUR</u></b>   |               |                           |                   |
|     | TO CHECK WIRING.   |               | 80.00                     | 30.00             |
|     | TO DISMANTLE & REFIX PDC SENSOR.   |               | 100.00                    | 50.00             |
|     | TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.   |               | 250.00                    | 100.00            |
|     | TO SPRAY RUST PROOFING.  |               | 180.00                    | 80.00             |
|     | TO CONDUCT WHEEL ALIGNMENT.  |               | 120.00                    | 80.00             |
|     | TO DISMANTLE & REFIX REAR WINDSCREEN.  |               | 150.00                    | 120.00            |
|     | TO DISMANTLE & REFIX REAR DOOR MECHANISM.  |               | 100.00                    | 60.00             |
|     | TO DISMANTLE & REPLACE REAR UNDERCARRIAGE.   |               | 300.00                    | 150.00            |
|     | TO MOUNT VEHICLE ON CAR O-LINER.   | NOT NECESSARY | 380.00                    | -                 |
|     | TO DIAGNOSTIC & REPROGRAMME SYSTEM.  |               | 300.00                    | 50.00             |
|     | LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER INNER PANEL N/S. |               | 1,800.00                  | 900.00            |
|     | TO PUTTY AND SPRAY PAINTING.   |               | 1,800.00                  | 1,080.00          |
|     |  |               | 5,560.00                  | 2,700.00          |
|     | <b>GRAND TOTAL</b>   |               | <b>23,805.40</b>          | <b>13,791.65</b>  |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>  |               |                           | <b>11,000.00</b>  |

Report Ref No. CS/CTI18001519/Uka3s2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.