

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG18005598/DDA3Q2**Date:** 03/08/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700036970
Claimant
Vehicle No : SLL138G **Insured Vehicle No :** SKA853U
Date of Loss: 20/03/2018 Nature of Claim: TP Claim No: 7700635966SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL138G**
Make & Model: BMW 535I, 3.0 (A) Engine No: 09457398N55B30A
Reg. Date: 27/05/2010 (Man. Year: 2010) Chassis No: WBAFR72030C264749
Colour: White Odometer: 141967 km
Engine Capacity: 2979 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 R20 Rear Tyre Size: 255/35 R20
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	19,401.99	6,230.48	13,171.51	67.89	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,710.00	1,270.00	3,440.00	73.04	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	24,111.99	7,500.48	16,611.51	68.89	
Approved Total (Overridden) (S\$)		6,000.00			
	(S\$)	24,111.99	6,000.00	18,111.99	75.12
+ GST 7.00/7.00% (S\$)	1,687.84	420.00	1,267.84	75.12	
Nett Amount (S\$)	25,799.83	6,420.00	19,379.83	75.12	
+ Car Rental (3.0 x S\$180.00/day) (S\$)		540.00			
+ Doc/Search Fee (S\$)		7.45			
Nett Liability (S\$)		6,967.45			
Global Sum Settlement (S\$)		6,900.00			

INSPECTION

Date of Assignment: 26/03/2018
Date Inspected: 26/03/2018 Inspected At: Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
Singapore 408934
Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,932.00 FL	*- FL
2	1		*BOOTLID INNER TRIM	Not Necessary	146.40 FL	*- FL
3	2		*BOOTLID HINGE	Not Necessary	138.00 FL	*- FL
4	2		*BOOTLID LAMP	Not Necessary	816.00 FL	*- FL
5	1		*BOOTLID CENTR LOGO	Not Necessary	82.80 FL	*- FL
6	1		*BOOTLID LOCK MECHANISM	Not Necessary	254.40 FL	*- FL
7	1		*REAR BOOTLID LOCK CATCH	Not Necessary	63.60 FL	*- FL
8	1		*REAR BOOTLID CONTROL UNIT	Not Necessary	706.80 FL	*- FL
9	1		*END PANEL	Repair	981.60 FL	*- FL
10	1		*END PANEL GARNISH	Not Necessary	135.60 FL	*- FL
11	1		*END PANEL LOCK SENSOR	Not Necessary	445.00 FL	*- FL
12	1		*SPARE TYRE COMPARTMENT COVER	Not Necessary	822.00 FL	*- FL
13	2		*FENDER INNER TRIM	Not Necessary	384.00 FL	*- FL
14	2		*REAR BUMPER RETAINER	Serviceable	240.00 FL	*- FL
15	1		*REAR BUMPER BRACKET CENTRE	Broken	91.20 FL	*91.20 FL
16	1		*REAR BUMPER CENTRE UPPER HOLDER	Deformed	78.00 FL	*78.00 FL
17	1		*REAR BUMPER CENTRE LOWER HOLDER	Not Necessary	58.80 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Dented	858.00 FL	*858.00 FL
19	2		*REAR BUMPER REFLECTOR	Not Necessary	84.72 FL	*- FL
20	1		*REAR BUMPER TOW COVER	Not Necessary	67.20 FL	*- FL
21	4		*REAR BUMPER PARKING SENSOR	Damaged (2 PCS ONLY)	1,480.00 FL	*740.00 FL
22	4		*REAR BUMPER PARKING SENSOR HOLDER	Not Necessary	307.20 FL	*- FL
23	2		*REAR BUMPER LOWER SIDE GARNISH	Not Necessary	348.00 FL	*- FL
24	2		*REAR TAILLAMP	Not Necessary	1,375.20 FL	*- FL
25	1		*REAR EXHAUST MOUNTING	Not Necessary	64.00 FL	*- FL
26	1		*REAR BUMPER LOWER TRIM	Not Necessary	210.00 FL	*- FL
27	1		*REAR BUMPER (AFTER MARKET)	Distorted	2,500.00 FS	*1,650.00 FS
28	1		*REAR BUMPER LOWER GARNISH (AFTER MARKET)	Broken	1,500.00 FS	*1,000.00 FS
29	1		*REAR EXHAUST ASSY (AFTER MARKET)	Bent	3,500.00 FS	*1,960.00 FS
30	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
31	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
32	1		*JOINT SEALANT	Not Necessary	150.00 FS	*- FS
33	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,010.52	6,407.20
- List Item Discount on L Items 5.00/10.00% (\$)	608.53	176.72
Total Parts (\$)	19,401.99	6,230.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	0.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	40.00
3	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	80.00
4	DIAGNOIS CHECK AND CLEAR FAULT CODE	New	400.00	0.00
5	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,500.00	500.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	500.00
8	REMOVE AND RENEW REAR STICKERS ON AFFECTED PANEL	New	800.00	150.00
Gross Labour Cost (\$\$)			4,710.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >