

ASS. REC. BY:

REF: CS/FCI18005615/Kqd3n2 Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Karen Tan

of

FCI

Date/Time: 26/3/18 @ 12:22pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKL 3966A

Insured:

SHC 32664

at Workshop m/s:

Alan's United

Tel:

64538686

of

Blk 7 Sin Ming Ind. Est # 01-76

Policy No:

D-18088936MFSH

Claim No:

D18002293MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/03/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

4:21pm @ 26/3/18

Person Contacted:

Kenny

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL 3966A-X
	SHC 32664 - CS/FCI15022438/vb
24/3/18 @ 4:21pm	Revised to Karen Tan by email.
2/4	L1 Sp @ 5550L Confirmed by email (Red # 3554.10, 39%)

ASS. REC. BY:

REF:

FC11

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKL 3906A

Yr Regn:

11, 13

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Mc 2180

c.c.

1595

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

93813

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W00 2040312A 888520

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

17/3/18

D.O.I.

26/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/3

File pass to Catherine

RECEIVED 04 APR 2018

Date/Time, File Pass to?

1) 03/4 11:00

Date/Time, File Return to?

2)

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TP

5550

170

50

50 + 50

26

346



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005615/Kqd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-03-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3266U	Veh. Inspected	SKL 3966A
Policy No.		Coverage (\$)	0.00
Claim No.	D18002293MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	26/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	17/03/2018	Inspection Date	26/03/2018
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002293MFSH

Date: 27 March 2018

Our Ref: CS/FCI18005615/Kqd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SKL 3966A**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/03/2018 at the premises of M/s ALAN'S UNITED, and have the following to report:-

Workshop Estimate Amount	: S\$ 9,104.10 .
Revised Estimate Amount	: S\$ 5,799.50 .
"Check" Items Amount	: S\$ 1,154.70 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

**Description of Damage:**

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

Date	20-03-2018	Our Ref No. D18002293MFSH
Accident Date	17-03-2018	Claim Type. Third Party
Insured Vehicle	SHC3266U	Third Party Vehicle. SKL3966A
Survey Location	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76	
Contact Person.	KENNY	
Contact No.	64538686/ 0	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	ALAN'S UNITED AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236167)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18002293MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & ALAN'S UI
<b>Workshop Name</b>	ALAN'S UNITED AUTO PTE LTD (Contact Person : KENNY )	<b>Survey Location &amp; Contact Details</b>	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 <b>Mobile:</b> 0 , <b>Phone:</b> 64538686 , <b>Fax:</b> 0 <b>EmailId:</b> KENNYCHAN@ALANUTD.COM		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	DIRECT SETTLEMENT:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHC3266U	<b>TP Vehicle No</b>	SKL3966A
<b>PRI Recieved Date</b>	23-03-2018 01:33:14 PM	<b>Surveyor Appointed Date</b>	26-03-2018 12:21:51 PM	<b>Surveyor Accept Date</b>	26-03-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>		<b>Surveyor Report Date</b>	27-03-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	Please Select Make ▼	<b>Model</b>	Please Select Model ▼	<b>Year</b>	Select Year ▼
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

[Upload Multiple Documents](#)

File Name

Action

## Surveyor Job Remarks

Remarks

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Tuesday, 27 March 2018 4:21 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18002293MFSH/1  
**Attachments:** CSFCI18005615Kqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SKL 3966A.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Monday, 26 March 2018 4:24 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18002293MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Monday, 26 March 2018 12:21 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [KARENTAN@MSFIRSTCAPITAL.COM.SG](mailto:KARENTAN@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18002293MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited

Vehicle Type:	
Vehicle Scheme:	-
Vehicle Attachment 1:	No Attachment
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 BLUEEFFICIENCY
Primary Colour:	Black
Secondary Colour:	-
Passenger Capacity:	4
Chassis No.:	WDD2040312A888520
Engine No.:	27491030081086
Engine Capacity / Power Rating:	1595 cc / -
Maximum Power Output:	115.0 kW ( 154 bhp )
Propellant:	Petrol
Max Unladen Weight:	1485 kg
Maximum Laden Weight:	2000 kg
Open Market Value:	\$29,334.00



For Customer Service please visit

1 Pickering Street

#01-01 Great Eastern Centre

Tel: +65 6248 2888 Fax: +65 6327 3080

## Certificate of Insurance

ORIGINAL

Road Transport Act 1987 (Federation of Malaysia)  
The Motor Vehicles (Third-Party Risks) Rules, 1959 (Federation of Malaysia)  
The Motor Vehicles (Third-Party Risks and Compensation) Act, (Cap.189 of the Revised Edition) (Republic of Singapore)  
The Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960. (Republic of Singapore)

FORM MX1

Policy No. : 2017-V8008737-VDP-E002

Risk# : 0001

Policy Type : Drive And Save Plus

Cover : Comprehensive any Workshop

DESCRIPTION OF VEHICLES:

Vehicle Registration : SKL3966A

Vehicle Make & Model : MERCEDES-BENZ - C180

Name of Insured : NG HUI TING

Period of Insurance : 14-11-2017 (1202 HRS ) to 13-11-2018

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE \*

(a) The Policyholder.

The Policyholder may also drive a motor car not belonging to or hired (under a hire purchase agreement or otherwise) to him/her or his/her employer or his/her partner.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

(c) In the event of the death of the Policyholder; (i) any member of the Policyholder's family, or a paid driver who has been driving the car during the lifetime of the Policyholder & permission to drive had not been withdrawn prior to the death of the Policyholder; (ii) any other person who has been given permission to drive the vehicle prior to the death & such permission had not be withdrawn by the Policyholder.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

LIMITATIONS AS TO USE


Use for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any other trade or business or use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Signed for and on behalf of the Company



Authorised Signature

GPGIGCH

19-03-2018

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05752

Vehicle Insured : SHC 3266U

Accident Date : 17-Mar-2018

Date : 22-Mar-2018

Our Ref : 218057 (FIRST) / CHAN

PAGE : 1

NG HUI TING  
BLK 778 YISHUN AVE 2  
#09-1565  
Singapore 760778

*Not Authorized*  
*61 Lp 87*  
*Resurvey After Paint 6 days*

## ESTIMATED COST OF REPAIR FOR MERCEDES BENZ C180 BLUEEFFICIENCY SKL3966A

1 pc	Boot lid		<i>R</i> 1,772.00	<i>X</i>
1 pc	Boot lid "C180" emblem		<i>RM</i> 89.00	<i>  </i>
1 pc	Boot lid logo		<i>RM</i> 51.00	<i>  </i>
1 pc	Boot lid "7 G-TRONIC" emblem		<i>RM</i> 120.00	<i>  </i>
1 pc	Rear bumper fascia		<i>CRM</i> 1,499.00	<i>  </i>
1 pc	Rear bumper centre moulding		<i>RM</i> 205.00	<i>  </i>
2 pcs	Rear bumper side moulding	@ S\$145.00	<i>RM</i> 290.00	<i>  </i>
1 pc	Rear bumper reinforcement		<i>RM</i> 738.00	<i>  </i>
3 pcs	Rear bumper lower bracket	@ S\$ 18.00	<i>CRM</i> 54.00	<i>  </i>
1 pc	Rear bumper inner parts		<i>CRM</i> 148.00	<i>  </i>
2 pcs	Rear bumper side retainer	<i>MSD</i> @ S\$ 39.00	78.00	<i>  </i>
1 pc	Rear end panel		<i>RM</i> 1,358.00	<i>  </i>
1 pc	Rear end panel top garnish		<i>CRM</i> 397.00	<i>  </i>
1 pc	Rear spare tyre panel		<i>RM</i> 397.00	<i>  </i>
1 pc	Spare tyre panel sealant		<i>RM</i> 253.00	<i>  </i>
			7,449.00	
			Less 10% :	744.90

*301*  
1 ~~pc~~ Rear bumper reverse sensor (4pc)

*RM* 6,704.10  
*RM* 400.00 *sn* ✓

To apply undersealing

100.00 *301*

To putty and spray replaced parts

900.00 *7501*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

1,000.00 *7001*

Total : S\$ 9,104.10

Singapore Dollars Nine Thousand One Hundred and  
Four and Cents Ten Only

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier's quotation must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005615/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-04-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 3266U	Veh. Inspected	SKL 3966A	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002293MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	26/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES C180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD2040312A888520	Colour	METALLIC BLACK	
Odometer	93813	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	BRIDGESTONE	3 mm	
L/H Front Tyre	225/45 R17	BRIDGESTONE	3 mm	
R/H Rear Tyre	225/45 R17	BRIDGESTONE	3 mm	
L/H Rear Tyre	225/45 R17	BRIDGESTONE	3 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/03/2018	Inspection Date	26/03/2018	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 3966A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOT LID	TO REPAIR SEE LABOUR	1,772.00	-
1	BOOT LID "C180" EMBLEM	NECESSARY	89.00	89.00
1	BOOT LID LOGO	NECESSARY	51.00	51.00
1	BOOT LID "7G-TRONIC" EMBLEM	NECESSARY	120.00	120.00
1	REAR BUMPER FASCIA	CRACKED	1,499.00	1,499.00
1	REAR BUMPER CENTRE MOULDING	DENTED	205.00	205.00
2	REAR BUMPER SIDE MOULDING @\$145.00	NECESSARY	290.00	290.00
1	REAR BUMPER REINFORCEMENT	BENT	738.00	738.00
3	REAR BUMPER LOWER BRACKET @\$18.00	CRACKED	54.00	54.00
1	REAR BUMPER INNER PARTS	CRACKED	148.00	148.00
2	REAR BUMPER SIDE RETAINER @\$39.00	N/S DISTORTED	78.00	39.00
1	REAR END PANEL	BENT	1,358.00	1,358.00
1	REAR END PANEL TOP GARNISH	MTG DISTORTED	397.00	397.00
1	REAR SPARE TYRE PANEL	CRACKED	397.00	397.00
1	SPARE TYRE PANEL SEALANT	NECESSARY	253.00	253.00
	LESS 10% DISCOUNT		-744.90	-563.80
			6,704.10	5,074.20
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER REVERSE SENSOR (4 PCS)(SN)	DENTED	400.00	400.00
			400.00	400.00
<b>LABOUR</b>				
	TO APPLY UNDERSEALING.		100.00	30.00
	TO PUTTY AND SPRAY REPLACED PARTS.		900.00	750.00
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF BOOT LID.		1,000.00	700.00
			2,000.00	1,480.00
<b>GRAND TOTAL</b>			<b>9,104.10</b>	<b>6,954.20</b>

Report Ref No. CS/FCI18005615/Kqd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,550.00
---	--	--	----------

Report Ref No. CS/FCI18005615/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.