

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18005619/AVBN2**Date:** 09/07/2018REFERENCE

Insured/Claimant: PHOON YEE WEI Policy No: 2100452593-02
Date of Loss: 23/03/2018 Nature of Claim: OD Claim No: 2708140786SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA479E**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN002314
Reg. Date: 19/02/2016 (Man. Year: 2015) Chassis No: WAUZZZF46GA021643
Colour: Black Odometer: 27857 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$118,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,399.00	9,492.96	5,906.04	38.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,452.00	4,227.00	3,225.00	43.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,851.00	13,719.96	9,131.04	39.96
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	22,251.00	13,119.96	9,131.04	41.04
+ GST 7.00/7.00% (S\$)	1,557.57	918.40	639.17	41.04
Nett Amount (S\$)	23,808.57	14,038.36	9,770.21	41.04

INSPECTION

Date of Assignment: 26/03/2018
Date Inspected: 26/03/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	1		*FRONT BUMPER SECURING STRIP	Not Necessary	60.00 FS	*- FS
3	1		*AIR GRILLE GUIDE-RHS	Not Necessary	73.00 FS	*- FS
4	1		*FRONT AIR GRILLE-RHS	Not Necessary	118.00 FS	*- FS
5	1		*BUMPER GUIDE-RHS	Not Necessary	32.00 FS	*- FS
6	1		*FRONT FENDER-RHS	Dented	665.00 FS	*532.00 FS
7	1		*FRONT FENDER CLOSING ELEMENT-RHS	Not Necessary	44.00 FS	*- FS
8	1		*FRONT FENDER INNER BRACKET-RHS	Not Necessary	31.00 FS	*- FS
9	1		*FRONT FENDER OUTER BRACKET-RHS	Not Necessary	43.00 FS	*- FS
10	1		*FRONT FENDER BRACKET-RHS	Not Necessary	27.00 FS	*- FS
11	1		*POP RIVET	Necessary	24.00 FS	*18.56 FS
12	1		*FRONT FENDER BRACE-RHS	Bent	103.00 FS	*82.40 FS
13	1		*FRONT WHEEL HOUSE LINER-RHS	Not Necessary	209.00 FS	*- FS
14	1		*FRONT WHEEL SPOILER-RHS	Not Necessary	63.00 FS	*- FS
15	1		*STONE CHIP GUARD-RHS	Not Necessary	44.00 FS	*- FS
16	1		*COVER	Necessary	20.00 FS	*15.36 FS
17	1		*LED HEADLIGHT-RHS	Cracked	6,973.00 FS	*5,578.40 FS
18	1		*LED POWER MODULE-RHS	Not Necessary	695.00 FS	*- FS
19	1		*HEADLIGHT CONTROL UNIT-RHS	Not Necessary	657.00 FS	*- FS
20	1		*BONNET	Dented	2,163.00 FS	*1,730.40 FS
21	2		*BONNET HINGE-LHS/RHS	Not Necessary	532.00 FS	*- FS
22	1		*BONNET ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
23	1		*BONNET SEAL (3 Pcs)	Necessary	72.00 FS	*56.64 FS
24	1		*BONNET STRIKER	Not Necessary	44.00 FS	*- FS
25	1		*BONNET LID LOCK	Not Necessary	188.00 FS	*- FS
26	1		*FRONT WINDOW CHROME TRIM-RHS	Not Necessary	265.00 FS	*- FS
27	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **15,399.00** **9,492.96**

LKK Auto Consultants Pte Ltd/SLA479E/09/07/2018 07:57

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,RHS HEADLIGHT AND BONNET.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,700.00	1,750.00
3	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER,BONNET,RHS FRONT DOOR AND RHS A-PILLAR	New	3,900.00	1,925.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE RHS FRONT DOOR PANEL TRIMS,RENEW DAMAGED RHS WING MIRROR ASSY FOR FOOR PAINTING	New	300.00	-
Gross Labour Cost (S\$)			7,452.00	4,227.00

LKK Auto Consultants Pte Ltd/SLA479E/09/07/2018 07:57

< END OF ESTIMATES >