

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18005628/SEA3Q2

Date: 28/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0016
Claimant		
Vehicle No : SJN1133B	Insured Vehicle No :	SH8503X
Date of Loss: 22/03/2018	Nature of Claim: TP	Claim No: MCT18030867

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN1133B		
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Engine No:	B444J576N13B16A
Reg. Date:	13/12/2013 (Man. Year: 2013)	Chassis No:	WBA3A16050NS36117
Colour:	Black	Odometer:	75513 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,838.35	11,951.05	4,887.30	29.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	2,130.00	1,100.00	34.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,068.35	14,081.05	5,987.30	29.83
Approved Total (Overridden) (\$\$)		11,250.00		
Nett Amount (\$\$)	20,068.35	11,250.00	8,818.35	43.94
+ Medical Costs (\$\$)		120.00		
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (\$\$)		1,177.00		
Nett Liability (\$\$)		12,547.00		

INSPECTION

Date of Assignment:	26/03/2018	
Date Inspected:	26/03/2018	Inspected At: SEAH MOTOR TRADING CO. LLP Blk 2 Kranji Loop #01-06 Singapore 739538
Estimated Period of Repair:	10.0 days	

Adjuster: Sebastian Yeang Wai Keen

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2020)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN1133B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REAR EXHAUST SILENCER & PIPE	Dented	2,050.00 FL	*1,900.00 FL
2	1		*REAR BUMPER	Broken	1,018.15 FL	*1,018.15 FL
3	4		*REVERSE SENSOR	Broken	947.40 FL	*947.40 FL
4	1		*REVERSE SENSOR CONTROL UNIT	Shorted	526.30 FL	*526.30 FL
5	1		*REAR END PANEL	Dented	592.25 FL	*592.25 FL
6	2		*REAR EXHAUST HOOK	Not Necessary	110.00 FL	*- FL
7	2		*REAR BUMPER REFLECTOR	Broken	70.40 FL	*70.40 FL
8	1		*REAR BUMPER CENTRE MOULDING	Broken	57.00 FL	*57.00 FL
9	1		*REAR BOOT	Dented	1,204.80 FL	*1,204.80 FL
10	1		*REAR BOOT REFLECTOR	N/S Broken	499.60 FL	*249.80 FL
11	1		*SET REAR NUMBER PLATE	Cut	40.00 FL	*35.00 FL
12	1		*TAILLAMP	N/S Broken	713.80 FL	*356.90 FL
13	1		*REAR BOOT LOGO	Necessary	69.50 FL	*69.50 FL
14	1		*FRONT BONNET	Dented	1,219.70 FL	*1,189.00 FL
15	1		*FRONT BUMPER	Dented	982.75 FL	*982.75 FL
16	1		*FRONT BONNET LOGO	Necessary	69.50 FL	*69.50 FL
17	1		*FRONT HEADLAMP ASSY	N/S Broken	4,271.70 FL	*2,083.00 FL
18	1		*FRONT BUMPER LOWER GRILLE	Broken	97.90 FL	*97.90 FL
19	1		*FRONT FOG LAMP COVER LH	Broken	37.60 FL	*37.60 FL
20	1		*FRONT FOG LAMP MOULDING LH	Cut	85.00 FL	*85.00 FL
21	1		*RADIATOR SUPPORT PANEL BRACKET TOP	Cut	56.65 FL	*56.65 FL
22	2		*FRONT BONNET INNER LOCK	Not Necessary	471.30 FL	*- FL
23	1		*FRONT BUMPER BEAM -ALUMINIUM	Not Necessary	850.00 FL	*- FL
24	1		*REAR BOOT INNER LOCK	Bent	211.85 FL	*211.85 FL
25	1		*REVERSE SENSOR CABLE AND HARNESS	Necessary	370.00 FL	*370.00 FL
26	2		*FRONT HEADLAMP BEACKETS	Not Necessary	107.90 FL	*- FL
27	1		*FRONT BONNET INSULATOR	Not Necessary	163.30 FL	*- FL
28	2		*TAILLAMP GARNISH	Not Necessary	79.70 FL	*- FL
29	1		*REAR BOOT RUBBER	Not Necessary	82.25 FL	*- FL
30	1		*REAR BUMPER BRACKETS	Broken	32.10 FL	*32.10 FL
31	1		*REAR TYRE COMPARTMENT PANEL	Dented	184.80 FL	*184.80 FL
32	1		*SMALL REAR TYRE COMPARTMENT INSULATOR	Necessary	125.00 FL	*125.00 FL
33	1		*BIG REAR TYRE COMPARTMENT INSULATOR	Necessary	175.00 FL	*175.00 FL
34	1		*REAR BUMPER LOWER GARNISH	Broken	125.00 FL	*125.00 FL
35	1		*FRONT RADIATOR AIR DUCT	Broken	195.00 FL	*195.00 FL
36	2		*FRONT GRILLE	Cut	231.30 FL	*231.30 FL
37	1		*REVERSE SENSOR CONTROL UNIT	Repeated	526.30 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,650.80	13,278.95
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,812.45	1,327.90
Total Parts (\$\$)	16,838.35	11,951.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT FRONT & REAR WIRE HARNESS TO FACILITATE REPAIRS ,TO FOCUS HEADLAMPS	New	150.00	100.00
2	TO KNOCKOUT/WELD/CUT AND TO STRAIGHTEN /ALIGN FRONT DAMAGE AND REAR DAMAGES	New	1,100.00	1,000.00
3	TO DIAGNOSTIC SCAN ,TO CLEAR FAULT CODES AND TO REGISTER AND ACTIVATE REAR BUMPER SENSOR CONTROL MODULE	New	580.00	0.00
4	TO PUTTY AND PAINTING FRONT AND REAR DAMAGES	New	1,200.00	1,000.00
5	TO APPLY TURF COAT FOR REPAIRED AND REPLACED PARTS	New	200.00	30.00
Gross Labour Cost (\$\$)			3,230.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >