



Your Ref : SNM18D01593

Date: 26th July 2019

Our Ref : CC6/CTI18005639/Aeb3s2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00
Springleaf Tower
Singapore 079909
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKJ 6030R
ACCIDENT ON 24/03/2015 INSURED VEHICLE SGM 9238X**

Instruction was received to inspect the vehicle Reg. No. SKJ 6030R. The inspection was conducted on 26/03/2018 at the premises of Modern Automotive Pte Ltd, Blk 3023A Ubi Road 1 #01-61 Singapore 408717.

The following vehicle information was recorded:

Registration Number	: SKJ 6030R
Make/Model	: Mercedes Benz E200
Year of Registration	: 1998
Body Colour	: Black
Chassis Number	: WDB2100352A476845
Engine Capacity	: 1998 cc
Speedometer Reading	: 327455 km

The vehicle sustained damages at the front n/s portion. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	SS	500.00
Less: Paper Value	(SS)	15.00)
Nett Liability	SS	<u>485.00</u>

Vehicle Inspected By:



ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser



K.K.LAU
MSc(Eng M), B.Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.