

ASS. REC. BY:

REF: CS/FCI18005644/Dtd3n2 Special Instruction:

Surveyor: Bryan ASSIGNMENT (Office)

From (Person): Maly chua of FCI Date/Time: 2:07pm @ 19/3/18

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 7941M Insured: SHC 3190D

at Workshop m/s Chynni Motor Tel: 65425119

of AMIC Autopoint # 01-56

Policy No: \_\_\_\_\_ Claim No: D18002203MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 15/3/18  
(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>up?</sup> H.O.D. Endorsement: \_\_\_\_\_


Date/Time: 2:29pm @ 20/3/18 Person Contacted: Lynn Vehicle  IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 7941M - NS/INC16023334/H/16v2 D.O.A: 3/12/16
	SHC 3190D - CC3/AIG14022264/H/sm3w2 D.O.A: 26/11/14

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 13 ~~7~~ days Res: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Yr. Regn: 2015 Oct  
 Type: M. Car / M. Cycle / Bus / Van / Lorry /  Prime Mover /  
 Truck / Trailer or  
 Make: Hyundai I40 CC 1685  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 297472 T/Radio: Insured / Std / NI / NA  
 Eng. No: D4FD Fu 547420  
 C/No: KMHLB41UMGU078529  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In Order / Jammed / Leaked / Burnt or  
 Brake:  In Order / Jammed / Leaked / Burnt or  
 Modi:  Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/60 R16  
 R: ———  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Hankook  
 Front Rear  
 R/Bal: 8 mm R/Bal: 8 mm  
 L/Bal: 8 mm L/Bal: 8 mm  
 D.O.A. 15/03/2018 D.O.I. 20/03/2018  
 Survey held at Chunni AMK  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 4/5 Front & 4/5 Body  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
 16/04/18 FCI, BHC 3190P  
 13 days 2/5 10,800/- with 13 days 7 r.v. (Red: 12406.76 & 53%)

RECEIVED 18 APR 2018

Date/Time File Pass to?  : Preli. Report  
 : Final Report  
 1) 13/4 Typist  
 Date/Time File Return to?

Days Of Repair: 13  
 Resurvey No. of Trip: 2

Add Fee:  Site Insp. 1\$  
 Interview 1\$  
 Tech. Drive 1\$  
 Weekend 1\$

Survey Fee: 13x15 = 195  
 170 + 195  
 50  
 50 + 50  
 120  
 635  
 18/4/18

Report Format: TP  
 Lump Sum / I.B. 1: 10,800



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005644/Dtd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3190M	Veh. Inspected	SHA 7941M
Policy No.		Coverage (\$)	0.00
Claim No.	D180032203MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	27/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/03/2018	Inspection Date	20/03/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D180032203MFSH

Date: 28/3/2018

Our Ref: CS/FCI18005644/Dtd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 7941M.**

Please be informed that we had conducted the inspection of the abovementioned vehicle 20/3/2018 at the premises of M/s Chun Ni and have the following to report: -

Workshop Estimate Amount	: <u>S\$ 23,206.76</u>
Revised Estimate Amount	: <u>S\$ 13,600.52</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

**Description of Damage:**

The vehicle sustained damages at the N/S front and n/s body.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Bryan Tani

Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	16-03-2018	<b>Our Ref No.</b> D18002203MFSH
<b>Accident Date</b>	15-03-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC3190D	<b>Third Party Vehicle.</b> SHA7941M
<b>Survey Location</b>	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
<b>Contact Person.</b>	LYNN OR IRENE	
<b>Contact No.</b>	64836016/ 65425119	<b>Fax No.</b> 65426039
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	CHUNNI MOTOR WORK PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MAY CHUA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236053)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18002203MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & CHUNNI M
<b>Workshop Name</b>	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE)	<b>Survey Location &amp; Contact Details</b>	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06 <b>Mobile:</b> 65425119 , <b>Phone:</b> 64836016 , <b>Fax:</b> 6542603 <b>EmailId:</b> CHUNNIMOTOR@GMAIL.COM		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHC3190D	<b>TP Vehicle No</b>	SHA7941M
<b>PRI Recieved Date</b>	16-03-2018 09:19:02 PM	<b>Surveyor Appointed Date</b>	19-03-2018 02:06:50 PM	<b>Surveyor Accept Date</b>	20-03-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	20-03-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 28 March 2018 9:53 AM  
**To:** 'Claim Workflow System'  
**Cc:** SUR; assignments  
**Subject:** FW: SURVEY ASSESSMENT - D18002203MFSH/1  
**Attachments:** PRELI ADVISED SHA 7941M.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHA 7941M**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 20 March 2018 10:16 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18002203MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Monday, 19 March 2018 2:06 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [MAYCHUA@MSFIRSTCAPITAL.COM.SG](mailto:MAYCHUA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18002203MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department

**CHUNNI MOTOR WORK PTE LTD**

To survey bus (LKK)

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 7941M

DATE : 16.03.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039 FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (LH) <i>Dented</i>			\$ 619.00 ✓
	Front Fender Shield (LH) <i>distorted</i>			\$ 169.80 ✓
	Front Door (LH) <i>Dented</i>			\$ 1,403.00 ✓
	Front Door Rubber <i>Nic</i>			\$ 290.50 ✓
	Front Door Gear / Regulator (LH) <i>✓ 1st</i>			\$ 785.50 ✓✓
	Front Door Hinge Upper (LH) <i>✓ 1st</i>			\$ 53.40 ✓✓
	Front Door Hinge Lower (LH) <i>✓ 1st</i>			\$ 53.40 ✓✓
	Front Door Check (LH) <i>✓ 1st</i>			\$ 110.15 ✓✓
	Front Door Mirror (LH) <i>NA</i>			\$ 980.50 X
	Front Door Power Motor <i>NA</i>			\$ 950.90 X
	Front Door Trim Board (LH) <i>✓ mounting crack</i>			\$ 1,196.90 ✓✓
	Door Centre Pillar Outer (LH) <i>✓ Dented</i>			\$ 1,786.20 ✓✓
	Rocker Panel Outer Garnish <i>✓ 1st</i>			\$ 483.60 ✓
	Rear Door (LH) <i>✓</i>			\$ 1,351.00 X
	Front Windscreen Glass <i>NA</i>			\$ 1,059.25 X
	Front Windscreen Moulding <i>✓ NA</i>			\$ 60.00 ✓ X
	Front Windscreen Pillar Outer (LH) <i>✓ Dented</i>			\$ 1,843.10 ✓✓
	Front Wheel Rim (LH) <i>✓ distorted</i>			\$ 351.90 ✓✓
	Front Wheel Hub Cap (LH) <i>✓</i>			\$ 150.70 ✓
	Front Wheel Bearing <i>✓ Dam</i>			\$ 258.50 ✓✓
	Front Shock Absorber (Assy) (LH) <i>✓ distorted</i>			\$ 342.20 ✓✓
	Front Shock Absorber Mounting (LH) <i>NA</i>			\$ 75.10 X
	Front Drive Shaft (LH) <i>NA</i>			\$ 1,069.55 X
	Rack & Pinion Assy <i>✓ distorted</i>			\$ 2,184.00 ✓✓
	STG Tie End <i>✓ distorted</i>			\$ 69.50 ✓✓
	Front Suspension Lower Arm (LH) <i>✓ distorted</i>			\$ 715.10 ✓✓
	Knuckle Arm (LH) <i>✓ distorted</i>			\$ 582.95 ✓✓
	Engine Under Cover <i>NA</i>			\$ 343.10 X
	Engine Crossmember <i>NA</i>			\$ 2,236.90 X
	ABS Sensor, LH <i>NA</i>			\$ 261.50 X
				<b>13449.40</b>
				<b>10759.52</b>
				<b>SUB TOTAL</b>
				<b>LESS 20%</b>
				<b>DISCOUNTED TOTAL</b>
				<b>\$ 21,837.20</b>
				<b>\$ 4,367.44</b>
				<b>\$ 17,469.76</b>
	Front Fender Advertisement Logo (LH) <i>Nic</i>			\$ 100.00 Nett ✓
	Front Door Comfort Logo (LH) <i>Nic</i>			\$ 75.00 Nett ✓
	Front Door Advertisement Logo (LH) <i>Nic</i>			\$ 100.00 Nett ✓
	Rear Door Advertisement Logo (LH) <i>Nic</i>			\$ 100.00 Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>Nic</i>			\$ 80.00 Nett ✓
	Front Windscreen Sealant <i>✓ NA</i>			\$ 46.00 Nett ✓ X
	Front Tyre (LH) <i>punctured 80%</i>			\$ 216.00 Nett ✓
				<b>627.80</b>
				<b>\$ 717.00</b>
				<b>172.80</b>

SHA 7941M

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	<b>Labour Charge</b>			
	Panel Beating			\$ 2,000.00 1000/-
	Spray Painting Charge			\$ 1,300.00 800/-
	Wiring Charge			\$ 100.00 30/-
	Tuff Kote			\$ 150.00 40/-
	Towing Charge			\$ 50.00 40/-
	Transfer of Door		\$ 120.00	\$ 240.00 60/-
	Remove/Refix Undercarriage (FRT)			\$ 400.00 180/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Dashboard			\$ 450.00 40/-
	Remove/Refix Front Windscreen Glass			\$ 120.00 40/-
	Remove/Refix Cushion & Upholstery Front		2170/-	\$ 90.00 NA
	<b>TOTAL LABOUR</b>			\$ 5,020.00
	<b>ESTIMATE TOTAL</b>			\$ 23,206.76
				13557.32
				4510,800/-

20/03/2018 @ 1100w  
 Not Actual  
 2/ Same 13  
 6 days.  
 2KK Auto  
  
 Check IV  
 Photo after repair.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME  
ADDRESS

Home Tel.:  
VIN:  
Registration: SHA 7941 M  
Technician:  
Mileage: 297472  
Time Printed 20.3.18 11:59 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
6°48'		-3°00' 3°00'
3°33'		-0°19' 5°41'
25°18'		-1°30' 1°30'
11°46'		
18°34'		

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
1°51'		-3°00' 3°00'
4°10'		-0°19' 5°41'
-0°07'		-1°30' 1°30'
13°04'		
14°54'		

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	BEFORE	Specified Range
4°57'		-3°00' 3°00'
-0°36'		-3°00' 3°00'
-1°18'		-3°00' 3°00'
25°11'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°29'		-3°30' 2°30'
0°22'		-1°30' 1°30'

Camber  
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°01'		-3°30' 2°30'
-0°20'		-1°30' 1°30'

Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	BEFORE	Specified Range
-0°28'		-3°00' 3°00'
0°02'		-3°00' 3°00'
0°21'		-3°00' 3°00'



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005644/Dtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3190D	Veh. Inspected	SHA 7941M
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18002203MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	19/03/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU078529	Colour	BLUE
Odometer	297472	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	8 mm
L/H Front Tyre	205/60 R16	HANKOOK	8 mm
R/H Rear Tyre	205/60 R16	HANKOOK	8 mm
L/H Rear Tyre	205/60 R16	HANKOOK	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/03/2018	Inspection Date	20/03/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>13 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7941M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT FENDER (LH)	DENTED	619.00	619.00
1	FRONT FENDER SHIELD (LH)	DEFORMED	169.80	169.80
1	FRONT DOOR (LH)	DENTED	1,403.00	1,403.00
1	FRONT DOOR RUBBER	NECESSARY	290.50	290.50
1	FRONT DOOR GEAR/REGULATOR (LH)	BENT	785.50	785.50
1	FRONT DOOR HINGE UPPER (LH)	BENT	53.40	53.40
1	FRONT DOOR HINGE LOWER (LH)	BENT	53.40	53.40
1	FRONT DOOR CHECK (LH)	BENT	110.15	110.15
1	FRONT DOOR MIRROR (LH)	NOT NECESSARY	980.50	-
1	FRONT DOOR POWER MOTOR	NOT NECESSARY	950.90	-
1	FRONT DOOR TRIM BOARD (LH)	MOUNTING CRACKED	1,196.90	1,196.90
1	DOOR CENTRE PILLAR OUTER (LH)	DENTED	1,786.20	1,786.20
1	ROCKER PANEL OUTER GARNISH	BENT	483.60	483.60
1	REAR DOOR (LH)	TO REPAIR SEE LABOUR	1,351.00	-
1	FRONT WINDSCREEN GLASS	NOT NECESSARY	1,059.25	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	60.00	-
1	FRONT WINDSCREEN PILLAR OUTER (LH)	DENTED	1,843.10	1,843.10
1	FRONT WHEEL RIM (LH)	DISTORTED	351.90	351.90
1	FRONT WHEEL HUB CAP (LH)	CUT	150.70	150.70
1	FRONT WHEEL BEARING	DAMAGED	258.50	258.50
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	75.10	-
1	FRONT DRIVE SHAFT (LH)	NOT NECESSARY	1,069.55	-
1	RACK & PINION ASSY	DISTORTED	2,184.00	2,184.00
1	STG TIE END	DISTORTED	69.50	69.50
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	715.10	715.10
1	KNUCKLE ARM (LH)	DISTORTED	582.95	582.95
1	ENGINE UNDER COVER	NOT NECESSARY	343.10	-
1	ENGINE CROSSMEMBER	NOT NECESSARY	2,236.90	-

Report Ref No. CS/FCI18005644/Dtd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ABS SENSOR,LH	NOT NECESSARY	261.50	-
	LESS 20% DISCOUNT		-4,367.44	-2,689.88
			17,469.76	10,759.52
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	FRONT DOOR COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH)(SN)	NECESSARY	80.00	80.00
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
1	FRONT TYRE (LH(80%)(SN)	PUNCTURE	216.00	172.80
			717.00	627.80
	<b>LABOUR</b>			
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR DOOR (LH).		2,000.00	1,000.00
	SPRAY PAINTING CHARGE.		1,300.00	800.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		150.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
1	TRANSFER OF DOOR.		240.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		400.00	180.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX DASHBOARD.	NOT NECESSARY	450.00	-
	REMOVE/REFIX FRONT WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT.	NOT NECESSARY	90.00	-
	-		-	-
	-		-	-
	-		-	-
			5,020.00	2,170.00
<b>GRAND TOTAL</b>			<b>23,206.76</b>	<b>13,557.32</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,800.00
---	--	--	-----------

Report Ref No. CS/FC118005644/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.