

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

# **SMRT Accident Vehicle Repair Estimates**

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No.

SMB3548C

Ref. No

BUS/09/17/1031

Reg. Date

25/09/2017

Vehicle Type

DOUBLE DECK

Make

ALEXANDER DENNIS

Model

**ENVIRO 500** 

Name of Driver

Liu Changyue

Type of Accident

HEAD TO REAR

Date / Time of Accident

21/09/2017 10:05:00 AM

Accident Reported Date / Time :

22/09/2017 12:00:00 AM

Surveyor is Required?

Yes

Survey by

AIG

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

No

Accident Repair Job Card No :

Special Instruction to ARC, if any :


SMB3548C - REAR RIGHT PORTION GBB7914H (TP) - INSURED WITH AIG

Prepared Date

25/09/2017 03:32:44 PM











LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No :

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

1,590.00

0.00

Total Spray Painting Charges

1,200.00

0.00

Total Material Charges

4,196.34

4,196.34

Other Charges

0.00

0.00

TOTAL

6,986.34

**Lum Sum Total** 

0.00

0.00

No. of Repair Days

4.00

0.00 0.00

Prepared / Adjusted By

3 days

Arc / Surveyor Sing Off Date

: 01/01/1900 12:00:00 AM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date :

26/03/2018 01:41:02 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

LKK Auto Consultants nence notify the Repairer of the following: + To resurvey before/after soray painting

. To demay damaged part's) during resurvey

· Parts those are subject to confirmation

. " " " the survey is on a "Without Projudice" basis

beache a fainn kallippe ...

- Store institute by man most be insurveyed and а зислест to final approval from insurance Company

... etc. stedged by Repairer

Bulstoic

ets.G

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR REAR RHS PORTION	1,590.00	0.00- 1060		
Total Labour	1,590.00	0.00		

## Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,200.00	0.00 720			
Total Spray Painting & Panel Beating	1,200.00	0.00			

# Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

BUS/09/17/1031 Page: 3

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
31160628		6011070	BUMPER REAR EXTERIOR	1	4,125.00	10.00	3,712.50	Replace	Replace	No (Nan)
31155514		6011069	R/H TAIL LIGHT POD	1	1,703.25	10.00	1,532.92	Replace	Replace	No R
TOTAL MATERIALS						·		5,245.43	5,245.42	-
TOTAL MATERIALS(Discounted)							4,196.34	4,196.34		

### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	тот	AL SUPPLEMENTARY	MATERIA	ALS					

BUS/09/17/1031 Page: