

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18005658/SDS3Q2

Date: 08/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100487297

Claimant
Vehicle No : SJA7008J **Insured Vehicle No :** GBF4567A

Date of Loss: 23/03/2018 Nature of Claim: TP Claim No: 3478360153SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA7008J		
Make & Model:	MITSUBISHI LANCER, 1.6 (M)	Engine No:	4G18JM6614
Reg. Date:	18/12/2007 (Man. Year: 2007)	Chassis No:	JMYSNCS3A8U002367
Colour:	Black	Odometer:	362671 km
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45Z R16	Rear Tyre Size:	205/45Z R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,929.40	1,935.20	1,994.20	50.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,770.00	810.00	31.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,509.40	3,705.20	2,804.20	43.08
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	6,509.40	2,950.00	3,559.40	54.68
+ GST 7.00/7.00% (S\$)	455.66	206.50	249.16	54.68
Nett Amount (S\$)	6,965.06	3,156.50	3,808.56	54.68
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,800.50		

INSPECTION

Date of Assignment: 26/03/2018

Date Inspected: 03/04/2018 Inspected At:

Hua Hong Pte Ltd (Sungei Kadut)
25D Sungei Kadut Street 1
Singapore 729332

Estimated Period of Repair: 5.0 days

Adjuster: Sebastian Yeang Wai Keen**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	678.00 FL	*678.00 FL
2	10		*REAR BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER BRACKET (LH/RH)	Broken	90.00 FL	*90.00 FL
4	1		*REAR BUMPER BRACKET RIVET (X15) (15 PCS)	Necessary	30.00 FL	*20.00 FL
5	8		*REAR TAIL LAMP BRACKET CLIP (X4)	Not Necessary	24.00 FL	*- FL
6	1		*REAR BUMPER LOWER LIP	Not Necessary	670.00 FL	*- FL
7	2		*REAR TAIL LAMP (LH/RH)	Not Necessary	840.00 FL	*- FL
8	1		*REAR REINFORCEMENT	Dented	195.00 FL	*195.00 FL
9	1		*REAR BOOT	Dented	580.00 FL	*580.00 FL
10	1		*REAR BOOT LOCK	Bent	75.00 FL	*75.00 FL
11	1		*REAR BOOT WEATHERSTRIP	Crumpled	175.00 FL	*175.00 FL
12	1		*REAR EMBLEM	Necessary	48.00 FL	*48.00 FL
13	1		*REAR LOGO (LANCER)	Necessary	28.00 FL	*28.00 FL
14	1		*REAR LOGO (GLX)	Necessary	27.00 FL	*27.00 FL
15	1		*REAR END PANEL	Repair	430.00 FL	*- FL
16	1		*REAR FENDER (RH)	Repair	380.00 FL	*- FL
17	1		*REAR BUMPER CENTRE BRACKET	Dented	128.00 FL	*128.00 FL
18	1		*END PANEL TOP GARNISH	Crumpled	95.00 FL	*95.00 FL
19	1		*REAR BOOT HINGE	Not Necessary	95.00 FL	*- FL
20	1		*REAR NUMBER PLATE	Not Necessary	35.00 FS	*- FS
21	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,853.00	2,369.00
- List Item Discount on L Items 20.00/20.00% (\$)	923.60	433.80
Total Parts (\$)	3,929.40	1,935.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ,CUT & WELD REAR END PANEL ,CHARGE REAR BUMPER ,LOWER LIP ,REAR BUMPER ,REAR LH/RH TAIL LAMP ,REAR BOOT ,KNOCKING & PULL STRAIGHT REAR LH/RH TAIL LAMP PANEL ,REAR LH/RH FENDER ,REAR TYRE FLOOR PANEL AND ALL AREA AFFECTED BY ACCIDENT	New	1,200.00	800.00
2	TO PERFORM WIRE CHECKING	New	20.00	20.00
3	TO DISMANTLE REAR CUSHION SEAT AND CHARGE REAR BOOT HINGE (LH/RH)	New	100.00	30.00
4	TO DISMANTLE & REFIT REAR REVERSE SENSOR	New	60.00	20.00
5	TO DISMANTLE ,REPAIR AND RESPRAY REAR BOOT SPOILER	New	200.00	100.00
6	TO SPRAY REAR BUMPER ,REAR BUMPER LIP ,REAR BOOT ,REAR PANEL,REAR LH/RH TAIL LAMP PANEL ,REAR TYRE FLOOR PANEL AND TOUCH UP REAR LH/RH FENDER	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,580.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >