

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III18005662/R1PA3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLD283L	Insured Vehicle No :	SHA2611Z
Date of Loss:	25/03/2018	Nature of Claim:	TP
		Claim No:	MCT18030842

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD283L		
Make & Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Engine No:	3ZRB737461
Reg. Date:	22/06/2016 (Man. Year: 2015)	Chassis No:	ZSU600073470
Colour:	White	Odometer:	22899 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,901.80	1,222.29	679.51	35.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,270.00	450.00	820.00	64.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,171.80	1,672.29	1,499.51	47.28
Approved Total (Overridden) (S\$)		1,300.00		

(S\$)	3,171.80	1,300.00	1,871.80	59.01
+ GST 7.00/7.00% (S\$)	222.03	91.00	131.03	59.01
Nett Amount (S\$)	3,393.83	1,391.00	2,002.83	59.01
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 26/03/2018

Date Inspected: 27/03/2018

Estimated Period of Repair: 2.0 days

Inspected At: Shu Fatt Auto Works (HQ)
Block 1009 Bukit Merah Lane 3, #01-90
Singapore 159723

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Apr 2019)	
Parts:	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD283L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Scratched	1,570.92 FL	*1,570.92 FL
2	1		*SET FRT BUMPER CLIPS	Necessary	58.80 FL	*58.80 FL
3	2		*FRT BUMPER SIDE RETAINERS	Not Necessary	185.42 FL	*- FL
4	1		*RT FRT LIGHT GARNISH	Not Necessary	184.31 FL	*- FL
5	1		*FRT BUMPER LOWER GARNISH	Not Necessary	377.80 FL	*- FL
					Sub Total (S\$)	2,377.25
					- List Item Discount on L Items 20.00/25.00% (S\$)	475.45
					Total Parts (S\$)	1,901.80
						1,222.29

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK FRT SUPPORT PANEL,LEFT FRT FENDER ,RENEW FRT BUMPER AND ASSEMBLY	New	550.00	200.00
2	TO RESPRAY DAMAGED PARTS	New	720.00	250.00
Gross Labour Cost (S\$)			1,270.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >