



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving

34 2014 ISUZU FVR34SUQDC ISUXXX (YN6252E)

Date of Loss

10 March 2018

Time of Loss

5.00

Loss Description

YN6252E (INSD) C/W INTO PROPERTY

Comment

### Workshop Details

Total Rebate Amount

35120

Nett Loss Amount

\$34,880.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion \*

29/05/2018



Days of work completion \*

64



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration#

YN6252E

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

01/10/2014



Mileage

Age of Vehicle

3

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2014

ASSESSMENT INFO...

2014

### Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

MUHAMMAD FAIZAL BIN MOHD ISA

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... ISUZU FVR34SUQDC

ASSESSMENT INFO... ISUZU

CATEGORY Model

POLICY INFORMAT... ISUXXX

ASSESSMENT INFO... FVR34SUQDC

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JALFVR347E7000509

CATEGORY Date of Birth

FNOL INFORMATI... 1 January 1986

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 32

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JALFVR347E7000509

CATEGORY Engine No

POLICY INFORMAT... 6HK1660326

ASSESSMENT INFO... 6HK1660326

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 7790

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 70000

FNOL INFORMATI... 9

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF... ▼

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2009

POST SURVEY INF... dd/mm/yyyy 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY Address

FNOL INFORMATI... HDB Bedok, 18 Bedok South Road #14-55, 460018, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S8601630C

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

28/03/2018



Total Loss

**Yes**

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

2500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

275/70R22.5

## Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

**No**

Footbrake (Serviceable)

Yes

**No**

Handbrake (Serviceable)

Yes

**No**

Engine Modification

**Yes**

No

Pre-accident condition

Fair



## Tyre Condition

Spare wheel

Rear Tyre Size

275/70R22.5(D)



---

Front left side

MIRAGE8mm

Front right side

MIRAGE8mm

---

Rear left side

MIRAGE8/8mm

Rear right side

MIRAGE8/8mm



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes☐ No

Part Supplied by AXA

Assessment Details

| General & Workshop Details |      |       |           |          |      |                          |             |                        |           |            |             |            |           |                 |                |
|----------------------------|------|-------|-----------|----------|------|--------------------------|-------------|------------------------|-----------|------------|-------------|------------|-----------|-----------------|----------------|
| Vehicle & Driver Details   |      |       |           |          |      |                          |             |                        |           |            |             |            |           |                 |                |
| Vehicle Condition          |      |       |           |          |      |                          |             |                        |           |            |             |            |           |                 |                |
| Taxes & Ratio              |      |       |           |          |      |                          |             |                        |           |            |             |            |           |                 |                |
| Parts & Labour             |      |       |           |          |      |                          |             |                        |           |            |             |            |           |                 |                |
| Miscellaneous              |      |       |           |          |      |                          |             |                        |           |            |             |            |           |                 |                |
| Summary                    |      |       |           |          |      |                          |             |                        |           |            |             |            |           |                 |                |
| Parts                      |      |       |           |          |      |                          |             |                        |           |            |             |            |           |                 |                |
| <div>AddApproveDeny</div>  |      |       |           |          |      |                          |             |                        |           |            |             |            |           |                 |                |
|                            | EDIT | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME                | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPR/ BTTR% | DISC OUNT% | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) |
|                            |      | 1     | 1         |          |      | HEAD LAMP ASSY RH        |             |                        | Cracked   | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 2     | 1         |          |      | LAMP FOG / SIGNAL RH     |             |                        | Cracked   | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 3     | 1         |          |      | PANEL CORNER RH          |             |                        | Cracked   | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 4     | 1         |          |      | STAY MIRROR RH           |             |                        | Bent      | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 5     | 1         |          |      | MIRROR (M)               |             |                        | Damaged   | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 6     | 1         |          |      | DOOR PANEL RH            |             |                        | Damaged   | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 7     | 1         |          |      | FENDER SIDE RH           |             |                        | Damaged   | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 8     | 1         |          |      | BUMPER ASSY              |             |                        | Bent      | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 9     | 1         |          |      | PANEL BACK CORNER RH     |             |                        | Cut       | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 10    | 1         |          |      | PANEL BACK CORNER LWR RH |             |                        | Damaged   | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 11    | 1         |          |      | STEP UPPER RH            |             |                        | Cracked   | 0          |             |            |           | 0               | Reviewing      |
|                            |      | 12    | 1         |          |      | GARNISH STEP LWR RH      |             |                        | Cracked   | 0          |             |            |           | 0               | Reviewing      |

|  | EDIT | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME                 | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION   | LIST PRICE | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) |
|--|------|-------|-----------|----------|------|---------------------------|-------------|------------------------|-------------|------------|--------------|------------|-----------|-----------------|----------------|
|  |      | 13    | 1         |          |      | STEP PLATE LWR RH         |             |                        | Damaged     | 0          |              |            |           | 0               | Reviewing      |
|  |      | 14    | 1         |          |      | WINDSCREEN FRONT          |             |                        | Cracked     | 0          |              |            |           | 0               | Reviewing      |
|  |      | 15    | 1         |          |      | MOULDING W/SCREEN OTR TOP |             |                        | Necessary   | 0          |              |            |           | 0               | Reviewing      |
|  |      | 16    | 1         |          |      | MOULDING W/SCREEN OTR LWR |             |                        | Necessary   | 0          |              |            |           | 0               | Reviewing      |
|  |      | 17    | 1         |          |      | RH DOOR GLASS             |             |                        | Damaged     | 0          |              |            |           | 0               | Reviewing      |
|  |      | 18    | 1         |          |      | DOOR REGULATOR RH         |             |                        | Serviceable | 0          | 0            | 0          | 0         | 0               | Deny           |
|  |      | 19    | 2         |          |      | DOOR HINGE                |             |                        | Bent        | 0          |              |            |           | 0               | Reviewing      |

#### Labour

|  | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                                                          | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMO |
|--|------|-------|-------------------------|------------------------------------------------------------------------------------|------------|---------------|-------|-----------------|---------|------|
|  |      | 1     |                         | TO REPAIR AND CUT RHS BOTTOM PILLAR & JOIN HOLLOW SECTION                          | 0          | 0             | 0     | Reviewing       |         |      |
|  |      | 2     |                         | TO SUPPLY AND INSTALL 3PCS ALUMINIUM SHEET                                         | 0          | 0             | 0     | Reviewing       |         |      |
|  |      | 3     |                         | NEED TO ALIGNMENT                                                                  | 0          | 0             | 0     | Reviewing       |         |      |
|  |      | 4     |                         | TO SUPPLY WHITE SPRAY PAINT                                                        | 0          | 0             | 0     | Reviewing       |         |      |
|  |      | 5     |                         | TO SUPPLY AND INSTALL 1PC 5'X10' STAINLESS STEEL PLATE AT INTERIOR BOX C/W WELDING | 0          | 0             | 0     | Reviewing       |         |      |

|                                                                                   | EDIT                                                                              | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME             | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMO                                                                                |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-------|-------------------------|-----------------------|------------|---------------|-------|-----------------|---------|-------------------------------------------------------------------------------------|
|  |  | 6     |                         | STEERING ROD ASSEMBLY | 0          | 0             | 0     | Deny            |         |  |
|  |  | 7     |                         | LABOUR                | 0          | 0             | 0     | Reviewing       |         |  |

# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

| EDIT                     |                                                                                   | SR NO | NAME                     | ACTION    | AMOUNT | COMMENT | REMOVE                                                                              |
|--------------------------|-----------------------------------------------------------------------------------|-------|--------------------------|-----------|--------|---------|-------------------------------------------------------------------------------------|
| <input type="checkbox"/> |  | 1     | DAYS OF REPAIR : 10 DAYS | Reviewing |        |         |  |
| <input type="checkbox"/> |  | 2     | FINAL LUMP SUM           | Reviewing | 14000  |         |  |

# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount

\$11,500.00

Claim Amount

\$11,500.00

| CATEGORY      | ESTIMATE    | REVISED AMOUNT |
|---------------|-------------|----------------|
| Miscellaneous | \$14,000.00 | \$14,000.00    |
| Excess        | -\$2,500.00 | -\$2,500.00    |

Submit for Review