

ASS. REC. BY:

REF: CS/FCI18005685/Kgd3/n2 Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person): Karen Tan

of

FCI

Date/Time: 27/3/18 @ 3.31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 3606A

Insured:

SH 7856J

at Workshop m/s

Lian Hong Seng

Tel:

97804939/96754083

of

Blk 5035, Amk Ind. Prk 2# 01-345

Policy No:

D-18088936 MFSH

Claim No:

D18002417 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/3/2018

CA / REV / REP. / REV 24 HRS

1wp

28/03/18

H.O.D. Endorsement:

Date/Time:

4:09pm @ 27/3/18

Person Contacted:

Ah Tock

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLV 3606A-X

SH 7856J - NSI/MC14016231/111gm3c3

D.O.A: 23/8/14

03/4/18 @ 2:35pm messaged to Karen Tan by email.

Kenneth confirmed us \$5150, 6 days.

(Red \$4968, 4972)

REF: FCI

ASSIGNMENT

From: Date: 28/3/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLV 3606A

at Workshop n/s: Lian Hong Seng
of BLK 5035, AMK Ind. Prk 2 #01-345

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lump Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lwp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLV 3606A Yr Regn: 12 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 24/3/18

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 28/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/3 File pass to Catherine

RECEIVED 25 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

17/5 lwp

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

) \$ + RS. \$

) Photos:

) Others:

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

TP

5150

170
50
50
21

291



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005685/Kqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7856J	Veh. Inspected	SLV 3606A
Policy No.		Coverage (\$)	0.00
Claim No.	D18002417MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	27/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/03/2018	Inspection Date	
Survey held at	LIAN HONG SENG MOTOR WORKS BLK 5035 ANG MO KIO IND.PARK 2 #01-345 SINGAPORE 569537		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002417MFSH

Date: 03 April 2018

Our Ref: CS/FCI18005685/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 3606A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/03/2018 at the premises of M/s LIAN HONG SENG, and have the following to report:-

Workshop Estimate Amount	: S\$ 10,118.00 .
Revised Estimate Amount	: S\$ 5,396.37 .
"Check" Items Amount	: S\$ 3,213.44 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	26-03-2018	Our Ref No. D18002417MFSH
Accident Date	24-03-2018	Claim Type. Third Party
Insured Vehicle	SH7856J	Third Party Vehicle. SLV3606A
Survey Location	BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-345	
Contact Person.	NA	
Contact No.	97804939/ 96754083	Fax No. 64843538
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LIAN HONG SENG MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236326)



PRI Documents



Close



PRI Header Details

Claim No	D18002417MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & LIAN HON
Workshop Name	LIAN HONG SENG MOTOR WORKS (Contact Person : NA)	Survey Location & Contact Details	BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-345 Mobile: 96754083 , Phone: 97804939 , Fax: 64843531 EmailId: LHSTOK@YAHOO.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7856J	TP Vehicle No	SLV3606A
PRI Recieved Date	27-03-2018 01:48:22 PM	Surveyor Appointed Date	27-03-2018 03:30:03 PM	Surveyor Accept Date	27-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-03-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 3 April 2018 2:35 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002417MFSH/1
Attachments: CSFCI18005685Kqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SLV 3606A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Tuesday, 27 March 2018 4:11 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18002417MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Tuesday, 27 March 2018 3:29 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18002417MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

LKK Auto Consultants Pte Ltd
• Resurvey before/after Spray Painting
• Damaged parts to Display when Re-inspected
• Parts prices subject to confirmation by MSFC
• Third Party Survey
• No illegal modification is allowed

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
#01-345 SINGAPORE 569538

DATE: 27/3/2018
VEHICLE NO: SLV3606A
MODEL: KIA CAREN
ACCIDENT DATE: 24/3/2018
TYPE OF CLAIM: TP
CLAIM ADVISOR: TOK
LHSTOK@YAHOO.COM
96754083

ESTIMATE

ATTN: FIRST CAPITAL INSURANCE

DESCRIPTION	QTY	LIST PRICE
PARTS		
TAILGATE	1	\$ 1,567.90
TAILGATE LOCK	1	\$ 278.50
REAR EMBLEM	1	\$ 75.40
REAR LOGO - CARENS	1	\$ 65.30
REAR LOGO - CRDI	1	\$ 63.10
REAR BUMPER	1	\$ 997.50
REAR BUMPER LOWER - BLACK	1	\$ 771.30
REAR BUMPER LOWER GARNISH (SILVER)	1	\$ 543.10
REAR BUMPER CLIPS	10	\$ 30.00
REAR BUMPER RETAINER	2	\$ 88.40
REAR BUMPER BRACKET	2	\$ 144.60
REAR BUMPER REFLECTOR	2	\$ 362.20
REAR REINFORCEMENT	1	\$ 435.50
END PANEL	1	\$ 645.80
SPARE TYRE PANEL	1	REPAIR
LH REAR FENDER	1	REPAIR
END PANEL TOP GARNISH	1	\$ 289.60
REAR WEATHER STRIP	1	\$ 255.70
REVERSE SENSOR - 1SET	1	\$ 456.10
TOTAL:		\$ 7,070.00
DISCOUNT 10%:		\$ 707.00
		\$ 6,363.00

Not Authorized

1. B. 1
Resurvey B4 paint

5 days

He nash
96910663

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
#01-345 SINGAPORE 569538

DATE: 27/3/2018
VEHICLE NO: SLV3606A
MODEL: KIA CAREN

S/NET

REAR WINDSCREEN SEALANT	1	<i>nu</i>	\$	100.00
END PANEL SEALANT	1	<i>nu</i>	\$	100.00
REAR NUMBER PLATE	1	<i>pu</i>	\$	45.00
TOTAL			\$	245.00

405N
7 305N
X

LABOUR

	PRICE
LABOUR FOR FACILITATE REPAIR - REAR PORTION	\$ 1,500.00
TO RESPRAY AFFECTED AREAS - REAR PORTION	\$ 1,300.00
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$ 50.00
TO REMOVE AND REFIT TAILGATE COMPONENT	\$ 200.00
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$ 200.00
TO REMOVE AND REFIT REVERSE SENSOR	\$ 80.00
SUNDARIES	\$ 80.00
RUST PROOFING	\$ 100.00

TOTAL: \$ 3,510.00

TOTAL: \$ 10,118.00

7 600
6601
201
601
7X111
601
7X111
301

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
#01-345 SINGAPORE 569538

DATE: 2/7/2018
VEHICLE NO: SLV3606A
MODEL: KIA CAREN
ACCIDENT DATE: 24/3/2018
TYPE OF CLAIM: TP
CLAIM ADVISOR: TOK
LHSTOK@YAHOO.COM
96754083

ESTIMATE

ATTN: FIRST CAPITAL INSURANCE

DESCRIPTION	QTY	LIST PRICE
PARTS		
TAILGATE	1	\$ 1,567.90
TAILGATE LOCK	1	\$ 278.50
REAR EMBLEM	1	\$ 75.40
REAR LOGO - CARENS	1	\$ 65.30
REAR LOGO - CRDI	1	\$ 63.10
REAR BUMPER	1	\$ 997.50
REAR BUMPER LOWER - BLACK	1	\$ 771.30
REAR BUMPER LOWER GARNISH (SILVER)	1	\$ 543.10
REAR BUMPER CLIPS	10	\$ 30.00
REAR BUMPER RETAINER	2	\$ 88.40
REAR BUMPER BRACKET	2	\$ 144.60
REAR BUMPER REFLECTOR	2	\$ 362.20
REAR REINFORCEMENT	1	\$ 435.50
END PANEL	1	\$ 645.80
SPARE TYRE PANEL	1	REPAIR
LH REAR FENDER	1	REPAIR
END PANEL TOP GARNISH	1	\$ 289.60
REAR WEATHER STRIP	1	\$ 255.70
REVERSE SENSOR - 1SET	1	\$ 456.10
TOTAL:		\$ 7,070.00
DISCOUNT 10%:		\$ 707.00
		\$ 6,363.00

NOT AUTHORIZED

Presurvey 1-B.1
34 pages

5 days

6 days

the north

96910663

resumy quista week on 29/3

61 Lyr @ 5150h

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
#01-345 SINGAPORE 569538

DATE: 27/3/2018
VEHICLE NO: SLV3606A
MODEL: KIA CAREN

S/NET

REAR WINDSCREEN SEALANT	1	✓	100.00
END PANEL SEALANT	1	✓	100.00
REAR NUMBER PLATE	1	✓	45.00
TOTAL			\$ 245.00

4000
74030580
X

LABOUR

	PRICE
LABOUR FOR FACILITATE REPAIR - REAR PORTION	✓ \$ 1,500.00
TO RESPRAY AFFECTED AREAS - REAR PORTION	✓ \$ 1,300.00
TO CHECK AND RECONNECT ALL NECESSARY WIRING	✓ \$ 50.00
TO REMOVE AND REFIT TAILGATE COMPONENT	✓ \$ 200.00
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	✓ \$ 200.00
TO REMOVE AND REFIT REVERSE SENSOR	✓ \$ 80.00
SUNDARIES	nn x \$ 80.00
RUST PROOFING	✓ \$ 100.00
TOTAL:	\$ 3,510.00
TOTAL:	\$ 10,118.00

7400 600
6601
201
601
X
601
1530
301

Total: \$ 7,149.32

LS: \$ 5,700

5 days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005685/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7856J	Veh. Inspected	SLV 3606A	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002417MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	27/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA CARENS CRDI (A)	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNAHU815VJ7194256	Colour	RED	
Odometer	18597	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	HANKOOK	9 mm	
L/H Front Tyre	225/45 R17	HANKOOK	9 mm	
R/H Rear Tyre	225/45 R17	HANKOOK	9 mm	
L/H Rear Tyre	225/45 R17	HANKOOK	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/03/2018	Inspection Date	28/03/2018	
Survey held at	LIAN HONG SENG MOTOR WORKS BLK 5035 ANG MO KIO IND.PARK 2 #01-345 SINGAPORE 569537			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 3606A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BENT	1,567.90	1,567.90
1	TAILGATE LOCK	DENTED	278.50	278.50
1	REAR EMBLEM	NECESSARY	75.40	75.40
1	REAR LOGO-CARENS	NECESSARY	65.30	65.30
1	REAR LOGO-CRDI	NECESSARY	63.10	63.10
1	REAR BUMPER	BUCKLED	997.50	997.50
1	REAR BUMPER LOWER-BLACK	DENTED / DISTORTED	771.30	771.30
1	REAR BUMPER LOWER GARNISH (SILVER)	CRACKED	543.10	543.10
10	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER RETAINER	SERVICEABLE	88.40	-
2	REAR BUMPER BRACKET	TO REPAIR SEE LABOUR	144.60	-
2	REAR BUMPER REFLECTOR	N/S SCRATCHED / O/S SERVICEABLE	362.20	181.10
1	REAR REINFORCEMENT	BENT	435.50	435.50
1	END PANEL	BENT	645.80	645.80
1	SPARE TYRE PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	LH REAR FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	END PANEL TOP GARNISH	SERVICEABLE	289.60	-
1	REAR WEATHERSTRIP	SERVICEABLE	255.70	-
1	SET REVERSE SENSOR	DENTED / SHORTED	456.10	456.10
	LESS 10% DISCOUNT		-707.00	-611.06
			6,363.00	5,499.54
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
1	END PANEL SEALANT (SN)	NECESSARY	100.00	30.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	45.00	-

Report Ref No. CS/FCI18005685/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDARIES (SN)	NOT NECESSARY	80.00	-
			325.00	70.00
	LABOUR			
	LABOUR FOR FACILITATE REPAIR-REAR PORTION.INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET,SPARE TYRE PANEL AND LH REAR FENDER.		1,500.00	600.00
	TO RESPRAY AFFECTED AREAS-REAR PORTION.		1,300.00	660.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		50.00	20.00
	TO REMOVE AND REFIT TAILGATE COMPONENT.		200.00	60.00
	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR.	NOT NECESSARY	200.00	-
	TO REMOVE AND REFIT REVERSE SENSOR.		80.00	60.00
	RUST PROOFING.		100.00	30.00
			3,430.00	1,430.00
GRAND TOTAL			10,118.00	6,999.54
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,150.00

Report Ref No. CS/FCI18005685/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.